SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
6	223 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10	243 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14	321 S CENTRAL AVE	UNK	C	Y	1"	1/1/2009	L	1"	UNK	NONRES	UNK	L	1"	UNK	CONNECTED TO 5/8" LEAD 11'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17	327 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23	333 S CENTRAL AVE	UNK	C	Y	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	CONNECTED TO 5/8" LEAD 12'E OF BOX. A-1 EXCAVATING. 4/23: Received note from owner that service is copper inside at the entrance.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26	343 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	C	1 1/2"	UNK	NONRES	UNK	C	1 1/2"	UNK	INSTALLED 1-1/2" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
29	345 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
39	421 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	CONNECTED TO 1" COPPER 12'E OF BOX	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
42	435 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45	107 E 5TH ST	UNK	C	UNK	1"	1/1/2015	C	1"	UNK	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48	551 S CENTRAL AVE	N	C	Y	1"	1/1/2009	L	1"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	ATTACHED TO 5/8 LEAD 1'E OG BOX. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	6/13/2013	Cross connection survey	
53	601 S CENTRAL AVE	UNK	UNK-LG	UNK	4"	1/1/1926	CI-U	4"	1/1/1926	NONRES	UNK	CI-U	CI-U		2010- REMOVED MANHOLE & INSTALLED VALVE BOX	Installation Record	N			Field Inspection Only	Y	1/17/2024	Cross Connection Survey	
65	109 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	L	UNK	1/1/1926	NONRES	UNK	UNK	UNK		LOCKING VALVE. Lead on property side per customer.	Previous eval	Y	1/1/2022	Customer self id	Field inspection only	Y	1/1/2022	Customer self id	
65	109 E 9TH ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	NONRES	UNK	L	UNK	UNK	LOCKING VALVE. Lead on property side per customer.	Installation record	N		Visual insp during install or repair	Previous eval	Y	7/19/2023	Customer self id	
68	901 S CENTRAL AVE	UNK	P	Y	2"	7/9/2021	P	2"	UNK	NONRES	UNK	P	2"	UNK	7/9/2021: Removed 4-Lead Goosneck manifold @ WM and 2" existing copper from manifold to CS. Installed new 2" tap 5' West of existing taps. Gaffney installed 2" CS & Box & 2" HDPE from CS - Meter.	Installation Record	Y	7/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
75	630 S CENTRAL AVE-WATER	UNK	DI	UNK	4"	1/1/2009	DI	4"	UNK	NONRES	UNK	DI	4"	UNK	POTABLE SERVICE	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
78	510 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER INTO BLDG. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
84	105 W 5TH ST	UNK	C	UNK	1"	1/1/2013	C	1"	UNK	NONRES	UNK	C	1"	UNK	ATTACHED TO EXISTING 3/4" COPPER 5' PAST VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
90	450 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER 11'W OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
93	444 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2005	C	1"	UNK	NONRES	UNK	C	1"	UNK	BADGER ENVIRONMENTAL 3/4" copper on customer side	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
93	444 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER 10'W OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
99	434 S CENTRAL AVE	UNK	DI	UNK	6"	1/1/2009	DI	6"	UNK	NONRES	UNK	DI	6"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
106	414 S CENTRAL AVE	N	C	Y	1"	1/1/2009	L	1"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	CONNECTED TO 5/8 LEAD 10.5'W OF BOX A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	6/11/2014	Cross connection survey	
108	400 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2013	C	1 1/2"	UNK	NONRES	UNK	C	1 1/2"	UNK	ATTACHED TO 1-1/2" COPPER 3' PAST VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
115	107 W 3RD ST	N	C	Y	1"	1/1/2013	L	1"	1/1/2013	NONRES	UNK	L	UNK	1/1/2013	CONNECTED TO 5/8 LEAD 2.5'N OF VALVE	SL repair/replace record	Y	1/1/2013	Visual insp during install or repair	Previous eval	Y	1/1/2013	Visual Insp during install or repair	
120	236 S CENTRAL AVE	N	C	Y	1 1/2"	1/1/2009	L	1 1/2"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	CONNECTED TO 1-1/2" LEAD 10'W OF BOX	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	12/15/2014	Cross connection survey	
129	115 W 2ND ST	UNK	C	UNK	2"	1/1/2013	C	2"	UNK	NONRES	UNK	C	2"	UNK	ATTACHED TO EXISTING 2" COPPER @ CURB VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
134	166 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	UNK	NONRES	UNK	C	1"	UNK	ATTACHED TO 1" COPPER 10'W OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
144	140 S CENTRAL AVE	N	C	UNK	1"	1/1/2001	L	1"	1/1/2001	NONRES	UNK	L	UNK	1/1/2001	MEWD	SL repair/replace record	Y	1/1/2001	Visual insp during install or repair	Previous eval	Y	10/11/2013	Cross connection survey	
155	126 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2001	C	1 1/2"	UNK	NONRES	UNK	C	1 1/2"	UNK	MEWD. 1-1/2" copper on property side	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
158	122 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2001	C	1"	UNK	NONRES	UNK	C	1"	UNK	MEWD. 3/4" copper on property side	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
165	300 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		SERVICE COMES OFF A PRIVATE LINE ON BLODGETT ST	Installation Record	N			Field Inspection Only	Y	9/16/2013	Cross Connection Survey	
168	308 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		DUPLEX WITH 308A, LV/CB UNKNOWN	Installation Record	N			Field Inspection Only	Y	6/2/2014	Cross Connection Survey	
174	316 N CENTRAL AVE	N	C	UNK	1"	6/4/2020	C	1"	UNK	SF	UNK	C	1"	UNK	EARTH INC. - CONNECTED TO EXISTING 3/4" COPPER 2.5' BEHIND CURB STOP. DUPLEX W/ 316 N. CENTRAL AVE. (Pg. 9 of Const. Report)	Installation Record	Y	6/4/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
177	104 W CLEVELAND ST	N	C	Y	1"	6/9/2020	C	1"	UNK	NONRES	UNK	C	1"	UNK	Earth INC. - Removed lead on street side, connected to existing 3/4" copper 1' behind CS with 1" copper. (Pg. 12 of Const. Report)	Installation Record	Y	6/9/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
184	311 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		DUPLEX WITH 311A, LV/CB UNKNOWN. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	6/9/2014	Cross Connection Survey	
187	305 N CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2009-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	9/12/2013	Cross Connection Survey	
190	UNK	N	L	UNK	5/8"	1/1/1926	P	5/8"	1/1/1926	NONRES	UNK	P	UNK	1/1/1926	2008-REPLACED LEAD WIPE WITH NEW CURB VALVE.	SL repair/replace record	Y	2008	Mech excav	Field inspection only	Y	1/1/2011	Visual Insp during install or repair	
227	133 S CENTRAL AVE #A	N	C	Y	1"	1/1/2001	C	1"	UNK	NONRES	UNK	C	1"	UNK	Verified Lead on customer side via customer photo. MEWD. 10/22: Customer replaced lead service w/ 1" copper.	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
230	137 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2001	C	1"	UNK	NONRES	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
234	145 S CENTRAL AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
238	113 E 2ND ST	UNK	C	UNK	2"	1/1/2015	P	2"	UNK	NONRES	UNK	P	2"	UNK	2" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
241	206 W KALSCHED ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	INSULATED 2X2 1981	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
247	1110 N CHESTNUT AVE	N	UNK	UNK	5/8"	UNK	C	5/8"	UNK	SF	UNK	C	5/8"	UNK	INSULATED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
250	308 W KALSCHED ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	INSULATED 1981	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
253	312 W KALSCHED ST	N	C	UNK	1"	1/1/1962	C	1"	1/1/1962	SF	UNK	C	1"	UNK	INSULATED 2X4 1981, 1-1-2020 J&R VACUUM EXCAVATED MID TERRACE, FOUND 1" COPPER 7'1" DEEP	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
256	400 W KALSCHED ST	N	UNK	UNK	5/8"	1/1/1963	C	5/8"	1/1/1963	SF	UNK	C	5/8"	UNK	SCHRIENERS	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
259	408 W KALSCHED ST	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	SF	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
262	412 W KALSCHED ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SCHUH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
265	416 W KALSCHED ST	UNK	C	UNK	1"	1/1/1969	C	1"	1/1/1969	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED AT CB, FOUND 1" COPPER 8' DEEP	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
268	418 W KALSCHED ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
271	424 W KALSCHED ST	UNK	C	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS. 1-1-2020 J&R VACUUM EXCAVATED 1' FROM CB FOUND 3/4" COPPER 7'7" DEEP	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
274	419 W KALSCHED ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
277	409 W KALSCHED ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
280	405 W KALSCHED ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
283	401 W KALSCHED ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	STRAIGHT OUT OF EAST SIDE OF HOUSE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
286	1208 N FIG AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
289	404 W LEONHARD ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
292	412 W LEONHARD ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1971	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
295	416 W LEONHARD ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1974	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
298	422 W LEONHARD ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1971	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
304	514 W UPHAM ST	UNK	C	UNK	1"	1/1/1969	C	1"	1/1/1969	NONRES	UNK	C	1"	UNK	2003-NEW 1" CORP CONNECTED TO EXISTING 1" COPPER	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
307	1211 N WALNUT AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
310	1205 N WALNUT AVE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-NEW 1" CORP CONNECTED TO EXISTING 3/4 COPPER	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
316	421 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
319	415 W JEFFERSON ST	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
322	411 W JEFFERSON ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
325	407 W JEFFERSON ST	N	C	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	1-1-2020 J&R VACUUM EXCAVATED 1' FROM CB, FOUND 3/4" COPPER 7'2" DEEP	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
328	403 W JEFFERSON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
331	315 W JEFFERSON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
334	313 W JEFFERSON ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
337	311 W JEFFERSON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
340	307 W JEFFERSON ST	N	L	UNK	3/4"	1/1/1958	C	3/4"	1/1/1958	SF	UNK	C	UNK	1/1/1958	2011-REMOVED LEAD WIPE & INSTALLED 1" CURB STOP/BOX. INSTALLED 1" PLASTIC FROM STOP TO INSIDE.	SL repair/replace record	Y	2011	Mech excav	Field inspection only	Y	8/25/2016	Cross Connection Survey	
343	301 W JEFFERSON ST	N	C	UNK	3/4"	9/22/1995	C	3/4"	9/22/1995	SF	UNK	C	3/4"	UNK	REMOVED WIPE @MAIN, INSTALLED 3/4" COPPER FROM MAIN TO CURB VALVE. INSTALLED NEW CURB VALVE. INSULATED MAIN WITH STYROFOAM	Installation Record	Y	9/22/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
349	119 W JEFFERSON ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
352	117 W JEFFERSON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R vac excavated @ EOP, found copper 6' deep. 9/3/2024: removed lead wipe @ wm, replaced w/ 3/4" copper.	Installation Record	Y	9/3/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
355	113 W JEFFERSON ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
358	1200 N CENTRAL AVE	UNK	CI-U	UNK	6"	1/1/1978	CI-U	6"	1/1/1978	NONRES	UNK	CI-U	6"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
361	114 W JEFFERSON ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
364	1009 N CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
367	304 W JEFFERSON ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
370	306 W JEFFERSON ST	N	L	UNK	3/4"	1/1/1959	C	3/4"	1/1/1959	SF	UNK	C	UNK	1/1/1959	2006-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2006	Mech excav	Field inspection only	Y	9/16/2016	Cross Connection Survey	
373	308 W JEFFERSON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
376	316 W JEFFERSON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
379	1010 N FIG AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
382	404 W JEFFERSON ST	N	C	UNK	1"	1/1/1963	C	1"	1/1/1963	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED, FOUND 1" COPPER 6'7" DEEP	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
385	412 W JEFFERSON ST	N	C	UNK	3/4"	1/1/1960	C	3/4"	1/1/1960	SF	UNK	C	3/4"	UNK	1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 3/4" COPPER 7'7" DEEP	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
388	414 W JEFFERSON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1999: MEYERS INSTALLED A CURB BOX	Installation Record	Y	1/1/1999	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
391	1013 N WALNUT AVE	N	C	UNK	1"	1/1/2004	C	1"	UNK	SF	UNK	C	1"	UNK	2004-INSTALLED 1" CORP,COPPER,VALVE,BOX.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
394	1009 N WALNUT AVE	N	C	UNK	1"	1/1/2004	C	1"	UNK	SF	UNK	C	1"	UNK	2004-INSTALLED 1" CORP.COPPER,VALVE,BOX.INSULATED @MAIN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
397	1007 N WALNUT AVE	N	C	UNK	UNK	1/1/2004	C	UNK	UNK	SF	UNK	C	UNK	UNK	2004-INSTALLED 1" CORP,COPPER,VALVE,BOX. INSULATED SERVICE	Installation Record	Y	1/1/2004	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
400	423 W IVES ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2004-INSTALLED 3/4 CORP.	Installation Record	Y	1/1/2004	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
403	904 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	UNK	SF	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
406	902 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	UNK	SF	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
409	814 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	UNK	SF	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
412	800 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	UNK	SF	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
415	414 W IVES ST	N	UNK	UNK	5/8"	8/10/1960	C	5/8"	UNK	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	8/10/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
418	410 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
421	419 W IVES ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
424	415 W IVES ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
427	407 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
430	403 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
433	401 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
436	315 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
439	313 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
442	311 W IVES ST	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VACUUM EXCAVATED @ BOC, FOUND COPPER 6'10" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
445	307 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
448	203 W IVES ST	N	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	STUB-OUT MEYERS. 3/4" Copper on property side confirmed by JN	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
451	117 W IVES ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
454	115 W IVES ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ BOC, FOUND COPPER 7'1" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
457	111 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
460	109 W IVES ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
463	1100 N CENTRAL AVE	UNK	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	NONRES	UNK	C	3/4"	UNK	RETAPPED 2000	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
466	113 W HARRISON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
469	115 W HARRISON ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
472	909 N CHESTNUT AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED WIPE, LOWERED, & INSULATED 1987	Installation Record	Y	1/1/1987	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
475	911 N CHESTNUT AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	INSULATED IN ROAD 1987	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
478	917 N CHESTNUT AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	JOE SCHUB INSULATED 1989	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
481	912 N CHESTNUT AVE	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED LEAD WIPE & INSULATED 1987	Installation Record	Y	1/1/1987	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
484	910 N CHESTNUT AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED WIPE, LOWERED, & INSULATED 1987	Installation Record	Y	1/1/1987	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
487	904 N CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPE & INSULATED 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
490	812 N CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
493	114 W HARRISON ST	N	C	UNK	3/4"	1/1/2007	C	3/4"	1/1/2007	SF	UNK	C	3/4"	UNK	2007-INSTALLED NEW COPPER FROM CORP TO TERRACE.	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
496	108 W HARRISON ST	N	C	UNK	3/4"	1/1/2007	C	3/4"	1/1/2007	SF	UNK	C	3/4"	UNK	2007-INSTALLED 3/4 COPPER FROM CORP TO TERRACE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
499	111 W GRANT ST	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/24/2016	Cross Connection Survey	
502	113 W GRANT ST	UNK	UNK-LG	UNK	UNK	1/1/1934	C	UNK	1/1/1934	SF	UNK	C	C		1996-REMOVED LEAD WIPE @ MAIN	Installation Record	N			Field Inspection Only	Y	9/14/2016	Cross Connection Survey	
505	112 W GRANT ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" COPPER LAID FROM MAIN TO CURB BOX	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
508	110 W GRANT ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" COPPER LAID FROM MAIN TO CURB BOX 7" DEEP	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
511	111 W FRANKLIN ST	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		REPLACED 10' OF LEAD FROM THE MAIN TOWARD THE CURB BOX	Installation Record	N			Field Inspection Only	Y	9/8/2016	Cross Connection Survey	
514	115 W FRANKLIN ST	N	L	UNK	3/4"	1/1/1943	C	3/4"	1/1/1943	SF	UNK	C	UNK	1/1/1943	2006-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2006	Mech excav	Field inspection only	Y	5/18/2020	Cross Connection Survey	
517	610 N CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1938	C	3/4"	1/1/1938	SF	UNK	UNK	UNK		<Null>	Installation Record	N			Field Inspection Only	Y	8/15/2016	Cross Connection Survey	
520	608 N CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/27/2016	Cross Connection Survey	
523	606 N CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1935	C	UNK	1/1/1935	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/15/2016	Cross Connection Survey	
526	600 N CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		REMOVED WIPE & INSULATED 1987	Installation Record	N			Field Inspection Only	Y	8/23/2016	Cross Connection Survey	
529	204 W EDISON ST	UNK	UNK-LG	UNK	UNK	1/1/1944	C	UNK	1/1/1944	SF	UNK	C	C		CORNER HOUSE	Installation Record	N			Field Inspection Only	Y	8/18/2016	Cross Connection Survey	
532	508 N CHESTNUT AVE	N	C	UNK	3/4"	9/7/2017	C	3/4"	9/7/2017	SF	UNK	C	3/4"	UNK	NEW COPPER INSTALLED FROM MAIN TO INSIDE HOUSE, GAFFNEY PLBG--2017	Installation Record	Y	9/7/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
541	201 W DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
544	205 W DOEGE ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	GOOSENECK	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
547	209 W DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/29/2016	Cross Connection Survey	
556	511 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	DIRECTIONAL BORED. 3/4" COPPER INSIDE.	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
559	212 W EDISON ST	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	SERVICE COMES OFF 16" ON WALNUT. DIRECTIONAL BORED. 5/8" COPPER INSIDE.	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
562	603 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
565	607 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	DIRECTIONAL BORED, 3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
568	611 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	DIRECTIONAL BORED, 3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
571	615 N WALNUT AVE	N	C	Y	1"	1/1/2006	L	1"	1/1/2006	SF	UNK	L	UNK	1/1/2006	DIRECTIOAL BORED LEAD ON PROP.SIDE / COPPER INSIDE	SL repair/replace record	Y	1/1/2006	Visual insp during install or repair	Previous eval	Y	9/12/2016	Cross connection survey	
574	612 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
580	508 N WALNUT AVE	N	C	UNK	1"	1/1/2006	L	1"	1/1/2006	SF	UNK	L	UNK	1/1/2006	5/8" LEAD INSIDE	SL repair/replace record	Y	1/1/2006	Visual insp during install or repair	Previous eval	Y	8/25/2016	Cross connection survey	
586	400 W DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
589	314 W DOEGE ST	N	L	UNK	5/8"	1/1/1940	C	5/8"	1/1/1940	SF	UNK	C	UNK	1/1/1940	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 4'9" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	1/6/2014	Visual Insp during install or repair	
592	412 N WALNUT AVE	UNK	C	Y	1"	1/1/2021	C	1"	1/1/2021	SF	UNK	C	1"	UNK	2021: Replaced lead with copper from main to meter. Installed 1" corp 3' East of old 3/4" corp. New curb valve and 1" copper to meter	Installation Record	Y	1/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
595	406 N WALNUT AVE	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	NEW 1" CORP, 1" COPER FOR CORP TO CURB BOX. 3/4" COPPER INSIDE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
598	409 N WALNUT AVE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	NEW 1" CORP, 1" COPPER FROM CORP TO CURB BOX. 3/4 COPPER INSIDE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
601	208 W DOEGE ST	N	C	UNK	1"	1/1/1962	C	1"	1/1/1962	SF	UNK	C	1"	UNK	Y'D SERVICE WITH 208 W DOEGE. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 4'6" DEEP	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
604	109 W DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1939	C	UNK	1/1/1939	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/10/2016	Cross Connection Survey	
607	113 W DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/10/2016	Cross Connection Survey	
610	507 N CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
613	513 N CHESTNUT AVE	UNK	UNK-LG	UNK	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	C		Y-CONNECTION INSTALLED.	Installation Record	N			Field Inspection Only	Y	9/7/2016	Cross Connection Survey	
616	109 W EDISON ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1" COPPER OFF CHESTNUT TO 'Y' & 3/4" CONTINUES TO 109 W. EDISON.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
619	611 N CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/14/2016	Cross Connection Survey	
622	613 N CHESTNUT AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF FRANKLIN. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 5'9" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
625	507 N CEDAR AVE	N	C	Y	3/4"	6/1/2022	C	3/4"	6/1/2022	SF	UNK	C	3/4"	UNK	6/22: Dug & removed lead from wm-sidewalk. Replaced w/ 1" copper, new 1" corp., 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
628	306 E EDISON ST	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 17 of the construction report	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
631	603 N CEDAR AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 5'7" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
634	607 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/2/22: Dug @ wm & found 3' lead gooseneck. Removed and replaced w/ 3/4" copper. Re-used exsiting corp., connected to existing 3/4" copper.	Installation Record	Y	6/2/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
637	609 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22: Dug @ wm & found 3' lead gooseneck. Removed lead & replaced w/ 3/4" copper. Reused existing corp & connected to existing 3/4" copper.	Installation Record	Y	6/2/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
640	613 N CEDAR AVE	N	C	Y	1"	6/24/2022	C	1"	6/24/2022	SF	UNK	C	1"	UNK	6/24/22: Replaced lead from wm - sidewalk w/ 1" copper. Connected to existing 3/4" copper @ the sidewalk. Used existing corp due to there being no space for a new tap. Stopped 1" copper 2' from wm & conn. to exist. corp w/ 3/4" copper	Installation Record	Y	6/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
643	312 E FRANKLIN ST	UNK	C	UNK	1"	6/16/2022	C	1"	6/16/2022	SF	UNK	C	1"	UNK	Pg. 16 of Construction Report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/16/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
646	400 E FRANKLIN ST	UNK	C	UNK	1"	6/16/2022	C	1"	6/16/2022	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	6/16/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
649	701 N CEDAR AVE	N	C	Y	1"	6/23/2022	C	1"	6/23/2022	SF	UNK	C	1"	UNK	6/23/22: Removed lead from wm - sidewalk. Installed 1" copper, new 1" cs & box and new 1" tap and corp. Connected to existing 3/4" copper on the east edge of the sidewalk. Abandoned existing corp. 3' South of the new corp.	Installation Record	Y	6/23/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
652	703 N CEDAR AVE	N	UNK	UNK	3/4"	1/1/1995	C	3/4"	1/1/1995	SF	UNK	C	3/4"	UNK	CURB STOP PUT IN DURING SEWER REPAIR	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
655	709 N CEDAR AVE	UNK	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22: Dug @ wm & found 3' lead gooseneck. Removed lead & replaced w/ 3/4" copper. Reused existing corp & connected to existing 3/4" copper.	Installation Record	Y	6/2/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
658	717 N CEDAR AVE	N	C	Y	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE IN STREET--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
661	306 E GRANT ST	N	C	UNK	1"	5/2/2022	C	1"	5/2/2022	SF	UNK	C	1"	UNK	5/2/22: Installed new 1" tap w/ tapping saddle, 12" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/2/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
664	712 N CHERRY AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1971	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
667	706 N CHERRY AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
670	304 E GRANT ST	UNK	C	UNK	1"	5/24/2022	C	1"	5/24/2022	SF	UNK	C	1"	UNK	5/25/22: Installed 8" tapping saddle w/ 1" C.C., ran 1" copper to new curb valve and box and extended 1" copper to South edge of sidewalk. Original service in the driveway was abandonded when new wm was installed.	Installation Record	Y	5/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
675	910 N CEDAR AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
678	904 N CEDAR AVE	UNK	C	UNK	3/4"	10/1/2019	P	3/4"	10/1/2019	SF	UNK	P	3/4"	UNK	GAFFNEY PLBG - 3/4" COPPER FROM CURB VAVLE TO BACK OF CURB. 1" PLASTIC FROM CURB VAVLE TO HOUSE. FEEDS 904 AND 906 N. CEDAR	Installation Record	Y	10/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
681	900 N CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
684	812 N CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
690	808 N CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
693	215 E GRANT ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
696	211 E GRANT ST	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VACUUM EXCAVATED @ BOC, FOUND COPPER 7'6" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
703	714 N CEDAR AVE	N	C	Y	1"	5/18/2021	C	1"	5/18/2021	SF	UNK	C	1"	UNK	5/18/21 - Abandoned old corp. 3' North of new corp. Replaced lead w/ 1" copper from wm to house. (Reigel). Reduced to 3/4" copper 6" after cs. Reigel replaced galvanized on customer side with 3/4" copper	Installation Record	Y	5/18/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
706	710 N CEDAR AVE	N	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	REPLACED FROM METER TO MAIN 2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
709	708 N CEDAR AVE	UNK	C	Y	1"	6/1/2022	C	1"	6/1/2022	SF	UNK	C	1"	UNK	6/22: Dug & found lead from wm - sidewalk. Replaced w/ 1" copper. Abandoned existing corp and installed new 1" corp. Also installed new 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
712	704 N CEDAR AVE	UNK	C	Y	1"	6/1/2022	C	1"	6/1/2022	SF	UNK	C	1"	UNK	6/22: Dug & found lead from wm - sidewalk. Removed lead & replaced w/ 1" copper. Abandoned old corp & installed new 1" corp. Connected to existing 3/4" coppper 18" East of the 1" cs.	Installation Record	Y	6/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
715	610 N CEDAR AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
718	606 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22: Dug @ wm & found 3' Lead gooseneck. Removed lead & replaced w/ 3/4" copper. Reused existing corp.	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
721	213 E EDISON ST	N	C	Y	1"	6/1/2022	L	1"	6/1/2022	SF	UNK	L	UNK	6/1/2022	6/22: Dug & removed lead from wm-cs. Replaced lead w/ 1" copper, new 1" corp. connected to existing 3/4" copper 12" East of cs. Found 6" of 3/4" copper connected to lead after the cs. Lead is in the house before the meter.	SL repair/replace record	Y	6/1/2022	Visual insp during install or repair	Previous eval	Y	10/20/2016	Cross connection survey	
724	214 E EDISON ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
727	508 N CEDAR AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/27/22: Dug @ wm and found 3/4" copper buried in 3/4" clean stone. Found newer cb also that wasn't mapped.	Installation Record	Y	6/27/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
730	504 N CEDAR AVE	N	C	Y	3/4"	9/25/2020	C	3/4"	9/25/2020	SF	UNK	C	3/4"	UNK	9-25-2020 REMOVED LEAD WIPE AT WM, INSTALLED NEW 3/4" COPPER FROM MAIN TO NEW CS & BOX, 3/4" COPPER ON CUSTOMER SIDE. 2022: Removed all lead from service, 3/4" copper frm main to meter. Service is 100% copper.	Installation Record	Y	9/25/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
733	215 E DOEGE ST	N	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	CB/LV UNKNOWN. 6/22: Dug & found 1" copper from wm-cs. Installed 1" curb box due to street dept. damaging during ditching.	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
736	212 E DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/20/2016	Cross Connection Survey	
739	210 E BECKER RD	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
743	501 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/24/2016	Cross Connection Survey	
746	505 N MAPLE AVE	N	C	Y	3/4"	9/13/2017	C	3/4"	9/13/2017	SF	UNK	C	3/4"	UNK	REPLACED LEAD W/ 3/4" COPPER FROM MAIN TO INSIDE OF HOUSE--2017	Installation Record	Y	9/13/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
749	507 N MAPLE AVE	N	C	Y	3/4"	10/18/2017	C	3/4"	10/18/2017	SF	UNK	C	3/4"	UNK	1982-RETAPPED, LOWERED, INSULATED/REMOVED LEAD & INSTALLED NEW COPPER FROM MAIN TO HOUSE, INSULATED--2017	Installation Record	Y	10/18/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
752	513 N MAPLE AVE	UNK	C	Y	1"	7/15/2021	C	1"	7/15/2021	SF	UNK	C	1"	UNK	7/15/2021: Retapped 6' South of old tap. 1" copper pulled in from wm-cs (replaced full lead). Aaron Plbg. replaced lead w/ 1" HDPE from cs-meter. Installed new cs & box	Installation Record	Y	7/15/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
755	209 E EDISON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
758	207 E EDISON ST	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/10/2016	Cross Connection Survey	
761	605 N MAPLE AVE	N	C	Y	3/4"	11/22/2022	C	3/4"	11/22/2022	SF	UNK	C	3/4"	UNK	11/22/22: Removed all lead, replaced w/ 3/4" copper from main to house. (Kasner)	Installation Record	Y	11/22/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
764	609 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/20/2016	Cross Connection Survey	
767	701 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1942	C	UNK	1/1/1942	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/19/2016	Cross Connection Survey	
770	703 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/27/2016	Cross Connection Survey	
773	705 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	IRON	Installation record	N		Visual insp during install or repair	Previous eval	Y	9/27/2016	Cross connection survey	
776	707 N MAPLE AVE	N	L	UNK	UNK	1/1/1926	P	UNK	1/1/1926	SF	UNK	P	UNK	1/1/1926	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 7' DEEP; 3/4" Copper Inside	Previous eval	Y	2020	Mech excav	Field inspection only	Y	12/18/2017	Visual Insp during install or repair	
779	709 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/6/2016	Cross Connection Survey	
783	713 N MAPLE AVE	UNK	C	Y	1"	11/29/2023	C	1"	11/29/2023	SF	UNK	C	1"	UNK	11/29/23: Replaced 3/4" copper and lead in the street w/ 1" copper. used existing corp.	Installation Record	Y	11/29/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
786	207 E GRANT ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
789	803 N MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
792	815 N MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
795	901 N MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
798	907 N MAPLE AVE	N	C	UNK	3/4"	1/1/2003	C	3/4"	1/1/2003	SF	UNK	C	3/4"	UNK	2003-REPLACED SERVICE MAIN TO LOT LINE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
801	911 N MAPLE AVE	N	C	UNK	UNK	1/1/2003	C	UNK	1/1/2003	SF	UNK	C	UNK	UNK	2003- NEW 3/4 COPPER MAIN TO TERRACE.LOWERED UNDER STORM	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
804	913 N MAPLE AVE	N	C	UNK	UNK	1/1/2003	C	UNK	1/1/2003	SF	UNK	C	UNK	UNK	2003- NEW 3/4 COPPER MAIN TO LOT LINE	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
824	908 N MAPLE AVE	N	C	UNK	UNK	1/1/2003	C	UNK	1/1/2003	SF	UNK	C	UNK	UNK	2003-NEW 3/4 COPPER MAIN TO TERRACE	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
830	900 N MAPLE AVE	N	C	UNK	3/4"	1/1/2003	C	3/4"	1/1/2003	SF	UNK	C	3/4"	UNK	2003-REPLACED & LOWERED FROM MAIN TO CURB VALVE - REPLACE FROM CS TO HOUSE WITH 3/4" COPPER 2018	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
833	109 E HARRISON ST	N	C	UNK	UNK	1/1/2003	C	UNK	1/1/2003	SF	UNK	C	UNK	UNK	2003- NEW 3/4 COPPER FROM MAIN TO 2' BEHIND GAS MAIN	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
839	808 N MAPLE AVE	UNK	C	Y	1"	11/9/2022	C	1"	11/9/2022	SF	UNK	C	1"	UNK	11-9-22: Removed lead both property side & street side and replaced w/ copper.	Installation Record	Y	11/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
842	800 N MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
845	704 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	P	UNK	1/1/1922	SF	UNK	P	P		<Null>	Installation Record	N			Field Inspection Only	Y	9/30/2016	Cross Connection Survey	
849	608 N MAPLE AVE	N	L	UNK	UNK	1/1/1945	C	UNK	1/1/1945	SF	UNK	C	UNK	1/1/1945	2012-REMOVED LEAD WIPE AT CURB VALVE(GAFFNEY PLBG.)	Previous eval	Y	2012	Mech excav	Field inspection only	Y	9/6/2016	Visual Insp during install or repair	
852	506 N MAPLE AVE	N	C	Y	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD & INSTALLED NEW COPPER FROM MAIN TO C.B/C.V., INSULATED--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
855	504 N MAPLE AVE	N	C	Y	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	2017-REPLACED LEAD SERVICE FROM CORP TO CURB VALVE WITH 3/4" COPPER. 4/24/23: Gaffney replaced galvanized w/ 3/4" copper cs-meter. Installed new 3/4" cs & box.	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
858	412 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		1982-RETAPPED, LOWERED & INSULATED	Installation Record	N			Field Inspection Only	Y	9/2/2016	Cross Connection Survey	
864	408 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		1982-RETAPPED, LOWERED & INSULATED	Installation Record	N			Field Inspection Only	Y	9/1/2016	Cross Connection Survey	
868	505 N CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 6'6" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	6/24/2013	Cross Connection Survey	
871	507 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		LOCATION VERIFIED 1/97	Installation Record	N			Field Inspection Only	Y	6/20/2013	Cross Connection Survey	
880	701 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		3/4" COPPER LOCKING VALVE. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	6/20/2013	Cross Connection Survey	
883	712 N CENTRAL AVE	UNK	C	Y	1"	5/11/2021	UNK	1"	5/11/2021	NONRES	UNK	UNK	1"	UNK	5/11/2021-Lead removed in street (main-cs). New tap 5' South of old tap and 2.5' North of new tap for 708 N. Central Ave. Installed new CS & Box, did not connect to anything after CS.	Installation Record	Y	5/11/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
886	706 N CENTRAL AVE	N	L	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2009-REIGELS INSTALLED CURB VALVE W/ BOX	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	12/2/2014	Cross Connection Survey	
889	702 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		LOCATION VERIFIED 1/97	Installation Record	N			Field Inspection Only	Y	12/3/2014	Cross Connection Survey	
894	700 N CENTRAL AVE	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
901	500 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	12/8/2014	Cross Connection Survey	
904	500 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
907	504 N CHERRY AVE	N	C	Y	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX 8/23/22-Customer replaced lead w/ 1" copper	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
910	512 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX. CONNECTED TO COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
913	313 E EDISON ST	UNK	C	UNK	1"	8/23/2023	C	1"	8/23/2023	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 18 of the construction report	Installation Record	Y	8/23/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
916	411 E EDISON ST	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 19 of the construction report	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
919	503 E EDISON ST	UNK	C	UNK	1"	8/1/2023	C	1"	8/1/2023	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 19 of the construction report	Installation Record	Y	8/1/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
922	513 E EDISON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
925	515 E BECKER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
931	606 N ASH AVE	UNK	C	UNK	1"	6/8/2021	C	1"	6/8/2021	SF	UNK	C	1"	UNK	30' of 1" Type 'K' Copper from WM - CS then 14.5' of 1" from CS to existing 3/4" Copper	Installation Record	Y	6/8/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
933	608 N ASH AVE	UNK	C	UNK	1"	6/7/2021	C	1"	6/7/2021	SF	UNK	C	1"	UNK	30' - 1" Type 'K' Copper from WM - CS then 15' - 1" Copper from CS to existing 3/4" Copper	Installation Record	Y	6/7/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
936	610 N ASH AVE	UNK	Unk	UNK	1"	6/4/2021	C	1"	6/4/2021	SF	UNK	C	1"	UNK	30' - 1" Type 'K' Copper from WM - CS then 10' of 1" Copper from CS to existing 3/4" Copper	Installation Record	Y	6/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
939	612 N ASH AVE	UNK	C	UNK	1"	6/3/2021	C	1"	6/3/2021	SF	UNK	C	1"	UNK	30' - 1" Type 'K' Copper from WM - CS then 12" - 1" Copper to existing 3/4" Copper	Installation Record	Y	6/3/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
942	614 N ASH AVE	UNK	C	UNK	1"	6/3/2021	C	1"	6/3/2021	SF	UNK	C	1"	UNK	6/3/2021-30' of 1" copper from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper	Installation Record	Y	6/3/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
945	616 N ASH AVE	UNK	C	UNK	1"	6/2/2021	C	1"	6/2/2021	SF	UNK	C	1"	UNK	6/2/2021-28' of 1" from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper	Installation Record	Y	6/2/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
948	620 N ASH AVE	UNK	C	UNK	1"	6/2/2021	C	1"	6/2/2021	SF	UNK	C	1"	UNK	6/2/2021- 30' of 1" copper from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper	Installation Record	Y	6/2/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
951	622 N ASH AVE	UNK	C	UNK	1"	6/1/2021	C	1"	6/1/2021	SF	UNK	C	1"	UNK	27' of 1" from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper. Water service is 5' north of sanitary manhole & insulated	Installation Record	Y	6/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
954	626 N ASH AVE	UNK	C	UNK	1"	6/1/2021	C	1"	6/1/2021	SF	UNK	C	1"	UNK	27' of 1" from main to curb box - 12" of 1" from curb valve to existing 3/4" copper	Installation Record	Y	6/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
957	623 N PLUM AVE	N	C	Y	1"	5/27/2022	C	1"	5/27/2022	SF	UNK	C	1"	UNK	5/27/22: Pg. 7 of construction report. Installed new 1" corp., 4' - 1" copper, connected to existing 3/4" copper. Tap is 40' East from hyd tee. (no lead)	Installation Record	Y	5/27/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
960	618 N PEACH AVE	N	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
963	626 N PEACH AVE	N	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
966	707 N PLUM AVE	N	C	UNK	1"	1/1/1966	C	1"	1/1/1966	SF	UNK	C	1"	UNK	SCHREINERS. 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 6' DEEP	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
969	711 N PLUM AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	BILL REIGEL/DUPLEX WITH 713 N PLUM	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
972	605 E FRANKLIN ST	UNK	C	UNK	1"	5/19/2022	C	1"	5/19/2022	SF	UNK	C	1"	UNK	5/19/22: Pg 3 of Cons. Report. Replaced existing 3/4" copper service w/ 1" copper, 1" corp. and 1" cs & box. Conn. to exist. 3/4" copper @ the sidewalk.	Installation Record	Y	5/19/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
975	712 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
978	716 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
981	720 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
984	627 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
987	701 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
990	713 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
993	721 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
996	725 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
999	801 N PEACH AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	NONRES	UNK	C	1"	UNK	2001-3/4" CORP,CURB VALVE & BOX.SERVICE IS OFF GRANT ST.	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1002	815 N PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1005	901 N PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1008	724 N PEACH AVE	N	C	UNK	1"	5/11/2022	C	1"	5/11/2022	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED 2' FROM CB, FOUND 3/4" COPPER 7'3" DEEP. 5/11/22: Installed new 1" tap w/ tapping saddle, 18" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1011	606 E GRANT ST	N	C	UNK	1"	5/12/2022	C	1"	5/12/2022	SF	UNK	C	1"	UNK	5/12/22: Installed new 1" tap w/ tapping saddle, 18" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/12/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1014	508 E GRANT ST	N	C	UNK	1"	5/9/2022	C	1"	5/9/2022	SF	UNK	C	1"	UNK	5/9/22: Installed new 1" tap w/ tapping saddle, 30" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1017	504 E GRANT ST	N	C	UNK	1"	5/9/2022	C	1"	5/9/2022	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 7' DEEP, 5/9/22: Installed new 1" tap w/ tapping saddle, 18" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1020	500 E GRANT ST	N	C	UNK	1"	5/5/2022	C	1"	5/5/2022	SF	UNK	C	1"	UNK	5/5/22: Installed new 1" tap w/ tapping saddle, 4' - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/5/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1023	408 E GRANT ST	N	C	UNK	1"	5/4/2022	C	1"	5/4/2022	SF	UNK	C	1"	UNK	5/4/22: Installed new 1" tap w/ tapping saddle, 12" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/4/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1029	509 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1032	513 E FOREST ST	N	C	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	1-1-2020 J&R VACUUM EXCAVATED 6' FROM CB, FOUND 3/4" COPPER 6'7" DEEP	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1035	504 E FOREST ST	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1967	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1038	500 E FOREST ST	N	UNK	UNK	5/8"	1/1/1966	C	5/8"	1/1/1966	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1966	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1041	422 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1044	412 E FOREST ST	UNK	C	UNK	1"	1/1/1970	C	1"	1/1/1970	SF	UNK	C	1"	UNK	GAFFNEY. J&R VACUUM EXCAVATED 1-1-2020, FOUND 1" COPPER 1' FROM CB 7' DEEP	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1047	415 E FRANKLIN ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2022 - Replaced lead gooseneck at water main, replaced w/ 3/4" copper.	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1050	417 E FRANKLIN ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1053	419 E FRANKLIN ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1056	425 E FRANKLIN ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1059	509 E FRANKLIN ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1062	623 N ASH AVE	UNK	C	UNK	1"	6/1/2021	C	1"	6/1/2021	SF	UNK	C	1"	UNK	17' of 1" from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper	Installation Record	Y	6/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1065	619 N ASH AVE	UNK	C	UNK	1"	6/2/2021	C	1"	6/2/2021	SF	UNK	C	1"	UNK	6/2/2021-18' of 1" copper from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper	Installation Record	Y	6/2/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1068	613 N ASH AVE	UNK	C	UNK	1"	6/3/2021	C	1"	6/3/2021	SF	UNK	C	1"	UNK	17' of 1" Copper from main to curb valve. 12" of 1" from curb valve to existing 3/4" Copper	Installation Record	Y	6/3/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1071	611 N ASH AVE	UNK	C	UNK	1"	6/4/2021	C	1"	6/4/2021	SF	UNK	C	1"	UNK	17' - 1" Type 'K' Copper from WM - CS then 12" - 1" Copper from CS to existing 3/4" Copper	Installation Record	Y	6/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1074	609 N ASH AVE	UNK	C	UNK	1"	6/7/2021	C	1"	6/7/2021	SF	UNK	C	1"	UNK	17' - 1" Type 'K' Copper from WM - CS then 8" of 1" Copper from CS to 3/4" Copper then 12" - 3/4" Copper to existing 5/8" Copper	Installation Record	Y	6/7/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1077	613 E BECKER RD	UNK	UNK-LG	UNK	UNK	1/1/1940	C	UNK	1/1/1940	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/1/2016	Cross Connection Survey	
1080	615 E BECKER RD	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1083	610 N PLUM AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1086	614 N PLUM AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1089	622 N PLUM AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1092	626 N PLUM AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1095	617 E BECKER RD	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER/ SERVICE COME OFF BECKER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1098	611 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIEWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1101	601 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1104	713 E BECKER RD	N	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1110	708 E BECKER RD	N	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1113	517 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	UNK	3/4"	1/1/2001	SF	UNK	UNK	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1116	515 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1119	513 N PEACH AVE	N	C	Y	3/4"	UNK	C	3/4"	6/27/2023	SF	UNK	C	3/4"	UNK	6/27/23: Dug @ wm, replaced lead gooseneck and 12' 3/4" copper. connected to existing 3/4" copper @ swr. main. Meyers replaced sanitary lateral from main to house. Found 3/4" copper East of the sidewalk.	Installation Record	Y	6/27/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1122	511 N PEACH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/27/23: Dug @ wm, replaced 18" lead wipe w/ 3/4" copper. Conn. to existing 3/4" copper @ wm.	Installation Record	Y	6/27/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1125	507 N PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1128	501 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1941	C	UNK	1/1/1941	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/14/2016	Cross Connection Survey	
1131	500 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		C.B. LOCATION VERIFIED 5/19/97	Installation Record	N			Field Inspection Only	Y	11/21/2016	Cross Connection Survey	
1134	504 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	12/20/2016	Cross Connection Survey	
1137	508 N PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1140	514 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/28/2016	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1143	515 N ASH AVE	UNK	C	Y	1"	5/19/2021	C	1"	5/19/2021	SF	UNK	C	1"	UNK	5-19-21 - New 1" tap 3' East of old tap (left in place), Removed lead from main to cs & replaced w/ 1" copper. Installed new 1" cs. Reigel Plbg installed 3/4" copper to house.	Installation Record	Y	5/19/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1146	511 N ASH AVE	N	C	Y	1"	6/7/2024	L	5/8"	1/1/1929	SF	UNK	C	C		6/7/24: Removd lead from wm-cs. Replaced w/ 1" corp, 1" copper, 1" cs & box. Conn. to existing 5/8" lead 18" after cs. Old corp is 4' North of new corp.	SL repair/replace record	Y	6/7/2024	Visual insp during install or repair	Field Inspection Only	Y	6/7/2024	Visual Insp during install or repair	
1149	509 N ASH AVE	UNK	C	UNK	1"	6/10/2024	C	1"	6/10/2024	SF	UNK	C	1"	UNK	6/10/24: Installed new 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 12" after cs.	Installation Record	Y	6/10/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1152	507 N ASH AVE	N	C	UNK	1"	6/10/2024	C	3/4"	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	Y	6/10/2024	Visual insp during install or repair	Field Inspection Only	Y	10/21/2016	Cross Connection Survey	
1155	505 N ASH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/7/24: Lead wipe removed at wm. Connected to existing 3/4" copper at wm.	Installation Record	Y	6/7/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1158	503 N ASH AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1161	501 N ASH AVE	N	C	Y	1"	6/5/2024	C	3/4"	1/1/1947	SF	UNK	C	C		6/5/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 12" after cs. Old corp is 1.5' North of old corp.	SL repair/replace record	Y	6/5/2024	Visual insp during install or repair	Field Inspection Only	Y	6/5/2024	Visual Insp during install or repair	
1164	500 N ASH AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	NEW 3/4" CURB VALVE & BOX INSTALLED. 3/4" COPPER INSTALLED ALL THE WAY TO WWATER MAIN.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1167	508 N ASH AVE	N	C	Y	3/4"	10/6/2000	C	3/4"	10/6/2000	SF	UNK	C	3/4"	UNK	CURB BOX CUT-IN 10-6-00. LEAD REPLACED FROM MAIN TO CURB BOX.	Installation Record	Y	10/6/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1170	512 N ASH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/6/2021 - Removed Lead from WM-CS & replaced with copper. 1/2" Copper on property side.	Installation Record	Y	7/6/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1176	512 N VINE AVE	UNK	C	UNK	1"	8/28/2023	C	1"	8/28/2023	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 1/2" copper that was pushed through iron pipe. See sheet 20 of the construction report	Installation Record	Y	8/28/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1179	508 N VINE AVE	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Removed 3/4" copper and replaced w/ 1" copper from main to existing 3/4" CS & Box. See sheet 6 of the construction report	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1182	503 N VINE AVE	UNK	C	Y	1"	7/25/2023	C	1"	7/25/2023	SF	UNK	C	1"	UNK	Removed lead and 3/4" copper and replaced w/ 1" copper from main to exisitng 3/4" CS & Box. See sheet 5 of the construction report.	Installation Record	Y	7/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1185	501 N VINE AVE	UNK	C	UNK	1"	7/26/2023	C	1"	7/26/2023	SF	UNK	C	1"	UNK	Installed 1" CU from main to existing 3/4" copper at the cs. See sheet 6 of the construction report	Installation Record	Y	7/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1188	413 N VINE AVE	N	C	Y	1"	5/23/2024	C	3/4"	1/1/1937	SF	UNK	C	C		5/23/24: Replaced lead from wm-cs with 1" corp, 1" cu & 1" cs & box. connected to existing 3/4" copper. Old corp is 2' North of old corp.	SL repair/replace record	Y	5/23/2024	Visual insp during install or repair	Field Inspection Only	Y	5/23/2024	Visual Insp during install or repair	
1191	407 N VINE AVE	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CORP IS 46' W & 10' N OF S.W.C.H., RETAPPED - OLD CORP IS 2' NORTH, INSULATED TO SEWER. 10/2023: Meyers installed cs & box and verified 3/4" copper crossing the street	Installation Record	Y	10/1/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1194	405 N VINE AVE	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-INSTALLED NEW COPPER FROM MAIN TO CURB. RETAPPED CORP IS 57'W & 2'S OF SW COR. OF HSE. OLD CORP. IS 3'N	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1197	401 N VINE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4 COPPER LOCKING VALVE CORP IS 59'W & 34'S OF NW COR. OF HSE. OLD CORP IS 3'N ON TOP. 5/17/2024: Dug and verified 3/4" copper at main and cs. Installed new cs & box @ the sidewalk.	Installation Record	Y	5/17/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1200	308 N VINE AVE	N	C	Y	UNK	4/11/1990	C	UNK	4/11/1990	SF	UNK	C	UNK	UNK	LEAD REMOVED & INSULATED 4/90	Installation Record	Y	4/11/1990	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1203	400 N VINE AVE	N	C	Y	1"	5/17/2024	C	3/4"	1/1/1929	SF	UNK	C	C		5/17/2024: Removed 3'-3/4" copper @ wm & lead to sidewalk. Replaced w/ new 1" corp., 1" copper & 1" cs & box. Connected to existing 3/4" copper 12" West of the cs. 6" clay San. lateral is on top of wm.	SL repair/replace record	Y	5/17/2024	Visual insp during install or repair	Field Inspection Only	Y	5/17/2024	Visual Insp during install or repair	
1206	404 N VINE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	RETAPPED CORP IS 49'E & 2'S OF NE COR. OF HSE. INSULATED. OLD CORP IS 2'N. 5/21/2024: Dug and verified 3/4" copper at main and cs.	Installation Record	Y	5/21/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1209	412 N VINE AVE	N	C	Y	UNK	4/1/1990	C	3/4"	1/1/1929	SF	UNK	C	C		4-90: Retapped new coper to curb box then. 5/21/2024: Dug and verified 3/4"copper at main and cs.	SL repair/replace record	Y	5/21/2024	Visual insp during install or repair	Field Inspection Only	Y	5/21/2024	Visual Insp during install or repair	
1215	407 N CHERRY AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1215	407 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1218	405 N CHERRY AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1221	401 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1227	313 N CHERRY AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REPLACED COPPER FROM CORP TO NEW CURB BOX	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1230	400 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1236	408 N CHERRY AVE	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2015- INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1239	505 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1242	405 N CEDAR AVE	UNK	C	UNK	1"	4/30/2024	C	1"	4/30/2024	SF	UNK	C	1"	UNK	Old corp is 3' South of new corp. 1"x3/4" fitting is 24" West of curb stop (on street side of curb stop)	Installation Record	Y	4/30/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1248	113 E ARNOLD ST	N	L	UNK	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	UNK	1/1/1926	3/4" Copper inside, Lead outside, removed wipe 2/23/95	SL repair/replace record	Y	1995	Mech excav	Field inspection only	Y	11/15/2016	Cross Connection Survey	
1251	204 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/29/2016	Cross Connection Survey	
1254	208 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	12/22/2016	Cross Connection Survey	
1257	108 E BLODGETT ST	UNK	UNK-LG	UNK	UNK	1/1/1941	C	UNK	1/1/1941	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/15/2016	Cross Connection Survey	
1261	302 N MAPLE AVE	N	C	Y	1"	5/13/2024	L	5/8"	1/1/1927	SF	UNK	C	C		5/13/2024: Removed lead, installed 1" cbv, connected to lead homeowner side.	SL repair/replace record	Y	5/13/2024	Visual insp during install or repair	Field Inspection Only	Y	5/13/2024	Visual Insp during install or repair	
1264	304 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/30/2013	Cross Connection Survey	
1267	313 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/3/2016	Cross Connection Survey	
1270	311 N MAPLE AVE	UNK	C	UNK	1"	6/21/2023	C	1"	6/21/2023	SF	UNK	C	1"	UNK	6/21/23: Installed 1" corp, 1" copper wm-cs. Corp is 3' North of corp for 308 N. Maple. Meyers replaced galvanized w/ 1" copper from cs-meter and installed 1" cs & box. Unmarked 1/2" GAS runs parelle with service 3' north of service.	Installation Record	Y	6/21/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1273	303 N MAPLE AVE	N	C	Y	1"	5/15/2024	C	3/4"	1/1/1925	SF	UNK	C	C		5/15/2024: Replaced lead with 1" copper from wm - cs. Attached to existing 3/4" copper coming out of cs. Old corp. is 3' South of the new one.	SL repair/replace record	Y	5/15/2024	Visual insp during install or repair	Field Inspection Only	Y	5/15/2024	Visual Insp during install or repair	
1276	213 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CURB STOP BUT NO BOX	Installation Record	N			Field Inspection Only	Y	12/6/2016	Cross Connection Survey	
1279	211 N MAPLE AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2015-CAL'S INSTALLED NEW CURB BOX	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1282	207 N MAPLE AVE	N	L	UNK	UNK	1/1/1926	P	UNK	1/1/1926	SF	UNK	P	UNK	1/1/1926	4/12/2016 - REPLACED OLD CORP, AND 5' OF 3/4" COPPER CONNECTED TO LEAD SERVICE	SL repair/replace record	Y	2016	Mech excav	Field inspection only	Y	12/9/2016	Cross Connection Survey	
1285	201 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/17/2016	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1291	113 N MAPLE AVE	N	C	UNK	1"	9/26/2017	P	1"	9/26/2017	SF	UNK	P	1"	UNK	NEW TAP, COPPER AND C.B./C.V.--2017	Installation Record	Y	9/26/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1303	207 E ARNOLD ST	Y	L	Y	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	2003-REMOVED LEAD WIPE & INSTALLED CURB VALVE W/ BOX	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1306	209 E ARNOLD ST	UNK	UNK-LG	UNK	UNK	1/1/1937	C	UNK	1/1/1937	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/16/2016	Cross Connection Survey	
1309	200 N CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2015- VERIFIED SERVICE COME OFF OF ARNOLD	Installation Record	N			Field Inspection Only	Y	11/8/2016	Cross Connection Survey	
1312	201 N CEDAR AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1315	205 N CEDAR AVE	N	C	UNK	1"	1/1/2015	P	1"	1/1/2015	SF	UNK	P	1"	UNK	1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1318	207 N CEDAR AVE	N	C	UNK	1"	1/1/2015	P	1"	1/1/2015	SF	UNK	P	1"	UNK	1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1321	208 E BLODGETT ST	UNK	C	Y	1"	UNK	C	1"	6/27/2023	SF	UNK	C	1"	UNK	6/27/23: Replaced lead wm-cs w/ 1" tap, 1" corp, 1" copper wm-cs. Gaffney replaced lead with 3/4" copper from cs-meter. Gaffney also installed a 1" cs & box.	Installation Record	Y	6/27/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1324	300 N CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/14/2016	Cross Connection Survey	
1327	304 N CEDAR AVE	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2008-INSTALLED COPPER FROM MAIN TO CURB VALVE.INSTALLED CURB VALVE & BOX	Installation Record	Y	1/1/2008	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1330	306 N CEDAR AVE	N	C	UNK	3/4"	1/1/2008	C	3/4"	1/1/2008	SF	UNK	C	3/4"	UNK	2008-INSTALLED COPPER FROM MAIN TO CURB VALVE. INSTALLED CURB VALVE.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1333	308 N CEDAR AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	4/26/24: Verified all 3/4" copper from main to 9' to the West (bottom of ditch)	Installation Record	Y	4/26/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1336	309 N CEDAR AVE	UNK	C	UNK	1"	4/25/2024	C	1"	4/25/2024	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	4/25/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1339	305 N CEDAR AVE	N	C	UNK	3/4"	1/1/1935	C	3/4"	1/1/1935	SF	UNK	C	C		5/1/24: Dug and verified 3/4" copper from wm-cs. Corp is 40' East & 5' North of the NECH @ 302 N Cedar. Moved cs out of the driveway.	Installation Record	Y	5/1/2024	Mech excav	Field Inspection Only	Y	5/1/2024	Mech excav	
1343	309 E BLODGETT ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	TYPE 'K' COPPER - LEAD REPLACEMENT	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1346	308 E BLODGETT ST	N	C	Y	3/4"	8/19/2019	C	3/4"	8/19/2019	SF	UNK	C	3/4"	UNK	TYPE K COPPER - LEAD REPLACEMENT - REIGELS	Installation Record	Y	8/19/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1349	314 E BLODGETT ST	N	C	Y	3/4"	8/23/2018	C	3/4"	8/23/2018	SF	UNK	C	3/4"	UNK	8-23-18 REMOVED ALL LEAD AND REPLACED WITH 3/4" COPPER FROM MAIN TO HOUSE	Installation Record	Y	8/23/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1352	206 N CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/16/2016	Cross Connection Survey	
1355	204 N CHERRY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1358	200 N CHERRY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1361	308 E ARNOLD ST	UNK	UNK-LG	UNK	UNK	1/1/1969	C	UNK	1/1/1969	NONRES	UNK	C	C		SCHREINERS	Installation Record	N			Field Inspection Only	Y	6/17/2013	Cross Connection Survey	
1365	400 E ARNOLD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	2/24/2015	Cross Connection Survey	
1367	201 N CHERRY AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1370	205 N CHERRY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CURB BOX.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1373	402 E BLODGETT ST	Y	C	UNK	3/4"	5/6/2024	P	3/4"	5/6/2024	SF	UNK	P	3/4"	UNK	5/6/24: Hit existing corp., removed & replaced w/ 6"x12" sleeve w/ 1" CC. Conn. to existing 3/4" copper 3' South of main. Dug @ cs, verified copper on street side & copper-hdpe on customer side. Corp is 10' East of cs.	Installation Record	Y	5/6/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1376	401 E BLODGETT ST	UNK	C	Y	1"	5/6/2024	C	1"	5/6/2024	SF	UNK	C	1"	UNK	5/6/24: Removed lead from wm-cs replaced w/ new 1" corp, 1" cs & box. Connected to exisitng 3/4" copper 12" North of cs. Old corp is 6' West of the new corp.	Installation Record	Y	5/6/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1379	405 E BLODGETT ST	N	C	Y	1"	5/1/2024	C	1/2"	1/1/1938	SF	UNK	C	C		5/1/24: Lead removed from wm-cs. Replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 1/2" copper after cs.	SL repair/replace record	Y	5/1/2024	Visual insp during install or repair	Field Inspection Only	Y	5/1/2024	Visual Insp during install or repair	
1382	414 E BLODGETT ST	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Service feeds both 412 & 414 E. Blodgett. 5/10/24: Verified copper @ main and terrace. One tap at main and found two curb stops in the terrace. Assumed service is y'd under curb and gutter.	Installation Record	Y	5/10/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1385	112 N VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/12/2016	Cross Connection Survey	
1388	110 N VINE AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	5/8 LEAD TO CURBSTOP-3/4 COPPER TO HOUSE 2002	SL repair/replace record	Y	2002	Mech excav	Field inspection only	Y	1/1/2005	Visual Insp during install or repair	
1391	108 N VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/8/2016	Cross Connection Survey	
1394	413 E DEPOT ST	UNK	UNK-LG	UNK	UNK	1/1/1920	C	UNK	1/1/1920	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/28/2016	Cross Connection Survey	
1400	309 E DEPOT ST	UNK	UNK-LG	UNK	UNK	1/1/1920	C	UNK	1/1/1920	NONRES	UNK	C	C		CB LOCATION VERIFIED 6/4/97. 2020 - Property side material verified per customer	Installation Record	N			Field Inspection Only	Y	11/25/2014	Cross Connection Survey	
1404	111 N VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/10/2016	Cross Connection Survey	
1407	117 N VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		SERVICE COMES OFF OF ARNOLD	Installation Record	N			Field Inspection Only	Y	11/28/2016	Cross Connection Survey	
1410	208 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN FROM CURB VALVE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1413	304 N ASH AVE	N	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	1999-INSTALLED COPPER FROM MAIN TO INSIDE OF HOUSE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1416	312 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1419	400 N ASH AVE	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REPLACED THE LEAD FROM THE MAIN TO THE CURB STOP	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1422	404 N ASH AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	IRON UNDER SIDEWALK	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1425	406 N ASH AVE	N	C	Y	1"	6/3/2024	G	UNK	UNK	SF	UNK	UNK	UNK	UNK	6/3/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing galvanized 30" after cs (under sidewalk). Old corp. is 2' South of new corp.	SL repair/replace record	Y	6/3/2024	Visual insp during install or repair	Field Inspection Only	Y	Monday, June 3, 2024	Visual Insp during install or repair	
1428	408 N ASH AVE	N	C	Y	1"	5/29/2024	L	5/8"	1/1/1946	SF	UNK	C	C		5/29/2024: Removed lead and replaced w/ copper from wm-cs. old corp is 3' North of new corp. san lateral is above wm. 7' of 1" copper from cs to 1X3/4" fitting then 12" of 3/4" copper to 5/8" lead.	SL repair/replace record	Y	5/29/2024	Mech excav	Field Inspection Only	Y	5/29/2024	Visual Insp during install or repair	
1431	412 N ASH AVE	N	C	UNK	1"	5/29/2024	C	3/4"	1/1/1929	SF	UNK	C	C		New corp. is 4' North of old corp. from cs - 12" of 3/4" copper to new 1" copper on street side - curb stop does work.	SL repair/replace record	Y	5/29/2024	Visual insp during install or repair	Field Inspection Only	Y	5/30/2024	Mech excav	
1437	409 N ASH AVE	UNK	C	Y	1"	5/28/2024	C	1"	5/28/2024	SF	UNK	C	1"	UNK	1" tap, 1" copper from main to curb stop(removed existing lead). 3/4" copper on private side. Old corp. is 1.5' South of new, tapped on top.	Installation Record	Y	5/28/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1440	603 E CLEVELAND ST	UNK	C	Y	1"	8/26/2021	C	1"	8/26/2021	SF	UNK	C	1"	UNK	All lead removed, new 1" tap & 1" curb stop. Old corp is 3' North of the new tap	Installation Record	Y	8/26/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1443	313 N ASH AVE	N	C	UNK	3/4"	1/1/2015	P	3/4"	1/1/2015	SF	UNK	P	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1446	311 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1449	307 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1452	303 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1455	301 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1458	213 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1461	205 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2019-CUSTOMER REPLACED THERE PORTION OF SERVCEI ; 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1464	600 E ARNOLD ST	UNK	C	UNK	1 1/4"	1/1/1985	C	1 1/4"	1/1/1985	NONRES	UNK	C	1 1/4"	UNK	TIES TO THE 4" MAIN. 1" copper to 600 E. Arnold	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1469	612 E ARNOLD ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	2003-NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1472	200 N PEACH AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	NEW 1" CORP,COPPER,VALVE,BOX. 1"COPPER 5' W OF CURBVALVE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1475	204 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/10/2016	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1478	210 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/2/2016	Cross Connection Survey	
1481	212 N PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y	1/1/2005	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1484	304 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/23/2016	Cross Connection Survey	
1487	306 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	11/16/2016	Cross Connection Survey	
1490	310 N PEACH AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2005-INSTALLED NEW 3/4" CURB VALVE AND CURB BOX	Installation Record	Y	1/1/2005	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1493	312 N PEACH AVE	N	C	Y	1"	11/14/2024	C	3/4"	1/1/1927	SF	UNK	C	C		11/14/24: Removed Lead Street Side	Installation Record	Y	11/14/2024	Mech excav	Field Inspection Only	Y	11/28/2016	Cross Connection Survey	
1496	400 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/19/2017	Cross Connection Survey	
1499	402 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/16/2016	Cross Connection Survey	
1502	406 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/21/2016	Cross Connection Survey	
1505	410 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/26/2017	Cross Connection Survey	
1508	412 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	10/25/2016	Cross Connection Survey	
1511	413 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	O	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/29/2016	Cross Connection Survey	
1514	409 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1938	C	UNK	1/1/1938	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	1/3/2017	Cross Connection Survey	
1517	407 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2015-NEW CURB VALVE INSTALLED	Installation Record	N			Field Inspection Only	Y	12/2/2016	Cross Connection Survey	
1520	405 N PEACH AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1520	405 N PEACH AVE	UNK	C	Y	3/4"	6/26/2023	C	3/4"	6/26/2023	SF	UNK	C	3/4"	UNK	6/26/23: Removed lead gooseneck and replaced with 3/4" copper. conn. to existing 3/4" copper @ wm. Cut in 3/4" cs at the West edge of walk between sidewalk and FIBOR OPTIC.	Installation Record	Y	6/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1523	401 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/15/2013	Cross Connection Survey	
1526	313 N PEACH AVE	N	C	Y	1"	11/14/2024	C	3/4"	1/1/1926	SF	UNK	C	C		11/14/24: Removed Lead Street Side	Installation Record	Y	11/14/2024	Mech excav	Field Inspection Only	Y	2/24/2017	Cross Connection Survey	
1529	309 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/26/2016	Cross Connection Survey	
1532	307 N PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN; 2018-INSIDE SERVICE MATERIAL VERIFIED VIA VAC EX.	Installation Record	Y	1/1/2018	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1535	301 N PEACH AVE	N	C	UNK	1"	1/1/2018	G	1"	1/1/2018	SF	UNK	G	UNK	1/1/2018	INSTALLED 1" CORP AND TAPPING SADDLE, 18' - 1" COPPER, 1" CS & BOX, CONNECTED TO 3/4" GALVANIZED PIP @ BACK OF WALK ON CUSTOMERS SIDE	SL repair/replace record	Y	1/1/2018	Visual insp during install or repair	Previous eval	Y	11/22/2016	Cross connection survey	
1538	700 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 30' - 1" COPPER TO CS, CONNECTED TO 3/4" COPPER ON CUSTOMER SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1541	704 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" CU ON CUSTOMER SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1548	712 E BLODGETT ST	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CONNCECTED TO EXISTING 3/4" CU ON CUSTOMERS SIDE (BACK OF WALK)	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1551	713 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CONNECTED TO NEW 3/4" CU ON CUSTOMERS SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1554	803 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - Installed 1" corp with tapping saddle, 1' of 1" cu connected to existing 3/4" copper. 5/23/24: 1" cu from main to cs and connected to 3/4" cu customer side.	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1557	800 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	1/2" COPPER W/ LOCKING VALVE RE-TAPPED 27' OF COPPER CONNECTION MADE 45'N & 2'E OF NE COR. OF HSE. *2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1566	907 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON CUSTOMERS SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1569	211 N ELM AVE	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1" CORP,COPPER,CURB VALVE W/BOX.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1572	203 N ELM AVE	N	C	UNK	3/4"	1/1/2004	C	3/4"	1/1/2004	SF	UNK	C	3/4"	UNK	2004-NEW 3/4 CORP ATTACHED TO EXISTING COPPER. NEW CURB VALVE W/BOX	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1575	901 E ARNOLD ST	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1"CORP,COPPER,CURB VALVE W/BOX.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1578	815 E ARNOLD ST	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1" CORP,COPPER,CURB VALVE W/BOX.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1581	809 E ARNOLD ST	N	C	UNK	1"	1/1/2005	C	1"	1/1/2005	SF	UNK	C	1"	UNK	MFLD UTILITIES	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1584	801 E ARNOLD ST	N	C	UNK	3/4"	1/1/2005	C	3/4"	1/1/2005	SF	UNK	C	3/4"	UNK	NEW COPPER FROM MAIN TO EDGE OF DRIVEWAY-MFLD UTILITIES	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1587	717 E ARNOLD ST	N	C	UNK	3/4"	1/1/2005	C	3/4"	1/1/2005	SF	UNK	C	3/4"	UNK	MFLD UTILITIES	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1592	114 N APPLE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	3/4" copper on customer side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1595	801 E DEPOT ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1598	109 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1601	115 N APPLE AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 5/9/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1604	804 E ARNOLD ST	N	C	UNK	3/4"	1/1/2005	C	3/4"	1/1/2005	SF	UNK	C	3/4"	UNK	MFLD UTILITIES	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1607	810 E ARNOLD ST	N	C	UNK	3/4"	1/1/2005	C	3/4"	1/1/2005	SF	UNK	C	3/4"	UNK	MFLD UTILITIES	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1610	114 N ELM AVE	N	UNK	UNK	UNK	1/1/2004	C	UNK	1/1/2004	SF	UNK	C	UNK	UNK	NEW 3/4" CORP ATTACHED TO EXISTING SERVICE @ MAIN	Installation Record	Y	1/1/2004	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1613	108 N ELM AVE	N	C	UNK	3/4"	1/1/2004	UNK	3/4"	1/1/2004	SF	UNK	UNK	3/4"	UNK	2004-NEW 3/4 CORP ATTACHED TO EXISTING 3/4 COPPER @ MAIN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1616	105 N ELM AVE	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1" CORP, COPPER,CURB VALVE W/ BOX	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1619	104 N PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MAIN SHALLOW/INSULATED	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1622	103 N PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MAIN SHALLOW/INSULATED	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1625	109 N PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1628	111 N PALMETTO AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1631	115 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1634	102 N PURDY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF PURDY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1637	101 N PURDY AVE	UNK	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Mark Meyers - Service is off of Purdy - just north of Sanitary manhole. removed lead/copper from wm-cs replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1640	105 N PURDY AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1643	109 N PURDY AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1646	1100 E ARNOLD ST	N	UNK	UNK	UNK	1/1/1960	C	UNK	1/1/1960	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1649	1103 E ARNOLD ST	N	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	MEYERS: PROPERTY ALSO HAS A PRIVATE WELL.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1652	205 N PURDY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1655	207 N PURDY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1658	209 N PURDY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000: NEW CURB BOX.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1661	213 N PURDY AVE	N	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1664	304 N HINMAN AVE	N	C	UNK	1/2"	UNK	C	1/2"	UNK	SF	UNK	C	1/2"	UNK	RETAPPED OFF OF HINMAN 5-8-92	Installation Record	Y	5/8/1992	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1667	212 N HINMAN AVE	N	C	Y	UNK	1/1/2001	C	UNK	1/1/2001	SF	UNK	C	UNK	UNK	2001: REMOVED THE LEAD FROM THE MAIN TO THE CURB BOX/ REPLACED WITH COPPER.	Installation Record	Y	1/1/2001	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1670	204 N HINMAN AVE	N	C	Y	1"	6/12/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/12/24: Removed lead from wm-cs, replaced w/ 1" copper, 1" cs & box. Used existing corp. Connected to eixisting 3/4" copper 8" west of cs.	SL repair/replace record	Y	6/12/2024	Visual insp during install or repair	Field Inspection Only	Y	6/12/2024	Visual Insp during install or repair	
1673	200 N HINMAN AVE	N	C	Y	3/4"	UNK	C	3/4"	9/25/2001	SF	UNK	C	3/4"	UNK	9/25/01: REMOVED LEAD FROM SANITARY DITCH TO CURB BOX. 2022 - Replaced lead w/ copper wm-house 7/1/22: Lead wipe removed	Installation Record	Y	7/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1676	112 N HINMAN AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	2001: NEW SERVICE FROM MAIN TO CURB-BOX. NEW SERVICE FROM C.S. TO HOUSE (MEYERS 2020)	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1679	108 N HINMAN AVE	N	C	Y	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK	2001: REMOVED ALL LEAD FROM MAIN TO CURB-BOX. 12/2/22: Meyers replaced lead w/ 1" copper from cs-meter. Also installed cs & box.	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1682	103 N HINMAN AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1685	109 N HINMAN AVE	N	C	N	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	C		6/14/24: Dug and verified 3/4" copper from wm-cs.	SL repair/replace record	Y	6/14/2024	Mech excav	Field Inspection Only	Y	6/14/2024	Mech excav	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1688	113 N HINMAN AVE	N	C	UNK	3/4"	1/1/2022	C	3/4"	1/1/2022	SF	UNK	C	3/4"	UNK	2022: 3/4" copper from main to cs. 5' of 3/4" copper from cs to existing 3/4" copper. Insulated	Installation Record	Y	1/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1691	117 N HINMAN AVE	N	C	Y	3/4"	9/16/1994	C	3/4"	9/16/1994	SF	UNK	C	3/4"	UNK	Lead was replaced from the main to the curb box	Installation Record	Y	9/16/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1694	205 N HINMAN AVE	N	C	UNK	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	C		9/94: New cs & box. 6/12/24: Dug and verified 3/4" copper @ wm.	Field inspection only	Y	6/12/2024	Mech excav	Field Inspection Only	Y	1/6/2017	Cross Connection Survey	
1697	207 N HINMAN AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/11/24: Dug and verified 3/4" copper from wm-cs. No Lead. MU installed a 3/4" cs & box.	Installation Record	Y	6/11/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1700	213 N HINMAN AVE	N	C	UNK	3/4"	6/20/2018	C	3/4"	6/20/2018	SF	UNK	C	3/4"	UNK	NEW 3/4" COPPER MAIN - CURB BOX, ATTACHED TO EXISITNG COPPER	Installation Record	Y	6/20/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1703	1300 E BLODGETT ST	UNK	C	UNK	1"	1/1/1972	C	1"	1/1/1972	SF	UNK	C	1"	UNK	REIGEL. 2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1706	1310 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	LOWERED & INSULATED 6/80. 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1709	1402 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - 1" CORP AND TAPPING SADDLE, 3' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN STREET	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1712	1406 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED NEW 1" CORP WITH TAPPING SADDLE, 4' - 1" COPPER, CONNECT TO EXISTING 3/4" COPPER IN ROAD	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1715	1405 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1' CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1718	301 N JUNO AVE	UNK	C	UNK	1"	1/1/1970	C	1"	1/1/1970	SF	UNK	C	1"	UNK	MEYERS. 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1721	306 N JUNO AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS(GAFFNEY)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1724	409 N JUNO AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1727	400 N JUNO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1730	1308 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF JUNO. 3/4" copper on customer side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1733	1406 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1736	1410 E DOEGE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1742	1205 E DOEGE ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" C.V./C.B. INSTALLED BY BACH EXC--2017	Installation Record	Y	1/1/2017	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1745	1201 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	A "Y" CONNECTION W/1203 DOEGE. CURB VALVE FOR #1203 ONLY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1748	1209 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1751	413 N HINMAN AVE	N	UNK	UNK	UNK	1/1/1969	C	UNK	1/1/1969	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1969	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1754	407 N HINMAN AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/12/2021 - Verified all 3/4" copper from main. No lead found.	Installation Record	Y	5/12/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1757	405 N HINMAN AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN 4/29/98. Ran 3/4" copper from main connected to existing 3/4" copper - RE, JT Verified 5-12-2021	Installation Record	Y	5/12/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1760	403 N HINMAN AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/15/2021: Removed 3' lead gooseneck - ran 3/4" copper from main, connected to existing 3/4" copper	Installation Record	Y	5/15/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1763	1110 E CLEVELAND ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1766	1100 E CLEVELAND ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2004-RE-TAPPED SERVICE	Installation Record	Y	1/1/2004	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1769	402 N PALMETTO AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	DUPLEX WITH 404 N PALMETTO	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1772	401 N PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1775	1101 E CLEVELAND ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1778	1105 E CLEVELAND ST	N	UNK	UNK	5/8"	1/1/1961	C	5/8"	1/1/1961	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1781	402 N HINMAN AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/13/2021 - Removed 3' lead gooseneck - Ran 3/4" copper from main and connected to existing 3/4" copper	Installation Record	Y	5/13/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1785	404 N HINMAN AVE #A	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN 4/29/98. Ran 3/4" copper from main connected to existing 3/4" copper (Verified 5/12/2021)	Installation Record	Y	5/12/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1788	1122 E DOEGE ST	N	C	UNK	3/4"	1/1/2003	C	3/4"	1/1/2003	SF	UNK	C	3/4"	UNK	2003- MEYER. COPPER REPLACED FROM CORP TO NEW CURB VALVE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1791	1115 E DOEGE ST	N	C	UNK	UNK	1/1/1950	G	UNK	UNK	SF	UNK	G	UNK	UNK	galvanized on customer side per customer	Installation Record	N			Previous eval	Y	8/28/2006	Cross connection survey	
1794	506 N HINMAN AVE	UNK	C	UNK	1"	9/6/2022	C	1"	9/6/2022	SF	UNK	C	1"	UNK	Pg. 5 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs.	Installation Record	Y	9/6/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1797	511 N HINMAN AVE	UNK	C	UNK	1"	9/7/2022	C	1"	9/7/2022	SF	UNK	C	1"	UNK	Pg. 6 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs.	Installation Record	Y	9/7/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1800	513 N HINMAN AVE	UNK	C	UNK	1"	9/8/2022	C	1"	9/8/2022	SF	UNK	C	1"	UNK	Pg. 7 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs.	Installation Record	Y	9/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1803	515 N HINMAN AVE	UNK	C	UNK	1"	9/13/2022	C	1"	9/13/2022	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	9/13/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1806	606 N HINMAN AVE	UNK	C	UNK	1"	9/20/2022	C	1"	9/20/2022	SF	UNK	C	1"	UNK	Pg. 13 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1809	605 N HINMAN AVE	UNK	C	UNK	1"	9/14/2022	C	1"	9/14/2022	SF	UNK	C	1"	UNK	Pg. 10 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs.	Installation Record	Y	9/14/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1812	607 N HINMAN AVE	UNK	C	UNK	1"	9/19/2022	C	1"	9/19/2022	SF	UNK	C	1"	UNK	Pg. 12 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/19/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1815	609 N HINMAN AVE	UNK	C	UNK	1"	9/21/2022	C	1"	9/21/2022	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	9/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1818	703 N HINMAN AVE	N	C	UNK	1"	9/26/2022	C	1"	9/26/2022	SF	UNK	C	1"	UNK	Pg. 16 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs.	Installation Record	Y	9/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1821	707 N HINMAN AVE	UNK	C	UNK	1"	9/26/2022	C	1"	9/26/2022	SF	UNK	C	1"	UNK	Pg. 16 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs.	Installation Record	Y	9/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1824	711 N HINMAN AVE	UNK	C	UNK	1"	9/22/2022	C	1"	9/22/2022	SF	UNK	C	1"	UNK	Pg. 15 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/22/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1827	724 N HINMAN AVE	UNK	C	UNK	1"	9/20/2022	C	1"	9/20/2022	SF	UNK	C	1"	UNK	Pg. 13 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1830	718 N HINMAN AVE	UNK	C	UNK	1"	9/20/2022	C	1"	9/20/2022	SF	UNK	C	1"	UNK	Pg. 13 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1833	708 N HINMAN AVE	UNK	C	UNK	1"	9/28/2022	C	1"	9/28/2022	SF	UNK	C	1"	UNK	Pg. 18 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs.	Installation Record	Y	9/28/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1836	706 N HINMAN AVE	UNK	C	UNK	1"	9/13/2022	C	1"	9/13/2022	SF	UNK	C	1"	UNK	Pg. 9 of construction report. Installed 1" corp., 2'-1" copper, connected to existing 1" copper at the water main. Main is below sanitary lateral	Installation Record	Y	9/13/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1839	1115 E FILLMORE ST	UNK	C	UNK	1"	9/27/2022	C	1"	9/27/2022	SF	UNK	C	1"	UNK	Pg. 17 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs.	Installation Record	Y	9/27/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1842	1111 E FILLMORE ST	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1845	1109 E FILLMORE ST	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1848	705 N PALMETTO AVE	UNK	C	UNK	1"	7/10/2023	C	1"	7/10/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 17 of construction report)	Installation Record	Y	7/10/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1851	707 N PALMETTO AVE	UNK	C	UNK	1"	7/10/2023	C	1"	7/10/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 17 of construction report)	Installation Record	Y	7/10/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1854	1116 E FILLMORE ST	UNK	C	UNK	1"	9/21/2022	C	1"	9/21/2022	SF	UNK	C	1"	UNK	Pg. 14 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1857	1110 E FILLMORE ST	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1860	607 N PALMETTO AVE	UNK	C	UNK	1"	7/5/2023	C	1"	7/5/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 14 of construction report)	Installation Record	Y	7/5/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1863	603 N PALMETTO AVE	UNK	C	UNK	1"	6/22/2023	C	1"	6/22/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 8 of construction report)	Installation Record	Y	6/22/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1866	1117 E EDISON ST	UNK	C	UNK	1"	9/13/2022	C	1"	9/13/2022	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	9/13/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1869	1116 E EDISON ST	UNK	C	UNK	1"	9/7/2022	UNK	1"	9/7/2022	SF	UNK	UNK	1"	UNK	Pg. 6 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs. WM is below sanitary lateral.	Installation Record	Y	9/7/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1872	1112 E EDISON ST	N	C	UNK	1"	7/22/2019	C	1"	7/22/2019	SF	UNK	C	1"	UNK	CORP LOCATION IS 12' WEST OF SERVICE TO 11109 E. EDISON. INSTALLED NEW 1" SADDDLE , 1" CORP CONNECTED TO EXISTING 3/4 COPPER 4' SOUTH OF CORP	Installation Record	Y	7/22/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1875	513 N PALMETTO AVE	UNK	C	UNK	1"	6/22/2023	C	1"	6/22/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 8 of construction report)	Installation Record	Y	6/22/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1878	509 N PALMETTO AVE	UNK	C	UNK	1"	6/22/2023	C	1"	6/22/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 8 of construction report)	Installation Record	Y	6/22/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1881	1101 E DOEGE ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2011-REMOVED LEAD WIPE AT MAIN	Installation Record	Y	1/1/2011	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1884	1103 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1887	1105 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1890	1109 E DOEGE ST	N	C	UNK	1"	1/1/1968	C	1"	1/1/1968	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED AT CB, FOUND 1" COPPER 7'6" DEEP	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1893	1114 E DOEGE ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1896	902 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1899	812 E DOEGE ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB Verified 3-97	Installation Record	Y	3/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1902	810 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1905	806 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1908	800 E DOEGE ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/3/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1911	401 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF APPLE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1914	806 E CLEVELAND ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1917	905 E CLEVELAND ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS. 3/4" copper on property side	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1920	800 E CLEVELAND ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1923	312 N APPLE AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1926	400 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1998: MEYERS INSTALLED CURB BOX.	Installation Record	Y	1/1/1998	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1929	406 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1936	518 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1939	520 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
1962	201 S MAPLE AVE	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	NONRES	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1967	211 S MAPLE AVE	UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	NONRES	UNK	UNK	UNK	UNK	09/2020 - DISCONNECTED LEAD FROM MAIN @ CORP. - LEFT CORP OFF	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
1975	305 S MAPLE AVE	N	C	Y	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	4/20/21 - Meyers removed remaining lead on customers side & installed 3/4" copper. 1" x 3/4" reducer on backside of walk	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1978	307 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 1/2" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1981	309 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1985	200 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		3/4" copper on customer side	Installation Record	N			Field Inspection Only	Y	7/5/2013	Cross Connection Survey	
1991	411 S MAPLE AVE	N	C	Y	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO LEAD ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1994	413 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
1998	503 S MAPLE AVE	N	C	UNK	1"	1/1/2015	P	1"	1/1/2015	SF	UNK	P	1"	UNK	CONNECTED TO 1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2002	509 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2006	511 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2011	809 S MAPLE AVE	N	L	UNK	5/8"	1/1/1925	C	5/8"	1/1/1925	SF	UNK	C	UNK	1/1/1925	2005-LEAD WIPE REMOVED AT BOX.	SL repair/replace record	Y	2005	Mech excav	Field inspection only	Y	5/4/2017	Cross Connection Survey	
2017	204 E 9TH ST	N	C	Y	3/4"	10/12/2018	C	3/4"	10/12/2018	SF	UNK	C	3/4"	UNK	REMOVED LEAD & REPLACED WITH 3/4" (TYPE K) COPPER TO CS - MEYERS INSTALLED 3/4" COPPER TO HOUSE	Installation Record	Y	10/12/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2020	909 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/1/2017	Cross Connection Survey	
2023	207 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	10/27/2015	Cross Connection Survey	
2026	206 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		CB LOCATION VERIFIED 6/12/97	Installation Record	N			Field Inspection Only	Y	8/22/2014	Cross Connection Survey	
2029	200 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	O	UNK	C	C		NEW CURB VALVE INSTALLED BY MEYERS. REMOVED LEAD WIPES BOTH SIDES OF VALVE.	Installation Record	N			Field Inspection Only	Y	5/19/2017	Cross Connection Survey	
2032	1107 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/9/2014	Cross Connection Survey	
2035	1109 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/9/2017	Cross Connection Survey	
2038	1111 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1945	C	UNK	1/1/1945	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/17/2017	Cross Connection Survey	
2040	1505 S CENTRAL AVE	Y	UNK	UNK	1"	UNK	C	1"	UNK	NONRES	UNK	C	1"	UNK	2004-REMOVED WIPES @ MAIN INSTALLED 1" CORP	Installation Record	Y	1/1/2004	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2043	1619 S CENTRAL AVE	UNK	DI	UNK	4"	1/1/1970	DI	4"	1/1/1970	NONRES	UNK	DI	4"	UNK	STRATFORD PLB. 4" FIRE SERVICE & POTABLE	Installation Record	Y	1/1/1970	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
2046	1701 S CENTRAL AVE	N	C	UNK	1-1/2"	1/1/2009	C	1-1/2"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	ATTACHED TO EXISTING 1-1/2" COPPER. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	5/4/2017	Cross connection survey	
2049	2011 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	ATTACHED TO 1" COPPER @ CURB VALVE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2052	1806 S CENTRAL AVE	UNK	C	UNK	2"	1/1/2009	C	2"	1/1/2009	NONRES	UNK	C	2"	UNK	BORED-CONNECTED TO 2" COPPER. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2055	1702 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	BORED, A-1 EXCAVATING. ATTACHED TO 3/4" COPPER	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2058	1610 S CENTRAL AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	1998-NEW CURB STOP & BOX AND LOWERED UNDER STORM SEWER	Installation Record	Y	1/1/1998	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2061	1604 S RODDIS AVE	UNK	C	UNK	1"	UNK	C	1"	UNK	NONRES	UNK	C	1"	UNK	2009-INSTALLED NEW COPPER FROM MAIN TO CURB STOP W/ BOX.	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2064	1600 S RODDIS AVE	N	C	Y	1"	UNK	C	1"	UNK	NONRES	UNK	C	1"	UNK	2009- REMOVED LEAD WIPE @ MAIN AND INSTALLED 12' OF 1" COPPER UNDER STORM SEWER TO MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2067	1202 S MAPLE AVE	N	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	2013- NEW 3/4" TAP AND REMOVED LEAD WIPE AT MAIN	Installation record	N	1/1/2013	Visual insp during install or repair	Previous eval	Y	6/8/2017	Cross connection survey	
2070	1112 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/9/2017	Cross Connection Survey	
2073	1110 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/4/2017	Cross Connection Survey	
2076	1104 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/15/2017	Cross Connection Survey	
2079	1102 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/16/2014	Cross Connection Survey	
2081	112 E 11TH ST	N	C	UNK	1"	1/1/2000	C	1"	1/1/2000	NONRES	UNK	C	1"	UNK	TAPPED OFF MAPLE	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2084	109 E 11TH ST	N	C	UNK	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN - REMOVED 2" GALVANIZED MAIN, REPLACED W/ 2" POLY, MEYERS PULLED 3/4" CU FROM HOUSE TO NEW MAIN, INSTALLED NEW CB	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2087	912 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/8/2017	Cross Connection Survey	
2090	908 S MAPLE AVE	N	C	Y	3/4"	10/15/2020	C	3/4"	10/15/2020	SF	UNK	C	3/4"	UNK	10/15/2020 - Removed lead and replaced with copper on both sides (meyers)	Installation Record	Y	10/15/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2093	904 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/12/2017	Cross Connection Survey	
2096	804 S MAPLE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2105	504 S MAPLE AVE	N	C	UNK	1"	1/1/2017	C	3/4"	4/24/2023	SF	UNK	C	UNK	4/24/2023	2017-REPLACED LEAD SERVICE FROM CORP TO CURB VALVE WITH 3/4" COPPER. 4/24/23: Gaffney replaced galvanized w/ 3/4" copper cs-meter. Installed new 3/4" cs & box.	SL repair/replace record	Y	1/1/2017	Visual insp during install or repair	Previous eval	Y	1/1/2017	Visual Insp during install or repair	
2105	504 S MAPLE AVE	N	C	UNK	1"	1/1/2015	G	UNK	UNK	SF	UNK	UNK	UNK	UNK	CONNECTED TO 3/4" IRON ON PROP. SIDE	SL repair/replace record	Y	1/1/2015	Visual insp during install or repair	Field Inspection Only	Y	1/1/2015	Visual Insp during install or repair	
2108	118 E 3RD ST	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	O	UNK	C	1"	UNK	1" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2111	116 E 3RD ST	UNK	C	UNK	2"	1/1/2015	P	2"	1/1/2015	NONRES	UNK	P	2"	UNK	2" PLASTIC ON PROP SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2115	210 E 2ND ST	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2118	200 S CEDAR AVE	N	UNK	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1" Copper on property side. 8/24/2022: Removed lead wipe @ main. Service is 100% copper. lead free 3/4" copper	Installation Record	Y	8/24/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2122	208 S CEDAR AVE	N	C	Y	1"	8/24/2022	C	1"	8/24/2022	SF	UNK	C	1"	UNK	8/24/22: Removed lead and installed new 1" copper, used existing corp. New 1" curb valve & box. 3/4" copper on customers side.	Installation Record	Y	8/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2125	210 S CEDAR AVE	UNK	C	Y	1"	8/25/2022	C	1"	8/25/2022	SF	UNK	C	1"	UNK	8/25/22: Removed lead & installed new 1" Copper used existing corp. w/ tapping saddle. New 1" curb valve & box. Hooked to 3/4" copper on customers side	Installation Record	Y	8/25/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2128	212 S CEDAR AVE	N	C	Y	1"	8/25/2022	C	1"	8/25/2022	SF	UNK	C	1"	UNK	8/25/22: Removed lead and installed new 1" copper, used existing corp. New 1" box and curb valve. Hooked to 3/4" copper on customers side.	Installation Record	Y	8/25/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2131	306 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	9/22: Removed lead wipe @ main. Hooked to 3/4" copper	Installation Record	Y	9/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2134	312 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	9/6/22: Removed lead wipe @ main, service is 100% copper, 3/4" copper inside.	Installation Record	Y	9/6/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2137	210 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		REMOVED LEAD WIPE 1-2000.	Installation Record	N			Field Inspection Only	Y	4/27/2017	Cross Connection Survey	
2140	212 E 4TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2000: REMOVED LEAD GOOSE - NECK - 3/4" COPPER. 2022: Verified 3/4" copper. No lead service	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2143	404 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2022: Removed lead wipes. Service is 100% copper	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2146	408 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2003-INSTALLED NEW CURB VALVE W/ BOX. 1990-REMOVED LEAD WIPE IN STREET. 2022: Removed Lead wipe - no lead on service, 100% copper	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2153	212 E 5TH ST	N	C	UNK	3/4"	1/1/2019	C	3/4"	1/1/2019	SF	UNK	C	3/4"	UNK	JAKEL PLBG. - CLAY TILE SANITARY LATERAL IS ABOVE THE WATER MAIN	Installation Record	Y	1/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2158	804 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1/2" COPPER LOCKING VALVE. 2022: Removed lead wipe, fixed leak	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2161	806 S CEDAR AVE	N	C	UNK	1"	9/26/2022	C	1"	9/26/2022	SF	UNK	C	1"	UNK	2022: 1" copper frommain to curb valve, used existing corp, new 1" cs & box. 3/4" copper on house side	Installation Record	Y	9/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2164	213 E 9TH ST	N	C	Y	3/4"	9/14/2020	C	3/4"	9/14/2020	SF	UNK	C	3/4"	UNK	2017-CURB STOP W/ BOX INSTALLED BY BACH EXCAVATING. 9-14-2020 - Removed lead from Corp. to CS & replaced w/ 3/4" copper. connected to existing CS. 3/10/21 - Meyers removed lead & replaced w/ 3/4" copper on property side (cs - meter)	Installation Record	Y	9/14/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2167	902 S CEDAR AVE	N	C	Y	1"	9/28/2022	C	1"	9/28/2022	SF	UNK	C	1"	UNK	2022: removed lead wipes, new 1" copper from main to cs. Used existing corp. Hooked to 3/4" copper on house side	Installation Record	Y	9/28/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2170	904 S CEDAR AVE	N	C	Y	3/4"	9/28/2022	C	3/4"	9/28/2022	SF	UNK	C	3/4"	UNK	CALS PLBG INSTALLED CURB VALVE/BOX. 2022: Removed lead wipe 2022 lead free service	Installation Record	Y	9/28/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2174	910 S CEDAR AVE	N	C	UNK	1"	1/1/2022	C	1"	1/1/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to cs. New 1" cs & box. New 1" corp w/ Mainbreak 6" sleeve with 1" C.C. Hooked to 3/4" copper on owners side.	Installation Record	Y	1/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2178	1008 S CEDAR AVE	N	CI-U	UNK	6"	UNK	G	2"	UNK	NONRES	UNK	G	UNK	UNK	10/31/22: Dug @ the wm , found a 6"x6" tee. Dug behind the curb and found a 6" service valve 2' West of the Curb. Cast iron both sides of the service valve. Verified 2" galvanized inside.	SL repair/replace record	N	10/31/2022	Visual insp during install or repair	Previous eval	Y	10/31/2022	Visual insp at meter	
2182	1102 S CEDAR AVE	N	C	Y	1"	10/21/2022	C	1"	10/21/2022	SF	UNK	C	1"	UNK	2022: Verified no lead in service, existing 1" copper from main. Appears to may have been replaced with sewer lateral in the past	Installation Record	Y	10/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2185	1106 S CEDAR AVE	N	C	UNK	1"	10/1/2022	C	1"	10/1/2022	SF	UNK	C	1"	UNK	2022: New 1" copper form main to curb valve. Reused curb valve (3/4"), and found 3/4" copper inside. Installed new box and used the existing corp.	Installation Record	Y	10/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2188	1108 S CEDAR AVE	UNK	C	Y	1"	10/13/2022	C	1"	10/13/2022	SF	UNK	C	1"	UNK	10/13/22: Removed lead & replaced w/ 1" copper from wm-cs. Installed new 1" tap with sleeve and reused existing 3/4" cs but replaced the box. Verified 3/4" copper on customers side.	Installation Record	Y	10/13/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2191	215 E 14TH ST	N	C	UNK	1"	7/30/2024	C	3/4"	1/1/1946	SF	UNK	C	C		Earth Inc. 13' of 1" copper from cs to existing 3/4" copper. See sheet 26 of the construction report.	SL repair/replace record	Y	7/30/2024	Mech excav	Field Inspection Only	Y	7/30/2024	Visual Insp during install or repair	
2194	211 E 14TH ST	UNK	C	UNK	1"	7/19/2024	C	1"	7/19/2024	SF	UNK	C	1"	UNK	Earth Inc. 9' - 1" copper from cs to existing 3/4" copper. See sheet 22 of the construction report.	Installation Record	Y	7/19/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2197	1411 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1924	C	UNK	1/1/1924	SF	UNK	C	C		REMOVE WIPES 1989 COPPER INSIDE	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
2200	1501 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		REMOVED WIPES AT MAIN & BOX 1989	Installation Record	N			Field Inspection Only	Y	10/6/2014	Cross Connection Survey	
2203	1505 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		REMOVED WIPE AT CURB STOP 1989	Installation Record	N			Field Inspection Only	Y	5/2/2017	Cross Connection Survey	
2207	1509 S MAPLE AVE	N	UNK	UNK	3/4"	1/1/1989	C	3/4"	1/1/1989	SF	UNK	C	3/4"	UNK	NEW LINE FROM MAIN	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2210	1511 S MAPLE AVE	N	UNK	UNK	3/4"	1/1/1989	C	3/4"	1/1/1989	SF	UNK	C	3/4"	UNK	COPPER & IRON INSIDE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2213	1607 S MAPLE AVE	UNK	C	Y	1"	9/23/2024	C	1"	9/23/2024	SF	UNK	C	1"	UNK	12/20/2022: Existing cs was leaking on curstomer side. Gaffney removed & replaced w/ 1" cs & box & connected to exist. 1/2" copper. MU removed lead and replaced w/ 1" copper from wm - cs. Insulated at wm and cs. 9/24: MU installed 1" corp w/ saddle, 1" cu	Installation Record	Y	9/23/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2216	207 E 17TH ST	UNK	C	UNK	1"	8/8/2022	C	1"	8/8/2022	SF	UNK	C	1"	UNK	Pg. 28 of the construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 12.5' after cs.	Installation Record	Y	8/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2219	209 E 17TH ST	UNK	C	UNK	1"	8/8/2022	C	1"	8/8/2022	SF	UNK	C	1"	UNK	Pg. 28 of the construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 10' after cs.	Installation Record	Y	8/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2222	208 E 17TH ST	UNK	C	UNK	1"	8/9/2022	C	1"	8/9/2022	SF	UNK	C	1"	UNK	Pg. 29 of the construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 9.5' after cs.	Installation Record	Y	8/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2225	1705 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1933	C	UNK	1/1/1933	SF	UNK	C	C		Y CONNECTED WITH 1707. 3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	4/24/2017	Cross Connection Survey	
2228	1803 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LOWERED ACROSS ROAD	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2231	1809 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LOWERED IN STREET, REMOVED WIPES INSULATED AT MAIN 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2234	1909 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPE, LOWERED & INSULATED 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2237	1911 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPE, LOWERED & INSULATED 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2240	2001 S MAPLE AVE	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	1988	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2243	1904 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPE, INSULATED 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2248	1814 S MAPLE AVE	UNK	C	UNK	UNK	1/1/1989	C	UNK	1/1/1989	SF	UNK	C	UNK	UNK	REMOVED WIPE ALL COPPER 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2250	116 E 17TH ST	N	C	UNK	3/4"	1/1/1990	C	3/4"	1/1/1990	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2253	112 E 17TH ST	N	UNK	UNK	3/4"	1/1/1990	C	3/4"	1/1/1990	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2256	111 E 17TH ST	N	C	UNK	UNK	1/1/1990	C	UNK	1/1/1990	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2259	113 E 17TH ST	N	UNK	UNK	UNK	1/1/1990	C	UNK	1/1/1990	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2262	115 E 17TH ST	N	UNK	UNK	3/4"	1/1/1990	C	3/4"	1/1/1990	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2266	1414 S MAPLE AVE	N	C	UNK	2"	4/1/2014	C	2"	4/1/2014	SF	UNK	C	2"	UNK	Removed wipes @ main & CS - copper inside (Removed flair fitting customer side of vavle 04/01/2014)	Installation Record	Y	4/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2269	208 E 14TH ST	N	C	UNK	1"	7/30/2024	C	3/4"	1/1/1925	SF	UNK	C	C		Earth Inc. 13.5' of 1" copper from cs to existing 3/4" copper.	SL repair/replace record	Y	7/30/2024	Mech excav	Field Inspection Only	Y	7/30/2024	Visual Insp during install or repair	
2272	210 E 14TH ST	UNK	C	UNK	1"	7/30/2024	C	1"	7/30/2024	SF	UNK	C	1"	UNK	Earth Inc. 12.5' of 1" copper from cs to existing 3/4" copper.	Installation Record	Y	7/30/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2275	214 E 14TH ST	N	C	UNK	1"	7/30/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 12.5' of 1" copper from cs to existing 3/4" copper.	SL repair/replace record	Y	7/30/2024	Mech excav	Field Inspection Only	Y	7/30/2024	Visual Insp during install or repair	
2278	300 E 14TH ST	N	C	Y	1"	7/22/2024	C	3/4"	1/1/1932	SF	UNK	C	C		Earth Inc. 11' of 1" copper from cs to existing 3/4" copper. See sheet 23 of the construction report.	SL repair/replace record	Y	7/22/2024	Mech excav	Field Inspection Only	Y	7/22/2024	Visual Insp during install or repair	
2281	302 E 14TH ST	UNK	C	UNK	1"	7/23/2024	C	1"	7/23/2024	SF	UNK	C	1"	UNK	Earth Inc. 12' of 1" copper from cs to existing 3/4" copper. See sheet 24 of the construction report.	Installation Record	Y	7/23/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2284	1408 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1932	C	UNK	1/1/1932	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/26/2017	Cross Connection Survey	
2287	1504 S CEDAR AVE	UNK	C	Y	3/4"	6/13/2023	C	3/4"	6/13/2023	SF	UNK	C	3/4"	UNK	6/13/23: Replaced lead w/ 3/4" copper from wm-cs. Meyers replaced lead with 3/4" copper from cs-meter and also installed a new 3/4" cs & box.	Installation Record	Y	6/13/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2290	1506 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/17/2017	Cross Connection Survey	
2293	1508 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1940	C	UNK	1/1/1940	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/28/2017	Cross Connection Survey	
2296	1514 S CEDAR AVE	N	C	UNK	1"	7/26/2022	C	1"	7/26/2022	SF	UNK	C	1"	UNK	7/26/22: All new copper & curb valve. 1" copper on Utility side, 3/4" copper on customer side.	Installation Record	Y	7/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2299	1606 S CEDAR AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2302	1610 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1938	C	UNK	1/1/1938	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/24/2017	Cross Connection Survey	
2305	1612 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	4/21/2017	Cross Connection Survey	
2308	1614 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/3/2017	Cross Connection Survey	
2311	1616 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2314	1706 S CEDAR AVE	N	C	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	MFLD PLB. 7-1-2022: 3/4" Copper main to cs. - 3/4" copper on customer side. New box & rod installed	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2317	1800 S CEDAR AVE	N	C	UNK	1"	1/1/1966	C	1"	1/1/1966	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 6'6" DEEP	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2320	1804 S CEDAR AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	SCHRIENERS	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2323	1808 S CEDAR AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	MFLD PLB. 3/4" copper on property side	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2326	1812 S CEDAR AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2329	1900 S CEDAR AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1966	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2332	1906 S CEDAR AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2335	2000 S CEDAR AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2338	2004 S CEDAR AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2341	401 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2346	1801 S CEDAR AVE	N	UNK	UNK	3/4"	1/1/1963	UNK	3/4"	1/1/1963	SF	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2349	1707 S CEDAR AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2352	1701 S CEDAR AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2355	1621 S CEDAR AVE	N	C	Y	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Pg. 21 of construction reports. Removed lead gooseneck and replaced with 1" corp, 1" copper and connected to existing 3/4" copper @ main.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2358	1601 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2361	1505 S CEDAR AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1973	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2364	308 E 15TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/9/2017	Cross Connection Survey	
2367	310 E 15TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VACUUM EXCAVATED @ EOP, FOUND COPPER 7'9" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2370	314 E 15TH ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2373	1501 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2376	1406 S PROSPECT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2379	1411 S PROSPECT AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	8-2022: removed 5' lead wipe from main to sewer, 3/4" copper was found	Installation Record	Y	8/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2382	1409 S PROSPECT AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/10/2017	Cross Connection Survey	
2385	1405 S PROSPECT AVE	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK		Installation record	N		Visual insp during install or repair	Previous eval	Y	7/26/2017	Cross connection survey	
2388	310 E 14TH ST	N	C	UNK	1"	7/23/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 13' of 1" copper from cs to existing 3/4" copper. See sheet 24 of the construction report.	SL repair/replace record	Y	7/23/2024	Mech excav	Field Inspection Only	Y	7/23/2024	Visual Insp during install or repair	
2391	314 E 14TH ST	UNK	C	UNK	1"	7/23/2024	C	1"	7/23/2024	SF	UNK	C	1"	UNK	Earth Inc. 10' of 1" copper from cs to existing 3/4" copper. See sheet 24 of the construction report.	Installation Record	Y	7/23/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2394	318 E 14TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/3/2017	Cross Connection Survey	
2397	1404 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/21/2017	Cross Connection Survey	
2400	1412 S CHERRY AVE	N	C	Y	3/4"	7/3/2024	C	3/4"	1/1/1935	SF	UNK	C	C		7/3/2024: Removed lead from wm-cs and replaced w/ 3/4" copper. Connected to existing 3/4" copper after cs.	SL repair/replace record	Y	7/3/2024	Visual insp during install or repair	Field Inspection Only	Y	7/3/2024	Visual Insp during install or repair	
2403	1500 S CHERRY AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2406	1504 S CHERRY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2408	1505 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		MEYERS 09/13/97 - REMOVED LEAD WIPE @ CURB VALVE, INSTALLED NEW CURB VAVEL	Installation Record	N			Field Inspection Only	Y	6/1/2017	Cross Connection Survey	
2411	1415 S CHERRY AVE	N	C	UNK	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	C		7/3/2024: Dug and removed lead goosneck @ main. Connected to 3/4" copper.	Installation Record	Y	7/3/2024	Mech excav	Field Inspection Only	Y	7/3/2024	Mech excav	
2414	1409 S CHERRY AVE	N	C	UNK	1"	1/1/1968	C	1"	1/1/1968	SF	UNK	C	1"	UNK	MFLD PLB. 1-1-2020 J&R VACUUM EXCAVATED AT CB, FOUND 1" COPPER 6'1" DEEP	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2417	404 E 14TH ST	N	C	UNK	1"	7/31/2024	P	1"	1/1/1926	SF	UNK	C	C		Earth Inc. 11' of 1" copper from cs to existing1" plastic. See sheet 27 of the construction report.	SL repair/replace record	Y	7/31/2024	Mech excav	Field Inspection Only	Y	7/31/2024	Visual Insp during install or repair	
2420	406 E 14TH ST	N	C	Y	1"	8/2/2024	C	3/4"	1/1/1931	SF	UNK	C	C		Earth Inc. 13.5' of 1" copper from cs to existing 3/4" copper. See sheet 28 of the construction report.	SL repair/replace record	Y	8/2/2024	Mech excav	Field Inspection Only	Y	8/2/2024	Visual Insp during install or repair	
2423	408 E 14TH ST	UNK	C	UNK	1"	8/2/2024	C	1"	8/2/2024	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	8/2/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2426	207 N PALMETTO AVE	N	C	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD, *2018 - SERVICE TAPPED AFTER HYDRANT TEE, 3/4" TAP, 3' - 3/4" COPPER WITH 3/4" COUPLING	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2429	308 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2438	711 N GALVIN AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SANITARY GOES TO INTERSECTION OF BECKER & GALVIN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2479	1817 E MCMILLAN ST	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2483	1801 E MCMILLAN ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	CB VERIFIED 12-97	Installation Record	Y	12/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2639	919 W MCMILLAN ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2646	1003 W MCMILLAN ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2649	1011 W MCMILLAN ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2658	1101 W MCMILLAN ST	UNK	C	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2715	1406 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1963	C	5/8"	1/1/1963	NONRES	UNK	C	UNK	1/1/1963	LEAD ON BOTH SIDES OF NEW CURB BOX, FROM HOUSE TO CURB-2016 MEYERS	SL repair/replace record	Y	2016	Mech excav	Field inspection only	Y	7/24/2014	Cross Connection Survey	
2718	1100 N WALNUT AVE	UNK	C	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	2004-NEW 3/4" CORP	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2721	312 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2729	110 W HARRISON ST	N	C	UNK	3/4"	1/1/2007	C	3/4"	1/1/2007	SF	UNK	C	3/4"	UNK	2007-INSTALLED 3/4" COPPER FROM CORP TO TERRACE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2733	141 S CENTRAL AVE	N	C	UNK	3/4"	1/1/2001	L	3/4"	1/1/2001	NONRES	UNK	L	UNK	1/1/2001	2009-REPAIRED AND REPLACED 4-1/2' OF 3/4" COPPER INCLUDING CURB VALVE.	SL repair/replace record	Y	1/1/2001	Visual insp during install or repair	Previous eval	Y	9/17/2013	Visual insp at meter	
2736	407 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2740	710 E DEPOT ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2750	108 W 2ND ST	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2752	148 S CENTRAL AVE	N	C	UNK	3/4"	1/1/2001	L	3/4"	1/1/2001	NONRES	UNK	L	UNK	1/1/2001	MEWD	SL repair/replace record	Y	1/1/2001	Visual insp during install or repair	Previous eval	Y	12/2/2021	Cross connection survey	
2755	201 N ASH AVE	Y	L	Y	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	2009-REMOVED LEAD WIPE @ MAIN. INSTALLED 4' 3/4" COPPER. REMOVED FROM FREEZE-UP.	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2758	901 W MCMILLAN ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2762	721 N PLUM AVE	N	C	UNK	1"	1/1/1965	C	1"	1/1/1965	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 6'2" DEEP	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2767	804 N CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2771	510 N PEACH AVE	UNK	C	Y	1"	6/26/2023	C	1"	6/26/2023	SF	UNK	C	1"	UNK	6/26/23: Mu removed lead from wm-cs. Replaced w/ 1" corp, 1" copper. Meyers replaced lead from cs-meter w/ 1" copper, 1" cs & box.	Installation Record	Y	6/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2776	112 W HARRISON ST	N	C	UNK	3/4"	1/1/2007	C	3/4"	1/1/2007	SF	UNK	C	3/4"	UNK	2007-INSTALLED NEW COPPER FROM CORP TO TERRACE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2780	711 N CHERRY AVE	N	UNK	UNK	UNK	1/1/1965	C	UNK	1/1/1965	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF FOREST	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2783	411 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2798	912 S CEDAR AVE	N	C	Y	1"	10/12/2022	C	1"	10/12/2022	SF	UNK	C	1"	UNK	10/12/22: Removed lead from wm-cs and replaced w/ 1" copper and new 1" cs & box. Used existing corp., connected to existing 3/4" copper on customers side.	Installation Record	Y	10/12/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2805	701 N PLUM AVE	N	C	Y	3/4"	5/19/2022	C	3/4"	5/19/2022	SF	UNK	C	3/4"	UNK	5/19/22: Pg. 3 of construction report. Installed new 1" corp., 18" - 1 " copper, connected to existing 3/4" copper @ main. (no lead)	Installation Record	Y	5/19/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2812	313 E FRANKLIN ST	UNK	C	UNK	1"	6/15/2022	C	1"	6/15/2022	SF	UNK	C	1"	UNK	Pg. 15 of Construction Report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/15/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2815	210 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2821	406 E 20TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/18/97	Installation Record	Y	8/18/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2824	1708 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		REMOVED LEAD WIPES & LEAD 1989	Installation Record	N			Field Inspection Only	Y	4/29/2013	Cross Connection Survey	
2830	506 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	LV/CB UNKNOWN. 6/22: Dug @ the wm and found 3/4" copper. (No Lead)	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2833	415 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2836	711 N CHESTNUT AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2839	1003 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	UNK	C	3/4"	UNK	SF	UNK	G	UNK	UNK	INSTALLED NEW CURB VALVE/BOX, CONNECTED TO 3/4" IRON-2015	Installation record	N	1/1/2015	Visual insp during install or repair	Previous eval	Y	1/1/2015	Cross connection survey	
2842	101 W 4TH ST	UNK	C	UNK	2"	1/1/2013	C	2"	1/1/2013	NONRES	UNK	C	2"	UNK	ATTACHED TO 2" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2855	1712 S MAPLE AVE	N	L	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	UNK	1/1/1946	2009-REMOVED LEAD WIPE @ MAIN. INSTALLED CURB STOP W/ BOX AND 5' COPPER UNDER STORM SEWER.	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	5/22/2017	Cross Connection Survey	
2858	1603 S MAPLE AVE	N	C	UNK	1"	9/23/2024	C	UNK	1/1/1922	SF	UNK	C	C		9/23/24: Installed 1" corp w/ saddle, 1" copper, 1" cs & box. Connected to existing 3/4" copper.	SL repair/replace record	Y	9/23/2024	Visual insp during install or repair	Field Inspection Only	Y	9/23/2024	Visual Insp during install or repair	
2862	1114 N WALNUT AVE	UNK	C	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	2003-NEW 1" CORP CONNECTED TO EXISTING 1" COPPER. 1-1/2' S OF VALVE	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2866	309 E EDISON ST	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper 6' North of CS. See sheet 18 of the construction report	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2874	500 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	C	1 1/2"	1/1/2009	NONRES	UNK	C	1 1/2"	UNK	INSTALLED 1-1/2" INTO BLDG. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2879	406 W LEONHARD ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2884	100 E 14TH ST	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	A-1 EXCAVATING. 7' FROM BOX TO 3/4" COPPER	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2891	1110 N CENTRAL AVE #A	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	NONRES	UNK	C	1"	UNK	MEYERS. 1" copper on property side	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2894	310 W DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1939	C	UNK	1/1/1939	SF	UNK	C	C		CURB BOX LOCATION VERIFIED 12/17/96	Installation Record	N			Field Inspection Only	Y	8/4/2016	Cross Connection Survey	
2897	109 W GRANT ST	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		REMOVED LEAD WIPE @ CURB STOP, INSTALLED NEW 3/4" CURB STOP/BOX-2014	Installation Record	N			Field Inspection Only	Y	9/6/2016	Cross Connection Survey	
2900	112 E 4TH ST	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	NONRES	UNK	C	1"	UNK	CONNECTED TO 1/2" COPPER ON PROP. SIDE (SERVICE ON MAPLE)	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2904	1006 E ARNOLD ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2907	409 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2911	208 E DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1944	C	UNK	1/1/1944	SF	UNK	C	C		2009-INSTALLED CURB STOP W/ BOX.	Installation Record	N			Field Inspection Only	Y	9/27/2016	Cross Connection Survey	
2914	509 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015- INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2917	205 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	UNK-NOLG	UNK	1/1/1926	SF	UNK	UNK	UNK		Stainless steal property side	Installation Record	N			Field Inspection Only	Y	6/29/2017	Cross Connection Survey	
2920	1915 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	ATTACHED TO 3/4" COPPER 30'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2935	1113 E DOEGE ST	N	C	UNK	3/4"	11/17/2011	C	3/4"	11/17/2011	SF	UNK	C	3/4"	UNK	2011- INSTALLED 3/4" CURB VALVE & CURB BOX	Installation Record	Y	11/17/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2938	501 E FRANKLIN ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1975	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2941	120 W JEFFERSON ST	N	UNK	UNK	5/8"	1/1/1959	C	5/8"	1/1/1959	SF	UNK	C	5/8"	UNK	CHARLES SCHUH	Installation Record	Y	1/1/1959	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2944	901 E CLEVELAND ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2947	2005 S CEDAR AVE	N	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 3/4" COPPER 7'1" DEEP	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2951	317 N CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	REMOVED WIPES 1989. 2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 6' DEEP	SL repair/replace record	Y	2020	Mech excav	Field inspection only	Y	1/16/2014	Cross Connection Survey	
2954	503 N PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2957	401 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2963	307 E DOEGE ST	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	New curb box & stop installed. Service comes off Cedar 6-2020	Installation Record	Y	6/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2967	119 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2001	C	1 1/2"	1/1/2001	NONRES	UNK	C	1 1/2"	UNK	MEWD. 1-1/2" copper on property side	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2972	307 N CENTRAL AVE	N	C	UNK	3/4"	3/1/2000	C	3/4"	3/1/2000	NONRES	UNK	C	3/4"	UNK	New 3/4" COPPER from main to curb box 3-2000	Installation Record	Y	3/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2975	1014 E CLEVELAND ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
2978	1413 S PROSPECT AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/23/2017	Cross Connection Survey	
2981	404 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2985	729 N PEACH AVE	UNK	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2988	110 W JEFFERSON ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
2992	1804 S MAPLE AVE	N	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	1989 - REMOVED WIPE @ CORP & CS	Installation record	N	1/1/1989	Visual insp during install or repair	Previous eval	Y	5/5/2017	Cross connection survey	
2995	308 S CEDAR AVE	N	C	Y	3/4"	10/13/2019	C	3/4"	10/13/2019	SF	UNK	C	3/4"	UNK	10-13-19 - VERIFIED COPPER FROM CURB VALVE TO BACK OF CURB. REIGEL PLBG INSTALLED NEW CS & BOX WITH 3/4" COPPER TO HOUSE (DOINE DUG). 9/1/22: removed lead wipe @ main.	Installation Record	Y	10/13/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
2998	1208 E BLODGETT ST	N	C	UNK	1"	1/1/1960	C	1"	1/1/1960	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3000	1100 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3008	611 N PLUM AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3011	208 N CEDAR AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3017	700 N PLUM AVE	N	C	UNK	1"	1/1/1967	C	1"	1/1/1967	SF	UNK	C	1"	UNK	SEIGER. 1-1-2020 J&R VACUUM EXCAVATED 6" FROM CB, FOUND 1" COPPER 5'3" DEEP	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3021	410 W LEONHARD ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3025	717 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, CONNECTED TO 3/4" CU ON CUSTOMERS SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3028	307 N CEDAR AVE	N	C	UNK	3/4"	1/1/2008	C	3/4"	1/1/2008	SF	UNK	C	3/4"	UNK	2008-INSTALLED COPPER FROM MAIN TO CURB VALVE. INSTALLED CURB VALVE & BOX.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3031	1313 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3034	1402 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3037	510 N APPLE AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3040	1403 E BLODGETT ST	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" CU ON CUSTOMERS SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3046	615 N ASH AVE	UNK	C	UNK	1"	6/3/2021	C	1"	6/3/2021	SF	UNK	C	1"	UNK	6/3/2021-17' of 1" copper from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper	Installation Record	Y	6/3/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3049	810 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CONNECTION MADE 18' FROM BOX. 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3052	410 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN. 2022: Removed lead, Serive is 3/4" copper. No lead	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3056	401 E EDISON ST	UNK	C	UNK	1"	8/1/2023	C	1"	8/1/2023	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 19 of the construction report	Installation Record	Y	8/1/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3072	604 N MAPLE AVE	UNK	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Removed lead from main to c.b., new copper and c.b./c.v. 2015	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3076	1100 S CEDAR AVE	N	C	UNK	1"	10/24/2022	C	1"	10/24/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to curb valve. New curb valve and box. Used existing corp and connected to existing 3/4" copper on owners side.	Installation Record	Y	10/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3080	612 N MAPLE AVE	N	L	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	UNK	1/1/1936	9/18/2019 - FIXED LEAK & INSTALLED CB FROM CB - 12" OF 3/4" COPPER ATTACHED TO 5/8" LEAD ON UTILITY SIDE	SL repair/replace record	Y	2019	Mech excav	Field inspection only	Y	4/12/2016	Cross Connection Survey	
3083	201 N HINMAN AVE	N	C	UNK	3/4"	1/1/2022	C	3/4"	1/1/2022	SF	UNK	C	3/4"	UNK	2022: New 3/4" copper from main to cs - Connected to existing 1/2" copper under West edge of sidewalk	Installation Record	Y	1/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3086	1407 E BLODGETT ST	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	STRATFORD, DUPLEX WITH 1407. 2018 - FOUND TWO SERVICES, UNSURE WHICH SERICE WAS LIVE SO BOTH WERE HOOKED BACK UP. INSTALLED 2 - 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1" COUPLING, 3' - 1" COPPER WITH 1" - 3/4" COUPLING IN ROAD	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3093	1203 E DOEGE ST	N	UNK	UNK	UNK	UNK	UNK	UNK	UNK	SF	UNK	UNK	UNK	UNK	A "Y" CONNECTION W/1201 DOEGE. CURB VALVE FOR #1203 ONLY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3096	1204 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/11/2013	Cross Connection Survey	
3104	310 N MAPLE AVE	UNK	C	Y	1"	6/21/2023	C	1"	6/21/2023	SF	UNK	C	1"	UNK	6/21/23: Removed lead wm-cs, replaced w/ 1" copper,1"tap,1"cs & box. Conn to existing 3/4" copper after cs.	Installation Record	Y	6/21/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3112	217 E GRANT ST	UNK	C	UNK	3/4"	4/27/2022	C	3/4"	4/27/2022	SF	UNK	C	3/4"	UNK	4/27/2022: Installed 8" tapping sleeve w/ 1" C.C., connected to existing 3/4" copper under 12" SS crossing approx. 12' north of the water main.	Installation Record	Y	4/27/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3115	404 W IVES ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3119	209 E 3RD ST	N	C	Y	1"	9/7/2022	C	1"	9/7/2022	SF	UNK	C	1"	UNK	9/7/22: Removed lead and installed new 1" copper, used existing corp. Installed new 1" curb valve & box. Lead on customers side. 2022: Customer replaced lead w/ copper	Installation Record	Y	9/7/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3124	311 N JUNO AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 7/3/79	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3126	1400 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3134	1010 N WALNUT AVE	UNK	C	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	2004-INSTALLED 3/4" CORP	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3137	302 N PEACH AVE	UNK	UNK	UNK	UNK	UNK	P	UNK	UNK	SF	UNK	P	UNK	UNK	1" HDPE on customer side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3142	410 N CENTRAL AVE	Y	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	NONRES	UNK	C	3/4"	UNK	3 - 3/4" TAPS OFF DOEGE - FOR LAUNDRYMAT	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3145	206 E 17TH ST	UNK	C	UNK	1"	8/8/2022	C	1"	8/8/2022	SF	UNK	C	1"	UNK	Pg. 28 of the construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 13' after cs.	Installation Record	Y	8/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3148	418 W IVES ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3151	507 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	DIRECTIONAL BORED. 3/4" COPPER INSIDE.	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3154	211 W DOEGE ST	N	L	UNK	UNK	1/1/1941	C	UNK	1/1/1941	SF	UNK	C	UNK	1/1/1941	2014-INSTALLED NEW CURB VALVE/BOX, REMOVING LEAD WIPE ON STREETSIDE. 3/4" COPPER ON CUSTOMER SIDE	SL repair/replace record	Y	2014	Mech excav	Field inspection only	Y	8/10/2016	Cross Connection Survey	
3157	1210 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3161	717 N HINMAN AVE	UNK	C	UNK	1"	9/21/2022	C	1"	9/21/2022	SF	UNK	C	1"	UNK	Pg. 14 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3168	1805 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	NONRES	UNK	C	C		INSULATED MAIN 1989	Installation Record	N			Field Inspection Only	Y	12/11/2014	Cross Connection Survey	
3173	622 N PEACH AVE	UNK	UNK	UNK	UNK	1/1/2001	C	UNK	1/1/2001	SF	UNK	C	UNK	UNK		Installation Record	Y	1/1/2001	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3176	204 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3179	606 N PLUM AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3184	1909 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	ATTACHED TO 3/4" COPPER 17'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3204	905 N CEDAR AVE	UNK	UNK	UNK	3/4"	1/1/1964	UNK	3/4"	1/1/1964	NONRES	UNK	UNK	3/4"	UNK	3/4" TAPS	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3204	905 N CEDAR AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3207	401 N JUNO AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3212	507 E EDISON ST	N	C	Y	3/4"	1/1/2020	C	3/4"	1/1/2020	SF	UNK	C	3/4"	UNK	3/4" Copper in & out, New curb valve, replaced service in 2020 from lead to copper	Installation Record	Y	1/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3215	309 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	NO CURB BOX	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3219	804 E BLODGETT ST	N	C	Y	1"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	L	UNK	1/1/2018	2018 - Installed 1" corp and tapping saddle, 2' - 1" copper with 1"X3/4" coupling. 5/22/24: Replaced 5' of lead in terrace. Connected to exist. 3/4" copper at walk. service is 3/4" copper from main to cs. (still has 1" corp and short piece of 1" cu at wm.	SL repair/replace record	Y	5/22/2024	Visual insp during install or repair	Field Inspection Only	Y	5/22/2024	Visual Insp during install or repair	
3223	308 W DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3226	1207 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3229	812 E BLODGETT ST	N	C	UNK	1"	1/1/2018	L	1"	1/1/2018	SF	UNK	L	UNK	1/1/2018	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING	SL repair/replace record	Y	1/1/2018	Visual insp during install or repair	Previous eval	Y	12/20/2016	Cross connection survey	
3237	1206 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1980	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3240	724 N CHERRY AVE	N	C	UNK	1"	5/2/2022	C	1"	5/2/2022	SF	UNK	C	1"	UNK	5/2/22: Installed new 1" tap w/ tapping saddle, 12" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/2/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3243	1107 W MCMILLAN ST	UNK	C	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3247	1500 S CEDAR AVE	N	C	Y	3/4"	8/6/2020	C	3/4"	8/6/2020	SF	UNK	C	3/4"	UNK	2020- Verified via Vac Excavating Lead on Customer and Streetside. 8-6-2020 REMOVED LEAD FROM MAIN - METER, REPLACED W/ COPPER. REIGEL'S PLBG.	Installation Record	Y	8/6/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3250	209 E 5TH ST	UNK	UNK	UNK	1/2"	UNK	C	1/2"	UNK	SF	UNK	C	1/2"	UNK	CURB STOPS ARE 1' APART FOR 412 S. CEDAR AND 209 E 5TH. BE CAREFUL RETAPPED 06/21/79 3/4" COPPER ABANDONED ON TOP OF MAIN	Installation Record	Y	6/21/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3253	208 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	O	UNK	C	C		REMOVED LEAD WIPE 1-2000.	Installation Record	N			Field Inspection Only	Y	5/23/2017	Cross Connection Survey	
3257	204 E 14TH ST	N	C	UNK	1"	7/30/2024	C	3/4"	1/1/1925	SF	UNK	C	C		Earth Inc. 10' of 1" copper from cs to existing 3/4" copper.	SL repair/replace record	Y	7/30/2024	Visual insp during install or repair	Field Inspection Only	Y	7/30/2024	Visual Insp during install or repair	
3260	207 N CHERRY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3263	204 E 3RD ST	N	C	Y	3/4"	UNK	C	3/4"	9/1/2020	SF	UNK	C	3/4"	UNK	9/2020 - Removed lead service from main to house. New cs & box installed (Reigels)	Installation Record	Y	9/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3266	113 N ELM AVE	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1" CORP,COPPER,CURB VALVE W/ BOX	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3270	109 E ARNOLD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C			Installation Record	N			Field Inspection Only	Y	11/3/2016	Cross Connection Survey	
3273	400 N CENTRAL AVE	UNK	C	UNK	3/4"	4/4/2019	C	3/4"	4/4/2019	NONRES	UNK	C	3/4"	UNK	1' OF 1" CU AFTER CURB STOP CONNECTED TO EXISTING 3/4" CU ON CUSTOMERS SIDE	Installation Record	Y	4/4/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3278	110 N ELM AVE	N	C	Y	3/4"	1/1/2004	C	3/4"	1/1/2004	SF	UNK	C	3/4"	UNK	2004-NEW 3/4 CORP ATTACHED TO EXISTING 3/4 COPPER@ MAIN 2022- Customer replaced lead w/ copper. 5/19/22: Removed lead wipe @ cs. All copper from main to cs. Gaffney installed copper from cs to house.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3281	116 W JEFFERSON ST	N	C	Y	3/4"	1/1/1960	C	3/4"	1/1/1960	SF	UNK	C	3/4"	UNK	9/3/2024: removed lead wipe @ wm, replaced w/ 3/4" copper.	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3284	217 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3288	601 E BECKER RD	UNK	C	UNK	1"	6/8/2021	C	1"	6/8/2021	SF	UNK	C	1"	UNK	17' - 1" type 'K' Copper from WM - CS & 12' of 1" Copper from CS to existing 3/4" Copper	Installation Record	Y	6/8/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3296	700 N PEACH AVE	N	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3299	1409 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		REMOVED WIPES AT MAIN & BOX 1989 COPPER INSIDE	Installation Record	N			Field Inspection Only	Y	4/24/2017	Cross Connection Survey	
3302	506 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	P	UNK	1/1/1947	SF	UNK	P	P		2013-CURB VALVE/BOX INSTALLED, 1" PLASTIC INSIDE	Installation Record	N			Field Inspection Only	Y	10/25/2016	Cross Connection Survey	
3317	210 W DOEGE ST	Y	UNK	UNK	UNK	1/1/1962	C	UNK	1/1/1962	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3320	212 E 3RD ST	N	C	UNK	1"	1/1/1986	C	1"	1/1/1986	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3335	1300 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF DOEGE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3335	1300 E DOEGE ST	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	SF	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3335	1300 E DOEGE ST	UNK	C	UNK	1"	11/29/2021	P	1"	11/29/2021	SF	UNK	P	1"	UNK	10.5' from main to cs. 1" copper in street, 1" plastic on private. (Gaffney) Old service is disconnected. 15' N & 34' East off SEC of the garage. Under driveway 9-2022	Installation Record	Y	11/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3338	900 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3342	615 N PLUM AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3348	144 S CENTRAL AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	NONRES	UNK	C	3/4"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3356	701 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER 7'E OF BOX. A-1 EXCAVATING. COUPLER 14'E OF MAIN	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3359	306 W KALSCHED ST	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	INSULATED 2X4 1981	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3362	1500 E BLODGETT ST	UNK	C	UNK	1"	1/1/1972	C	1"	1/1/1972	SF	UNK	C	1"	UNK	2011-INSTALLED NEW CURB STOP/BOX 2'S OF OLD ONE THATS UNDER SIDEWALK. 2018 - INSTALLED 1 - 1" CORP WITH TAPPING SADDLE, 2' - 1" COPPER, 1"X3/4" COUPLING	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3365	507 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3369	408 W JEFFERSON ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2009-INSTALLED NEW CURB VALVE AND BOX.	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3374	411 E FOREST ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3377	702 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 12' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3380	110 E 17TH ST	N	UNK	UNK	3/4"	1/1/1990	C	3/4"	1/1/1990	SF	UNK	C	3/4"	UNK	RETAPPED & INSULATED	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3383	1100 N FIG AVE	N	UNK	UNK	3/4"	7/14/1960	C	3/4"	7/14/1960	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	7/14/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3388	411 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		1982-RETAPPED,LOWERED, & INSULATED	Installation Record	N			Field Inspection Only	Y	9/7/2016	Cross Connection Survey	
3393	169 N CENTRAL AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	NONRES	UNK	C	1"	UNK	MEWD	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3393	169 N CENTRAL AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	NONRES	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3399	107 E 11TH ST	N	C	UNK	3/4"	1/1/2019	C	3/4"	1/1/2019	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN - REMOVED OLD 2" GALVANIZED MAIN 2019, REPLACED W/ 2" PLOY, CONNECTED TO EXISTING 3/4" CU IN THE ROAD	Installation Record	Y	1/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3402	204 N VINE AVE	N	C	UNK	3/4"	UNK	G	3/4"	UNK	SF	UNK	G	UNK	UNK	1985 - LEAD WIPE REMOVED. 1990 - 6' DEEP @ MAIN RETAPPED & INSULATED-CORP 12'S & 41'E OF SE COR. OF 206 IS 1'N FOR 205 IS 2'S. 5/14/24: Verified 3/4" copper from main to crub (tunneled under curb w/ shovel)	SL repair/replace record	Y	5/14/2024	Mech excav	Field Inspection Only	Y	5/14/2024	Mech excav	
3410	418 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3423	111 E 14TH ST	UNK	C	UNK	2"	7/30/2024	C	2"	7/30/2024	NONRES	UNK	C	2"	UNK	Earth Inc. 13' of 2" copper from cs to existing 2" copper.	Installation Record	Y	7/30/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3426	412 E ARNOLD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	12/9/2016	Cross Connection Survey	
3429	1810 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3433	2007 S VINE AVE	UNK	UNK	UNK	1 1/2"	1/1/1981	C	1 1/2"	1/1/1981	NONRES	UNK	C	1 1/2"	UNK	STRATFORD PLB.	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3442	107 S CENTRAL AVE	UNK	C	Y	1"	1/1/2001	C	1"	1/1/2001	NONRES	UNK	C	1"	UNK	MEWD. 1" lead on property side. 6/13/23: Steves Plbg. replaced lead w/ 1" copper from cs-meter	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3449	202 W KALSCHED ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3452	117 N ELM AVE	N	C	UNK	3/4"	1/1/2004	C	3/4"	1/1/2004	SF	UNK	C	3/4"	UNK	2004-NEW 3/4 CORP,COPPER,CURB VALVE W/ BOX	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3457	112 E GRANT ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	1/3/2017	Cross Connection Survey	
3460	606 E FRANKLIN ST	N	C	Y	1"	5/31/2022	C	1"	5/31/2022	SF	UNK	C	1"	UNK	5/31/22: Shared w/ 608 E. Franklin. Pg. 8 of construction report. Installed 1" corp, 6' - 1" copper, connected to existing 3/4" copper @ wm. (no lead)	Installation Record	Y	5/31/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3465	104 N PURDY AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS, DUPLEX WITH 106 N PURDY	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3472	1611 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3478	417 W JEFFERSON ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	CURB-BOX TO HOUSE REPLACED 2001	Installation Record	Y	1/1/2001	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3481	110 W 1ST ST	UNK	DI	UNK	4"	1/1/2013	DI	4"	1/1/2013	NONRES	UNK	DI	4"	UNK	CLOW VALVE	Installation Record	Y	1/1/2013	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
3486	1607 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3489	305 N VINE AVE	UNK	C	Y	1"	5/30/2023	C	1"	5/30/2023	SF	UNK	C	1"	UNK	5/30/23: Removed lead wm-cs, replaced w/ 1" copper. Conn. to existing corp with short piece of 3/4" copper. Meyers installed 1" cs & box & 1" copper from cs-meter.	Installation Record	Y	5/30/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3493	415 E EDISON ST	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. CS closed for spare lot. See sheet 20 of the construction report	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3497	1111 E EDISON ST	N	C	UNK	1"	7/22/2019	C	1"	7/22/2019	SF	UNK	C	1"	UNK	INSTALLED NEW 1' SERVICE SADDLE , 1' CORP, 1 CS +_ BOX CONNECTED TO EXISTING 3/4 COPPER BEHIND CS	Installation Record	Y	7/22/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3507	109 N VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/2/2016	Cross Connection Survey	
3513	307 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	L	1"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	CONNECTED TO 5/8 LEAD 10'E OF BOX. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	2/5/2014	Cross connection survey	
3518	204 E 11TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3522	311 E EDISON ST	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 1" copper. See sheet 18of the construction report	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3525	1203 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	MEYERS - 3/4" CU ON CUSTOMERS SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3528	1000 N CENTRAL AVE	UNK	UNK	UNK	1 1/4"	1/1/2000	C	1 1/4"	1/1/2000	NONRES	UNK	C	1 1/4"	UNK	2005-REPLACED CURB VALVE, MOVED OUT OF SIDEWALK	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3531	621 N ASH AVE	UNK	C	UNK	1"	6/2/2021	C	1"	6/2/2021	SF	UNK	C	1"	UNK	6/2/2021-18' of 1" from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper	Installation Record	Y	6/2/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3535	1112 S CEDAR AVE	UNK	C	Y	1"	7/30/2021	C	1"	7/30/2021	SF	UNK	C	1"	UNK	7/30/2021: Removed Lead & replaced w/ 1" Copper. Retapped 3' North of abandoned tap. Reigel Plbg. installed a 1" CS & Box w/ 1" copper to the meter. Reigel had to dig around the porch to the NE corner of the basement. San. lateral repaired in street	Installation Record	Y	7/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3538	203 N VINE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	INSULATED 1990. 5/15/2024: Dug and verifired 3/4" copper at main and cs.	Installation Record	Y	5/15/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3542	411 N CHERRY AVE	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3545	1007 W MCMILLAN ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3556	104 N VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/2/2016	Cross Connection Survey	
3559	808 S CEDAR AVE	UNK	C	UNK	1"	9/27/2022	C	1"	9/27/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to cs, used existing corp, new 1" cs & box. 3/4" copper on house side	Installation Record	Y	9/27/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3567	1211 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3570	507 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3574	606 N PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	Feeds 606 N. Peach	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3574	606 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER. *606 N. Peach is still fed from Plum* Service on Peach is stubbed out and not servicing 606 N. Peach.	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3577	331 S CENTRAL AVE #A	UNK	C	Y	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	CONNECTED TO 5/8 LEAD 10'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3580	910 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/13/2013	Visual insp at meter	
3583	907 S MAPLE AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	THIS COULD BE A "Y" SERVICE WITH 213. VERIFY WHEN POSSIBLE. 2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 7'6" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	6/1/2017	Cross connection survey	
3586	908 N CENTRAL AVE	UNK	UNK	UNK	2"	1/1/1974	C	2"	1/1/1974	NONRES	UNK	C	2"	UNK	FLAIRED.	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3598	409 N CENTRAL AVE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	RON MEYER & SON	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3600	404 N PEACH AVE	UNK	C	Y	1"	6/26/2023	C	1"	6/26/2023	SF	UNK	C	1"	UNK	6/26/23: Removed lead from wm-cs and replaced w/ 1" corp., 1" copper and 1" cs & box. Conn to existing 3/4" copper after cs. Used a 6" sleeve w, 1" CC for the tap. Dalton Tysver replaced the sewer from swr. main to cs.	Installation Record	Y	6/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3612	306 W DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		4/15/2021: MU visually confirmer material type in the basement by the meter	Installation Record	N			Field Inspection Only	Y	11/6/2013	Cross Connection Survey	
3616	305 E BLODGETT ST	N	C	Y	3/4"	6/7/2018	C	3/4"	6/7/2018	SF	UNK	C	3/4"	UNK	Replaced Lead on street side and Meyers replaced Galvanized on property side with 3/4" Copper.	Installation Record	Y	6/7/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3622	708 N PEACH AVE	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3630	115 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2001	C	1 1/2"	1/1/2001	NONRES	UNK	C	1 1/2"	UNK	MEWD. 1-1/2" copper on property side	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3635	1207 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3640	1604 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/20/2017	Cross Connection Survey	
3643	1501 S CHERRY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3646	817 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	G	1"	1/1/2009	NONRES	UNK	G	UNK	1/1/2009	COUPLER 17'E OF WATERMAIN. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	6/27/2013	Cross connection survey	
3650	208 N PURDY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3653	1414 S MAPLE AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPES @ MAIN & CURB STOP, 2" COPPER INSIDE/ REMOVED FLARE FITTING CUSTOMER SIDE OF VALVE-2014	Installation Record	Y	1/1/2014	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3658	711 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2001: REMOVED LEAD WIPE @ MAIN. 2002: REMOVED LEAD WIPE 2' EAST OF MAIN. 6/22: Dug & verified that all lead was removed. Found 3/4" copper @ the wm. No Lead	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3669	619 N PLUM AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3672	715 N HINMAN AVE	UNK	C	UNK	1"	9/22/2022	C	1"	9/22/2022	SF	UNK	C	1"	UNK	Pg. 15 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/22/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3678	1617 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3685	413 W IVES ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3688	915 W MCMILLAN ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3690	612 N CHESTNUT AVE	N	L	UNK	5/8"	1/1/1936	P	5/8"	1/1/1936	SF	UNK	P	UNK	1/1/1936	2010-REMOVED LEAD WIPE AND INSTALLED CURB VALVE W/ BOX	SL repair/replace record	Y	2010	Mech excav	Field inspection only	Y	8/16/2016	Cross Connection Survey	
3693	200 W DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3696	211 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	L	1"	1/1/2009	O	UNK	L	UNK	1/1/2009	CONNECTED TO 5/8" LEAD 10'E OF BOX. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	6/23/2014	Cross connection survey	
3698	211 S CENTRAL AVE	UNK	UNK	UNK	1 1/2"	1/1/1996	C	1 1/2"	1/1/1996	NONRES	UNK	C	1 1/2"	UNK	FEEDS AIR CONDITIONER UNIT	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3700	502 N CENTRAL AVE	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	RON MEYER & SON	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3704	423 E FRANKLIN ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3707	416 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3710	313 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3727	1408 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/6/2017	Cross Connection Survey	
3730	2001 S VINE AVE	UNK	UNK	UNK	1 1/2"	1/1/1983	C	1 1/2"	1/1/1983	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3735	312 N JUNO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3738	900 N CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3741	508 S CEDAR AVE	N	C	Y	1"	9/20/2022	C	1"	9/20/2022	SF	UNK	C	1"	UNK	2022: Replaced Lead w/ 1" copper from main to curb valve. Used existing corp. installed new 1" cs & box. Gaffney replaced Lead with 3/4" copper (Plbg. Permit 20221670)	Installation Record	Y	9/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3744	100 N PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 5/9/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3750	508 E CLEVELAND ST	N	C	UNK	3/4"	6/14/1961	C	3/4"	6/14/1961	SF	UNK	C	3/4"	UNK	7/25/22: New 3/4" copper from main to cs. New cs & box.	Installation Record	Y	6/14/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3753	315 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	8/14/2015	Cross Connection Survey	
3756	407 S MAPLE AVE	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	NONRES	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3763	410 E 20TH ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3766	1605 S CEDAR AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3769	511 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/3/2014	Cross Connection Survey	
3772	312 W JEFFERSON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3775	113 W FRANKLIN ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3781	916 N CENTRAL AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	REMOVED LEAD WIPES 2000.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3786	209 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/17/2016	Cross Connection Survey	
3789	506 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3792	1111 N CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3796	607 N CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1935	C	UNK	1/1/1935	SF	UNK	C	C		1/2" copper on customer side	Installation Record	N			Field Inspection Only	Y	6/6/2013	Cross Connection Survey	
3799	509 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/31/2016	Cross Connection Survey	
3802	1208 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
3805	1515 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/19/2017	Cross Connection Survey	
3811	200 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/22/2017	Cross Connection Survey	
3817	807 E ARNOLD ST	N	C	UNK	3/4"	1/1/2005	C	3/4"	1/1/2005	SF	UNK	C	3/4"	UNK	MFLD UTILITIES	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3823	208 N HINMAN AVE	N	C	Y	1"	6/13/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/13/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper. New corp is 2' North of old corp.	SL repair/replace record	Y	6/13/2024	Visual insp during install or repair	Field Inspection Only	Y	6/13/2024	Visual Insp during install or repair	
3826	1505 E BLODGETT ST	UNK	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS 1980. 2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3837	601 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3846	402 N CENTRAL AVE	N	C	Y	1"	6/27/2024	C	3/4"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2024: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper , 1" cs & box. Connected to existing 3/4" copper. 12" West of cs. Abandoned corp is 3' North of new corp.	SL repair/replace record	Y	6/27/2024	Visual insp during install or repair	Field inspection only	Y	6/27/2024	Visual Insp during install or repair	
3849	1309 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3852	611 N PALMETTO AVE	UNK	C	UNK	1"	7/6/2023	C	1"	7/6/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 15 of construction report)	Installation Record	Y	7/6/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3856	1801 S CENTRAL AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	TAPPED OFF 17TH ST. CURB BOX IS ON WEST SIDE OF BLDG. 1-1/2" Copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3859	800 S CEDAR AVE	N	C	UNK	1"	9/5/2018	C	1"	9/5/2018	SF	UNK	C	1"	UNK	9/5/18 - RIPPED EXISTING CORP. TAPPED ON TOP, FIXED WITH REPAIR SLEEVE WITH 1" CORP CUT-OUT, 1" CORP, 1" COPPER, CS & BOX, 1"X3/4" COPPER TO COPPER AFTER CURB STOP, INSULATED ABOVE CORP.	Installation Record	Y	9/5/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3862	1602 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/26/2017	Cross Connection Survey	
3866	406 N MAPLE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1982-RETAPPED & LOWERED. DEPTH OF SERVIVE @ CURB STOP IS 4-1/2. 6/28/22: Verified all copper. Installed new cs & box. **CAUTION-Fiber Optice is in the terrace, wasn't located**	Installation Record	Y	6/28/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3869	800 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	12/1/2014	Cross Connection Survey	
3874	307 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		STUB OUT	Installation Record	N			Field Inspection Only	Y	11/3/2016	Cross Connection Survey	
3876	1802 S MAPLE AVE	N	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	2017-INSTALLED NEW CORP, 4' OF 3/4" COPPER, C.V./C.B.; 1989-REMOVED WIPE, INSULATED;	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3879	400 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		(Service card address of 111 E. Cleveland) C.B. Location verified 6/3/1997. 2" copper on property side	Installation Record	N			Field Inspection Only	Y	6/24/2013	Cross Connection Survey	
3885	1907 S VINE AVE	UNK	C	UNK	2"	1/1/1990	C	2"	1/1/1990	NONRES	UNK	C	2"	UNK	32'W & 15'S OF SW COR. OF BLDG. OR 195'N & 63'E OF NE COR. OF GARAGE @420 E 20TH	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3885	1907 S VINE AVE	UNK	C	UNK	2"	1/1/1990	C	2"	1/1/1990	NONRES	UNK	C	2"	UNK	COMBINED WITH ANOTHER 2" SERVICE TO MAKE A 4" FIRE SERVICE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3888	312 E 17TH ST	UNK	C	UNK	1"	6/22/2022	C	1"	6/22/2022	SF	UNK	C	1"	UNK	Pg 18 of construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 1" copper 12' after cs.	Installation Record	Y	6/22/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3898	400 E 21ST ST	UNK	UNK	UNK	3/4"	1/1/1988	C	3/4"	1/1/1988	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3901	811 E BLODGETT ST	UNK	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	CURB BOX IS UNDER CONCRETE 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 3' - 1" COPPER WITH 1" COUPLING	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3906	837 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	G	1"	1/1/2009	NONRES	UNK	G	UNK	1/1/2009	COUPLER 18'E OF MAIN. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	12/11/2013	Cross connection survey	
3911	130 S CENTRAL AVE	UNK	C	UNK	2"	1/1/2013	C	2"	1/1/2013	NONRES	UNK	C	2"	UNK	ATTACHED TO EXISTING 2" COPPER @ CURB VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3921	1914 S MAPLE AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3960	804 N MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3971	811 E DEPOT ST	UNK	C	UNK	3/4"	1/1/2004	C	3/4"	1/1/2004	SF	UNK	C	3/4"	UNK	2004-NEW 3/4 CORP,COPPER, CURB VALVE W/ BOX	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3974	312 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	7/14/2017	Cross Connection Survey	
3979	415 W KALSCHED ST	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
3983	2106 N PEACH AVE	UNK	UNK	UNK	1 1/2"	1/1/1991	C	1 1/2"	1/1/1991	O	UNK	C	1 1/2"	UNK	STRATFORD	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3990	901 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING. SEWER FIXED BY CITY AFTER PIPE BURST	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
3993	524 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4006	1413 E BLODGETT ST	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	MEYERS 1979. 2018 - INTALLED NEW 1" CORP WITH TAPPING SADDLE, CURB STOP & BOX, 15'-1" COPPER, 1" - 3/4" CU-CU	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4009	808 E CLEVELAND ST	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4018	609 N PALMETTO AVE	UNK	C	UNK	1"	7/5/2023	C	1"	7/5/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 14 of construction report)	Installation Record	Y	7/5/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4021	1908 S VINE AVE	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4024	501 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	ATTACHED TO 1" COPPER 4'E OF BOX. A-1 EXCAVATING.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4031	318 E 17TH ST	UNK	C	UNK	1"	6/22/2022	C	1"	6/22/2022	SF	UNK	C	1"	UNK	Pg 18 of construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 1" copper 12' after cs.	Installation Record	Y	6/22/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4035	306 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4040	1110 E DOEGE ST	N	C	UNK	1"	1/1/1962	C	1"	1/1/1962	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED 2' FROM CB, FOUND 1" COPPER 4'10" DEEP	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4045	812 E CLEVELAND ST	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4049	801 N CHESTNUT AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4061	401 E 18TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4064	310 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	6/12/2014	Cross Connection Survey	
4067	116 N HINMAN AVE	N	C	Y	3/4"	1/1/2020	C	3/4"	1/1/2020	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO NEW C.S. - MEYERS REPLACED LEAD SERVICE TO HOUSE 2020	Installation Record	Y	1/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4070	621 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4073	315 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	L	1"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	CONNECTED TO 5/8" LEAD 11'E OF BOX. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	6/20/2014	Cross connection survey	
4079	505 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4083	207 W DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1970	P	3/4"	1/1/1970	SF	UNK	P	3/4"	UNK	SCHULTZ	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4088	204 S CEDAR AVE	N	C	Y	3/4"	4/16/2020	C	3/4"	4/16/2020	SF	UNK	C	3/4"	UNK	4/16/2020 REIGEL PLBG - INSULATED @ MAIN. LEAD REPLACED W/ COPPER FROM MAIN TO METER	Installation Record	Y	4/16/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4091	111 W HARRISON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4107	709 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4111	404 E 18TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4116	443 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	L	1"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	CONNECTED TO 5/8 LEAD 10'E OF BOX. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	2009	Cross connection survey	
4119	601 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1931	C	UNK	1/1/1931	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/7/2016	Cross Connection Survey	
4123	1815 S MAPLE AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPES, ALL COPPER 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4126	301 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4141	405 E 18TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4145	400 E 17TH ST	UNK	C	UNK	1"	6/21/2022	C	1"	6/21/2022	SF	UNK	C	1"	UNK	Pg. 17 of construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 1" copper 12' after cs.	Installation Record	Y	6/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4151	406 E 17TH ST	UNK	C	UNK	1"	6/21/2022	C	1"	6/21/2022	O	UNK	C	1"	UNK	Pg. 17 of construction report. 1" corp., 1" copper, 1" cs & box. Connected to existing 1" copper 10 after cs.	Installation Record	Y	6/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4157	408 E 18TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4160	1800 S CHERRY AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4177	409 E 18TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4195	1111 N FIG AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LV/CB UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4198	708 E DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		3/4" Copper locking valve	Installation Record	N			Field Inspection Only	Y	1/31/2017	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
4201	202 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB LOCATION VERIFIED 6/12/97	Installation Record	N			Field Inspection Only	Y	8/11/2017	Cross Connection Survey	
4204	906 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/17/2017	Cross Connection Survey	
4209	501 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4212	716 N CEDAR AVE	UNK	C	Y	3/4"	11/9/2017	C	3/4"	11/9/2017	SF	UNK	C	3/4"	UNK	REMOVED 5/8" LEAD AND INSTALLED NEW 3/4" COPPER FROM MAIN TO INSIDE HOUSE--2017	Installation Record	Y	11/9/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4215	601 N CHESTNUT AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4218	512 N MAPLE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/15/2021: Verified @ watermain & at curb stop is 3/4" copper	Installation Record	Y	7/15/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4221	1105 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/2/2017	Cross Connection Survey	
4237	110 E 14TH ST	UNK	C	UNK	1"	7/30/2024	C	1"	7/30/2024	NONRES	UNK	C	1"	UNK	Earth Inc. 15' of 1" copper from cs to existing 1" copper.	Installation Record	Y	7/30/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4251	414 E 18TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4255	400 E 18TH ST	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4262	700 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4264	112 E 2ND ST	UNK	DI	UNK	6"	1/1/2015	CI-U	6"	1/1/2015	NONRES	UNK	CI-U	6"	UNK	<Null>	Installation Record	Y	1/1/2015	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
4269	505 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4272	606 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1993	C	3/4"	1/1/1993	NONRES	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4292	1306 E BLODGETT ST	N	C	Y	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING. REMOVED LEAD WHIP. 6-10-2020 CUT IN 3/4" C.S. & INSTALLED C.B.	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4295	512 S CEDAR AVE	N	C	Y	1"	5/29/2024	C	1/2"	1/1/1926	SF	UNK	C	C		5/29/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper & 1" cs & box. Conn to exist 1/2" copper after cs. Old corp is 3' East of new. Street dept. replaced san. lat (clay tile) w/ 6" PVC that crosses over wm @ old corp location.	SL repair/replace record	Y	5/29/2024	Visual insp during install or repair	Field Inspection Only	Y	5/29/2024	Visual Insp during install or repair	
4298	905 N MAPLE AVE	N	C	UNK	3/4"	1/1/2003	C	3/4"	1/1/2003	SF	UNK	C	3/4"	UNK	2003-NEW 3/4 COPPER FROM MAIN TO BEHIND SIDEWALK,LOWERED UNDER STORM SEWER	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4301	411 N VINE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1990-CORP IS 57'W OF NW COR. OF HSE-RETAPPED OLD CORP 4'N-REMOVED GOOSENECK LOWERED WITH COPPER. 5/21/2024: Dug and verified 3/4" copper at main and cs.	Installation Record	Y	5/21/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4303	200 E 3RD ST	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	4/27/2021-1" copper street side & 3/4" copper customers side. Old live tap 3' West of new 1" corp. Corp is 25' South & 27' East of s.w.c.of 205 S. Maple and old corp is 3' West of new corp.	Installation Record	Y	4/27/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4309	501 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4320	410 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	12/7/2021	Cross Connection Survey	
4323	516 N PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4326	1109 E EDISON ST	N	C	UNK	1"	7/15/2019	C	1"	7/15/2019	SF	UNK	C	1"	UNK	INSTALLED NEW 1' SERVICE SLEEVE, 1" CORP, 1" CS + BOX CONNECTED TO 3/4" COPPER BEHIND CS	Installation Record	Y	7/15/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4329	1104 S CEDAR AVE	N	C	UNK	UNK	10/1/2022	C	UNK	10/1/2022	SF	UNK	C	UNK	UNK	2022: 1" copper from main to curb vavle, new 1" curb valve & box. Used existing corp and connected to existing 3/4" copper on owners side	Installation Record	Y	10/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4332	1901 S CHERRY AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4349	300 E 21ST ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4353	1711 S CEDAR AVE	UNK	C	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 3/4" COPPER 7' DEEP	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4357	1208 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/12/2017	Cross Connection Survey	
4362	406 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	NONRES	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4366	305 S CHESTNUT AVE	UNK	DI	UNK	6"	1/1/2013	DI	6"	1/1/2013	NONRES	UNK	DI	6"	UNK	CLOW VALVE	Installation Record	Y	1/1/2013	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
4372	1616 S RODDIS AVE	N	DI	UNK	UNK	UNK	DI	UNK	UNK	NONRES	UNK	DI	UNK	UNK	1616 S. CENTRAL AVE ON SERVICE CARD. THIS SERVICE IS FOR THE OFFICE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4376	114 E 9TH ST	UNK	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REPLACED LEAD SERVICE WITH 3/4" COPPER FROM C.V. TO CORP 2017	Installation Record	Y	1/1/2017	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4382	803 N PEACH AVE	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	NONRES	UNK	C	1"	UNK	DUPLEX	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4389	702 N MAPLE AVE	N	C	Y	3/4"	1/1/2020	C	3/4"	1/1/2020	SF	UNK	C	3/4"	UNK	2020 - Removed lead from main to meter w/ Meyers Plbg. Installed 3/4" copper w/ new C.S. & Box	Installation Record	Y	1/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4408	300 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4411	708 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/24/2016	Cross Connection Survey	
4456	600 N CENTRAL AVE	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	NONRES	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4462	706 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Lead wipe removed @ main & curb box installed. 6/22: Dug @ wm & verified all of the lead was removed. Found 3/4" copper @ the wm.	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4466	108 W 1ST ST	UNK	C	UNK	1 1/2"	1/1/2013	P	1 1/2"	1/1/2013	NONRES	UNK	P	1 1/2"	UNK	ATTACHED TO EXISTING 1-1/2" PLASTIC AT CURB VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4468	355 S CENTRAL AVE	UNK	C	UNK	2"	1/1/2015	P	2"	1/1/2015	NONRES	UNK	P	2"	UNK	CONNECTED TO 2" PLASTIC ON PROP. SIDE.	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4471	306 E 21ST ST	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4474	104 E CLEVELAND ST	UNK	UNK-LG	UNK	UNK	1/1/1940	C	UNK	1/1/1940	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/29/2017	Cross Connection Survey	
4500	2001 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	P	1 1/2"	1/1/2009	NONRES	UNK	P	1 1/2"	UNK	ATTACHED TO 1-1/4" COPPER. 2' PAST CURB VALVE IS AN OLD CURB VALVE ATTACHED TO 1-1/4" PLASTIC WITH HOSE CLAMPS ATTACHING TO FITTING.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4505	1301 E DOEGE ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	NONRES	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4508	1407 E DOEGE ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4516	306 N VINE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4524	715 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4529	212 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1930	C	3/4"	1/1/1930	O	UNK	UNK	UNK		CB/LV UNKNOWN. 2022 - verified copper in the basement at the meter	Installation Record	N			Field Inspection Only	Y	6/3/2014	Cross Connection Survey	
4532	625 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4535	724 N PLUM AVE	N	C	UNK	1"	5/10/2022	C	1"	5/10/2022	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 3/4" COPPER 7' DEEP. 5/10/22: Installed new 1" tap w/ tapping saddle, 24" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4545	413 E 18TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4550	412 E 17TH ST	UNK	C	UNK	1"	6/17/2022	C	1"	6/17/2022	SF	UNK	C	1"	UNK	Project 5859: Pg. 15 of construction report. Connected to existing 1" copper 10 past the cs.	Installation Record	Y	6/17/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4559	1621 S CENTRAL AVE	UNK	P	UNK	2"	9/23/2024	C	2"	9/23/2024	NONRES	UNK	C	2"	UNK	9/23/24: pex from main to fiver pack, copper from fiber to existing cs. Installed new box.	Installation Record	Y	9/23/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4563	1809 S CHERRY AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4569	505 E BLODGETT ST	UNK	UNK	UNK	1 1/4"	1/1/1986	C	1 1/4"	1/1/1986	SF	UNK	C	1 1/4"	UNK	IS IN DRIVE WAY	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4576	1900 S VINE AVE	UNK	UNK	UNK	2"	1/1/1990	C	2"	1/1/1990	SF	UNK	C	2"	UNK	TRIERWEILER CONST	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4579	610 N MAPLE AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4582	1502 S CENTRAL AVE	UNK	UNK	UNK	1 1/2"	1/1/1995	C	1 1/2"	1/1/1995	NONRES	UNK	C	1 1/2"	UNK	2009-INSTALLED 1-1/2" COPPER 7'E OF CURB VALVE UNDER STORM SEWER.	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4585	1502 S CENTRAL AVENUE	UNK	UNK	UNK	2"	1/1/1995	C	2"	1/1/1995	NONRES	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4591	104 E 14TH ST	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	A-1 EXCAVATING. 1' CURB BOX TO 3/4" COPPER	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4596	803 N CENTRAL AVE	UNK	UNK	UNK	1 1/2"	1/1/1995	C	1 1/2"	1/1/1995	NONRES	UNK	C	1 1/2"	UNK	GAFFNEY PLUMBING	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4600	550 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	ATTACHED TO 1" COPPER. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4604	705 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
4607	200 N VINE AVE	N	C	UNK	3/4"	4/6/1990	C	3/4"	1/1/1926	SF	UNK	C	C		4-6-90 INSULATED. 5/15/2024: Dug and verified 3/4" copper from wm to cs. Corp. is 28' East & 15' North of the NECH. Installed cs.	Installation Record	Y	5/15/2024	Mech excav	Field Inspection Only	Y	5/15/2024	Mech excav	
4610	111 N ELM AVE	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1" CORP,COPPER,CURB VALVE W/ BOX	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4616	808 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4619	104 N ELM AVE	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1" CORP,COPPER,CURB VALVE W/ BOX	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4622	1410 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		REMOVED WIPES AT MAIN & BOX 1989 COPPER INSIDE	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
4625	508 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4628	206 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CURB BOX LOCATION VERIFIED 2/21/97	Installation Record	N			Field Inspection Only	Y	8/2/2017	Cross Connection Survey	
4633	601 E 21ST ST	UNK	UNK	UNK	4"	1/1/1997	DI	4"	1/1/1997	NONRES	UNK	DI	4"	UNK	JAKEL PLUMBING	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
4636	751 S CENTRAL AVE	UNK	UNK	UNK	1 1/2"	1/1/1997	C	1 1/2"	1/1/1997	NONRES	UNK	C	1 1/2"	UNK	THE HYD RUN	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4645	1313 E DOEGE ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4652	318 E 21ST ST	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	DUPLEX	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4663	229 S CENTRAL AVE	UNK	UNK	Y	2"	1/1/1996	C	2"	1/1/1996	NONRES	UNK	C	2"	UNK	REMOVE 4 LEAD WIPES & ALL LEAD	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4670	411 N CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2008-REMOVED WIPE AT CURB VALVE. INSTALLED 36" OF 3/4 COPPER STREETSIDE OF VALVE	SL repair/replace record	Y	2008	Mech excav	Field inspection only	Y	9/3/2013	Cross Connection Survey	
4672	1705 S CENTRAL AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4676	611 N JUNO AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4683	1300 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4686	252 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	L	1"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	CONNECTED TO 5/8" LEAD 9'W OF BOX. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	10/28/2013	Cross connection survey	
4703	415 E 21ST ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	RON MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4706	301 N CEDAR AVE	N	C	Y	1"	5/3/2024	P	1"	1/1/1926	SF	UNK	P	P		5/3/24: Old corp is 3' West of new corp. Removed lead and replaced w/ 1" copper. Connected to existing 1" HDPE w/ an insert in it.	SL repair/replace record	Y	5/3/2024	Visual insp during install or repair	Field Inspection Only	Y	5/3/2024	Visual Insp during install or repair	
4713	510 N JUNO AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4718	313 E 21ST ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4721	411 N ASH AVE	N	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4725	604 N JUNO AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	606: UNKNOWN.	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4731	1402 JUNO CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4752	600 N JUNO AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	602: 6'S OF SIDEWALK & 2'E OF PORCH	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4755	509 N JUNO AVE	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	511: 5'S OF FRONT STEPS.	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4758	1508 S CENTRAL AVE	UNK	C	UNK	2"	1/1/1999	C	2"	1/1/1999	NONRES	UNK	C	2"	UNK	JACKEL	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4775	707 N CENTRAL AVE	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	NONRES	UNK	C	1"	UNK	REIGEL PLUMBING.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4781	207 N ELM AVE	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1' CORP,COPPER,CURB VALVE W/BOX	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4786	705 N CENTRAL AVE	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	NONRES	UNK	C	1"	UNK	REIGEL PLMB.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4789	301 E 21ST ST	UNK	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	LAST LOT BEFORE 21ST	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4815	113 E 4TH STREET	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	NONRES	UNK	C	1"	UNK	ALSO SERVICES 111 E 4TH	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4818	1005 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	6/19/2017	Cross connection survey	
4823	1710 S MAPLE AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPE, INSULATED 1989. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 6'3" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4826	1412 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	O	UNK	C	C		DUPLEX WITH 1412A	Installation Record	N			Field Inspection Only	Y	6/23/2017	Cross Connection Survey	
4833	420 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4836	725 N PLUM AVE	N	C	UNK	1"	5/12/2022	C	1"	5/12/2022	SF	UNK	C	1"	UNK	DUPLEX WITH 725A N PLUM. 5/12/22: Installed new 1" tap w/ tapping saddle, 18" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/12/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4839	701 N CHERRY AVE	UNK	C	UNK	1"	6/21/2022	C	1"	6/21/2022	SF	UNK	C	1"	UNK	Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4842	709 E BECKER RD	N	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4845	402 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4857	310 W EDISON ST	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	1" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4860	1404 JUNO CT	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4869	1408 JUNO CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4875	709 E BLODGETT ST	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	1' - 1" CU CONNECTED TO 1" EXISTING CU IN STREET	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4880	405 N JUNO AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4883	1101 E FILLMORE ST	UNK	C	UNK	1"	7/6/2023	C	1"	7/6/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 15 of construction report)	Installation Record	Y	7/6/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4886	514 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
4889	400 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
4899	810 N CENTRAL AVE	UNK	UNK	UNK	6"	1/1/2000	DI	6"	1/1/2000	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
4904	312 E 21ST ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4907	314 E 21ST ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4910	210 E 5TH ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	8/23/2017	Cross connection survey	
4914	112 E VETERANS PKWY	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	ROYAL TOKYO RESTURANT	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4926	414 E 19TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4926	414 E 19TH ST	UNK	C	UNK	2"	10/22/2018	P	2"	10/22/2018	SF	UNK	P	2"	UNK	MU TAP - MEYERS RAN COPPER (TYPE K) FROM WM TO CS, PEX FROM CS TO HSE	Installation Record	Y	10/22/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4928	409 N CHESTNUT AVE SUITE 2	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4944	111 E 2ND ST	UNK	C	UNK	1 1/2"	1/1/2015	C	1 1/2"	1/1/2015	NONRES	UNK	C	1 1/2"	UNK	1-1/2 COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4954	116 N CENTRAL AVE	UNK	UNK	UNK	2"	1/1/1986	C	2"	1/1/1986	NONRES	UNK	C	2"	UNK	STRATFORD	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4959	312 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		LV/CB UNKNOWN. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	6/11/2014	Cross Connection Survey	
4978	210 N PURDY AVE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK	REIGEL PLUMBING	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
4982	905 E GRANT ST	UNK	UNK	UNK	2"	1/1/2001	C	2"	1/1/2001	NONRES	UNK	C	2"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5006	319 E 21ST ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5011	123 NORTHRIDGE ST	UNK	UNK	UNK	6"	1/1/2001	DI	6"	1/1/2001	O	UNK	DI	6"	UNK	LAKELAND-FIRE SERVICE INCLUDED	Installation Record	Y	1/1/2001	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
5022	201 E 6TH ST	N	C	Y	1"	5/29/2024	C	3/4"	1/1/1926	SF	UNK	C	C		5/29/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper after the cs.	SL repair/replace record	y	5/29/2024	Visual insp during install or repair	Field Inspection Only	Y	5/29/2024	Visual Insp during install or repair	
5029	104 N HINMAN AVE	UNK	C	Y	1"	6/14/2024	C	1"	6/14/2024	SF	UNK	C	1"	UNK	6/14/24: Removed lead. Replaced w/ copper. Old corp is 2' South of new corp, 4" of 3/4" copper on East side (Street side) fo curb stop - connecting to 1" copper at that point.	Installation Record	Y	6/14/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5036	814 E ARNOLD ST	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW CORP ATTACHED TO EXISTING 1" COPPER @ MAIN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5051	907 E GRANT ST	UNK	C	UNK	2"	7/13/2001	C	2"	7/13/2001	NONRES	UNK	C	2"	UNK	MEWD. 6/10/2021: New CS installed. 18" of 2" Copper from CS to the North (on Customer side) to a 2" coupler - connecte to existing 2" copper at that point.	Installation Record	Y	7/13/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5062	2414 N CENTRAL AVE	UNK	UNK	UNK	6"	1/1/2001	DI	6"	1/1/2001	O	UNK	DI	6"	UNK	LAKELAND	Installation Record	Y	1/1/2001	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
5068	504 N ASH AVE	N	C	Y	1"	6/6/2024	C	3/4"	1/1/1946	SF	UNK	C	C		6/6/24: Removed lead and replaced with copper from wm-cs. New corp is 2' South of the old corp. 12" - 1" copper from cs to existing 3/4" copper on customer side.	SL repair/replace record	Y	6/6/2024	Mech excav	Field Inspection Only	Y	6/6/2024	Visual Insp during install or repair	
5071	401 N HINMAN AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/8" copper on customer side (per customer). 5/13/2021 - Removed 3' lead gooseneck, ran 3/4" copper from main and connected to existing 3/4" copper	Installation Record	Y	5/13/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
5078	1005 E GRANT ST	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5083	1905 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	ATTACHED TO 3/4" COPPER 16'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5093	714 N JUNO AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5102	907 N CENTRAL AVE	UNK	UNK	UNK	2"	1/1/1993	C	2"	1/1/1993	NONRES	UNK	C	2"	UNK	35444	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5106	409 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1940	C	UNK	1/1/1940	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/7/2016	Cross Connection Survey	
5129	2201 W VETERANS PKWY	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	O	UNK	C	2"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5133	12 N CENTRAL AVE	UNK	C	UNK	2"	1/1/2001	C	2"	1/1/2001	NONRES	UNK	C	2"	UNK	REIGELS	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5136	603 N JUNO AVE	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5143	407 E 19TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5147	906 S CEDAR AVE	UNK	C	Y	1"	10/5/2022	C	1"	10/5/2022	SF	UNK	C	1"	UNK	10/5/22: Removed lead from wm-cs and replaced w/ 1" copper. Reused existing 3/4" corp., installed new 1" cs & box, connected to existing 3/4" copper on customers side.	Installation Record	Y	10/5/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5166	1007 E GRANT ST	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5180	710 N JUNO AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5183	724 N JUNO AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5188	604 N CEDAR AVE	N	C	Y	3/4"	10/29/2018	P	3/4"	10/29/2018	SF	UNK	P	3/4"	UNK	REMOVED LEAD FROM MAIN TO HOUSE REPLACED WITH 3/4' COPPER IN STREET AND 3/4" PVC ON PROPERTY SIDE	Installation Record	Y	10/29/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5191	707 E DOEGE ST	N	C	Y	3/4"	1/1/2012	C	3/4"	1/1/2012	SF	UNK	C	3/4"	UNK	2012-REMOVED LEAD WIPE @ MAIN & CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5195	405 N MAPLE AVE	N	C	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	1982: Retapped & lowered @ main. 6/28/2022: New 12" - 3/4" copper from main to new 1" copper to cs & box. Connected to existing 3/4" copper on customers side.	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5202	608 N CENTRAL AVE	UNK	UNK	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK	RON MEYER & SON	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5208	506 N JUNO AVE	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5211	411 E 19TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5214	417 E 19TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5217	1501 E BLODGETT ST	UNK	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS 1980. 2018 - INTALLED 1" CORP WITH TAPPING SADDLE, 3' - 1" COPPER, 1" COUPLING	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5220	209 N ASH AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FORM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5229	308 N ASH AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5239	510 N ASH AVE	N	C	UNK	UNK	1/1/2008	C	UNK	1/1/2008	SF	UNK	C	UNK	UNK	2008-INSTALLED COPPER MAIN TO CURB VALVE.	Installation Record	Y	1/1/2008	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5244	106 N MAPLE AVE	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	NONRES	UNK	C	1"	UNK	NEW TAP, COPPER, C.B./C.V.--2017 CONN. TO 3/4" COPPER 4'W OF C.B.	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5247	508 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		1974-PINCHED OFF IN TERRACE	Installation Record	N			Field Inspection Only	Y	9/7/2016	Cross Connection Survey	
5266	1009 E GRANT ST	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5270	725 N JUNO AVE	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5297	1405 JUNO CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5303	1409 JUNO CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5309	707 N JUNO AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5318	719 N JUNO AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5318	719 N JUNO AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5325	711 N JUNO AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5332	1401 JUNO CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5341	1011 E GRANT ST	UNK	C	UNK	2"	1/1/2003	C	2"	1/1/2003	NONRES	UNK	C	2"	UNK	MEWD	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5360	126 N CENTRAL AVE	UNK	DI	UNK	6"	1/1/2001	DI	6"	1/1/2001	NONRES	UNK	DI	6"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
5363	1311 E FILLMORE ST	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5369	715 N JUNO AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5375	608 N JUNO AVE	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5390	209 E 9TH ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	6/2/2017	Cross connection survey	
5407	2107 N PEACH AVE	UNK	DI	UNK	6"	1/1/2003	DI	6"	1/1/2003	O	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
5411	503 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5414	1013 E GRANT ST	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK	STUB-OUT	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5427	125 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	NONRES	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5429	718 N CEDAR AVE	N	C	Y	3/4"	1/1/2019	C	3/4"	1/1/2019	SF	UNK	C	3/4"	UNK	INSTALLED TYPE 'K' 3/4" COPPER. LEAD REPLACEMENT - MARK MEYERS - THIS SERVICE FEEDS 210 EST GRANT AS WELL	Installation Record	Y	1/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5434	1512 S CEDAR AVE	N	C	Y	3/4"	6/7/2018	C	3/4"	6/7/2018	SF	UNK	C	3/4"	UNK	ALL LEAD REMOVED FROM WM TO HOUSE WITH NEW CURB STOP & BOX	Installation Record	Y	6/7/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5457	711 N MAPLE AVE	UNK	UNK	Y	1"	11/17/2021	C	1"	11/17/2021	SF	UNK	C	1"	UNK	11/17/21: Removed lead and replaced w/ copper both sides. Replaced existing corp. w/ 6" sleeve w/ 1" C.C. Meyers replaced lead with 1" copper from cs-meter. Insulated at watermain, 12" above water service	Installation Record	Y	11/17/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5462	511 N CENTRAL AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5467	1901 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPE, INSULATED 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5471	1618 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/1992	C	1 1/2"	1/1/1992	NONRES	UNK	C	1 1/2"	UNK	PROJECT- 1998.	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5476	107 N ELM AVE	N	C	Y	3/4"	1/1/2004	C	3/4"	1/1/2004	SF	UNK	C	3/4"	UNK	2004-NEW 3/4 CORP,COPPER.EXISTING CURB VALVEW/ BOX. 5/3/23: removed 10' of lead, installed 3/4" cs & box	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5479	114 N PURDY AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5482	1701 S RODDIS AVE	N	C	UNK	3/4"	1/1/2003	C	3/4"	1/1/2003	SF	UNK	C	3/4"	UNK	*LOWERED UNDER STORM SEWER. *2003-REMOVED LEAD WIPE AT CORP., 2018 - NEW COPPER FROM SEWER TO HOUSE, NEW CURB STOP AND BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5486	805 N PEACH AVE	N	UNK	UNK	3/4"	1/1/1996	C	3/4"	1/1/1996	NONRES	UNK	C	3/4"	UNK	FROM E. GRANT ST. ON 5/10/96.	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5489	604 N HINMAN AVE	UNK	C	UNK	1"	9/19/2022	C	1"	9/19/2022	SF	UNK	C	1"	UNK	Pg. 12 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	9/19/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5493	201 N VINE AVE	N	C	UNK	3/4"	1/1/2014	C	3/4"	1/1/2014	SF	UNK	C	3/4"	UNK	REPLACED 15' OF COPPER FROM CORP NORTH TO N SIDE OF SAN SEWER-1992, REPLACED COPPER FROM SAN SEWER TO NEW CB-2014	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5498	1107 N WALNUT AVE	N	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	2004-NEW 1" CORP,COPPER,VALVE.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5502	1101 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/31/2017	Cross Connection Survey	
5505	100 N HINMAN AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5508	813 E CLEVELAND ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5514	1600 S CEDAR AVE	N	C	UNK	3/4"	9/4/2019	C	3/4"	9/4/2019	SF	UNK	C	3/4"	UNK	MEYERS - 2 - MAIN BREAK SLEEVES STARTING 12" NORTH OF CORP. (TYPE K COPPER CUSTOMER SIDE) INSTALLED 2 MAINBREAK SLEEVES NORTH 12" NORTH OF CORP DUE TO MAIN BREAK & CORP THREAD LEAK	Installation Record	Y	9/4/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5517	1609 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5522	1108 E FILLMORE ST	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5535	600 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/15/2016	Cross Connection Survey	
5541	136 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	NONRES	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5545	409 E ARNOLD ST	N	C	Y	3/4"	8/14/2017	C	3/4"	8/14/2017	SF	UNK	C	3/4"	UNK	REPLACED LEAD W/ 3/4" COPPER FROM MAIN TO INSIDE HOUSE--2017	Installation Record	Y	8/14/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
5548	908 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5554	508 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5557	809 E CLEVELAND ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5562	304 W DOEGE ST	N	C	Y	3/4"	4/6/2010	C	3/4"	4/6/2010	SF	UNK	C	3/4"	UNK	New 3/4" CU, CS & BOX, connected to LEAD on owners side. Insulated service from South side curb out to North 16' towards center of raod to get over top of storm sewer. 6/19/23: Meyers replaced lead w/ 3/4" copper cs-meter.	Installation Record	Y	4/6/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5565	510 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/20/2016	Cross Connection Survey	
5568	1211 E DEPOT ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5571	903 N WALNUT AVE	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	DIRECTIONAL BORED, NEW CURB VALVE, NO CURB BOX EXIST. 3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5574	310 N APPLE AVE	N	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Y'd Service with 312 N. Apple, New curb box installed 5-7-2020, 13' of 1" copper from curb valve to the north to a 1" CU-CU Fitting	Installation Record	Y	5/7/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5579	114 E 14TH ST	UNK	C	UNK	1"	7/30/2024	C	1"	7/30/2024	NONRES	UNK	C	1"	UNK	Earth Inc. 12.5' of 1" copper from cs to existing 1" copper. Service is insulated (goes over storm sewer)	Installation Record	Y	7/30/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5583	505 N VINE AVE	UNK	C	UNK	1"	7/26/2023	C	1"	7/26/2023	SF	UNK	C	1"	UNK	Installed 1" CU from main to new 1 CS & Box. Conn to existing 3/4" copper after the cs. See sheet 6 of the construction report	Installation Record	Y	7/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5586	513 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5589	1601 S MAPLE AVE #A	UNK	C	Y	1"	9/23/2024	C	1"	9/23/2024	SF	UNK	C	1"	UNK	6/16/23: Meyers replaced galvanized & lead with 1" copper from cs-meter w/ a new 1" cs & box. 9/23/24: MU Installed 1" copper wm - cs. Connected to existing 1" copper	Installation Record	Y	9/23/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5592	1901 S CEDAR AVE	N	UNK	UNK	1"	1/1/1963	C	1"	1/1/1963	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5596	206 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1919	C	UNK	1/1/1919	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/22/2017	Cross Connection Survey	
5601	1000 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 1.5' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5604	112 N PURDY AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5613	706 E DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1939	C	UNK	1/1/1939	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/12/2006	Cross Connection Survey	
5616	412 E 14TH ST	N	C	Y	1"	8/5/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 12' of 1" copper from cs to existing 3/4" copper. See sheet 29 of the construction report.	SL repair/replace record	Y	8/5/2024	Mech excav	Field Inspection Only	Y	8/5/2024	Visual Insp during install or repair	
5621	512 E FOREST ST	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1967	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5625	248 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5628	1209 E BLODGETT ST	N	C	Y	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - REMOVED LEAD WIPE. INSTALLED 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5631	708 N CENTRAL AVE	N	C	Y	1"	5/11/2021	C	1"	5/11/2021	SF	UNK	C	1"	UNK	5/11/2021 - Full lead removed from main to house. (worked with Meyers) 3 old taps shut off at main 5', 6.5' & 8' North of new tap. New tap is 5' South of old tap.	Installation Record	Y	5/11/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5635	400 W IVES ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5638	300 N MAPLE AVE	Y	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22/23: Dug @ water main and found 3/4" copper. Meyers replaced lead w/ 3/4" copper from cs-meter.	Installation Record	Y	6/22/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5641	405 N ASH AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5644	1401 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	1882-RETAPPED & LOWERED	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5647	611 N HINMAN AVE	UNK	C	UNK	1"	9/27/2022	C	1"	9/27/2022	SF	UNK	C	1"	UNK	Pg. 17 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs.	Installation Record	Y	9/27/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5650	1108 E DOEGE ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICES 1108A. RETAPPED & LOWERED 1982 PAVING.	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5653	1412 S MAPLE AVE	UNK	C	UNK	3/4"	5/20/2019	C	3/4"	5/20/2019	SF	UNK	C	3/4"	UNK	3/4" COPPER FROM MAIN TO HOUSE W/ REIGEL PLBG.	Installation Record	Y	5/20/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5660	311 E 20TH ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5669	204 E 8TH ST	UNK	C	Y	2"	8/30/2021	UNK	2"	8/30/2021	SF	UNK	UNK	2"	UNK	8/30/2021 Maddrell Const. 2" copper tapped @ 8th & Maple ran with San. Sewer. 2"x1" Brass Y branch 5' West of the san. MH. 1" copper from Y branch to south to CS & Box. Connected to existing 5/8" lead. Shared with 700 S. Cedar.	Installation Record	Y	8/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5669	204 E 8TH ST	UNK	C	Y	1"	8/30/2021	C	1"	8/30/2021	SF	UNK	C	1"	UNK	8/30/2021 Maddrell Const. Installed 1" copper from 'Y' to corp to new CS & Box. Connected to existing 5/8" lead on north side of sidewalk. Shared with 700 S. Cedar. Installed with san. lateral. 5/22/23: Meyers replaced lead w/ 3/4" copper from cs-meter.	Installation Record	Y	8/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5672	419 S CENTRAL AVE	UNK	C	UNK	2"	1/1/2009	C	2"	1/1/2009	NONRES	UNK	C	2"	UNK	INSTALLED 2" COPPER TO INSIDE. A-1 EXCAVATION	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5675	111 W DOEGE ST	N	L	UNK	UNK	1/1/1942	C	UNK	1/1/1942	SF	UNK	C	UNK	1/1/1942	Removeed lead wipe, street side of CV, installed new 1" CV. Fittings Street side to CV : 5/8" Lead - 3/4" Copper, 3/4" Copper - 1" Copper, 1" CV, Connect to private side 2/23/98). 1" copper on property side	SL repair/replace record	Y	1998	Mech excav	Field inspection only	Y	8/11/2016	Cross Connection Survey	
5678	1813 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	ATTACHED TO 3/4" COPPER 24'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5683	711 N PEACH AVE	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5689	409 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 6/2/97	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5694	301 N PALMETTO AVE	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	MFLD PLB *2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 4' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5697	149 N CENTRAL AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	NONRES	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5705	905 N WALNUT AVE	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	DIRECTIONAL BORED, 1" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5708	306 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	10/25/2016	Cross Connection Survey	
5714	206 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER W/ LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	11/23/2016	Cross Connection Survey	
5718	313 E BLODGETT ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000: REPLACED FROM CURB BOX IN.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5721	913 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB LOCATION VERIFIED 5/5/97	Installation Record	N			Field Inspection Only	Y	6/9/2017	Cross Connection Survey	
5729	148 N CENTRAL AVE	UNK	C	UNK	2"	1/1/2011	C	2"	1/1/2011	NONRES	UNK	C	2"	UNK	PEMBER. 2" COPPER PROP. SIDE W/ 1" COPPER INSIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5732	618 N PLUM AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5736	1713 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2003-CURB VALVE W/ BOX INSTALLED. 1989-LOWERED ACROSS ROAD	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5739	1412 S PROSPECT AVE	N	L	UNK	5/8"	1/1/1925	C	5/8"	1/1/1925	SF	UNK	C	UNK	1/1/1925	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 4'7" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	5/8/2017	Visual Insp during install or repair	
5742	222 S CENTRAL AVE	UNK	DI	UNK	4"	1/1/2009	CI-U	4"	1/1/2009	NONRES	UNK	CI-U	4"	UNK	CONNECTED TO 4" CAST 32' FROM VALVE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
5755	105 W 3RD ST	N	C	UNK	1"	1/1/2013	L	1"	1/1/2013	NONRES	UNK	L	UNK	1/1/2013	ATTACHED TO EXISTING 5/8" LEAD 2'N OF VALVE	SL repair/replace record	Y	1/1/2013	Visual insp during install or repair	Previous eval	Y	1/1/2013	Visual Insp during install or repair	
5758	206 N CEDAR AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5761	205 N VINE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1990-INSULATED & RETAPPED	Installation Record	Y	1/1/1990	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5764	1106 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1935	C	UNK	1/1/1935	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/10/2017	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
5767	720 N CHERRY AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHULTZ	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5773	900 S CEDAR AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/31/2017	Cross Connection Survey	
5778	207 N VINE AVE	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	SF	UNK	C	3/4"	UNK	REIGEL - INSULATED 4-90	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5781	249 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2015	C	1 1/2"	1/1/2015	NONRES	UNK	C	1 1/2"	UNK	COPPER OF PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5783	554 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	L	1"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	ATTACHED TO 5/8 LEAD 12.5'W OF BOX. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	9/16/2013	Cross connection survey	
5790	100 N VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	11/4/2016	Cross Connection Survey	
5793	112 E BLODGETT ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		5-98: 3/4" COPPER NEW FROM CURB BOX TO HOUSE.	Installation Record	N			Field Inspection Only	Y	11/4/2016	Cross Connection Survey	
5796	906 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5804	719 N CEDAR AVE	UNK	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22: Dug @ wm & found 3' lead gooseneck. Removed lead & replaced w/ 3/4" copper. Reused existing corp & connected to existing 3/4" copper.	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5813	500 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	9/29/2016	Cross connection survey	
5816	1301 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5823	1413 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		COPPER INSIDE	Installation Record	N			Field Inspection Only	Y	10/13/2014	Cross Connection Survey	
5829	2001 S CEDAR AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5832	300 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN - DUPLEX WITH 300A	Installation Record	N			Field Inspection Only	Y	11/22/2016	Cross Connection Survey	
5835	612 N CEDAR AVE	UNK	C	Y	1"	6/1/2022	C	1"	6/1/2022	SF	UNK	C	1"	UNK	6/22: Dug & found full lead from wm - sidewalk. Replaced w/ 1" copper, installed new 1" corp. and abandoned existing corp. (new corp. is 3' South) Installed new 1" cs & box. Connected to existing 3/4" copper 12" West of the cs.	Installation Record	Y	6/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5849	412 E GRANT ST	N	C	UNK	1"	5/5/2022	C	1"	5/5/2022	SF	UNK	C	1"	UNK	5/5/22: Installed new 1" tap w/ tapping saddle, 12" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/5/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5857	200 E 8TH ST	N	C	Y	UNK	1/1/2016	C	UNK	1/1/2016	SF	UNK	C	UNK	UNK	WIPE REPLACE OUR SIDE, NEW CURB STOP & 1/2" X 3/4" SWEAT FITTING WITH 1/2" COMPRESSION FITTING ON INSIDE BY MEYERS 9-25-86. 2016 - REMOVED LEAD FROM MAIN TO EAST LINE OF MAPLE 2016	Installation Record	Y	1/1/2016	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5862	1511 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5865	308 N MAPLE AVE	N	C	Y	1"	11/29/2021	C	1"	11/29/2021	SF	UNK	C	1"	UNK	11/29/21: MU dug service @ the cs due to a leak. Found lead @ the cs on utility side, replaced w/ 1" copper from main to cs. Installed new 1" tap 3' South of existing tap. installed new 1" cs & box & connected to existing 3/4" copper 6" West of the new cs	Installation Record	Y	11/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5875	108 N PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5878	703 N PALMETTO AVE	UNK	C	UNK	1"	7/7/2023	C	1"	7/7/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 16 of construction report)	Installation Record	Y	7/7/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5881	911 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/5/2017	Cross Connection Survey	
5891	208 E 3RD ST	N	C	Y	3/4"	7/20/2018	C	3/4"	7/20/2018	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO HOUSE REPLACED WITH 3/4" COPPER, MEYER DID PRIVATE SIDE AND INSTALLED NEW CURB STOP AND BOX	Installation Record	Y	7/20/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5894	611 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/3/2016	Cross Connection Survey	
5900	601 N PALMETTO AVE	UNK	C	UNK	1"	6/22/2023	C	1"	6/22/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 8 of construction report)	Installation Record	Y	6/22/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5903	201 E 9TH ST	N	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5906	1703 S CENTRAL AVE	N	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	SERVICE IS TAPPED OFF 17TH	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5909	109 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	RE-TAPPED & INSULATED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5912	419 E FOREST ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
5916	511 S CENTRAL AVE	N	C	UNK	1"	1/1/2009	L	1"	1/1/2009	NONRES	UNK	L	UNK	1/1/2009	ATTACHED TO 5/8 LEAD 4' E OF BOX. A-1 EXCAVATING	SL repair/replace record	Y	1/1/2009	Visual insp during install or repair	Previous eval	Y	2009	Cross connection survey	
5920	1004 E BLODGETT ST	UNK	C	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYERS. 2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 2' - 1" COPPER WITH 1" COUPLING	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5923	406 S CEDAR AVE	N	C	UNK	3/4"	7/1/2021	C	3/4"	7/1/2021	SF	UNK	C	3/4"	UNK	7/1/2021 - New 3/4" Copper installed from WM-CS and new CS & Box installed. Verified Copper on customers side of CS	Installation Record	Y	7/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5926	412 S CEDAR AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	RETAPPED 6/21/1979 3/4 COPPER	Installation Record	Y	6/21/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5929	410 E 14TH ST	N	C	Y	1"	8/2/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 11.5' of 1" copper from cs to existing 3/4" copper. See sheet 28 of the construction report.	SL repair/replace record	Y	8/2/2024	Mech excav	Field Inspection Only	Y	8/2/2024	Visual Insp during install or repair	
5932	108 E 4TH ST	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	NONRES	UNK	C	1"	UNK	CONNECTED TO 1" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5940	206 S CEDAR AVE	N	C	Y	1"	8/24/2022	C	1"	8/24/2022	SF	UNK	C	1"	UNK	8/24/22: Removed lead and installed new 1" copper, used existing corp. New 1" curb valve & box. 3/4" copper on customers side.	Installation Record	Y	8/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5949	206 E 14TH ST	N	C	UNK	1"	7/30/2024	C	3/4"	7/30/2024	SF	UNK	C	C		Earth Inc. 12.5' of 1" copper from cs to existing 3/4" copper.	SL repair/replace record	Y	7/30/2024	Mech excav	Field Inspection Only	Y	7/30/2024	Visual Insp during install or repair	
5952	911 N WALNUT AVE #A	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	DIRECTIONAL BORED, 3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5955	107 W IVES ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	Verified service on property side (4/12/2021 - JN)	Installation Record	Y	4/12/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5961	502 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/20/2016	Cross Connection Survey	
5964	725 N CHERRY AVE	N	C	UNK	1"	5/3/2022	C	1"	5/3/2022	SF	UNK	C	1"	UNK	5/3/22: Installed new 1" tap w/ tapping saddle, 12" - 1" copper, connected to existing 3/4" copper.	Installation Record	Y	5/3/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
5967	1503 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	NO BOX 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5970	1908 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPE, LOWERED IN STREET 1989. 9/19/15: retapped on DIP from main break	Installation Record	Y	9/19/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
5994	705 N CEDAR AVE	N	C	UNK	UNK	1/1/2011	C	UNK	1/1/2011	SF	UNK	C	UNK	UNK	2011-INSTALLED CURB STOP/BOX AND INSTALLED 12' 3/4" COPPER FROM CURB STOP TOWARDS MAIN.COPPER COMPRESSION 12' FROM MAIN.	Installation Record	Y	1/1/2011	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6001	1015 E BLODGETT ST	UNK	C	UNK	1"	UNK	P	1"	UNK	SF	UNK	P	1"	UNK	2016-INSTALLED NEW CURB VALVE/BOX & INSTALLED PLASTIC ON PROP. SIDE. *2018 - 1" CORP AND SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING. INSULATED AT MAIN	Installation Record	Y	1/1/2016	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6004	202 E 3RD ST	N	C	Y	1"	9/7/2022	C	1"	9/7/2022	SF	UNK	C	1"	UNK	9/7/22: Removed lead and installed new 1" copper, used existing corp. New 1" curb valve and box. Hooked to Lead on customers side. 11/14/22: Customer replaced lead w/ copper (Gaffney Permit #20221898)	Installation Record	Y	9/7/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6007	108 E 12TH ST	N	C	UNK	1/2"	1/1/2018	C	1/2"	1/1/2018	SF	UNK	C	1/2"	UNK	2018 - FOUND 1/2" COPPER NORTH OF CURB STOP, CONNECTED AND RAN 3/4" TO HOUSE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6013	909 N WALNUT AVE	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	DIRECTIONAL BORED, 1" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6016	115 W DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	7/29/2016	Cross Connection Survey	
6022	608 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22: Dug @ wm & found 3' lead gooseneck. Removed lead & replaced w/ 3/4" copper. Reused existing corp.	Installation Record	Y	6/22/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6028	307 N VINE AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	RETAPPED & INSULATED 4/90. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 5' DEEP; 1/2" Copper Inside	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6032	200 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6035	113 N VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	7/11/2017	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
6038	1013 E BLODGETT ST	UNK	C	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD *2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 5' - 1" COPPER WITH 1" COUPLING	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6041	1005 E CLEVELAND ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS. 3/4" copper on property side	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6041	1005 E CLEVELAND ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6044	206 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	6/12/2017	Cross Connection Survey	
6052	171 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2016	C	1 1/2"	1/1/2016	NONRES	UNK	C	1 1/2"	UNK	ROMAC STAINLESS STEEL SERVICE SADDLE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6058	1701 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1924	C	UNK	1/1/1924	SF	UNK	C	C		REMOVED WIPES AT MAIN & BOX 1989	Installation Record	N			Field Inspection Only	Y	5/11/2017	Cross Connection Survey	
6061	1620 S CEDAR AVE	N	C	Y	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	9-20-2020: MU Replaced lead main-cs w/ 3/4" copper. Jackle Plbg. Replaced w/ 1" copper, 6' North of cs-meter. 7/25/22: Earth Inc. Intalled 1" corp, 4.5' - 1" copper conn. to exist. 3/4" copper @ main. (pg. 29 const. report)	Installation Record	Y	7/25/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6074	900 E CLEVELAND ST	UNK	UNK	UNK	UNK	1/1/1980	C	UNK	1/1/1980	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1980	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6080	508 N MAPLE AVE	N	C	UNK	3/4"	10/16/2018	C	3/4"	10/16/2018	SF	UNK	C	3/4"	UNK	REIGELS REPLACED 3/4" COPPER PORPERTY SIDE. 3/4" COPPER ON STREET SIDE DONE TOO	Installation Record	Y	10/16/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6086	717 N PLUM AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SPENCER/DUPLEX WITH 719 N PLUM	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6089	302 N CEDAR AVE	N	C	UNK	3/4"	1/1/2008	C	3/4"	1/1/2008	SF	UNK	C	3/4"	UNK	2008-INSTALLED NEW COPPER MAIN TO VALVE, NEW CURB VALVE & BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6092	721 N CEDAR AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	LOWERED & INSULATED SERVICE UP TO MIDDLE OF ROAD 5/87. 6/22: Dug & verified 3/4" copper @ wm. Installed new 3/4" cs & box.	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6097	213 N CEDAR AVE	N	C	Y	1"	5/3/2024	C	3/4"	1/1/1926	SF	UNK	C	C		5/3/24: Removed lead from wm-cs. Replaced w/ 1" copper, old corp is 3' East of new, installed 1" cs & box, connected to existing 3/4" copper 12" after cs.	SL repair/replace record	Y	5/3/2024	Visual insp during install or repair	Field Inspection Only	Y	5/3/2024	Visual Insp during install or repair	
6100	607 N MAPLE AVE	Y	C	Y	3/4"	6/1/2023	C	3/4"	6/1/2023	SF	UNK	C	3/4"	UNK	6/1/23: Removed lead from wm-cs, replaced w/ 3/4" copper and installed a 3/4" cs & box. Connected to existing 3/4" copper after cs	Installation Record	Y	6/1/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6105	306 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	6/20/2014	Cross Connection Survey	
6116	700 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" COPPER & LOCKING VAVLE. 6/22: Dug @ wm & found 3' lead gooseneck. Replaced lead w/ 3/4" copper. Connected to existing 3/4" copper. Reused existing corp.	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6123	406 N VINE AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SER BOX & VALVE IN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6126	400 E DOEGE ST #A	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	DUPLEX WITH 400 E. DOEGE. 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX.	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6129	210 N CEDAR AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6132	204 E BLODGETT ST #A	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/19/2016	Cross Connection Survey	
6135	208 N PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	2/13/2020	Cross Connection Survey	
6138	1111 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" CU ON CUSTOMERS SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6141	203 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		DUPLEX WITH 203A	Installation Record	N			Field Inspection Only	Y	5/19/2017	Cross Connection Survey	
6146	313 N VINE AVE	N	C	UNK	3/4"	4/1/1990	C	3/4"	1/1/1947	SF	UNK	C	C		RETAPPED OLD CORP IS 1'6"N - (3/4" Copper). 5/16/2024: Dug and verified 3/4" copper at main and cs.	Installation Record	Y	5/16/2024	Mech excav	Field Inspection Only	Y	5/16/2024	Mech excav	
6149	1615 S MAPLE AVE	UNK	C	UNK	1"	9/23/2024	C	1"	9/23/2024	SF	UNK	C	1"	UNK	9/23/24: Installed 1" corp w/ saddle, 1" copper, 1" cs & box. Connected to existing 3/4" copper.	Installation Record	Y	9/23/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6156	410 N VINE AVE	N	C	Y	1"	5/22/2024	C	3/4"	1/1/1929	SF	UNK	C	C		5/22/24: Removed lead and replaced w/ copper from cs-wm. Connected to existing 3/4" copper after the cs. Old corp. is 2' South of new corp.	Installed after lead ban	Y	5/22/2024	Mech excav	Field Inspection Only	Y	5/22/2024	Visual Insp during install or repair	
6160	900 N CENTRAL AVE	UNK	UNK	UNK	2"	1/1/1986	C	2"	1/1/1986	NONRES	UNK	C	2"	UNK	REIGEL	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6163	604 N CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6175	1009 E CLEVELAND ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6180	613 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1933	C	UNK	1/1/1933	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/23/2016	Cross Connection Survey	
6187	160 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	C	1 1/2"	1/1/2009	NONRES	UNK	C	1 1/2"	UNK	INSTALLED 1-1/2" COPPER TO INSIDE.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6191	404 E BLODGETT ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/1/24: 3/4" copper from wm - cs.	Installation Record	Y	5/1/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6195	305 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/3/2016	Cross Connection Survey	
6201	1011 E CLEVELAND ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6205	113 E 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	6/12/2017	Cross Connection Survey	
6209	1707 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1933	C	3/4"	1/1/1933	O	UNK	UNK	UNK		Y CONNECTED WITH 1707. 3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	8/19/2017	Visual Insp during install or repair	
6212	1700 S MAPLE AVE	UNK	C	UNK	1"	7/26/2022	C	1"	7/26/2022	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	7/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6215	1902 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		FLAIR COPPER, INSULATED 1989	Installation Record	N			Field Inspection Only	Y	5/2/2017	Cross Connection Survey	
6225	312 W DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1940	C	UNK	1/1/1940	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	9/7/2016	Cross Connection Survey	
6229	539 S CENTRAL AVE	UNK	C	UNK	2"	1/1/2009	C	2"	1/1/2009	NONRES	UNK	C	2"	UNK	ATTACHED TO EXISTING 2" COPPER. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6233	851 S CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		ONE METERED	Installation Record	N			Field Inspection Only	Y	6/28/2013	Cross Connection Survey	
6236	505 N PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6239	510 N VINE AVE	UNK	C	UNK	1"	7/26/2023	C	1"	7/26/2023	SF	UNK	C	1"	UNK	Installed new 1" copper from main to new CS & Box. There is 3/4" copper 8' past cs with 1" x 3/4" fitting. See sheet 6 of the construction report	Installation Record	Y	7/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6242	409 N VINE AVE	N	C	UNK	3/4"	4/1/1990	C	UNK	1/1/1929	SF	UNK	C	C		CORP IS 47' W. & 9' S. OF NWCH - RETAPPED 4/90	Installation Record	Y	5/22/2024	Mech excav	Field Inspection Only	Y	5/22/2024	Visual Insp during install or repair	
6245	403 N CEDAR AVE	UNK	C	UNK	1"	4/29/2024	C	1"	4/29/2024	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	4/29/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6248	513 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/27/22: Removed 3' lead gooseneck @ the wm. Replaced w/ 3/4" copper. Connected to existing 3/4" copper 3' from wm. Connected to exsiting corp.	Installation Record	Y	6/27/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6251	809 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6254	504 E 21ST ST	UNK	UNK	UNK	2"	1/1/1986	C	2"	1/1/1986	NONRES	UNK	C	2"	UNK	STRATFORD/SERVICES. ONLY 5'3" DEEP/ OWNER WILL BE RESPONSIBLE	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6260	411 N WALNUT AVE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	NEW 1" CORP, NEW COPPER FROM MAIN TO CURB VALVE, NEW CURB VALVE AND BOX	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6266	109 W HARRISON ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2000: CURB BOX CUT-IN.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6269	601 N CEDAR AVE	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 17 of the construction report	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6273	702 N CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22: Dug @ wm & found 3' lead gooseneck. Removed lead and replaced w/ 3/4" copper. Reused existing corp.	Installation Record	Y	6/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6279	503 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1935	C	UNK	1/1/1935	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/8/2016	Cross Connection Survey	
6282	112 E 8TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		OFF MAPLE	Installation Record	N			Field Inspection Only	Y	6/13/2017	Cross Connection Survey	
6285	301 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/7/2013	Cross Connection Survey	
6288	205 N MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/17/2017	Cross Connection Survey	
6297	108 E 8TH ST	UNK	C	UNK	1"	8/25/2021	C	1"	8/25/2021	SF	UNK	C	1"	UNK	8/25/22: Maddrell Exc., 1" corp. on main @ 8th & Maple, installed 1" copper to West w/ san. swr. (6" above sewer). Installed 1" cs & box 5' East of san. wye & 2' North of the sidewalk. 10/11/22: Gaffney ran 3/4" copper from cs to the house w/ new san. lat	Installation Record	Y	8/25/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6300	614 N CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		1/2" COPPER LOCKING VALVE. 1/2" COPPER INSIDE	Installation Record	N			Field Inspection Only	Y	9/8/2016	Cross Connection Survey	
6339	904 E CLEVELAND ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
6342	407 N MAPLE AVE	N	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	6/2/8/22: 12" of 3/4" copper from main then 1" copper to cs & box. Connected to existing 3/4" copper on customers side.	Installation Record	Y	6/2/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6350	301 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		ALSO FEEDS 303 N CENTRAL. 10/14/08 - REMOVED LEAD FROM MAIN 12' TO EAST. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	9/10/2013	Cross Connection Survey	
6353	203 W DOEGE ST	UNK	UNK-LG	UNK	UNK	1/1/1942	C	UNK	1/1/1942	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/15/2014	Cross Connection Survey	
6358	107 N PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MAIN SCHALLOW/INSULATED	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6362	502 S MAPLE AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6365	605 N CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1939	C	UNK	1/1/1939	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	8/17/2016	Cross Connection Survey	
6371	1107 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6383	408 E BLODGETT ST	N	C	Y	1"	5/9/2024	C	1/2"	1/1/1926	SF	UNK	C	C		5/9/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper & 1" cs & box. Conn to existing 1/2" copper after cs.	SL repair/replace record	Y	5/9/2024	Visual insp during install or repair	Field Inspection Only	Y	5/9/2024	Visual Insp during install or repair	
6386	504 N VINE AVE	UNK	C	UNK	1"	7/25/2023	C	1"	7/25/2023	SF	UNK	C	1"	UNK	Replaced existing 3/4" copper with 1" copper from main to existing 3/4" CS & Box. See sheet 5 of the construction report.	Installation Record	Y	7/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6389	312 N VINE AVE	N	C	Y	1"	7/19/2022	C	1"	7/19/2022	SF	UNK	C	1"	UNK	7/19/22: Removed lead and replaced w/ 12"x6"x2" C.C. sleeve, 1" corp, 1" copper, 1" cs & box. Gaffney installed 3/4" copper on customers side.	Installation Record	Y	7/19/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6394	111 N PURDY AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	FEEDS 113 N PURDY. 9/28/23: City sewer kinked the service, so replaced 5' of 3/4" copper - the West 3/4" fitting is @ centerline. The East 3/4" fitting is 5' East of centerline. Only saw 3/4" copper in hole	Installation Record	Y	9/28/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6397	1107 E BLODGETT ST	N	C	Y	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - Installed 1" corp and tapping saddle, 18' - 1" copper, 1" cs & box and connected to lead @ the back of the sidewalk on customers side. 11/28/22: Meyers Replaced lead w/ 1" copper cs-meter.	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6404	715 E BLODGETT ST	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" CU ON CUSTOMERS SIDE	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6411	403 S MAPLE AVE	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	NONRES	UNK	C	1"	UNK	CONNECTED TO 1/2" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6414	1905 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED WIPE, LOWERED IN STREET 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6420	253 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2015	C	1 1/2"	1/1/2015	NONRES	UNK	C	1 1/2"	UNK	COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6423	1004 N WALNUT AVE	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2004-INSTALLED 3/4" CORP	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6427	411 N CEDAR AVE	N	C	UNK	3/4"	1/1/2004	C	3/4"	1/1/2004	SF	UNK	C	3/4"	UNK	2004- NEW TAP 3/4 COPPER TO CORP TO NEW CURB VALVE	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6430	811 N MAPLE AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7'3" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6438	1702 S MAPLE AVE	Y	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	INSULATED 1989	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6441	912 N CENTRAL AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	NO CURB BOX. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6449	511 N PALMETTO AVE	UNK	C	UNK	1"	6/22/2023	C	1"	6/22/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 8 of construction report)	Installation Record	Y	6/22/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6458	1201 N WALNUT AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-NEW 1" CORP, CONNECTED TO EXISTING 3/4 COPPER	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6461	204 N CEDAR AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6465	402 E 14TH ST	N	C	Y	1"	8/5/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 12' of 1" copper from cs to existing 3/4" copper. See sheet 29 of the construction report.	SL repair/replace record	Y	8/5/2024	Mech excav	Field Inspection Only	Y	8/5/2024	Visual Insp during install or repair	
6469	1105 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6475	404 N APPLE AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6481	413 N CEDAR AVE	N	C	UNK	3/4"	1/1/2004	C	3/4"	1/1/2004	SF	UNK	C	3/4"	UNK	2004- NEW 3/4 COPPER FROM CORP TO NEW CURB VALVE	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6484	404 E 21ST ST	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6487	211 N CEDAR AVE	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	3/4" COPPER PROP, SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6499	608 N WALNUT AVE	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	1" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6502	604 N WALNUT AVE	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	1" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6509	303 N PEACH AVE	N	C	Y	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	AUG 2018 - REMOVED LEAD, INSTALLED COPPER FROM MAIN TO HOUSE W/ MEYER. NEW CURB STOP AND BOX	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6514	311 N VINE AVE	N	C	UNK	3/4"	4/1/1990	C	UNK	1/1/1947	SF	UNK	C	C		1990-RETAPPED @ 49'W & 17'N OF SW COR. OF HSE. 5/16/2024: Dug and verified 3/4" copper at main and cs. Installed new cs.	Installation Record	Y	5/16/2024	Mech excav	Field Inspection Only	Y	5/16/2024	Mech excav	
6517	209 N HINMAN AVE	N	C	Y	1"	6/12/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/12/24: Removed lead from wm-cs. Replaced w/ 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper 12" East of cs. New corp is 4' North of old.	SL repair/replace record	Y	6/12/2024	Visual insp during install or repair	Field Inspection Only	Y	6/12/2024	Visual Insp during install or repair	
6521	208 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	8/17/2017	Cross Connection Survey	
6525	117 E 17TH ST	N	UNK	UNK	3/4"	1/1/1990	C	3/4"	1/1/1990	SF	UNK	C	3/4"	UNK	CURB BOX CUT IN DURING PAVING PROJECT	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6532	111 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1/2" copper on customer side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6535	205 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	6/12/2017	Cross Connection Survey	
6538	1507 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		BOX COPPER INSIDE 1989	Installation Record	N			Field Inspection Only	Y	5/12/2017	Cross Connection Survey	
6552	606 N MAPLE AVE	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CAL'S PLMB. NEW CURB STOP/BOX, NEW COPPER FROM MAIN TO HOUSE.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6555	802 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		THIS FEEDS JUST THE FRONT APARTMENT	Installation Record	N			Field Inspection Only	Y	9/19/2016	Cross Connection Survey	
6564	404 N CENTRAL AVE	UNK	UNK	UNK	1 1/2"	1/1/1986	C	1 1/2"	1/1/1986	NONRES	UNK	C	1 1/2"	UNK	& 408 N CENTRAL-MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6584	1011 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6594	710 E DOEGE ST	N	C	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6597	501 N CENTRAL AVE #A	N	C	Y	3/4"	7/10/2019	C	3/4"	7/10/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD ON OUR SIDE AND INSTALLED COPPER (REMOVED 'Y' CONNECTION AS WELL BY CURB STOP)	Installation Record	Y	7/10/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6600	213 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		213 N CENTRAL FED BY 2 LINES. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	6/25/2013	Cross Connection Survey	
6603	1301 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 7' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6612	916 S MAPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/1/2017	Cross Connection Survey	
6615	102 N HINMAN AVE	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	SF	UNK	C	3/4"	UNK	2001: INSTALLED NEW 3/4 COPPER FROM MAIN TO CURB-BOX.	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6624	313 W DOEGE ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6630	410 N CHERRY AVE	N	C	UNK	3/4"	1/1/2015	P	3/4"	1/1/2015	SF	UNK	P	3/4"	UNK	2009- PLASTIC ON PROPERTY SIDE. 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6634	108 N PURDY AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1978	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6655	400 E 14TH ST	N	C	Y	1"	8/2/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 14.5' of 1" copper from cs to existing 3/4" copper. See sheet 28 of the construction report.	SL repair/replace record	Y	8/2/2024	Mech excav	Field Inspection Only	Y	8/2/2024	Visual Insp during install or repair	
6665	206 N VINE AVE	N	C	UNK	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	C		1990-LEAD WIPE REMOVED CORP REPLACED & INSULATED 6' @ MAIN. 5/14/24: Dug and verified 3/4" copper from wm-cs.	Installation Record	Y	5/14/2024	Mech excav	Field Inspection Only	Y	5/14/2024	Mech excav	
6668	440 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER 10'W OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6684	313 N JUNO AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6691	413 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 6/2/97. 3/4" copper on property side	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6694	500 E BLODGETT ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	INSULATED 4/90, MEYERS	Installation Record	Y	4/1/1990	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
6700	408 E 21ST ST	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6719	305 N CHERRY AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6735	1900 S CHERRY AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6743	1010 E CLEVELAND ST	UNK	UNK	UNK	3/4"	1/1/1987	C	3/4"	1/1/1987	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6746	309 N CHERRY AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6751	510 E 21ST ST	UNK	UNK	UNK	UNK	1/1/1987	C	UNK	1/1/1987	NONRES	UNK	C	UNK	UNK	STRATFORD	Installation Record	Y	1/1/1987	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6755	306 N CHERRY AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6758	615 N PEACH AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK	TRIERWILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6761	204 W DOEGE ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6815	808 E DOEGE ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6824	408 N CHESTNUT AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER-TAPPED OFF DOEGE	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6827	412 E 21ST ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6833	504 E BLODGETT ST	UNK	UNK	UNK	1 1/4"	UNK	C	1 1/4"	UNK	SF	UNK	C	1 1/4"	UNK	LINE COMES FROM VINE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6838	809 N CENTRAL AVE	UNK	UNK	UNK	1 1/4"	1/1/1982	C	1 1/4"	1/1/1982	NONRES	UNK	C	1 1/4"	UNK	REIGEL	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6838	809 N CENTRAL AVE	UNK	UNK	UNK	2"	1/1/1988	C	2"	1/1/1988	NONRES	UNK	C	2"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6844	412 W IVES ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6850	513 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6860	205 S MAPLE AVE	N	C	UNK	1"	1/1/2015	P	1"	1/1/2015	SF	UNK	P	1"	UNK	CONNECTED TO 1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6870	1305 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6874	1403 S MAPLE AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	NONRES	UNK	C	1"	UNK	1" Copper on property side	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6877	207 S MAPLE AVE	N	C	Y	1"	1/1/2015	C	1"	1/1/2015	SF	UNK	C	1"	UNK	2019-PROP. SIDE LEAD REMOVED AND REPLACED WITH 1" COPPER, MEYER	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6885	1104 E CLEVELAND ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6888	600 E 21ST ST	UNK	UNK	UNK	1 1/2"	1/1/1989	C	1 1/2"	1/1/1989	NONRES	UNK	C	1 1/2"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6899	207 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
6903	314 W IVES ST #A	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	NONRES	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
6936	302 E CLEVELAND ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
6988	1617 S MAPLE AVE	N	C	UNK	1"	9/23/2024	C	3/4"	1/1/1922	SF	UNK	C	C		9/23/24: Installed 1" corp w/ saddle, 1" copper, 1" cs & box. Connected to existing 3/4"	SL repair/replace record	Y	9/23/2024	Visual insp during install or repair	Field Inspection Only	Y	6/23/2024	Visual Insp during install or repair	
6991	602 E 21ST ST	UNK	UNK	UNK	1 1/2"	1/1/1989	C	1 1/2"	1/1/1989	NONRES	UNK	C	1 1/2"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7018	610 E 21ST ST	UNK	UNK	UNK	1 1/2"	1/1/1989	C	1 1/2"	1/1/1989	NONRES	UNK	C	1 1/2"	UNK	STRATFORD	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7072	308 W IVES ST #I	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	NONRES	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7100	1410 E BLODGETT ST	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS 1990. 2018 - INSTALLED 2'-1" COPPER FROM MAIN TO EXISTING 1" COPPER. NEW CORP INSTALLED WITH TAPPING SLEEVE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7103	309 E FRANKLIN ST	UNK	C	UNK	1"	6/9/2022	UNK	1"	6/9/2022	SF	UNK	UNK	1"	UNK	Pg. 12 of construction report: 6/9/22: Installed 1" corp, 1" copper and 1" cs & box. Connected to existing 1" copper after cs.	Installation Record	Y	6/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7106	310 E CLEVELAND ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS, DUPLEX WITH 312 E CLEVELAND	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7110	1313 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7128	308 E 17TH ST	UNK	C	UNK	1"	6/22/2022	C	1"	6/22/2022	SF	UNK	C	1"	UNK	Pg 18 of construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 1" copper 12' after cs.	Installation Record	Y	6/22/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7135	104 W BLODGETT ST	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	NONRES	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	6/3/2014	Cross Connection Survey	
7142	1000 S MAPLE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7148	1713 S RODDIS AVE	N	C	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	LOWERED UNDER STORM SEWER.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7151	105 S CEDAR AVE	N	C	Y	1"	8/18/2022	C	1"	8/18/2022	SF	UNK	C	1"	UNK	8/18/22: 8" main break sleeve w/ 1" C.C. for new tap. 1" copper new C.B.V. All lead removed. Connected to existing 3/4" copper on customers side.	Installation Record	Y	8/18/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7154	109 S CEDAR AVE	N	C	Y	1"	8/11/2022	C	1"	8/11/2022	SF	UNK	C	1"	UNK	8/11/22: New 1" copper. All lead removed. 1/2" copper going to house.	Installation Record	Y	8/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7157	111 S CEDAR AVE	N	C	Y	1"	8/11/2022	C	1"	8/11/2022	SF	UNK	C	1"	UNK	8/11/22: All lead removed. Installed new 1" tap, 1" copper, 1" cs & box in driveway. Connected to existing 3/4" copper on customers side	Installation Record	Y	8/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7160	201 S CEDAR AVE	N	C	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	2003-REMOVED 4-1" YOKE. RETAPPED TO 2". 2" copper on property side	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7163	303 E 3RD ST	N	C	Y	1"	8/26/2022	C	1"	8/26/2022	SF	UNK	C	1"	UNK	8/26/22: Removed lead and installed new 1" copper, used existing 3/4" corp. New 1" curb vavle and box. Hooked to 1/2" copper on house side.	Installation Record	Y	8/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7166	301 S CEDAR AVE	N	C	UNK	1"	9/6/2022	C	1"	9/6/2022	SF	UNK	C	1"	UNK	9/6/22: 1" copper from main to curb, used old corp, new 1" curb valve & box. Hooked up to 1/2" copper on owners side, very thin copper, will leak.	Installation Record	Y	9/6/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7169	303 S CEDAR AVE	UNK	C	UNK	1"	9/1/2022	C	1"	9/1/2022	SF	UNK	C	1"	UNK	9/22: New 1" copper used existing corp. New 1" curb valve & box. Hooked up o 1/2" copper on customers side.	Installation Record	Y	9/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7172	305 S CEDAR AVE	N	C	UNK	1"	9/1/2022	C	1"	9/1/2022	SF	UNK	C	1"	UNK	9/22: New 1" copper, used existing corp. w/ saddle. New 1" curb valve & 1" box. 3/4" copper on customers side.	Installation Record	Y	9/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7178	307 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	copper on property side per customer 9/1/22: Removed lead wipe @ main. 3/4" copper. Service is 100% lead free	Installation Record	Y	9/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7181	307 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/3/2017	Cross Connection Survey	
7184	309 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	6/8/2017	Cross Connection Survey	
7187	304 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	9/9/2014	Cross Connection Survey	
7190	405 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2022: Removed lead wipes, serive is 100% copper	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7196	300 E 5TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2005-REMOVED LEADWIPE @ MAIN. 2022: Lead removed from service - 3/4" copper	Installation Record	Y	1/1/2005	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7199	503 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2022: Removed lead wipe, hooked to 3/4" copper	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7202	507 S CEDAR AVE	N	C	UNK	1"	9/20/2022	C	1"	9/20/2022	SF	UNK	C	1"	UNK	2022: Replaced 1" copper from main to curb valve. Used existing corp & existing curb valve and box. Connected to existing 3/4" copper.	Installation Record	Y	9/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7208	701 S CEDAR AVE	UNK	C	Y	1"	9/9/2021	C	1"	9/9/2021	SF	UNK	C	1"	UNK	09/09/2021 Maddrell Const. Installed 1" corp 2' North of abandoned corp. New CS @ Box connected to existing 3/4" copper .5' after CS. Removed existing lead service.	Installation Record	Y	9/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7211	705 S CEDAR AVE	UNK	C	Y	1"	9/8/2021	C	1"	9/8/2021	SF	UNK	C	1"	UNK	9/8/2021 Maddrell Const. Installed 1" corp 2' North of the abandoned corp. New CS & Box connected to existing 3/4" copper .5' after CS. Removed existing 3/4" copper service with lead gooseneck at the watermain.	Installation Record	Y	9/8/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7214	707 S CEDAR AVE	UNK	C	Y	1"	9/8/2021	C	1"	9/8/2021	SF	UNK	C	1"	UNK	9/8/2021 Maddrell Const. Installed 1" corp 2' North of abandoned corp. New 1" CS & Box connected to existing 1/2" copper. Used 1"x3/4" , then 3/4"x1/2" compressoon fittings to connect to existing. Removed existing lead service.	Installation Record	Y	9/8/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7217	709 S CEDAR AVE	UNK	C	Y	1"	9/7/2021	C	1"	9/7/2021	SF	UNK	C	1"	UNK	9/7/2021 Maddrell Const. Installed 1" corp 2' North of the abandoned corp. New CS & Box is .5' West of gas main. Connected to existing 3/4" copper .5' after CS & Box. Removed existing lead service.	Installation Record	Y	9/7/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
7220	305 E 8TH ST	N	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	10/26/1978 Reigel Plbg. 9/7/2021 Maddrell Const. Excavated & verified 1" copper, 16'8" North from the center of San. MH @ 8th & Cedar. It's 9' deep from the pavement surface.	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7223	801 S CEDAR AVE	N	C	Y	1"	10/5/2022	C	1"	10/5/2022	SF	UNK	C	1"	UNK	10/5/2022: New 1" copper from mian to curb valve, new 1" curb valve & box. Used existing corp. J&R bored line in road. Meyers replaced lead w/ 1" copper.	Installation Record	Y	10/5/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7226	807 S CEDAR AVE	N	C	UNK	1"	9/26/2022	C	1"	9/26/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to cs, used existin corp., new 1" cs & box. 3/4" copper on house side	Installation Record	Y	9/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7229	809 S CEDAR AVE	N	C	UNK	1"	9/27/2022	C	1"	9/27/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to cs, used existing corp., new 1" cs & box. 3/4" copper on house side	Installation Record	Y	9/27/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7232	303 E 9TH ST	N	C	Y	3/4"	9/14/2020	C	3/4"	9/14/2020	SF	UNK	C	3/4"	UNK	9/14/2020 - Removed lead and replaced w/ 3/4" copper from corp to c.s. Pulled across street with 811 S Cedar water line at same time. Installed new C.S. & Box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	9/14/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7235	306 E 9TH ST	N	C	Y	1"	11/9/2021	C	1"	11/9/2021	SF	UNK	C	1"	UNK	11/9/21: MU abandoned exist. tap, re-tapped 18" West w/ 1" corp. Replaced lead goosneck (5') & 3/4" copper w/ 1" copper from wm-cs. MU installed 1" CS & box & conn. to 3/4" copper w/ 1'x3/4" comp. 12" South of CS. Tap is 2' East of tap for 305 E. 9th.	Installation Record	Y	11/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7238	300 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	6/9/2017	Cross Connection Survey	
7241	903 S CEDAR AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2022: Gooseneck removed already, found 3/4" copper	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7244	909 S CEDAR AVE	N	C	UNK	1"	9/29/2022	C	1"	9/29/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to cs, new 1" cs & box - used existing 3/4" tap. Hooked to existing 3/4" copper on house side	Installation Record	Y	9/29/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7247	911 S CEDAR AVE	N	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	2022: New 1" copper from main to cs. New 1" corp. w/ mainbreak sleeve with 1" C.C. New 1" cs & box. connected to 1/2" copper on owners side.	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7250	1105 S CEDAR AVE	N	C	UNK	1"	10/1/2022	C	1"	10/1/2022	SF	UNK	C	1"	UNK	2022: 1" copper from curb valve to main. New 1" curb valve & box. Used existing corp and connected to existing 3/4" copper on owners side.	Installation Record	Y	10/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7253	1115 S CEDAR AVE	N	C	UNK	1"	10/20/2022	C	1"	10/20/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to curb valve, new 1" curb valve & box. Used existing corp and connected to existing 3/4" copper on house side.	Installation Record	Y	10/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7256	309 E 14TH ST	UNK	C	UNK	1"	7/23/2024	C	1"	7/23/2024	SF	UNK	C	1"	UNK	Earth Inc. 11' of 1" copper from cs to existing 3/4" copper. See sheet 24 of the construction report.	Installation Record	Y	7/23/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7259	1100 S CHERRY AVE	N	C	Y	3/4"	5/12/2020	C	3/4"	5/12/2020	SF	UNK	C	3/4"	UNK	5/12/2020 -3/4" copper from main to curb stop, 1" poly to house. Removed lead in street, galvanized on customer side	Installation Record	Y	5/12/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7262	1004 S CHERRY AVE	N	C	UNK	3/4"	7/28/1986	G	3/4"	7/28/1986	SF	UNK	G	UNK	7/28/1986	REPLACED IRON ON OUR SIDE. IRON INSIDE. NEW BOX. DEPTH @ MAIN 6' ED.	SL repair/replace record	Y	7/28/1986	Visual insp during install or repair	Previous eval	Y	7/28/1986	Visual Insp during install or repair	
7266	912 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/31/2017	Cross Connection Survey	
7269	910 S CHERRY AVE	N	C	Y	3/4"	1/1/2009	C	3/4"	1/1/2009	SF	UNK	C	3/4"	UNK	2009-INSTALLED 3/4" COPPER IN STREET. REMOVED LEAD WIPE @ MAIN.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7271	908 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/31/2017	Cross Connection Survey	
7274	312 E 9TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	NEW COPPER FROM MAIN TO CURB STOP. NEW CURB STOP. SERVICE COMES OFF OF CHERRY. 10/4/22: Verified no lead	Installation Record	Y	10/4/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7278	804 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/15/2017	Cross Connection Survey	
7281	800 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/28/2017	Cross Connection Survey	
7284	712 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/31/2017	Cross Connection Survey	
7287	708 S CHERRY AVE	N	C	Y	3/4"	10/7/2018	C	3/4"	10/7/2018	SF	UNK	C	3/4"	UNK	LEAD REMOVED FROM MAIN TO CURB STOP, FOUND 1/2" COPPER ON PRIVATE SIDE FED THROUGH STEEL PIPE GOING TO HOUSE. 2021-3/4" copper on customer side.	Installation Record	Y	10/7/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7290	704 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER & LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	7/27/2017	Cross Connection Survey	
7293	702 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/17/2017	Cross Connection Survey	
7299	612 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
7303	500 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN. 3/4" copper on customer side	Installation Record	N			Field Inspection Only	Y	12/3/2014	Cross Connection Survey	
7306	410 S CHERRY AVE	N	C	Y	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	REMOVED LEAD, INTALLED 3/4" COPPER FROM MAIN TO HOUSE, CURB STOP AND BOX INSTALLED	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7309	408 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/14/2017	Cross Connection Survey	
7312	402 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	UNK-LG	UNK	1/1/1926	O	UNK	UNK	UNK		<Null>	Installation Record	N			Field Inspection Only	Y	8/7/2017	Cross Connection Survey	
7316	400 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/15/2017	Cross Connection Survey	
7319	306 S CHERRY AVE	Y	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD & COPPER (SEPERATE X-ING LINES) 6/5/23: Found 3/4" Copper from wm-cs. Installed new curb box.	Installation Record	Y	6/5/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7322	307 E 3RD ST	UNK	C	Y	1"	6/14/2023	C	1"	6/14/2023	SF	UNK	C	1"	UNK	6/14/23: Replaced lead w/ 1" copper from wm-cs. used 12" - 3/4" copper to connect to existing corp. Meyers replaced lead w/ 1" copper from cs-meter and installed a 1" cs & box.	Installation Record	Y	6/14/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7325	309 E 3RD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB VERIFIED 3-97	Installation Record	N			Field Inspection Only	Y	1/9/2014	Cross Connection Survey	
7328	313 E 3RD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER BALL VALVE. DUPLEX WITH 313A, 1/2" COPPER INTO HOUSE	Installation Record	N			Field Inspection Only	Y	7/18/2017	Cross Connection Survey	
7331	200 S CHERRY AVE	N	C	UNK	1"	1/1/2010	L	1"	1/1/2010	SF	UNK	L	UNK	1/1/2010	CONNECTED TO LEAD 15' PAST CURB VALVE.	SL repair/replace record	Y	1/1/2010	Visual insp during install or repair	Previous eval	Y	8/13/2013	Cross connection survey	
7334	114 S CHERRY AVE	N	C	UNK	1"	1/1/2010	P	1"	1/1/2010	SF	UNK	P	1"	UNK	CONNECTED TO 1" PLASTIC	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7337	106 S CHERRY AVE	UNK	C	UNK	1"	5/8/2023	C	1"	5/8/2023	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	5/8/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7340	104 S CHERRY AVE	N	C	Y	1"	5/4/2023	C	1"	5/4/2023	SF	UNK	C	1"	UNK	9/29/22: Removed all lead from both sides (utility and private). 1" copper customer side and street side. Small piece of 3/4" copper @ the main w/ coupler switching to 1". 5/4/23: Re-tapped w/ 1" corp. Conn to existing 1" copper 3' from wm.	Installation Record	Y	5/4/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7343	107 S CHERRY AVE	UNK	C	Y	1"	5/8/2023	C	1"	5/8/2023	SF	UNK	C	1"	UNK	5/8/23: Removed lead from wm-cs. Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	5/8/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7346	109 S CHERRY AVE	UNK	C	Y	1"	5/9/2023	C	1"	5/9/2023	SF	UNK	C	1"	UNK	5/9/23: Removed lead from wm-cs. Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	5/9/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7349	111 S CHERRY AVE	UNK	C	UNK	1"	5/10/2023	C	1"	5/10/2023	SF	UNK	C	1"	UNK	5/10/23: Removed 3/4" copper from wm-cs. Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	5/10/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7352	205 S CHERRY AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7355	207 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		CB LOCATION VERIFIED 12/5/97	Installation Record	N			Field Inspection Only	Y	10/8/2014	Cross Connection Survey	
7358	309 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	6/1/2017	Cross Connection Survey	
7361	313 S CHERRY AVE	UNK	UNK-LG	UNK	1/2"	1/1/1926	C	1/2"	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/1/2017	Cross Connection Survey	
7364	400 E 4TH ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	NONRES	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	8/31/2015	Cross connection survey	
7367	407 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/26/2017	Cross Connection Survey	
7370	411 S CHERRY AVE	N	C	UNK	1"	1/1/2005	C	1"	1/1/2005	SF	UNK	C	1"	UNK	2005-REPLACE SERVICE FROM MAIN TO HOUSE	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
7373	601 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/6/2017	Cross Connection Survey	
7376	607 S CHERRY AVE	N	L	UNK	5/8"	1/1/1926	P	5/8"	1/1/1926	SF	UNK	P	UNK	1/1/1926	2006-REMOVED LEAD WIPE @ CURB VALVE. INSTALLED NEW VALVE & BOX.	SL repair/replace record	Y	2006	Mech excav	Field inspection only	Y	6/9/2017	Cross Connection Survey	
7379	611 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/8/2017	Cross Connection Survey	
7382	613 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/7/2017	Cross Connection Survey	
7385	701 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/10/2017	Cross Connection Survey	
7389	707 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/18/2017	Cross Connection Survey	
7394	713 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2001: LOCKING VALVE AND LEAD WIPE REMOVED	Installation Record	N			Field Inspection Only	Y	5/26/2017	Cross Connection Survey	
7397	805 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/1/2017	Cross Connection Survey	
7400	809 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/19/2017	Cross Connection Survey	
7403	905 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	2/21/2022: JN Verified service material in the house as galvanized	Installation record	N	2/21/2022	Visual insp during install or repair	Previous eval	Y	6/13/2017	Cross connection survey	
7406	907 S CHERRY AVE	UNK	C	Y	1"	11/9/2022	C	1"	11/9/2022	SF	UNK	C	1"	UNK	11/9/22: Removed all lead and replaced w/ 1" copper from wm-cs (Meyers from cs to meter). New 1" tap	Installation Record	Y	11/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7409	1005 S CHERRY AVE	N	UNK	UNK	UNK	1/1/1982	C	UNK	1/1/1982	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1982	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7412	1007 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/5/2017	Cross Connection Survey	
7416	1009 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/6/2017	Cross Connection Survey	
7419	1011 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
7422	1107 S CHERRY AVE	N	C	UNK	1"	8/6/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 14.5' of 1" copper from cs to existing 3/4" copper. See sheet 30 of the construction report.	SL repair/replace record	Y	8/6/2024	Mech excav	Field Inspection Only	Y	8/6/2024	Visual Insp during install or repair	
7425	1012 S VINE AVE	N	L	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	UNK	1/1/1947	2013-REPLACED SERVICE ON PROP. SIDE. INSTALLED NEW CURB VALVE/BOX	SL repair/replace record	Y	2013	Mech excav	Field inspection only	Y	1/1/2020	Visual Insp during install or repair	
7428	1004 S VINE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7431	1000 S VINE AVE	N	L	UNK	5/8"	1/1/1926	P	5/8"	1/1/1926	SF	UNK	P	UNK	1/1/1926	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 6' DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	1/1/2010	Visual Insp during install or repair	
7434	908 S VINE AVE	N	L	UNK	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2010-REMOVED LEAD WIPE & INSTALLED CURB STOP/BOX	SL repair/replace record	Y	2010	Mech excav	Field inspection only	Y	9/6/2017	Cross Connection Survey	
7437	904 S VINE AVE	N	C	UNK	1"	12/1/2022	C	1"	12/1/2022	SF	UNK	C	1"	UNK	12/1/22: 1' of 3/4" copper @ wm then switches to 1" copper to cs & box. Meyers repalced galvanized w/ 1" copper from cs-meter. Insulatd @ main	Installation Record	Y	12/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7440	806 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/25/2017	Cross Connection Survey	
7443	804 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/31/2017	Cross Connection Survey	
7446	712 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1937	C	UNK	1/1/1937	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	6/11/2014	Cross Connection Survey	
7450	704 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	7/17/2017	Cross Connection Survey	
7456	610 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	6/10/2017	Cross Connection Survey	
7459	604 S VINE AVE	UNK	C	Y	3/4"	7/19/2019	C	3/4"	7/19/2019	SF	UNK	C	3/4"	UNK	7/19/2019: Serivce leaks, removed Lead & installed Copper from WM-CS w/ new CS & Box. 6" Clay Sanitary lateral crosses over WM 4" South of the corp. Found 3/4" copper 3.5' behind CS.	Installation Record	Y	7/19/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7463	602 S VINE AVE	N	C	Y	1"	7/28/2021	C	1"	7/28/2021	SF	UNK	C	1"	UNK	Removed Lead from main to new CS. Customer side is 1" Copper	Installation Record	Y	7/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7466	600 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	UNK-LG	UNK	1/1/1926	SF	UNK	UNK	UNK		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	8/5/2017	Cross Connection Survey	
7469	512 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/17/2017	Cross Connection Survey	
7472	510 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/25/2017	Cross Connection Survey	
7475	500 S VINE AVE	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	NONRES	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7478	503 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/30/2017	Cross Connection Survey	
7481	507 S VINE AVE	UNK	L	Y	UNK	1/1/1927	HDPE	UNK	1/1/2018	SF	UNK	UNK	UNK		2018-CONFIRMED AT TERRACE PLASTIC ON CUSTOMER SIDE AND LEAD STREETSIDE	Installation Record	Y	1/1/2018	Mech excav	Field Inspection Only	Y	5/16/2017	Cross Connection Survey	
7484	509 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		Y-SERVICE	Installation Record	N			Field Inspection Only	Y	5/10/2017	Cross Connection Survey	
7487	511 S VINE AVE	UNK	C	Y	3/4"	1/1/2021	C	3/4"	1/1/2021	SF	UNK	C	3/4"	UNK	2021 - Replaced Lead from main to meter 3/4" copper	Installation Record	Y	1/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7490	601 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/13/2017	Cross Connection Survey	
7493	603 S VINE AVE	UNK	C	Y	1"	7/28/2021	C	1"	7/28/2021	SF	UNK	C	1"	UNK	7/2/2021: Removed all Lead and replaced w/ 1" Copper. New tap is 2' South of abandoned tap. (1" copper on customer side)	Installation Record	Y	7/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7496	605 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/23/2017	Cross Connection Survey	
7499	607 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/5/2017	Cross Connection Survey	
7502	609 S VINE AVE	N	L	UNK	UNK	1/1/1945	C	UNK	1/1/1945	SF	UNK	C	UNK	1/1/1945	2005-REMOVED LEAD WIPE ON CURB VALVE.	SL repair/replace record	Y	2005	Mech excav	Field inspection only	Y	6/1/2017	Cross Connection Survey	
7505	611 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/3/2017	Cross Connection Survey	
7508	613 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/20/2017	Cross Connection Survey	
7511	615 S VINE AVE	N	C	Y	1"	5/23/2017	C	1"	5/23/2017	SF	UNK	C	1"	UNK	GAFFNEY-NEW 1" COPPER PROP SIDE, REMOVED LEAD WIPE ON STREETSIDE--2017	Installation Record	Y	5/23/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7514	701 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/22/2017	Cross Connection Survey	
7517	707 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/1/2017	Cross Connection Survey	
7520	709 S VINE AVE	N	L	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	UNK	1/1/1936	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 6'3" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	5/12/2017	Visual Insp during install or repair	
7523	711 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/9/2017	Cross Connection Survey	
7527	713 S VINE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2005-INSTALLED NEW 3/4" CURB VALVE W\BOX	Installation Record	Y	1/1/2005	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7530	801 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		IN SIDEWALK	Installation Record	N			Field Inspection Only	Y	5/3/2017	Cross Connection Survey	
7533	803 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/30/2017	Cross Connection Survey	
7536	805 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/27/2018	Cross Connection Survey	
7539	807 S VINE AVE	UNK	UNK-LG	UNK	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	C		3/4" COPPER	Installation Record	N			Field Inspection Only	Y	5/12/2017	Cross Connection Survey	
7542	907 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
7545	909 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/7/2017	Cross Connection Survey	
7548	1001 S VINE AVE	UNK	C	Y	1"	5/30/2023	C	1"	5/30/2023	SF	UNK	C	1"	UNK	5/30/23: Removed lead wm-cs, replaced w/ 1" copper. Conn. to existing corp with short piece of 3/4" copper. Meyers installed 1" cs & box & 1" copper from cs-meter.	Installation Record	Y	5/30/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7551	1005 S VINE AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2011-INSTALLED CURB BOX.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7554	1009 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	2/1/2017	Cross Connection Survey	
7557	512 E 10TH ST	N	C	UNK	1"	5/1/2022	C	1"	5/1/2022	SF	UNK	C	1"	UNK	5/22: 1" copper from main to house.	Installation Record	Y	5/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7560	508 E 10TH ST	N	L	UNK	UNK	1/1/1943	C	UNK	1/1/1943	SF	UNK	C	UNK	1/1/1943	2005-PROPERTY OWNER REMOVED LEAD FROM HOUSE TO CURB-BOX	SL repair/replace record	Y	2005	Mech excav	Field inspection only	Y	7/18/2017	Cross Connection Survey	
7563	507 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
7566	908 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/3/2017	Cross Connection Survey	
7569	906 S ASH AVE	N	C	Y	3/4"	1/1/2016	C	3/4"	1/1/2016	SF	UNK	C	3/4"	UNK	2016-INSTALLED NEW 3/4" COPPER MAIN TO CURB VALVE. 2014-REMOVED LEAD WIPE @ CURB STOP, INSTALLED NEW CURB STOP/BOX	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7572	812 S ASH AVE	N	C	UNK	3/4"	2/15/1988	C	3/4"	2/15/1988	SF	UNK	C	3/4"	UNK	Removed wipes, replaced iron w/ 3/4" copper	Installation Record	Y	2/15/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7575	802 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		REMOVED GOOSENECK & INSULATED, 1985 PAVING	Installation Record	N			Field Inspection Only	Y	6/2/2017	Cross Connection Survey	
7578	509 E 8TH ST	N	C	UNK	3/4"	1/1/2021	C	3/4"	1/1/2021	NONRES	UNK	C	3/4"	UNK	Installed 3/4" copper from main to curb vavle & new box	Installation Record	Y	1/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7584	710 S ASH AVE	N	C	Y	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO NEW C.B/C.V., INSTALLED NEW COPPER & INSULATED, CONNECTED TO COPPER--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7587	704 S ASH AVE	N	C	Y	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD AND INSTALLED NEW 3/4" COPPER FROM MAIN TO NEW C.B., INSULATED AT MAIN--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7590	702 S ASH AVE	N	C	UNK	3/4"	1/1/2014	C	3/4"	1/1/2014	SF	UNK	C	3/4"	UNK	2014-INSTALLED COPPER FROM MAIN TO NEW CURB VALVE/BOX. LOWERED AND INSULATED. ATTACHED TO 3/4" COPPER.	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
7593	700 S ASH AVE	N	C	UNK	3/4"	1/1/1946	C	3/4"	1/1/1946	O	UNK	C	C		REMOVED GOOSENECK, INSULATED, PAVING 1985. 11/15/24: Installed 3/4" curb stop & 1" curb box on existing 3/4" copper.	Installation Record	Y	11/15/2024	Mech excav	Field Inspection Only	Y	6/16/2017	Cross Connection Survey	
7596	612 S ASH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	INSULATED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7599	604 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1937	C	UNK	1/1/1937	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/2/2017	Cross Connection Survey	
7602	600 S ASH AVE	N	L	UNK	5/8"	1/1/1930	C	5/8"	1/1/1930	SF	UNK	C	UNK	1/1/1930	CB/LV UNKNOWN. 2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 7'6" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	5/31/2017	Cross Connection Survey	
7606	508 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
7609	502 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/15/2017	Cross Connection Survey	
7616	504 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	12/11/2014	Cross Connection Survey	
7619	412 E 4TH ST	UNK	UNK-LG	UNK	3/4"	1/1/1961	L	3/4"	1/1/1961	NONRES	UNK	L	UNK	1/1/1961	WHEEL VALVE. 2" lead on property	Installation record	N	1/1/1961	Visual insp during install or repair	Previous eval	Y	1/18/2024	Cross connection survey	
7622	404 E 4TH ST	UNK	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	NONRES	UNK	C	3/4"	UNK	WIPES TO FIT Y FIT, FEEDS 404 E 4TH. REPAIRED SERVICE IN STREET 7-3-86. 2 TAPS, 5/8" AND 3/4", TOOK OUT WIPES UP TO "Y" FITTING. 1-1/4" copper on property side	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7626	411 E 4TH ST	N	C	UNK	1"	10/14/2022	C	1"	10/14/2022	SF	UNK	C	1"	UNK	10/14/22: Installed 1" copper to new cs & box and connected to existing 3/4" copper	Installation Record	Y	10/14/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7629	413 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		2-15-96 : REPLACED WIPE UTILITY SIDE, BOX & VALVE INSTALLED. 1/2" COPPER INSIDE	Installation Record	N			Field Inspection Only	Y	8/30/2017	Cross Connection Survey	
7632	300 S VINE AVE	N	C	Y	1"	5/6/2021	C	1"	5/6/2021	SF	UNK	C	1"	UNK	5/6/21 - Removed all lead and installed a new 1" tap with 1" copper on both sides (Meyers installed 1" copper after cs to house	Installation Record	Y	5/6/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7635	409 E 3RD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/20/2017	Cross Connection Survey	
7638	210 S VINE AVE	UNK	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	9/21/2016	Cross connection survey	
7641	108 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7644	104 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7647	15 N VINE AVE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	2003- NEW 1" CORP, CONNECTED TO 1" COPPER	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7650	107 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7653	113 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7656	115 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	SEWER LATERAL COME OFF E. 2ND. CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7659	513 E 2ND ST	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7662	510 E 2ND ST	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER, SAN LATERAL AND WATER SERVICE RUN TOGETHER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7665	205 S VINE AVE	N	C	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7668	213 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/13/2016	Cross Connection Survey	
7674	606 E 3RD ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	NONRES	UNK	C	1"	UNK	RON MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7678	311 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/18/2016	Cross Connection Survey	
7681	511 E 4TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	REMOVED LEAD WIPES, NEW CURB BOX, METERS 08/97. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7684	611 E 4TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7686	300 S PEACH AVE	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	NONRES	UNK	C	1"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7697	711 E 2ND ST	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003: NEW 1" CORP,COPPER,VALVE,BOX,3/4" COPPER INSIDE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7703	714 E 2ND ST	N	C	UNK	3/4"	1/1/2002	C	3/4"	1/1/2002	SF	UNK	C	3/4"	UNK	2003: 3/4" TAP&CORP-2002: CURB BOX INSTALLED. REPLACED SERVICE FROM MAIN TO BOX. LOWERED UNDER SANATARY	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7711	209 S PEACH AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC. NEW 1" CORP,COPPER,VALVE,BOX (1/2" COPPER INSIDE)	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7714	713 E 4TH ST	N	C	Y	1"	6/25/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/17/24: Removed lead from wm-cs. Replaced w/ 1" corp, 1" copper & 1" cs & box. Connected to existing 3/4" copper 6" North of cs. Remeoved existing corp, replaced with mainbreak sleeve (2.5' East of new corp). 6" clay tile san lat. below water service.	SL repair/replace record	Y	6/25/2024	Visual insp during install or repair	Field Inspection Only	Y	6/25/2024	Visual Insp during install or repair	
7717	801 E 4TH ST	N	C	Y	1"	6/20/2024	C	1/2"	1/1/1926	SF	UNK	C	C		6/20/24: Replaced lead w/ 1" corp, 1" copper, 1" cs & box and connected to existing 1/2" copper 8" north of cs. Abandoned existing corp.	SL repair/replace record	Y	6/20/2024	Visual insp during install or repair	Field Inspection Only	Y	6/20/2024	Visual Insp during install or repair	
7720	807 E 4TH ST	N	C	Y	1"	6/20/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/20/24: Removed lead from wm-cs. Installed 1" corp., 1" copper & 1" cs & box. connected to existing 3/4" copper after cs.	SL repair/replace record	Y	6/20/2024	Visual insp during install or repair	Field Inspection Only	Y	6/20/2024	Visual Insp during install or repair	
7723	811 E 4TH ST	N	C	Y	1"	6/20/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/20/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper & 1" cs & box. Connected to existing 3/4" copper 12' after cs. Installed a 1" coupler 2' from wm.	SL repair/replace record	Y	6/20/2024	Visual insp during install or repair	Field Inspection Only	Y	6/20/2024	Visual Insp during install or repair	
7726	812 E 3RD ST	N	C	UNK	1"	7/28/2022	C	1"	7/28/2022	SF	UNK	C	1"	UNK	7/28/22: New 1" copper from main to cs. Hooked to 3/4" copper on owners side. Service is 100% copper. Old corp is 6' East of new corp.	Installation Record	Y	7/28/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7729	808 E 3RD ST	N	C	Y	1"	8/3/2022	C	1"	8/3/2022	SF	UNK	C	1"	UNK	8/3/22: Connected to 3/4" copper 12" South of curb valve on private side. Removed lead from main - cs replaced w/ 1" copper and 1" cs & box.	Installation Record	Y	8/3/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7732	800 E 3RD ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" COPPER LOCKING VALVE. 8/9/22: Lead goosneck removed @ main. replaced with 3/4" copper and connected to existing 3/4" copper @ main.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7738	801 E 3RD ST	N	C	UNK	1"	8/17/2022	C	1"	8/17/2022	SF	UNK	C	1"	UNK	1" copper main to curb box, new 1" tap	Installation Record	Y	8/17/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7742	813 E 3RD ST	UNK	C	UNK	1"	7/28/2022	C	1"	7/28/2022	SF	UNK	C	1"	UNK	7/28/22: New 1" copper from main to curb valve. Hooked up to 3/4" copper on owners side, new 1" corp and 1" cs & box.	Installation Record	Y	7/28/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7745	815 E 3RD ST	UNK	C	UNK	1"	7/28/2022	C	1"	7/28/2022	SF	UNK	C	1"	UNK	7/28/22: New 1" copper from main to curb valve. Hooked up to 3/4" copper on owners side. New 1" corp is 3' West of the old corp, 100% copper	Installation Record	Y	7/28/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7748	303 S PALMETTO AVE	N	C	Y	1"	6/1/2024	L	5/8"	1/1/1926	SF	UNK	C	C		REPLACED WITH BALL VALVE Y CONNECTION WITH 305 S PALMETTO (3/4" COPPER INSIDE 305) 7/22/24: Removed lead from wm-cs and replaced w/ 3/4" copper and 3/4" cs & box. Connected to lead after the cs. Service y'd and feeds 303 & 305	SL repair/replace record	Y	6/1/2024	Visual insp during install or repair	Field Inspection Only	Y	6/1/2024	Visual Insp during install or repair	
7751	305 S PALMETTO AVE	N	C	Y	1"	6/1/2024	L	5/8"	1/1/1926	O	UNK	UNK	UNK		REPLACED WITH BALL VALVE Y CONNECTION WITH 305 S PALMETTO (3/4" COPPER INSIDE 305) 7/22/24: Removed lead from wm-cs and replaced w/ 3/4" copper and 3/4" cs & box. Connected to lead after the cs. Service y'd and feeds 303 & 305	SL repair/replace record	Y	6/1/2024	Visual insp during install or repair	Field Inspection Only	Y	4/20/2016	Cross Connection Survey	
7754	311 S PALMETTO AVE	N	C	Y	3/4"	6/1/2024	C	3/4"	1/1/1925	SF	UNK	C	C		Lead Removed from main to curb box. 3/4" copper installed, connected to existing 3/4" copper on private.	SL repair/replace record	Y	6/1/2024	Visual insp during install or repair	Field Inspection Only	Y	6/1/2024	Visual Insp during install or repair	
7757	313 S PALMETTO AVE	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 4TH ST. 7/5/2022: lead wipe removed	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7760	814 E 4TH ST	N	C	Y	1"	6/26/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/26/24: Old corp is 2' East of new corp. Removed lead from wm-cs, replaced w/ 1" copper, 1" cs & box. connected to existing 3/4" copper 6" after cs.	SL repair/replace record	Y	6/26/2024	Visual insp during install or repair	Field Inspection Only	Y	6/26/2024	Visual Insp during install or repair	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
7763	808 E 4TH ST	N	C	UNK	1"	10/20/2022	C	1"	10/20/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to curb valve. New 1" curb valve and box. 3/4" copper inside of house.	Installation Record	Y	10/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7767	804 E 4TH ST	N	C	Y	1"	6/21/2024	C	3/4"	1/1/1926	SF	UNK	C	UNK	1/1/1926	6/21/24: Removed leadd from wm-cs. Replaced w/ 1" copper, 1" cs, reused curb box. Connected to existing 3/4" copper 12" South of cs. Old corp is 5' West of new corp. Old corp is in an abandon water manhole.	SL repair/replace record	Y	6/21/2024	Visual insp during install or repair	Field inspection only	Y	6/21/2024	Visual Insp during install or repair	
7770	802 E 4TH ST	N	C	Y	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	2018- CURB BOX INSTALLED, REMOVED LEAD FROM MAIN TO BASEMENT (GAFFNEY PRIVATE SIDE)	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7773	714 E 4TH ST	N	C	Y	1"	6/19/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/19/24: Removed lead from wm-cs. Installed 1" corp (2' East of old corp), 1" copper, 1" cs & box. Connected to existing 3/4" copper 12" after cs.	SL repair/replace record	Y	6/19/2024	Visual insp during install or repair	Field Inspection Only	Y	6/19/2024	Visual Insp during install or repair	
7777	710 E 4TH ST	N	C	Y	1"	6/19/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/19/24: Removed lead from wm-cs. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper 12" after cs.	SL repair/replace record	Y	6/19/2024	Visual insp during install or repair	Field Inspection Only	Y	6/19/2024	Visual Insp during install or repair	
7780	413 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/10/2016	Cross Connection Survey	
7783	717 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		C.B./L.B. UNKNOWN. REMOVED LEAD WIPE AT MAIN 8-97	Installation Record	N			Field Inspection Only	Y	6/7/2016	Cross Connection Survey	
7786	801 E 5TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7789	803 E 5TH ST	UNK	C	UNK	1"	1/1/2011	P	1"	1/1/2011	SF	UNK	P	1"	UNK	2011-NEW SERVICE, POLY FROM CB TO HOUSE. SHUT-OFF OLD SERVICE AT CORP.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7792	805 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	C		<Null>	Installation Record	N			Field inspection only	Y	2/4/2019	Cross Connection Survey	
7795	809 E 5TH ST	N	C	Y	1"	6/10/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/10/24: Replaced lead from wm-cs w/ 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper 12" after cs. Old corp is 4' west of new corp. Street dept replaced clay tile san. lat. w/ 6" pvc.	SL repair/replace record	Y	6/10/2024	Visual insp during install or repair	Field Inspection Only	Y	6/10/2024	Visual Insp during install or repair	
7798	808 E 5TH ST	N	C	Y	1"	6/10/2024	C	3/4"	UNK	SF	UNK	O	O	UNK	6/10/24: Replaced lead w/ 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper after cs. Old corp is 4' West of new. Street dept replaced clay tile san. lat. w/ 6" pvc	SL repair/replace record	Y	6/10/2024	Visual insp during install or repair	Field Inspection Only	Y	6/10/2024	Visual Insp during install or repair	
7801	800 E 5TH ST	N	C	Y	5/8"	UNK	C	5/8"	UNK	SF	UNK	C	5/8"	UNK	2006 REMOVED LEAD WIPE @ MAIN AND 25' OF LEAD PIPE. INSTALLED 3/4" COPPER (COPPER INSIDE)	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7804	500 S APPLE AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		COPPER SERVICE VERIFIED ON PROP. SIDE BY GAFFNEY	Installation Record	N			Field Inspection Only	Y	5/2/2016	Cross Connection Survey	
7807	708 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		IRON	Installation Record	N			Field Inspection Only	Y	5/11/2016	Cross Connection Survey	
7810	501 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	6/13/2016	Cross Connection Survey	
7813	412 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/7/2016	Cross Connection Survey	
7816	610 E 4TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7819	600 E 10TH ST	N	L	UNK	5/8"	1/1/1940	C	5/8"	1/1/1940	SF	UNK	C	UNK	1/1/1940	2014-MEYERS REMOVED LEAD WIPE ON OUR STREETSIDE OF CURB VALVE AMD INSTALLED NEW CURB VALVE/BOX	SL repair/replace record	Y	2014	Mech excav	Field inspection only	Y	4/11/2016	Cross Connection Survey	
7822	602 E 10TH ST	N	L	UNK	UNK	1/1/1940	C	UNK	1/1/1940	SF	UNK	C	UNK	1/1/1940	2003-REMOVED LEAD WIPE & INSTALLED NEW CURB VALVE.1997-CB LOCATION VERIFIED	SL repair/replace record	Y	2003	Mech excav	Field inspection only	Y	3/14/2016	Cross Connection Survey	
7825	608 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	10/22/2015	Cross Connection Survey	
7828	610 E 10TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7831	915 S PEACH AVE	N	UNK	UNK	3/4"	1/1/1994	C	3/4"	1/1/1994	SF	UNK	C	3/4"	UNK	34597	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7834	913 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1994-OLD BOX 1'S-SHUT OFF-USED TO FEED 915 S PEACH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7837	911 S PEACH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2015-REMOVED ALL LEAD. INSTALLED NEW CURB VALVE/BOX	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7840	907 S PEACH AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7843	901 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7846	900 S ERICKSON AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7849	1400 S ERICKSON AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7852	1404 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7855	1410 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7858	1412 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7861	1418 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED LV REIGEL 6/76	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7864	1500 S ERICKSON AVE	UNK	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LEAD WIPE 9/8/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7867	1504 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7870	1600 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7873	1400 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7876	1415 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7879	1421 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7882	1601 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7885	1603 S APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7888	1604 S ERICKSON AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7891	1616 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7894	1620 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7897	1621 S APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7900	1615 S ERICKSON AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2008- REMOVED LEAD GOOSE-NECK @ WATERMAIN.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7903	1601 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7906	1501 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7909	1421 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7912	1415 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7915	1413 S ERICKSON AVE	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000: REMOVED LEAD WIPE @ MAIN.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7918	1407 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7921	1403 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7924	907 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7927	808 E 9TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7930	807 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7933	805 S PALMETTO AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/30/2016	Cross Connection Survey	
7936	803 S PALMETTO AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2003-CURB VALVE INSTALLED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7939	801 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7942	606 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7945	608 S PALMETTO AVE	N	C	UNK	UNK	UNK	UNK	UNK	UNK	SF	UNK	UNK	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 8' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7948	813 E 7TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/6/2022: Dug and fixed main break near service. 3/28/2022 - Removed 2.5' lead gooseneck. 3/4" copper from main connected to existing 3/4" copper.	Installation Record	Y	3/28/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7951	700 S PALMETTO AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 5' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7954	706 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7957	708 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7960	710 S PALMETTO AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2013-CUT IN NEW CURB BOX - NEW COPPER FROM CURB VALVE TO EAST EDGE FO SIDEWALK 14'	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7963	800 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
7966	804 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
7969	819 E 9TH ST	N	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	NEW 5' PAST SIDEWALK.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7972	813 S APPLE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/26/2022: Dug at main found 3/4" copper from main to center of road.	Installation Record	Y	7/26/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7975	805 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/26/2022: Removed lead wipe @ main, connected to existing 3/4" copper 8' from main.	Installation Record	Y	7/26/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7978	801 S APPLE AVE	UNK	C	Y	1"	7/21/2022	C	1"	7/21/2022	SF	UNK	C	1"	UNK	7/21/22: Replaced lead w/ 1" copper from main to cs. Connected to existing corp. with 3/4" copper. Installed new 1" cs & box. Connected to existing 3/4" copper after the cs.	Installation Record	Y	7/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7981	711 S APPLE AVE	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF APPLE. 7/21/22: Removed lead wipe at the main, connected to existing 3/4" copper. Service is copper from main to house.	Installation Record	Y	7/21/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7984	707 S APPLE AVE	N	C	Y	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-CURB BOX INSTALLED, REMOVED LEAD AT MAIN SERVICE IS 3/4" COPPER ON STREETSIDE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
7987	703 S APPLE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/20/22: Dug and verified 3/4" copper at the main.	Installation Record	Y	7/20/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7990	613 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF APPLE. 7/20/22: Removed Lead to sidewalk, Replaced with 3/4" copper. Installed new 3/4" cs & box.	Installation Record	Y	7/20/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7993	607 S APPLE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/19/22: Dug at the main and verified the serive is 3/4" copper.	Installation Record	Y	7/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7996	603 S APPLE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	4/91: Replaced 90 degree fitting @ corp. Abandon 5/8" corp on west side of main 6' South of 603 Service. 7/19/22: Dug at main and verified 3/4" copper service.	Installation Record	Y	7/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
7999	601 S APPLE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICES COMES OFF OF APPLE. 7/19/22: Dug at main and verified 3/4" copper.	Installation Record	Y	7/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8002	814 E 6TH ST	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 6' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8005	512 S PALMETTO AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		REIGELS INSTALLED NEW CURB BOX.	Installation Record	N			Field Inspection Only	Y	4/8/2016	Cross Connection Survey	
8008	809 E 6TH ST	N	L	UNK	3/4"	1/1/1947	C	3/4"	1/1/1947	SF	UNK	C	UNK	1/1/1947	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 5'4" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	3/7/2016	Visual Insp during install or repair	
8011	513 S APPLE AVE	N	C	Y	3/4"	7/19/2022	C	3/4"	7/19/2022	SF	UNK	C	3/4"	UNK	7/19/22: Removed lead from main to cs, replaced w/ 3/4" copper. Connected to existing corp, intalled new 3/4" cs & box, connected to existing 3/4" copper after the cs.	Installation Record	Y	7/19/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8014	509 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/18/22: Removed lead from main to cs and replaced w/ 3/4" copper. Connected to existing corp, installed new 3/4" cs & box, connected to existing 3/4" copper after cs.	Installation Record	Y	7/18/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8017	505 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/18/22: Removed lead wipe at main, replaced with 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	7/18/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8020	510 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/20/22: Removed lead from main to cs and replaced w/ 3/4" copper. Connected to existing corp, installed new 3/4" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	7/20/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8023	700 E 4TH ST	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	NEW TAP ON NEW MAIN-2017 EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8026	600 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/19/22: Removed lead gooseneck at main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	7/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8029	604 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/19/22: Removed lead gooseneck at main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	7/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8032	612 S APPLE AVE	N	C	Y	3/4"	1/1/2007	C	3/4"	1/1/2007	SF	UNK	C	3/4"	UNK	2007- REMOVED LEAD INSTALLED 3/4" COPPER FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8035	700 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/20/22: Removed lead gooseneck at main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	7/20/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8038	706 S APPLE AVE	N	C	Y	3/4"	1/21/1999	C	3/4"	1/21/1999	SF	UNK	C	3/4"	UNK	REMOVED 2' OF LEAD @ THE MAIN AND REPLACED WITH COPPER.	Installation Record	Y	1/21/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8041	708 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2000: REMOVED LEAD WIPE @ MAIN. 7/20/22: Removed lead gooseneck at main and replaced w/ 3/4" copper. Connected to existing 3/4" copper. (Copper from main to hosue)	Installation Record	Y	7/20/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8044	800 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF APPLE. 7/26/2022: Removed lead @ main (18"). Connected to 3/4" copper.	Installation Record	Y	7/26/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8047	806 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/26/22: Removed lead wipe @ main, connected to exisiting 3/4" copper 18" from main.	Installation Record	Y	7/26/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8050	709 E 9TH ST	N	C	UNK	3/4"	6/1/2000	C	3/4"	6/1/2000	SF	UNK	C	3/4"	UNK	NEW UP TO SIDEWALK.	Installation Record	Y	6/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8053	807 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	4/8/2016	Cross Connection Survey	
8056	713 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8059	703 S PEACH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED ALL LEAD AND INSULATED AT MAIN 01/10/95	Installation Record	Y	1/10/1992	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8062	701 S PEACH AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8065	609 S PEACH AVE	UNK	C	Y	1"	8/11/2021	C	1"	8/11/2021	SF	UNK	C	1"	UNK	8/11/21- Removed lead & replaced w/ 1" copper from wm-cs. Re-tapped 3' South of abandoned tap with a 6"x12" repair sleeve w/ 1" C.C. Riegle Plbg. replaced lead on customers side w/ 3/4" copper from cs - meter w/ new 1" cs & box. 1"x3/4" coupling 1' East	Installation Record	Y	8/11/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8068	700 E 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	3/18/2016	Cross Connection Survey	
8071	505 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	3/9/2016	Cross Connection Survey	
8074	500 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	NONRES	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/25/2017	Cross Connection Survey	
8077	504 S PEACH AVE	N	L	UNK	5/8"	1/1/1922	C	5/8"	1/1/1922	SF	UNK	C	UNK	1/1/1922	2013-NEW CURB VALVE & BOX INSTALLED. 2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 6' DEEP, 4' FROM CB	Previous eval	Y	2020	Mech excav	Field inspection only	Y	2/17/2016	Cross Connection Survey	
8080	610 E 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	4/28/2016	Cross Connection Survey	
8083	606 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8086	612 S PEACH AVE	N	UNK	UNK	5/8"	1/1/1961	C	5/8"	1/1/1961	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8089	700 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1923	C	UNK	1/1/1923	NONRES	UNK	C	C		9/18/97 J.T. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	5/28/2014	Cross Connection Survey	
8092	702 S PEACH AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8095	708 S PEACH AVE	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8098	802 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/18/2016	Cross Connection Survey	
8101	804 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/3/2016	Cross Connection Survey	
8104	808 S PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8107	810 S PEACH AVE #A	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	3/8/2016	Cross Connection Survey	
8110	610 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	3/1/2016	Cross Connection Survey	
8113	904 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8116	913 S ASH AVE	N	L	UNK	5/8"	1/1/1927	C	5/8"	1/1/1927	SF	UNK	C	UNK	1/1/1927	2012-REMOVED LEAD WIPE @ CURB VALVE, INSTALLED 3/4" CURB VALVE & BOX	SL repair/replace record	Y	2012	Mech excav	Field inspection only	Y	6/11/2012	Visual insp at meter	
8119	907 S ASH AVE	N	C	Y	3/4"	1/1/2016	C	3/4"	1/1/2016	SF	UNK	C	3/4"	UNK	2016-REMOVED LEAD WIPE AT MAIN CONNECTING TO 3/4" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
8122	905 S ASH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8126	813 S ASH AVE	N	C	Y	3/4"	8/25/2017	C	3/4"	8/25/2017	SF	UNK	C	3/4"	UNK	REPLACED LEAD W/ NEW 3/4" COPPER FROM MAIN TO C.B., GAFFNEY INSTALLED COPPER FROM C.B. TO INSIDE HOUSE--2017	Installation Record	Y	8/25/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8129	807 S ASH AVE	N	UNK	UNK	5/8"	1/1/1983	C	5/8"	1/1/1983	SF	UNK	C	5/8"	UNK	RETAPPED AND COPPER INSTALLED WHEN CITY REPLACED SEWER IN 1983	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8132	801 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		REMOVED GOOSENECK & INSULATED, 1985 PAVING	Installation Record	N			Field Inspection Only	Y	2/19/2016	Cross Connection Survey	
8135	713 S ASH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Removed lead & insulated-1985 paving. 5-5-2021: verified all 3/4" copper from main to 2' west of centerline - No Lead Found. Water line for 605 E. 8th goes through 713 S. Ash on private property to 605 E. 8th.	Installation Record	Y	5/5/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8138	709 S ASH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2008-REPAIRED LEAK ON CORP. 1995-INSTALLED CURB BOX. 1985-REMOVED LEAD & INSULATED	Installation Record	Y	1/1/2008	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8141	705 S ASH AVE	N	C	Y	3/4"	10/5/2017	C	3/4"	10/5/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD AND INSTALLED NEW 3/4" COPPER FROM MAIN TO HOUSE AND NEW C.B., INSULATED AT MAIN--2017	Installation Record	Y	10/5/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8144	609 S ASH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	PAVING	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8147	601 S ASH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8150	513 S ASH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8153	511 S ASH AVE	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED LEAD & INSULATED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8156	507 S ASH AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ BOC, FOUND COPPER 4'6" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8159	505 S ASH AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" COPPER LOCKING VALVE 3/14/22: Fixed leak at corp, replaced 2' of 3/4" copper and insalled new 45 degree fitting onto existing corp. Used 3/4" compression to connect to existing copper	Installation Record	Y	3/14/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8162	501 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	2/24/2016	Cross Connection Survey	
8165	606 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1945	C	UNK	1/1/1945	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	3/10/2016	Cross Connection Survey	
8176	110 W 14TH ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	CB/LV UNKNOWN	Installation record	N		Visual insp during install or repair	Previous eval	Y	7/10/2024	Visual insp at meter	
8176	110 W 14TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	L	UNK	1/1/1922	SF	UNK	UNK	UNK		CB/LV UNKNOWN	Installation Record	N			Field inspection only	Y	2/4/2019		
8179	1507 S CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8182	1514 S CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8185	1512 S CHESTNUT AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1/22/18 - 4' - 3/4" COPPER AND 2 - 3/4" COMPRESSION FITTINGS (41.5' EAST & 5' SOUTH FROM N.E.C.H. 1512 S CHESTNUT) USED TO REPLACE KINKED COPPER WHILE FIXING WM LEAK. 3/4" copper on property side	Installation Record	Y	1/22/2018	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8188	1504 S CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8191	1500 S CHESTNUT AVE	N	C	Y	3/4"	1/1/1993	C	3/4"	1/1/1993	SF	UNK	C	3/4"	UNK	1993-CUB BOX INSTALLED, LEAD WIPE REMOVED, COPPER REPLACED FROM MAIN TO CURB BOX.	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8194	1400 S CHESTNUT AVE	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8197	204 W 14TH ST	N	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	2009-BORED AND TAPPED NEW SERVICE. 2008-CAL'S PLMB REPLACED CUSTOMER SIDE	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8202	212 W 14TH ST	UNK	C	Y	3/4"	8/11/2020	C	3/4"	8/11/2020	NONRES	UNK	C	3/4"	UNK	8/11/2020 - REMOVED LEAD IN STREET & REPLACED W/ 3/4" COPPER FROM MAIN - C.S. 3/4" COPPER INTALLED TO METER	Installation Record	Y	8/11/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8206	400 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 14TH	Installation Record	Y	1/1/1993	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8209	404 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8212	408 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8215	510 W 14TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1993-REPLACED WIPES INSTALLED NEW COPPER FROM Y TO HOUSE	Installation Record	Y	1/1/1993	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8218	602 W 14TH ST	N	C	UNK	1"	1/1/2009	C	1"	1/1/2009	SF	UNK	C	1"	UNK	2009-BORED NEW SERVICE ACROSS W. 14TH	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8221	608 W 14TH ST	N	C	UNK	1"	1/1/2009	C	1"	1/1/2009	SF	UNK	C	1"	UNK	2009-BORED NEW SERVICE ACROSS W. 14TH	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8224	610 W 14TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 10/13/97	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8227	612 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8230	702 W 14TH ST	N	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8233	1401 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS. 1" copper on property side	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8237	1413 S ADAMS AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8240	1419 S ADAMS AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STARTFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8244	714 W 14TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	NONRES	UNK	C	3/4"	UNK	RON MEYER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8247	1400 S BALBOA AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8251	515 W 14TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8254	600 W 13TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	DUPLEX WITH 602 W 13TH - CB LOCATION VERFIED 10/10/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8257	509 W 13TH ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS. DUPLEX WITH 511. C.B. LOCATION VERIFIED 1997	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8260	501 W 13TH ST	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8263	500 W 13TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8266	501 W 14TH ST	UNK	C	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL: CB LOCATION VERIFIED 10/13/97	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8272	401 W 14TH ST	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8276	1200 S OAK AVE	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	NONRES	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8282	209 W 14TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/13/2015	Cross Connection Survey	
8285	201 W 14TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		SERVICE COMES OFF OF CHESTNUT	Installation Record	N			Field Inspection Only	Y	10/20/2015	Cross Connection Survey	
8288	1306 S CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	02/14/95 - REMOVED LEAD WIPE OUR SIDE PUT IN NEW CURB STOP, IRON ON INSIDE	Installation record	N	2/15/1995	Visual insp during install or repair	Previous eval	Y	3/24/2010	Cross connection survey	
8291	1304 S CHESTNUT AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8294	1302 S CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		1" copper on property side	Installation Record	N			Field Inspection Only	Y	5/30/2017	Cross Connection Survey	
8297	1212 S CHESTNUT AVE	N	C	Y	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	3/4" COPPER FROM MAIN TO CURB BOX 7-1-2020. LEAD REPLACED DUE TO LEAK	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8300	1202 S CHESTNUT AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2017-REMOVED ALL LEAD REPLACED WITH 8' 3/4" COPPER2000: REMOVED LEAD WIPE BY MAIN.	Installation Record	Y	1/1/2017	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8303	206 W 11TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8306	208 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		CB VERIFIED 3-97	Installation Record	N			Field Inspection Only	Y	8/8/2013	Cross Connection Survey	
8309	212 W 11TH ST	N	C	UNK	UNK	1/1/2013	L	UNK	1/1/2013	SF	UNK	L	UNK	1/1/2013	2013-NEW COPPER & CURB VALVE/BOX	SL repair/replace record	Y	1/1/2013	Visual insp during install or repair	Previous eval	Y	10/29/2015	Cross connection survey	
8312	216 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/30/2015	Cross Connection Survey	
8315	218 W 11TH ST	N	L	UNK	UNK	1/1/1928	P	UNK	1/1/1928	SF	UNK	P	UNK	1/1/1928	2012-REMOVED LEAD WIPE @ CURB VALVE, INSTALLED 3/4" CURB VALVE & BOX	SL repair/replace record	Y	2012	Mech excav	Field inspection only	Y	1/30/2017	Cross Connection Survey	
8318	220 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	L	UNK	1/1/1928	SF	UNK	C	C		BALL VALVE - NOT LOCKING VALVE. 4-16-25: Customer emailed photo of lead with a fitting.	Installation Record	N			Field Inspection Only	Y	4/16/2025	Customer self id	Customer emailed a photo (4/16/25)
8321	222 W 11TH ST	N	C	UNK	1"	1/1/2009	C	1"	1/1/2009	SF	UNK	C	1"	UNK	2009-NEW SERVICE MEYERS	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8324	226 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/21/2015	Cross Connection Survey	
8327	230 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		Locking Valve	Installation Record	N			Field Inspection Only	Y	10/15/2015	Cross Connection Survey	
8330	227 W 11TH ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8333	221 W 11TH ST	N	C	UNK	1"	1/1/1969	C	1"	1/1/1969	SF	UNK	C	1"	UNK	REIGEL. 3/4" copper on property side. 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 8' DEEP	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8336	213 W 11TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8340	211 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	C		1978-HYD CAPPED OFF	Installation Record	N			Field Inspection Only	Y	7/31/2017	Cross Connection Survey	
8343	205 W 11TH ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8346	111 W 12TH ST	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		NO CURB BOX.	Installation Record	N			Field Inspection Only	Y	3/19/2014	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
8349	1207 S CHESTNUT AVE	UNK	C	Y	3/4"	8/18/2021	C	3/4"	8/18/2021	SF	UNK	C	3/4"	UNK	8/18/21: All lead removed from watermain to house. Replaced with 3/4" copper from watermain to house. Meyers replaced from cs to meter.	Installation Record	Y	8/18/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8352	1209 S CHESTNUT AVE	UNK	C	Y	1"	11/18/2021	C	1"	11/18/2021	SF	UNK	C	1"	UNK	11/18/2021:Removed lead on both sides, 1" copper street side and 3/4" copper on customer side. Had to open cut across the road (would not pull through sanitary trench) Meyers installed cs & box and 3/4" copper from cs to meter.	Installation Record	Y	11/18/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8355	1213 S CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	2/10/2016	Cross Connection Survey	
8358	1309 S CHESTNUT AVE	N	C	Y	3/4"	1/1/2003	C	3/4"	1/1/2003	SF	UNK	C	3/4"	UNK	LEAD WIPE REMOVED, NEW COPPER & NEW CB INSTALLED - MEYERS	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8362	112 W 12TH ST	N	C	Y	3/4"	8/14/2024	C	3/4"	1/1/1945	SF	UNK	C	C		8/14/24: Removed lead and replaced with 3/4" copper. Installed 3/4" cs & box. Connected to existing 3/4" copper after cs.	SL repair/replace record	Y	8/14/2024	Visual insp during install or repair	Field Inspection Only	Y	8/14/2024	Visual Insp during install or repair	
8365	1112 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2009- INSTALLED NEW CORP (5/8") & INSULATED. 1" HDPE on property side	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	3/4/2010	Cross Connection Survey	
8371	1106 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2009-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	10/20/2015	Cross Connection Survey	
8374	UNK	N	L	UNK	5/8"	1/1/1926	C	3/4"	1/1/1926	O	UNK	UNK-LG	UNK	1/1/1926	Y SERVICE FOR 1106 & 1108 S. CENTRAL. 2009-RENOVED LEAD WIPE @ MAIN.	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	1/1/2009	Visual Insp during install or repair	
8380	114 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1926	SF	UNK	UNK	UNK		<Null>	Installation Record	N			Previous eval	Y	2/13/2020	Cross Connection Survey	
8380	112 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/9/2015	Cross Connection Survey	
8383	114 W 11TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8386	116 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1942	C	UNK	1/1/1942	SF	UNK	C	C		COMES OFF OF 11TH	Installation Record	N			Field Inspection Only	Y	10/2/2014	Cross Connection Survey	
8389	111 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/29/2012	Cross Connection Survey	
8393	1014 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2009-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	1/1/2009	Visual Insp during install or repair	
8403	134 W 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	P	UNK	1/1/1928	SF	UNK	P	P		REMOVED WIPE 12/1/93	Installation Record	N			Field Inspection Only	Y	11/15/2018	Cross Connection Survey	
8405	137 W 9TH ST	N	L	UNK	1"	1/1/1928	C	1"	1/1/1928	NONRES	UNK	C	UNK	1/1/1928	2007-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2007	Mech excav	Field inspection only	Y	10/15/2014	Cross Connection Survey	
8408	113 W 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		CB VEREFIED 3-97. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	10/21/2013	Cross Connection Survey	
8417	1001 S CENTRAL AVE	UNK	C	UNK	3/4"	1/1/2009	C	3/4"	1/1/2009	NONRES	UNK	C	3/4"	UNK	2009-BORED 3/4" COPPER MAIN TO CURB VAVLE. USED EXISTING 5/8" CORP	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8425	1111 S CENTRAL AVE	Y	L	Y	5/8"	UNK	G	5/8"	UNK	SF	UNK	G	5/8"	UNK	2009-REMOVED LEAD WIPE @ MAIN.	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8428	1209 S CENTRAL AVE	N	L	UNK	1-1/4"	1/1/1926	C	1-1/4"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2005-REMOVED LEAD WIPE AT WATERMAIN	SL repair/replace record	Y	2005	Mech excav	Field inspection only	Y	10/16/2014	Cross Connection Survey	
8432	1213 S CENTRAL AVE	N	C	UNK	1"	7/30/2024	C	3/4"	1/1/1922	NONRES	UNK	C	C		Earth Inc. 19.5' of 1" copper from cs to existing 3/4" copper.	SL repair/replace record	Y	7/30/2024	Mech excav	Field Inspection Only	Y	7/30/2014	Visual Insp during install or repair	
8435	1008 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8439	1006 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8442	1004 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- EARTH INC	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8445	1000 S OAK AVE	N	C	UNK	1"	5/3/2022	C	1"	5/3/2022	SF	UNK	C	1"	UNK	5/3/22: New 1" tap and 1" copper and 1" cs & box. 3/4" copper inside	Installation Record	Y	5/3/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8448	1001 S SEVERNS AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN. 5/3/22: Removed 3' lead wipe @ main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	5/3/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8451	1003 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO DITCH & CONNECTED TO EXISTING 3/4" CU AT DITCH	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8454	1009 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	SEWER LATERAL IS 1.5' BELOW WATER SERVICE. REMOVED LEAD FROM MAIN TO THE EDGE OF THE DITCH IN DRIVEWAY. CONNECTED TO EXSTING 3/4" COPPER	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8457	1011 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	SEWER LATERAL IS 1.5' BELOW WATER SERVICE. REMOVED LEAD FROM MAIN TO EDGE OF DITCH, CONNECTED TO EXISTING 3/4" COPPER	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8460	1013 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	O	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO NEW CS, CONNECTED TO EXISTING 3/4" COPPER ON CUSTOMER SIDE. SEWER LATERAL IS 3" BELOW CS.	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8463	1015 S SEVERNS AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8463	1015 S SEVERNS AVE	N	C	UNK	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	NEW TAP TO RUN WATER SERVICE IN SAME TRENCH AS NEW SEWER LATERAL. CONNECTED TO EXISTING 3/4" CU IN DRIVEWAY OF 1013 SEVERNS. NEW SEWER LATERAL IS 1' BELOW SERVICE	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8466	1018 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO NEW CB. 6' OF 3/4" CU FROM CS TO EXISTING 3/4" CU ON CUSTOMER SIDE. SERVICE IS TAPPED ON TOP OF MAIN. SEWER LATERAL IS 3' BELOW WATER SERVICE	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8469	1014 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO NEW CB - CONNECTED TO EXISTING 3/4" COPPER ON CUSTOMERS SIDE. SEWER LATERAL IS 1.5' BELOW WATER SERVICE	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8472	1010 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO NEW CURB STOP - INSTALLED 1 - 6"X12" SLEEVE W/ 1" CC W/ 3/4" CORP. CONN. TO EXISTING COPPER ON CUSTOMER SIDE. SEWER LATERAL IS 2' BELOW WATER SERVICE	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8475	1006 S SEVERNS AVE	N	C	UNK	3/4"	8/5/2019	C	3/4"	8/5/2019	SF	UNK	C	3/4"	UNK	INSALLED NEW 3/4" CU FROM CORP TO NEW CS & BOX. CONNECTED TO EXISTING 3/4" COPPER	Installation Record	Y	8/5/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8478	1002 S SEVERNS AVE	N	C	Y	3/4"	8/5/2019	C	3/4"	8/5/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD INSTALLED NEW 3/4" CU FROM CORP TO CU-CU FITTING. CONNECTED TO EXISTING 3/4" COPPER	Installation Record	Y	8/5/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8481	908 W ARLINGTON ST	N	C	Y	1"	5/10/2022	C	1"	5/10/2022	SF	UNK	C	1"	UNK	5/10/22: Removed lead from wm-cs, replaced w/ 1" copper. Connected to existing 3/4" copper 18" South of the cs. New tap is 3' West of the old tap.	Installation Record	Y	5/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8484	908 W ARLINGTON ST #A	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/6/22: Removed 3' lead wipe @ main. Replaced w/ 3/4" copper. Connected to 3/4" copper.	Installation Record	Y	5/6/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8487	916 W ARLINGTON ST	N	C	Y	1"	5/11/2022	C	1"	5/11/2022	SF	UNK	C	1"	UNK	5/11/22: Removed lead from wm-cs and replaced w/ 1" copper. Installed a 1" cs & box @ the Back of curb & connected to 3/4" copper, 12" South of cs. Installed new tap 3' West of the existing corp.	Installation Record	Y	5/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8493	1004 W ARLINGTON ST	N	C	Y	1"	5/13/2022	C	1"	5/13/2022	SF	UNK	C	1"	UNK	5/13/22: Removed lead from wm-cs, replaced w/ 1" copper & connected to 3/4" copper 2' South of the new cs & box. New 1" corp. installed 4' West of the abandoned corp.	Installation Record	Y	5/13/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8496	1006 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/13/2022: Dug @ wm and removed 4' lead gooseneck. Replaced w/ 3/4" copper and connected to existing 3/4" copper @ the main. Used existing corp.	Installation Record	Y	5/13/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8499	1008 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	11-22-21: Removed lead gooseneck @ main. Replaced with 3' - 3/4" copper from main to existing copper. Existing copper is inside 2" galvanized pipe crossing the road.	Installation Record	Y	11/22/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8502	1010 W ARLINGTON ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/17/2022: Dug @ wm and found 3/4" copper.	Installation Record	Y	5/17/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8505	1014 W ARLINGTON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8508	1007 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8512	1011 S ADAMS AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
8512	1011 S ADAMS AVE	UNK	UNK	UNK	4"	1/1/1995	C	4"	1/1/1995	SF	UNK	C	4"	UNK	CB VERIFIED 6/5/97	Installation Record	Y	1/1/1995	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
8515	1017 W PARK ST	UNK	C	Y	1"	7/16/2021	C	1"	7/16/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/16/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8518	1013 W PARK ST	UNK	C	Y	1"	7/19/2021	C	1"	7/19/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/19/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8521	1009 W PARK ST	UNK	C	Y	1"	7/19/2021	C	1"	7/19/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/19/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8524	1010 S CLARK AVE	UNK	C	Y	1"	8/6/2021	C	1"	8/6/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	8/6/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8527	1013 S CLARK AVE	UNK	C	Y	1"	8/10/2021	C	1"	8/10/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	8/10/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8530	1015 S CLARK AVE	UNK	C	Y	1"	8/10/2021	C	1"	8/10/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	8/10/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8533	1107 S CLARK AVE	UNK	C	Y	1"	8/9/2021	C	1"	8/9/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	8/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8536	1004 W PARK ST	UNK	C	Y	1"	7/26/2021	C	1"	7/26/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/26/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8539	1008 W PARK ST	UNK	C	Y	1"	7/26/2021	C	1"	7/26/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/26/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8542	1012 W PARK ST	UNK	C	Y	1"	7/23/2021	C	1"	7/23/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/23/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8545	1014 W PARK ST	UNK	C	Y	1"	7/23/2021	C	1"	7/23/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/23/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8548	1018 W PARK ST	UNK	C	UNK	1"	7/22/2021	C	1"	7/22/2021	SF	UNK	C	1"	UNK	1" copper installed 21' S. of curb valve to the house to keep service out of the driveway. Connected to existing 3/4" copper	Installation Record	Y	7/22/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8551	1020 W PARK ST	UNK	C	Y	1"	7/22/2021	C	1"	7/22/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/22/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8554	1012 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8557	1004 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8560	1102 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/31/97: Service lowered & lead wipe removed. 8/2/2021: Dug to corp., fitting was leaking at corp. Replaced gasket and reconnected. Verified 3/4" copper @ WM	Installation Record	Y	8/2/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8563	1112 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Removed lead wipe on main and lowered from main to center of road. 8/5/2021: Verified copper in the road	Installation Record	Y	8/5/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8566	1204 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	8/6/2021: Dug & removed Lead gooseneck @ WM. Replaced w/ 3/4" copper. Connected to existing 3/4" copper 3' from WM.	Installation Record	Y	8/6/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8569	1206 W ARLINGTON ST	N	C	Y	3/4"	1/1/1958	C	3/4"	1/1/1958	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN. 8/9/2021: Removed Lead gooseneck @ WM & replaced it w/ 3/4" copper. Connected to existing 3/4" copper 2' from WM.	Installation Record	Y	1/1/1958	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8572	1300 W ARLINGTON ST	UNK	C	UNK	1"	8/17/2022	C	1"	8/17/2022	SF	UNK	C	1"	UNK	8/17/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/17/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8575	1306 W ARLINGTON ST	UNK	C	UNK	1"	8/17/2022	C	1"	8/17/2022	SF	UNK	C	1"	UNK	8/17/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/17/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8579	1402 W ARLINGTON ST	UNK	C	UNK	1"	8/15/2022	C	1"	8/15/2022	SF	UNK	C	1"	UNK	8/15/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/15/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8582	1412 W ARLINGTON ST	UNK	C	UNK	1"	8/11/2022	C	1"	8/11/2022	SF	UNK	C	1"	UNK	8/11/22: Installed 1" tapping saddle, 1" corp. and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8585	1414 W ARLINGTON ST	UNK	C	UNK	1"	8/15/2022	C	1"	8/15/2022	SF	UNK	C	1"	UNK	8/15/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/15/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8588	1500 W ARLINGTON ST	UNK	C	UNK	1"	8/15/2022	C	1"	8/15/2022	SF	UNK	C	1"	UNK	8/15/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/15/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8591	1508 W ARLINGTON ST	UNK	C	UNK	1"	8/10/2022	C	1"	8/10/2022	SF	UNK	C	1"	UNK	8/10/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8594	1600 W ARLINGTON ST	UNK	C	UNK	1"	8/9/2022	C	1"	8/9/2022	SF	UNK	C	1"	UNK	8/9/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8597	1607 W ARLINGTON ST	UNK	C	UNK	1"	8/3/2022	C	1"	8/3/2022	SF	UNK	C	1"	UNK	8/3/22: Installed tapping saddle on 8" C-900 w/ 1" corp. 1" cu and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/3/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8600	1601 W ARLINGTON ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8603	1203 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	8/6/2021: Dug & removed Lead gooseneck @ WM. Replaced w/ 3/4" copper & connected to existing 3/4" copper 3' from WM.	Installation Record	Y	8/6/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8606	910 S ADAMS AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	VERIFIED COPPER 07/2017 REIGEL PMBG- SERVICE COMES OFF ARLINGTON. 8/2/2021: Removed Lead gooseneck at WM, replaced w/ 3/4" Copper and connected to existing 3/4" copper 4' from WM	Installation Record	Y	8/2/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8609	1011 W ARLINGTON ST	N	C	Y	1"	5/17/2022	C	1"	5/17/2022	SF	UNK	C	1"	UNK	5/17/2022: Removed lead and installed new 1" corp., 1" copper from wm-cs, new 1" cs & box.	Installation Record	Y	5/17/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8612	1007 W ARLINGTON ST	UNK	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8615	1003 W ARLINGTON ST	N	C	Y	1"	5/12/2022	C	1"	5/12/2022	SF	UNK	C	1"	UNK	5/12/22: Replaced lead from wm-cs w/ 1" copper. Installed 1" cs & box 2' south of the sidewalk. Installed 1" corp 3' East of old corp. Conn. to existing 3/4" copper after cs. Dalton Tysver replaced san. lateral alsol. (see card)	Installation Record	Y	5/12/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
8618	1001 W ARLINGTON ST	N	C	Y	1"	5/11/2022	C	1"	5/11/2022	SF	UNK	C	1"	UNK	1999: Meyers removed lead wipes @ cs, installed new cs & box, ran new copper to the house. 5/12/22: Removed lead from wm-cs, replaced w/ 1" copper. Installed new cs & box, 1" corp. (3' West of old corp.) San. lateral is under the wm, runs w/ the service.	Installation Record	Y	5/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8621	919 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" copper on customer side. 5/11/22: Dug & removed lead wipe @ main& replaced w/ 3/4" copper. Connected to 3/4" copper 2.5' from the main.	Installation Record	Y	5/11/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8624	917 W ARLINGTON ST	N	C	Y	1"	5/10/2022	C	1"	5/10/2022	SF	UNK	C	1"	UNK	5/10/22: Removed lead from wm-cs, abandoned existing corp. Made new tap 3' West of old tap. Replaced lead w/ 1" copper, 1" cs & box, Connected to 3/4" copper 18" north of new cs.	Installation Record	Y	5/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8627	913 W ARLINGTON ST	UNK	C	Y	1"	8/11/2021	C	1"	8/11/2021	SF	UNK	C	1"	UNK	Mu Replaced Sewer from riser to terrace (6" PVC). Removed Lead from main to CS. New 1" tap w/ 1" CS & Box. Connected to existing 1" Copper on customers side.	Installation Record	Y	8/11/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8630	909 W ARLINGTON ST	N	C	Y	1"	5/10/2022	UNK	1"	5/10/2022	SF	UNK	UNK	1"	UNK	5/10/22; Removed lead from main-cs, replaced w/ 1" copper. Connected to 3/4" copper 12" North of cs. New 1" tap is located 3' West of the old corp. New box.	Installation Record	Y	5/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8633	903 W ARLINGTON ST	N	C	Y	1"	5/6/2022	C	1"	5/6/2022	SF	UNK	C	1"	UNK	5/6/22: Replaced lead w/ 1" tap, 1" copper and 1" cs & box. Connected to 3/4" copper service from house. New tap is 3' East of old tap	Installation Record	Y	5/6/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8636	813 W ARLINGTON ST	N	C	UNK	1"	5/3/2022	C	1"	5/3/2022	SF	UNK	C	1"	UNK	5/3/22: Retapped 1" - 1" copper to cs & box. Gaffney ran new 3/4" copper from cs to house.	Installation Record	Y	5/3/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8639	811 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/3/22: Removed 2' lead wipe @ main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	5/3/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8642	803 W ARLINGTON ST	N	C	Y	3/4"	4/12/1961	C	3/4"	4/12/1961	SF	UNK	C	3/4"	UNK	5/3/22: Removed 3' lead wipe @ main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	4/12/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8645	900 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	EARTH INC. JO#5344	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8648	812 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8651	806 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8654	810 W 8TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8657	812 W 8TH ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8660	900 W 8TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8663	902 W 8TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8666	906 W 8TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8669	910 W 8TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8672	914 W 8TH ST	N	C	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	SCHREINERS INC. 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 3/4" COPPER 8'3" DEEP	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8675	1002 W 8TH ST	UNK	C	Y	1"	5/3/2023	C	1"	5/3/2023	SF	UNK	C	1"	UNK	5/3/23: Removed lead, replaced w/ 1" copper, 1" tap (4' West of old corp.) Meyers replaced private lead w/ 1" copper, 1" cs & box.	Installation Record	Y	5/3/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8678	1008 W 8TH ST	N	L	UNK	1"	1/1/1959	C	1"	1/1/1959	SF	UNK	C	UNK	1/1/1959	<Null>	Installation Record	Y	2007	Mech excav	Field inspection only	Y	10/21/2014	Cross Connection Survey	Internal Notes
8681	803 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF ADAMS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8684	901 S ADAMS AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	4/29/2021- Removed 2' lead wipe and installed new copper and connected to existing copper. Found existing copper inside steel pipe	Installation Record	Y	4/29/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8687	907 S ADAMS AVE	N	UNK	UNK	UNK	1/1/2014	C	UNK	1/1/2014	SF	UNK	C	UNK	UNK	NEW 3/4" COPPER FROM CORP TO W SIDE OF STORM, REMOVED WIPE AT CORP, INSULATED W/ 2" STYROFOAM-2014	Installation Record	Y	1/1/2014	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8690	906 S ADAMS AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	4/29/21-Removed 2' lead wipe @ main and replaced with 3/4" copper to connect to existing copper & insualted.	Installation Record	Y	4/29/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8693	900 S ADAMS AVE	N	C	Y	3/4"	4/29/2021	C	3/4"	4/29/2021	SF	UNK	C	3/4"	UNK	4/29/2021-Removed lead wipe @ main and replaced with new copper from main to curb box and insulated.	Installation Record	Y	4/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8696	804 S ADAMS AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	4/28/21 - Removed lead wipe @ main, connected to 3/4" copper	Installation Record	Y	4/28/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8699	802 S ADAMS AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF 8TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8702	905 S DRAKE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	INSULATED 2 X 4 1981	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8705	902 S DRAKE AVE	N	L	UNK	UNK	1/1/1954	C	UNK	1/1/1954	SF	UNK	C	UNK	1/1/1954	2012-REMOVED LEAD WIPES AT CURB VALVE AND AT MAIN	SL repair/replace record	Y	2012	Mech excav	Field inspection only	Y	6/23/2015	Cross Connection Survey	
8708	900 S DRAKE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2017-CONFIRMED COPPER IN TERRACE VIA VAC XCAVATE	Installation Record	Y	1/1/2017	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8711	808 S DRAKE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	10-25-21: MU removed lead wipe that was leaking and replaced with copper. Installed Valve and box.	Installation Record	Y	10/25/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8714	805 S COLUMBUS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	OF NW CORNER OF GARAGE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8717	813 S COLUMBUS AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7'6" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8720	905 S COLUMBUS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8723	909 S COLUMBUS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8726	910 S COLUMBUS AVE	UNK	C	UNK	1"	8/10/2022	C	1"	8/10/2022	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	8/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8729	904 S COLUMBUS AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8732	1211 W 8TH ST	N	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8735	710 S DRAKE AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8738	718 S DRAKE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8741	1107 W 8TH ST	N	C	UNK	1"	1/1/1960	C	1"	1/1/1960	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8744	1101 W 8TH ST	N	C	UNK	5/8"	1/1/1961	C	5/8"	1/1/1961	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8747	1007 W 8TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8750	919 W 8TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF W 8TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8753	915 W 8TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8756	911 W 8TH ST	N	C	Y	3/4"	9/10/2024	C	3/4"	9/10/2024	SF	UNK	C	3/4"	UNK	Lead wipe removed at wm. 3/4" copper from main to private 3/4" copper service.	Installation Record	Y	9/10/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8759	909 W 8TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF W 8TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8762	905 W 8TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8765	901 W 8TH ST	N	C	Y	3/4"	5/15/2018	C	3/4"	5/15/2018	SF	UNK	C	3/4"	UNK	ALL LEAD REMOVED AND REPLACED WITH 3/4" COPPER AND NEW CURB STOP & BOX	Installation Record	Y	5/15/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8768	716 S HIGHLAND AVE	N	C	UNK	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	2018 - INSTALLED COPPER FROM MAIN TO CURB STOP/BOX	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8771	714 S HIGHLAND AVE	UNK	C	Y	1"	6/12/2023	C	1"	6/12/2023	SF	UNK	C	1"	UNK	6/12/23: Replaced lead w/ 1" copper from wm-cs. conn. to existing corp. w/ 3/4" copper @ the main. Conn. to existing copper after cs. Installed 1" cs & box.	Installation Record	Y	6/12/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8774	702 S HIGHLAND AVE	N	C	UNK	1"	6/1/2023	G	1"	6/1/2023	SF	UNK	G	UNK	6/1/2023	6/1/23: Replaced lead w/ 1" copper from wm-cs. Put in a short piece of 3/4" copper to used existing corp. Installed new 1" cs & box. Connected to galvanized after the cs.	SL repair/replace record	Y	6/1/2023	Visual insp during install or repair	Previous eval	Y	1/28/2015	Cross connection survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
8777	611 S HIGHLAND AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1981- LOWERED FROM MAIN TO CURB VALVE. 4' DEEP @ BOX. 3/23/2022 - JN verified 1/2" copper in the basement	Installation Record	Y	3/23/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8780	613 S HIGHLAND AVE	N	C	UNK	1"	5/31/2023	L	1"	5/31/2023	SF	UNK	L	UNK	5/31/2023	5/31/23: Replaced lead w/ 1" copper from wm-cs. Conn to existing 3/4" corp with 18" - 3/4" copper. Installed 1" cs & box. Conn. to lead after the cs.	SL repair/replace record	Y	5/31/2023	Visual insp during install or repair	Previous eval	Y	3/12/2015	Cross connection survey	
8783	701 S HIGHLAND AVE	UNK	C	Y	1"	5/31/2023	C	1"	5/31/2023	SF	UNK	C	1"	UNK	5/31/23: Replaced lead w/ 1" copper from wm-cs. Used existing corp, Installed new 1" cs & box. Conn. to existing 3/4" copper after cs.	Installation Record	Y	5/31/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8786	705 S HIGHLAND AVE	N	C	UNK	1"	6/1/2023	G	1"	6/1/2023	SF	UNK	G	UNK	6/1/2023	6/1/23: Removed lead from wm-cs w/ 1" copper. Used a short piece of 3/4" copper to conn. to existing corp. Installed new 1" cs & box, connected to existing galvanized at the back of sidewalk.	SL repair/replace record	Y	6/1/2023	Visual insp during install or repair	Previous eval	Y	2/13/2015	Cross connection survey	
8789	709 S HIGHLAND AVE	UNK	C	Y	1"	6/6/2023	C	1"	6/6/2023	SF	UNK	C	1"	UNK	6/6/23: Replaced lead from wm-cs, replaced w/ 1" copper and installed 1" cs & box. Connected to existing 3/4" copper after cs. Conn. to existing corp. using 18" - 3/4" copper @ wm.	Installation Record	Y	6/6/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8792	711 S HIGHLAND AVE	UNK	C	Y	1"	6/6/2023	C	1"	6/6/2023	SF	UNK	C	1"	UNK	6/6/23: Replaced lead from wm-cs, replaced w/ 1" copper and installed 1" cs & box. Connected to existing 1" copper after cs. Conn. to existing corp. using 18" - 3/4" copper @ wm.	Installation Record	Y	6/6/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8795	717 S HIGHLAND AVE	UNK	C	Y	3/4"	8/30/2018	C	3/4"	8/30/2018	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM WM - HOUSE, RIEGEL INSTALLED NEW CURB STOP & BOX	Installation Record	Y	8/30/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8798	807 W 8TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
8801	716 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- EARTH INC. 2019 - Meyers installed copper on customer side	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8804	712 S OAK AVE	N	C	UNK	1"	1/1/2003	L	1"	1/1/2003	SF	UNK	L	UNK	1/1/2003	2003- EARTH INC. CONNECTED TO 5/8" LEAD ON CUSTOMER SIDE	SL repair/replace record	Y	1/1/2003	Visual insp during install or repair	Previous eval	Y	2/2/2015	Cross connection survey	
8807	704 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8810	700 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003 EARTH INC. JO#5344	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8813	614 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8816	612 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8819	610 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8822	606 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8825	602 S OAK AVE	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/26/23: Verified 3/4" copper @ main and the terrace.	Installation Record	Y	7/26/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8828	605 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8831	609 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8834	709 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8837	713 S OAK AVE	UNK	C	Y	3/4"	6/20/2022	C	3/4"	6/20/2022	SF	UNK	C	3/4"	UNK	6/20/22: Removed lead from main to cs, replaced w/ 3/4" copper. Installed new 3/4" tap and 3/4" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8840	304 W PARK ST	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-INSTALLED NEW 3/4" COPPER FROM EXISTING CORP TO NEW CURB VALVE/BOX	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8843	308 W PARK ST	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO CURB VALVE/BOX INSTALLLED. 2022-CONFIRMED COPPER VIA GAFFNEY	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8846	402 W PARK ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8849	412 W PARK ST	N	C	UNK	3/4"	UNK	P	3/4"	UNK	SF	UNK	P	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO CURB VALVE \/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8852	502 W PARK ST	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	NONRES	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8855	516 W PARK ST	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8858	518 W PARK ST	UNK	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8861	509 W PARK ST	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013 NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8864	507 W PARK ST	N	C	UNK	3/4"	1/1/2013	P	3/4"	1/1/2013	SF	UNK	P	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8867	908 S PINE AVE	N	C	UNK	1"	5/10/2021	P	1"	5/10/2021	SF	UNK	P	1"	UNK	5/10/2021 - 1" copper from main-curb vavle, 1" PEX to house after curb valve. New 1" tap 3' North of old corp. (abandonded old corp. in place)	Installation Record	Y	5/10/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8870	417 W PARK ST	N	C	UNK	3/4"	1/1/2013	P	3/4"	1/1/2013	SF	UNK	P	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8873	413 W PARK ST	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLLED	Installation Record	Y	1/1/2013	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8879	311 W PARK ST	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8882	306 W MAGEE ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1/2" COPPER INSIDE. 5/19/22: Copper found @ main	Installation Record	Y	5/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8885	310 W MAGEE ST	N	C	Y	1"	5/19/2022	C	1"	5/19/2022	SF	UNK	C	1"	UNK	5/19/22: Removed lead from main-cs, replaced with new 1" tap, 1" copper and 1" cs & box. Connected to existing 3/4" copper on property side.	Installation Record	Y	5/19/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8888	804 S SPRUCE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		12" OF BOX CUT OFF BUT CAN TURN WITH PIPE WRENCH	Installation Record	N			Field Inspection Only	Y	4/1/2015	Cross Connection Survey	
8891	802 S SPRUCE AVE	N	C	Y	3/4"	1/1/2015	P	3/4"	1/1/2015	SF	UNK	P	3/4"	UNK	2015-3/4" PLASTIC PROP. SIDE. REMOVED LEAD WIPES AT CURB VALVE INSTALLING NEW VALVE/BOX. 5/15/2020 - Replaced lead w/ CU from main to CS	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8894	412 W MAGEE ST	N	C	Y	1"	5/24/2022	C	1"	5/24/2022	SF	UNK	C	1"	UNK	5/24/22: Removed lead from main-cs, replaced w/ 1" tap, 1" copper, 1" cs & box. Connected to existing 3/4" copper on property side	Installation Record	Y	5/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8897	414 W MAGEE ST	UNK	C	Y	1"	6/6/2022	C	1"	6/6/2022	SF	UNK	C	1"	UNK	6/6/2022: New 1" tap, removed Lead from main to cb, replaced with 1" copper. Used existing curb valve.	Installation Record	Y	6/6/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8900	416 W MAGEE ST	N	C	Y	1"	5/26/2022	UNK	1"	5/26/2022	SF	UNK	UNK	1"	UNK	5/26/22: Removed lead from main-cs, replaced w/ 1" tap, 1" copper, 1" box. Connected to existing 3/4" copper on utility side. Used existing cs.	Installation Record	Y	5/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8903	418 W MAGEE ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2007-REPAIRED LEAK @ CORP 3/4" 90 DEG. BRASS FITTING REPLACED. -6/14/22: dug and verified copper at main and terrace	Installation Record	Y	6/15/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8906	502 W MAGEE ST	N	C	Y	1"	5/26/2022	C	1"	5/26/2022	SF	UNK	C	1"	UNK	5/26/22: Removed lead from main-cs, replaced w/ 1" copper, 1" tap, 1" cs & box. Connected to exisitng copper on property side.	Installation Record	Y	5/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8909	506 W MAGEE ST	N	C	Y	3/4"	5/28/2021	C	3/4"	5/28/2021	SF	UNK	C	3/4"	UNK	Removed lead wipe and installed 3/4" copper to new curb box. Verified 3/4" copper on property side	Installation Record	Y	5/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8912	508 W MAGEE ST	N	C	Y	UNK	5/31/2022	C	UNK	5/31/2022	SF	UNK	C	UNK	UNK	5/31/2022: Removed lead from main-cs, replaced w/ 1" copper, 1" tap, 1" cs & box. Connected to exisitng copper on property side.	Installation Record	Y	5/31/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
8918	512 W MAGEE ST	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7' DEEP. 4/15/2021: Customer emailed picture of service in basement shows copper through floor by the meter.	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8921	518 W MAGEE ST	UNK	C	UNK	1"	1/1/2022	C	1"	1/1/2022	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8927	909 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8931	517 W MAGEE ST	UNK	C	UNK	1"	10/13/2021	C	1"	10/13/2021	SF	UNK	C	1"	UNK	10-13-2021 New 1" copper from main to meter. New curb valve & box. Old corp is 2' East of new corp. Mark Meyers installed private side.	Installation Record	Y	10/13/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8934	515 W MAGEE ST	UNK	C	Y	1"	6/3/2022	C	1"	6/3/2022	SF	UNK	C	1"	UNK	6/3/22: Removed lead from main to cs, replaced w/ 1" copper. Installed new 1" tap and 1" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/3/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8937	513 W MAGEE ST	UNK	C	Y	1"	6/1/2022	C	1"	6/1/2022	SF	UNK	C	1"	UNK	6/1/22: Removed lead from main to cs, replaced w/ 1" copper. Installed new 1" tap and 1" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8940	507 W MAGEE ST	N	C	UNK	3/4"	5/28/2021	C	3/4"	5/28/2021	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	5/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8943	504 W 8TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" COPPER LOCKING VALVE. 6/24/22: Lead wipe removed.	Installation Record	Y	6/24/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8946	506 W 8TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 6'7" DEEP. 6/24/22: Lead wipe removed @ main	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8949	508 W 8TH ST	Y	C	UNK	3/4"	11/13/1962	C	3/4"	11/13/1962	SF	UNK	C	3/4"	UNK	The old service, (iron inside broke under the footing and was shut off on 8-14--91. It is fine up to the cb. 41'N & 20'W of the NWCH. 6-22-2022: Verified copper at the main and ditch.	Installation Record	Y	11/13/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8952	512 W 8TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22/2022: removed lead from main to cs, replaced with 3/4" copper.	Installation Record	Y	6/22/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8955	509 W 8TH ST	UNK	C	Y	3/4"	6/20/2022	C	3/4"	6/20/2022	SF	UNK	C	3/4"	UNK	6/20/22: Removed lead from main to cs, replaced w/ 3/4" copper. Installed new 3/4" tap and 3/4" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8958	505 W 8TH ST	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/24/22: New 3/4" copper from main to cs & box. Connected to existing 3/4" copper on private side.	Installation Record	Y	6/24/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8961	501 W 8TH ST	N	C	Y	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM WM - HOUSE, NEW CURB STOP AND BOX. WORKED WITH REIGLE PLBG.	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8964	704 S PINE AVE	UNK	C	UNK	3/4"	6/29/2022	C	3/4"	6/29/2022	SF	UNK	C	3/4"	UNK	6/29/22: New 3/4" copper from main to curb valve. New 3/4" cs & box.	Installation Record	Y	6/29/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8967	700 S PINE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2022: Removed lead from main to cs, replaced w/ 3/4" copper. Used existing corp and installed new 3/4" cs & box. Connected to existing 3/4" copper on customers side.	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8970	506 W 7TH ST	UNK	C	Y	1"	6/20/2022	C	1"	6/20/2022	SF	UNK	C	1"	UNK	6/20/22: Removed lead from main to cs, replaced w/ 1" copper. Installed new 1" tap and 1" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8974	508 W 7TH ST	UNK	C	Y	1"	6/21/2022	C	1"	6/21/2022	SF	UNK	C	1"	UNK	6/21/22: Removed lead from main to cs, replaced w/ 1" copper. Installed new 1" tap and 1" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8977	509 W 7TH ST	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	1/29/2014	Cross Connection Survey	
8980	411 W 7TH ST	UNK	C	Y	1"	6/16/2022	C	1"	6/16/2022	SF	UNK	C	1"	UNK	6/16/22: Removed lead from main to cs, replaced w/ 1" copper. Installed new 1" tap and 1" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/16/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8983	409 W 7TH ST	UNK	C	Y	1"	6/9/2022	C	1"	6/9/2022	SF	UNK	C	1"	UNK	6/9/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8986	400 W 7TH ST	UNK	C	Y	1"	6/7/2022	C	1"	6/7/2022	SF	UNK	C	1"	UNK	6/7/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/7/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8990	408 W 7TH ST	UNK	C	Y	1"	6/14/2022	C	1"	6/14/2022	SF	UNK	C	1"	UNK	6/14/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/14/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8993	709 S PINE AVE	N	C	Y	3/4"	9/26/2017	C	3/4"	9/26/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD AND INSTALLED NEW 3/4" COPPER FROM MAIN TO NEW C.B.--2017	Installation Record	Y	9/26/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
8996	711 S PINE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/29/22: New 3/4" copper from main to cs, new 3/4" cs & box. Copper on customers side	Installation Record	Y	6/29/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
8999	413 W MAGEE ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2022-Replaced lead w/ copper from wm-house	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9002	313 W MAGEE ST	N	C	UNK	1"	5/20/2022	C	1"	5/20/2022	SF	UNK	C	1"	UNK	5/20/22: New 1" tap, new 1" cs & box. Connected to existing 3/4" copper on customers side	Installation Record	Y	5/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9005	309 W MAGEE ST	N	C	Y	1"	5/24/2022	C	1"	5/24/2022	SF	UNK	C	1"	UNK	5/24/22: Abandoned original galvanized/lead service on 7th, retapped on Magee. Installed 1" tap, 1" copper, 1" cs & box. Meyers installed 1" copper on property side.	Installation Record	Y	5/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9007	610 S CHESTNUT AVE	UNK	C	UNK	2"	1/1/2013	C	2"	1/1/2013	NONRES	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9009	610 S CHESTNUT AVENUE	UNK	C	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	NONRES	UNK	C	3/4"	UNK	2000: NEW UP TO BUILDING.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9012	606 S WALNUT AVE	UNK	DI	UNK	4"	1/1/2012	P	4"	1/1/2012	NONRES	UNK	P	4"	UNK	SERVICE COMES OFF 7TH ST. CURB BOX IS IN STREET. 6" TEE WITH 4" REDUCER OUT OF TEE.	Installation Record	Y	1/1/2012	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
9017	506 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/2/2015	Cross Connection Survey	
9020	510 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		MAIN 15' TO THE SOUTH	Installation Record	N			Field Inspection Only	Y	5/1/2015	Cross Connection Survey	
9023	509 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		CB LOCATION VERIFIED 6/6/97	Installation Record	N			Field Inspection Only	Y	9/17/2015	Cross Connection Survey	
9026	503 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1931	C	UNK	1/1/1931	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/28/2015	Cross Connection Survey	
9029	501 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/23/2015	Cross Connection Survey	
9032	403 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	UNK-LG	UNK	1/1/1926	SF	UNK	UNK	UNK		<Null>	Installation Record	N			Field Inspection Only	Y	4/10/2015	Cross Connection Survey	
9035	309 W 6TH ST	UNK	C	UNK	3/4"	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2000: CURB BOX INSTALLED. 2024: Vac'd at the curb, found 3/4" copper.	Field inspection only	Y	1/1/2024	Mech excav	Field Inspection Only	Y	3/30/2015	Cross Connection Survey	
9038	307 W 6TH ST	UNK	C	UNK	3/4"	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		1/2" COPPER INSIDE. CURB BOX INSTALLED SEPT. 2000. 2024: Vac'd at the curb, found 3/4" copper.	Field inspection only	Y	1/1/2024	Mech excav	Field Inspection Only	Y	9/2/2015	Cross Connection Survey	
9045	208 W 5TH ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	JIM JAKEL PLBG.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9060	504 S CHESTNUT AVE	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	VALVE ATTACHED TO EXISTING 1" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9063	114 W 5TH ST	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	CONNECTED TO EXISTING 1" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9066	112 W 5TH ST	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	CONNECTED TO EXISTING 3/4" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9070	114 W 4TH ST	N	C	UNK	1"	1/1/2013	C	1"	1/1/2013	SF	UNK	C	1"	UNK	CONNECTED TO 1/2" COPPER, 1/2" INSIDE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9073	112 W 4TH ST	N	C	UNK	1"	1/1/2013	C	1"	1/1/2013	SF	UNK	C	1"	UNK	ATTACHED TO 1/2" COPPER 13'S OF VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9076	110 W 4TH ST	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	ATTACHED TO 3/4" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9083	600 W 5TH ST	UNK	UNK	Y	2"	1/1/1987	C	2"	1/1/1987	NONRES	UNK	C	2"	UNK	2" LEAD & 4-1" CORPS REPLACED WITH 2" COPPER 12-30-97	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9086	800 W 6TH ST	N	C	Y	1"	7/19/2023	C	3/4"	1/1/1926	SF	UNK	C	C		7/19/23: Lead removed. 1" tap, 1" copper from main to 3/4" service (private). 1" cs & box	Installation Record	Y	7/19/2023	Visual insp during install or repair	Field Inspection Only	Y	12/9/2014	Cross Connection Survey	
9089	808 W 6TH ST	UNK	C	Y	1"	7/17/2023	C	1"	7/17/2023	SF	UNK	C	1"	UNK	7/17/23: Lead removed. 1" tap, 1" copper from main to 1/2" copper (slipped through galvanized) private service. 1" CS & Box. 5/28/24: Reigle replaced 1/2" copper w/ 3/4" copper from curb valve to meter.	Installation Record	Y	7/17/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
9092	906 W 6TH ST	N	C	UNK	1"	6/23/2023	L	1"	6/23/2023	SF	UNK	L	UNK	6/23/2023	6/23/23: Removed lead wm-cs and replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to 5/8" lead at the sidewalk. Used 1"x3/4" cu-cu then 3/4"x5/8" lead-cu after the cs.	SL repair/replace record	Y	6/23/2023	Visual insp during install or repair	Previous eval	Y	3/24/2016	Cross connection survey	
9095	910 W 6TH ST	N	C	Y	3/4"	5/7/2019	C	3/4"	5/7/2019	SF	UNK	C	3/4"	UNK	REMOVED ALL IRON AND LEAD, INSTALLED COPPER FROM WM - HSE & NEW CS & BOX WITH REIGEL PLBG.	Installation Record	Y	5/7/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9098	912 W 6TH ST	N	C	UNK	3/4"	5/6/2019	C	3/4"	5/6/2019	SF	UNK	C	3/4"	UNK	New 3/4" Copper Service, 05/06/2019 from main to house	Installation Record	Y	5/6/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9101	918 W 6TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	6/22/23: Removed lead wipe @ wm replaced w/ 3/4" copper. Conn to existing copper. Used existing corp.	Installation Record	Y	6/22/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9104	1000 W 6TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	RE-TAPPED & INSULATED 1983. CUT IN CURB BOX 5-4-99 MEYER	Installation Record	Y	5/4/1999	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9107	1006 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	RETAPPED & INSULATED 1983 PAVING	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9110	1010 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	RETAPPED & INSULATED 1983 PAVING	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9113	701 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9116	921 MARTIN DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9119	917 MARTIN DR	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1966	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9122	911 MARTIN DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9125	909 MARTIN DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9128	905 MARTIN DR	N	C	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	1-1-2020 J&R VACUUM EXCAVATED AT CB, FOUND COPPER 7'1" DEEP	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9131	903 MARTIN DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9134	901 MARTIN DR	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1969	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9137	900 MARTIN DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9140	902 MARTIN DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9143	904 MARTIN DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9146	906 MARTIN DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9149	908 MARTIN DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9152	910 MARTIN DR	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9155	1006 GEORGE DR	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9158	708 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9161	709 S DRAKE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9164	700 S DRAKE AVE	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9167	1110 W 7TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 7TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9170	1111 W 7TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 7TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9173	1107 W 7TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9176	1101 W 7TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9179	600 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1983-LOWERED & INSULATED. 2003- CURB VALVE & BOX INSTALLED	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9182	1112 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF DRAKE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9185	610 S DRAKE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9188	1200 W 6TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9191	1208 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9194	1205 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/27/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9197	1204 W 5TH ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 6/13/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9197	1204 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1963	UNK	3/4"	1/1/1963	SF	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9200	514 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SER LEAK 1/84 BOX IS NOW IN TERRACE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9203	1015 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9207	512 S HARDACRE AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		CB LOCATION VERIFED 12/5/97	Installation Record	N			Field Inspection Only	Y	11/19/2014	Cross Connection Survey	
9210	915 W 6TH ST	N	C	Y	1"	1/1/2019	C	1"	1/1/2019	SF	UNK	C	1"	UNK	LEAD LINE REPLACEMENT MAIN TO HOUSE 2019	Installation Record	Y	1/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9213	911 W 6TH ST	N	C	Y	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	INSULATED 1983 PAVING. 6/22/23: Removed 1" lead gooseneck @ wm, replaced w/ 1" copper, conn. to 1" copper @ the curb. Installed new 1" corp. 2' West of old corp.	Installation Record	Y	6/22/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9216	903 W 6TH ST	Y	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	2023- Dug and verified 1" copper in the street	Installation Record	Y	1/1/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9219	511 S WISCONSIN AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	06/23: Dug at the water main found 3/4" copper	Installation Record	Y	6/1/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9223	805 W 6TH ST	N	C	UNK	3/4"	5/13/2019	C	3/4"	5/13/2019	SF	UNK	C	3/4"	UNK	REIGEL PLBG. INSTALLED 3/4" COPPER W/ CS & BOX - MU INSTALLED NEW 3/4" COPPER FROM WM - CS. 6" PVC SAN. LAT. 1' EAST OF WATER SERVICE ON WM	Installation Record	Y	5/13/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9226	801 W 6TH ST	N	C	Y	3/4"	11/16/2017	P	3/4"	11/16/2017	SF	UNK	P	3/4"	UNK	REMOVED LEAD & INSTALLED NEW COPPER MAIN TO C.B./C.V., PLASTIC ON PROP SIDE, INSULATE TO SIDEWALK--2017	Installation Record	Y	11/16/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9229	906 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS. 2019 - INSIDE REPLACED TO HOUSE 1"	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9232	910 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS: ATTACHED TO 1" PLASTIC	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9235	1000 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS. CONNECTED TO 1" PLASTIC	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9235	1000 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS: ATTACHED TO 1" PLASTIC	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9238	1010 W 5TH ST	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	O	UNK	P	1"	UNK	HAAS: ATTACHED TO 1" PLASTIC	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9241	1100 W 5TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 5TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9244	1110 W 5TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/13/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9247	1005 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS 1" PLASTIC INSIDE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9254	915 W 5TH ST	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9257	907 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS: ATTACHED TO 1" PLASTIC 4' PAST CURB VALVE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9260	903 W 5TH ST	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS ATTACHED TO 1" PLASTIC 15' PAST CURB VALVE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9263	815 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	5-21-2020 REIGEL PLBG INSTALLED NEW 1" COPPER FROM 4' NORTH OF SIDEWALK TO METER	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9268	813 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9270	803 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS 1" PLASTIC	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9273	709 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS 1" PLASTIC INSIDE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9277	705 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS. 1" HDPE on property side	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9280	703 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9282	613 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS. 1" HDPE on property side	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9285	503 W 5TH ST	N	C	Y	1"	UNK	C	1"	9/26/2022	SF	UNK	C	1"	UNK	9/26/22: Removed all lead, 6' piece of 3/4" copper @ main then switches to 1" copper all the way to cs & box, 1" copper customer side too (Meyers)	Installation Record	Y	9/26/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9289	501 W 5TH ST	UNK	C	Y	1"	6/9/2023	C	1"	6/9/2023	NONRES	UNK	C	1"	UNK	6/9/23: Replaced lead w/ 1" copper from wm-cs. Connected to existing corp. w/ 3' - 3/4" copper. Meyers replaced lead w/ 1" copper from cs-meter and installed a 1" cs & box	Installation Record	Y	6/9/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9293	411 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB LOCATION VERIFIED 12/04/97	Installation Record	N			Field Inspection Only	Y	1/14/2015	Cross Connection Survey	
9296	409 W 5TH ST	N	C	UNK	1"	4/29/2022	C	1"	4/29/2022	SF	UNK	C	1"	UNK	4/29/22: Installed new 1" corp & 1" copper with a 1"cs, 1" copper from main to cs. Hooked up to new 3/4" copper on homeowners side. Old corp is 4' East of the new corp.	Installation Record	Y	4/29/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9300	405 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB LOCATION VERIFIED 3/25/97	Installation Record	N			Field Inspection Only	Y	12/17/2014	Cross Connection Survey	
9303	401 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	1/28/2017	Cross Connection Survey	
9312	307 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/8/2014	Cross Connection Survey	
9315	214 W 5TH ST SUITE A	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	NONRES	UNK	C	1"	UNK	NEW COPPER; MAIN TO CURB BOX.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
9321	503 S WALNUT AVE	N	C	Y	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	2000-NEW COPPER FROM MAIN TO 5' PAST SIDEWALK. 4/27/21 - Replaced lead on customers side with 3/4" copper into house	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9327	504 S WALNUT AVE	N	C	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	NEW COPPER FROM MAIN, 5' PAST SIDEWALK. 10-21-2022: Verified 1/2" Copper inside.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9330	306 W 5TH ST	N	C	Y	1"	3/29/2022	C	1"	3/29/2022	SF	UNK	C	1"	UNK	3/29/2022: Leaked at the back of curb. Dug and replaced lead from wm-sidewalk. Replaced w/ 1" copper, 1" cs & box. Connected to 3/4" copper at the sidewalk. Re-tapped 18" West of existing tap. abandoned old tap in place.	Installation Record	Y	3/29/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9334	310 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	11/26/2014	Cross Connection Survey	
9337	500 S SPRUCE AVE	N	C	UNK	UNK	UNK	UNK	UNK	UNK	SF	UNK	UNK	UNK	UNK	NEW COPPER FROM MAIN TO CURB BOX 9-98	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9343	404 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	12/17/2014	Cross Connection Survey	
9346	502 W 5TH ST	N	C	UNK	1"	1/1/2022	C	1"	1/1/2022	SF	UNK	C	1"	UNK	2022: Connected to existing corp., installed 1' - 3/4" copper then ran 1" copper to rest of the way to the house with Meyers.	Installation Record	Y	1/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9349	504 W 5TH ST	Y	L	UNK	5/8"	UNK	L	5/8"	UNK	SF	UNK	L	5/8"	UNK	NEW INSIDE VALVE 3/94	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9352	506 W 5TH ST	UNK	C	Y	1"	6/8/2023	C	1"	6/8/2023	SF	UNK	C	1"	UNK	6/8/23: Removed lead from wm-cs, replaced w/ 1" copper, 1" cs & box. Conn to existing 3/4" copper after cs. Conn to existing corp with 18" - 3/4" copper.	Installation Record	Y	6/8/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9355	510 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/23/2015	Cross Connection Survey	
9358	514 W 5TH ST	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9361	409 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2020-VERIFIED 1/2" COPPER INSIDE. 2003- EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9361	409 S OAK AVE	UNK	C	UNK	1 1/2"	1/1/2003	UNK	1 1/2"	1/1/2003	SF	UNK	UNK	1 1/2"	UNK	SERVICE FOR 406 & 409	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9364	512 W 4TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CURB STOP & BOX INSTALLED 1998	Installation Record	Y	1/1/1998	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9367	510 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/10/2024	Cross Connection Survey	
9370	506 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	10/28/2014	Cross Connection Survey	
9373	504 W 4TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9376	500 W 4TH ST	N	C	Y	3/4"	UNK	C	3/4"	3/1/1978	SF	UNK	C	3/4"	UNK	3/78 - Replaced lead line in road w/ 3/4" copper. 10/1/2020 - Removed 2' of lead on utility side w/ 3/4" copper, Meyers Plbg. Replaced lead on customer side w/ 3/4" copper. New C.S. & Box installed. San. Lat. replaced at same time	Installation Record	Y	10/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9379	414 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2005-INSTALLED CURB VALVE W/ BOX	Installation Record	N			Field Inspection Only	Y	3/3/2014	Cross Connection Survey	
9382	412 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		INSTALLED CURB STOP/BOX-2012	Installation Record	N			Field Inspection Only	Y	10/15/2014	Cross Connection Survey	
9385	410 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	2/6/2015	Cross Connection Survey	
9388	408 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER & LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	12/4/2014	Cross Connection Survey	
9391	312 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	1/5/2015	Cross Connection Survey	
9394	310 W 4TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2002: NEW 3/4 COPPER FROM MAIN TO CURB-	Installation Record	Y	1/1/2002	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9397	404 S WALNUT AVE	UNK	C	UNK	3/4"	UNK	C	3/4"	1/1/2022	SF	UNK	C	3/4"	UNK	2022: New 3/4" copper from main to curb valve, used existing corp. 3/4" copper from curb valve to meter (Meyers 2022). 2023: Leak MU side of cs, replaced 3/4" cs w/ new 3/4" cs & conn to existing 3/4" copper 18" West of cs.	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9400	400 S CHESTNUT AVE	UNK	C	UNK	1 1/2"	1/1/1970	C	1 1/2"	1/1/1970	NONRES	UNK	C	1 1/2"	UNK	3-1" TAPS; 2007-INSULATED FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9403	608 W 4TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/1/23: Removed lead wipe @ wm. Connected to 3/4" copper.	Installation Record	Y	5/1/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9406	700 W 4TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE AT MAIN. 5/1/23: Dug @ watermain and verified 3/4" copper @ water main.	Installation Record	Y	5/1/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9409	704 W 4TH ST	Y	C	Y	3/4"	5/1/2023	C	3/4"	5/1/2023	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN. 5/23: Removed Lead gooseneck @ wm. Replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	5/1/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9412	706 W 4TH ST	UNK	C	Y	1"	5/11/2023	C	1"	5/11/2023	SF	UNK	C	1"	UNK	5/11/23: Removed lead from wm-cs and replaced w/ 1" copper. Installed new 1" copper, 1" cs & box. Connected to exisitng 3/4" copper after cs.	Installation Record	Y	5/11/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9415	710 W 4TH ST	N	C	Y	3/4"	10/17/2020	C	3/4"	10/17/2020	SF	UNK	C	3/4"	UNK	1/25/2020 - Meyers replace Lead on Customer side and installed new CB. 10/17/2020 - MU replaced lead on street side with 3/4" copper.	Installation Record	Y	10/17/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9418	712 W 4TH ST	UNK	C	Y	1"	5/15/2023	C	1"	5/15/2023	SF	UNK	C	1"	UNK	5/15/23: Removed lead from wm-cs. Installed 1" tap, 1" copper, 1" cs & box. Connected to 3/4" copper on private side.	Installation Record	Y	5/15/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9421	714 W 4TH ST	UNK	C	Y	1"	5/16/2023	C	1"	5/16/2023	SF	UNK	C	1"	UNK	5/16/23: Removed lead from wm-cs. 1" tap, 1" copper, 1" cs & box. Conn. to 3/4" copper on private side.	Installation Record	Y	5/16/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9424	802 W 4TH ST	UNK	C	Y	1"	5/18/2023	C	1"	5/18/2023	SF	UNK	C	1"	UNK	5/18/23: Removed lead from wm-cs. Installed 1" tap, 1" copper, 1" cs & box. Connected to Lead on private side.	Installation Record	Y	5/18/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9427	810 W 4TH ST	UNK	C	UNK	1"	5/23/2023	C	1"	5/23/2023	SF	UNK	C	1"	UNK	5/23/23: New 1" tap, 1" copper from main to private service (galvanized). 6/19/23: Reigle replaced gal. service w/ 1" copper (cs-meter) Plgb. permit #20230915	Installation Record	Y	5/23/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9430	814 W 4TH ST	N	C	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	5/23/2024: Dug and found 3/4" copper at the water main.	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9433	914 W 4TH ST	N	C	UNK	3/4"	1/1/1995	C	3/4"	1/1/1995	SF	UNK	C	3/4"	UNK	RE-TAPPED W/ 3/4" CORP, LOWERED W/ NEW 3/4" COPPER TO BACK OF CURB. INSULATED AT MAIN 1995	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9436	1008 W 4TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LOWERED SERVICE FROM MAIN TO CENTER OF ROAD. INSULATED AT MAIN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9439	401 S ADAMS AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9442	1009 W 4TH ST	UNK	UNK	UNK	1"	5/25/2023	C	1"	5/25/2023	SF	UNK	C	1"	UNK	1" Copper from main to 3/4" copper private service. 1" cs & box installed. Repair clamp w/ 1" CC	Installation Record	Y	5/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9445	1005 W 4TH ST	UNK	C	Y	1"	5/25/2023	C	1"	5/25/2023	SF	UNK	C	1"	UNK	5/25/2023: Remved Lead (wm-cs). 1" tap, 1" copper from main to 3/4" copper private service. 1" cs & box	Installation Record	Y	5/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9448	901 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	P	UNK	1/1/1926	SF	UNK	P	P		CB LOCATION VERIFIED 8/5/97	Installation Record	N			Field Inspection Only	Y	12/2/2014	Visual insp at meter	
9451	310 S WISCONSIN AVE	UNK	UNK-LG	UNK	UNK	1/1/1939	C	UNK	1/1/1939	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/5/2014	Cross Connection Survey	
9454	306 S WISCONSIN AVE	N	C	Y	3/4"	8/20/2020	C	3/4"	8/20/2020	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD. 8/20/2020 - REMOVED ALL LEAD ON STREET SIDE REPLACED W/ 3/4" COPPER. MEYERS REMOVED GALVANIZED ON CUSTOMER SIDE REPLACED W/ 3/4" COPPER. INSTALLED NEW C.S. & BOX	Installation Record	Y	8/20/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9457	302 S WISCONSIN AVE	N	C	Y	3/4"	4/1/2020	C	3/4"	4/1/2020	SF	UNK	C	3/4"	UNK	4/2020 - Removed lead on utility side & replaced w/ 3/4" copper, galvanized on customer side replaced w/ 3/4" copper	Installation Record	Y	4/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9460	216 S WISCONSIN AVE	N	C	UNK	3/4"	1/1/2020	C	3/4"	1/1/2020	SF	UNK	C	3/4"	UNK	2020 - Installed 3/4" copper from main to home	Installation Record	Y	1/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9462	214 S WISCONSIN AVE	UNK	UNK-LG	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/26/2014	Cross Connection Survey	
9465	208 S WISCONSIN AVE	N	C	Y	3/4"	1/1/2014	C	3/4"	1/1/2014	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN, 3/4" COPPER FROM MAIN TO HOUSE-2014	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
9468	204 S WISCONSIN AVE	N	C	Y	3/4"	5/15/2020	C	3/4"	5/15/2020	SF	UNK	C	3/4"	UNK	5/15/2020 REMOVED ALL LEAD PROPERTY SIDE AND STREET SIDE. REPLACED WITH COPPER BOTH SIDES (MEYRES)	Installation Record	Y	5/15/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9471	200 S WISCONSIN AVE	UNK	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	2009-CB VERIFIED	Installation record	N		Visual insp during install or repair	Previous eval	Y	10/14/2014	Cross connection survey	
9474	910 W ADLER RD	N	UNK	UNK	UNK	1/1/1964	C	UNK	1/1/1964	SF	UNK	C	UNK	UNK	<Null>	Installation Record	N	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9477	207 WESTVIEW DR	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	916 ADLER RD - SERVICE RUNS THROUGH 910 ADLER. ADLER'S PROPERTY. Serves 207 Westview Dr.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9480	1007 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9483	1017 W ADLER RD	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9486	1003 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9489	915 W ADLER RD	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2014-NEW CURB STOP/BOX. REMOVED LEAD WIPE @ MAIN. CONNECTED TO 3/4" COPPER ON CUSTOMER'S SIDE.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9495	907 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9498	905 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9504	809 W ADLER RD	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 6'10" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9507	805 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9510	803 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF ADLER RD	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9513	719 W ADLER RD	N	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	MEWD/REPLACED CORP TO CURB BOX	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9516	707 W ADLER RD	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	MEWD/REPLACED CORP TO CURB STOP	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9519	701 W ADLER RD	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/5/2014	Cross Connection Survey	
9524	800 W ADLER RD	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" COPPER LOCKING VALVE	Installation Record	Y	9/22/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9527	808 W ADLER RD	N	C	Y	3/4"	10/4/2017	C	3/4"	10/4/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD AND INSTALLED NEW 3/4" COPPER FROM MAIN TO C.V./C.B.--2017	Installation Record	Y	10/4/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9530	207 S WISCONSIN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9533	213 S WISCONSIN AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	9/22: 3/4" copper from main to house w/ new cs & box (Meyers)	Installation Record	Y	9/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9536	217 S WISCONSIN AVE	N	C	Y	3/4"	5/8/2020	C	3/4"	5/8/2020	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN & INSTALLED 12' OF 3/4" COPPER-2014. 5/8/2020 - Removed all lead & replaced with 3/4" copper from main to cs	Installation Record	Y	5/8/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9539	301 S WISCONSIN AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	11/19/2014	Cross Connection Survey	
9542	313 S WISCONSIN AVE	N	L	UNK	UNK	1/1/1945	C	UNK	1/1/1945	SF	UNK	C	UNK	1/1/1945	2013-NEW 3/4" COPPER SERVICE & CURB BOX/VALVE. 5/8 LEAD OUR SIDE.2014-REMOVED LEAD WIPE @ MAIN & INSTALLED 13' OF 3/4" COPPER.CONNECTED TO 5/8" LEAD AT WEST SIDE OF DITCH.	SL repair/replace record	Y	2013	Mech excav	Field inspection only	Y	10/29/2014	Cross Connection Survey	
9545	815 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1939	C	UNK	1/1/1939	SF	UNK	C	C		2002: MEYERS CUT-IN CURB BOX	Installation Record	N			Field Inspection Only	Y	10/30/2014	Cross Connection Survey	
9548	314 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1940	C	UNK	1/1/1940	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/26/2014	Cross Connection Survey	
9551	312 S STATE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9554	308 S STATE AVE	N	C	Y	3/4"	5/2/2018	C	3/4"	5/2/2018	SF	UNK	C	3/4"	UNK	CUSTOMER REPLACE LEAD SERVICE, NEW CURB STOP WITH COPPER, GAFFNEY PLBG, 7' DEPTH TOP OF WM	Installation Record	Y	5/2/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9557	304 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1942	C	UNK	1/1/1942	SF	UNK	C	C		3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	11/6/2014	Cross Connection Survey	
9560	302 S STATE AVE	N	L	UNK	UNK	1/1/1937	C	UNK	1/1/1937	SF	UNK	C	UNK	1/1/1937	2009-NEW 1" CURB STOP & BOX. 1" COPPER TO INSIDE. REMOVED LEAD WIPES @ CURB STOP.	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	11/4/2014	Cross Connection Survey	
9563	300 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/22/2014	Cross Connection Survey	
9566	214 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1937	C	UNK	1/1/1937	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/6/2014	Cross Connection Survey	
9569	212 S STATE AVE	N	C	UNK	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	NEW COPPER FROM MAIN TO HOUSE 7-20-2018	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9572	210 S STATE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
9575	205 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		REMOVED LEAD WIPES @ MAIN & 12' OF LEAD PIPE-2014	Installation Record	N			Field Inspection Only	Y	4/25/2016	Cross Connection Survey	
9578	207 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1939	C	UNK	1/1/1939	SF	UNK	C	C		2014-REMOVED LEAD WIPE @ MAIN	Installation Record	N			Field Inspection Only	Y	11/11/2014	Cross Connection Survey	
9581	213 S STATE AVE	Y	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN; REMOVED LEAD WIPE @ MAIN & 10' OF LEAD PIPE-2014	Installation Record	Y	1/1/2014	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9584	215 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1935	C	UNK	1/1/1935	SF	UNK	C	C		REMOVED LEAD WIPE IN ROAD TO CL-2014	Installation Record	N			Field Inspection Only	Y	6/9/2015	Cross Connection Survey	
9587	301 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/31/2014	Cross Connection Survey	
9590	305 S STATE AVE	N	L	UNK	UNK	1/1/1945	C	UNK	1/1/1945	SF	UNK	C	UNK	1/1/1945	2009-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	9/17/2014	Cross Connection Survey	
9593	309 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		1981-DUG AND LOWERED	Installation Record	N			Field Inspection Only	Y	11/24/2014	Cross Connection Survey	
9596	315 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/31/2014	Cross Connection Survey	
9599	715 W 4TH ST	UNK	C	Y	1"	5/16/2023	C	1"	5/16/2023	SF	UNK	C	1"	UNK	2016: Repaired leak 10' South of house w/ cs. 5/16/23:Replaced lead from wm-cs. 1" tap, 1" copper, 1" cs & box. Conn. to 3/4" copper on private side.	Installation Record	Y	5/16/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9602	711 W 4TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN. 5/15/23: Dug at water main and removed lead wipe. replaced w/ 3/4" copper (connected to 3/4" copper)	Installation Record	Y	5/15/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9605	709 W 4TH ST	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 5'6" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9608	701 W 4TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE ID OFF OF CONCORD. 5/4/23: Removed lead wipe @ wm, replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	5/4/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9611	318 S CONCORD AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 6'4"' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9614	316 S CONCORD AVE	UNK	C	Y	3/4"	5/3/2023	C	3/4"	5/3/2023	SF	UNK	C	3/4"	UNK	5/3/23: Removed lead wipe @ wm, replaced w/ 3/4" copper from wm-cs. Used existing corp. Installed new 3/4" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	5/3/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9617	308 S CONCORD AVE	UNK	C	Y	1"	4/28/2023	C	1"	4/28/2023	SF	UNK	C	1"	UNK	4/28/23: Removed lead from wm-cs, replaced w/ 1" copper. Installed new 1" tap, 1" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	4/28/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9620	306 S CONCORD AVE	UNK	C	Y	1"	4/27/2023	C	1"	4/27/2023	SF	UNK	C	1"	UNK	4/27/23: Removed lead from wm-cs, replaced w/ 1" copper. Installed new 1" tap, 1" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	4/27/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9623	214 S CONCORD AVE	N	C	UNK	1"	1/1/2009	P	1"	1/1/2009	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9626	210 S CONCORD AVE	UNK	C	Y	1"	4/24/2023	C	1"	4/24/2023	SF	UNK	C	1"	UNK	5/2/23: Removed lead wipe, replaced w/ 1" copper. Installed new 1" tap, 1" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	4/24/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9629	215 S CONCORD AVE	UNK	C	UNK	1"	4/25/2023	C	1"	4/25/2023	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	4/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9632	301 S CONCORD AVE	UNK	C	Y	1"	4/27/2023	C	1"	4/27/2023	SF	UNK	C	1"	UNK	4/27/23: Removed lead from wm-cs, replaced w/ 1" copper. Installed new 1" tap, 1" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	4/27/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9635	305 S CONCORD AVE	Y	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REPLACED 20' EAST FROM MAIN WITH COPPER	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9638	307 S CONCORD AVE	N	C	UNK	3/4"	10/2/2018	C	3/4"	10/2/2018	SF	UNK	C	3/4"	UNK	25' OF COPPER FROM CORP TO CURB VAVLE	Installation Record	Y	10/2/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9641	309 S CONCORD AVE	UNK	C	UNK	1"	4/28/2023	C	1"	4/28/2023	SF	UNK	C	1"	UNK	4/28/23: Dug and Verified 1" copper from wm-sw. Installed 1" cs & box. Verified 1" copper on customer side.	Installation Record	Y	4/28/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
9644	313 S CONCORD AVE	UNK	C	Y	1"	5/2/2023	C	1"	5/2/2023	SF	UNK	C	1"	UNK	5/2/23: Removed lead from wm-cs, replaced w/ 1" copper. Installed new 1" tap, 1" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	5/2/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9647	319 S CONCORD AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/4/23: Removed lead wipe @ wm, replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	5/4/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9650	323 S CONCORD AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/4/23: Removed lead wipe @ wm, replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	5/4/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9653	603 W 4TH ST	N	C	Y	1"	9/1/2020	C	1"	9/1/2020	SF	UNK	C	1"	UNK	TAKEN OFF & WHEEL VALVE PUT ON 2-76. 9-2020 REMOVED LEAD FROM MAIN TO HOUSE WITH MEYERS, RETAPPED & INSTALLED 1" COPPER. LOWERD MAIN FOR SAN. LATERAL	Installation Record	Y	9/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9657	300 S OAK AVE	UNK	DI	UNK	6"	8/4/2020	P	6"	8/4/2020	NONRES	UNK	P	6"	UNK	6' OF DIP ON UTILITES SIDE - C900 ON CUSTOMERS SIDE (REIGELS)	Installation Record	Y	8/4/2020	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
9664	315 W 4TH ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	9/24/2014	Cross connection survey	
9667	307 W 4TH ST	N	C	Y	3/4"	1/1/2002	C	3/4"	1/1/2002	SF	UNK	C	3/4"	UNK	REPLACED COPPER FROM MAIN TO CURB,LEAD INSIDE-8-20-02	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9670	308 S WALNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		4'X8' INSULATION, 2015-CURB VALVE/BOX INSTALLED. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	5/12/2015	Cross Connection Survey	
9675	300 S WALNUT AVENUE	N	C	UNK	1 1/4"	1/1/1999	C	1 1/4"	1/1/1999	NONRES	UNK	C	1 1/4"	UNK	<Null>	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9678	215 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		CB/LV UNKNOWN. 4' X 30' INSULATION	Installation Record	N			Field Inspection Only	Y	6/22/2015	Cross Connection Survey	
9681	211 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2000: NEW CURB BOX.	Installation Record	N			Field Inspection Only	Y	3/17/2016	Cross Connection Survey	
9684	201 W 4TH ST	N	C	UNK	1"	1/1/2013	C	1"	1/1/2013	SF	UNK	C	1"	UNK	SERVICE COMES OF CHESTNUT. ATTACHED TO 1" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9687	306 S CHESTNUT AVE	N	C	UNK	1"	1/1/2013	C	1"	1/1/2013	SF	UNK	C	1"	UNK	ATTACHED TO 1/2" COPPER 5' W OF VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9690	200 W 3RD ST	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	ATTACHED TO 1" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9693	212 W 3RD ST	N	L	UNK	1"	1/1/1926	C	1"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2005-REMOVED LEAD WIPE @ CURB VALVE, INSTALLED NEW VALVE AND BOX	SL repair/replace record	Y	2005	Mech excav	Field inspection only	Y	9/4/2014	Cross Connection Survey	
9696	215 W 3RD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	10/10/2014	Cross Connection Survey	
9699	211 W 3RD ST	N	C	Y	1"	9/23/2021	C	1"	9/23/2021	SF	UNK	C	1"	UNK	CB VERIFIED 3-97. 9/23/21: Meyers worked w/ MU to replace lead w/ 1" Copper from wm- house. MU installed a 6" sleeve w/ a 1" C.C. Plbg. Permit 202111312	Installation Record	Y	9/23/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9703	208 S CHESTNUT AVE	N	P	UNK	2"	7/15/2022	C	2"	7/15/2022	NONRES	UNK	C	2"	UNK	7/15/22: Removed 4 - 3/4" corp manifold (copper) and abandoned corps (tapped on top). Installed 2" corp. with 2" tapping sleeve. Ran 2" HDPE from corp for 8' to 2" rigid copper. Connected to existing just South of the Fiber Optic line.	Installation Record	Y	7/15/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9709	202 S CHESTNUT AVE	UNK	C	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	TO CURB BOX AND BRASS INTO THE BUILDING.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9951	517 W PARK ST	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/25/2015	Cross Connection Survey	
9954	509 S SPRUCE AVE	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	2011- NEW CURB STOP/BOX. COMES OFF OF 6TH	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9959	811 E 9TH ST	N	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	NEW 5' PAST SIDEWALK.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9963	306 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		Y-SERVICE TO 306 & 308 ALSO	Installation Record	N			Field Inspection Only	Y	2/4/2019	Cross Connection Survey	
9963	308 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		Y-SERVICE TO 306 & 308 ALSO (1/2" COPPER LOCKING VALVE)	Installation Record	N			Field Inspection Only	Y	6/2/2017	Cross Connection Survey	
9966	1412 S ADAMS AVE	UNK	UNK	UNK	UNK	1/1/1977	CI-U	UNK	1/1/1977	NONRES	UNK	CI-U	UNK	UNK	4" cast iron on property side	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9971	1508 S CHESTNUT AVE	N	C	Y	3/4"	7/23/2018	C	3/4"	7/23/2018	SF	UNK	C	3/4"	UNK	LEAD REMOVED 7-23-2018	Installation Record	Y	7/23/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9974	808 E 8TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	PRIVATE SERVICE WHICH RUNS DOWN THE CENTER OF 8TH STREET TO PALMETO. INSULATED FROM CURB TO SEWER TAP 1982	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9978	1423 S ADAMS AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	35586	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
9981	704 E 4TH ST	N	C	Y	1"	6/18/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/18/2024: Removed lead from wm-cs. installed 1" corp (2' West of old corp), 1" copper, 1" cs & box. Connected to existing 3/4" copper 6" after cs.	SL repair/replace record	Y	6/18/2024	Visual insp during install or repair	Field Inspection Only	Y	6/18/2024	Visual Insp during install or repair	
9984	1009 S CLARK AVE	UNK	C	Y	1"	8/11/2021	C	1"	8/11/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	8/11/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9986	1201 S OAK AVE	UNK	C	UNK	1 1/2"	1/1/2006	C	1 1/2"	1/1/2006	NONRES	UNK	C	1 1/2"	UNK	MFLD UTILITIES	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9989	1010 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
9992	313 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		SERVICES COMES OFF OF CHERRY	Installation Record	N			Field Inspection Only	Y	6/6/2017	Cross Connection Survey	
10007	1208 S CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		1999: MEYERS REMOVED LEAD WIPE @ THE CURB STOP, NEW COPPER TO HOUSE FROM BOX	Installation Record	N			Field Inspection Only	Y	9/29/2015	Cross Connection Survey	
10010	413 S CEDAR AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10014	912 S ASH AVE	N	UNK	UNK	UNK	5/1/1990	C	UNK	5/1/1990	SF	UNK	C	UNK	UNK	NEW COPPER MAIN TO STOP 5/90	Installation Record	Y	5/1/1990	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10017	514 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		11/04/86 - BOX INSTALLED AND NEW LINE RAN INSIDE	Installation Record	N			Field Inspection Only	Y	12/2/2014	Cross Connection Survey	
10020	713 W ADLER RD	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	MEWD/REPLACED CORP TO CURB BOX. 9-3-2021 - Meyers replaced galvanized with 3/4" copper on customers side.	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10023	405 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/1/2015	Cross Connection Survey	
10025	1301 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10028	910 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10031	900 W 5TH ST	N	C	UNK	1"	1/1/207	L	1"	1/1/1900	SF	UNK	L	G	1/1/1900	HAAS: ATTACHED TO 1" LEAD 15' PAST CURB VALVE	Installation Record	Y	1/1/2007	Mech excav	Previous eval	Y	2/12/2025	Visual insp at meter	
10035	1006 S ASH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 7/3/97. 2020 - REPLACED 2"x3/4" SODDERED COPPER FITTING W/ THREADED BRASS. 2" SERVICE RUNS WITH SANTIARY MAIN. 2022-Replaced w/ copper, Meyers replace lead w/ 1" copper cs-meter, new cs & box	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10038	514 W 6TH ST	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10044	903 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REPLACED LINE TO HOUSE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10047	1300 S ADAMS AVE	UNK	C	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10050	1005 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10055	605 E 9TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10060	1113 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1950	C	5/8"	1/1/1950	SF	UNK	C	UNK	1/1/1950	4'X8' INSULATION, VALVE IN TERRACE. 3/4" copper on property side	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	10/30/2015	Cross Connection Survey	
10066	312 E 3RD ST	UNK	C	Y	1"	6/5/2023	C	1"	6/5/2023	SF	UNK	C	1"	UNK	6/5/23: Removed lead from wm-cs, replaced w/ 1" corp, 1" copper. Meyers replaced lead w/ 1" copper from cs-meter and installed 1" cs & box.	Installation Record	Y	6/5/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10069	710 W ADLER RD	N	C	UNK	3/4"	1/1/2001	G	3/4"	1/1/2001	SF	UNK	G	UNK	1/1/2001	MEWD/REPLACED CORP TO CURB BOX	SL repair/replace record	Y	1/1/2001	Visual insp during install or repair	Previous eval	Y	3/18/2016	Cross connection survey	
10072	702 S VINE AVE	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	4/9/1998	Installation record	N	4/9/1998	Visual insp during install or repair	Previous eval	Y	9/2/2015	Cross connection survey	
10075	500 S PALMETTO AVE	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	N		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10077	1502 S ADAMS AVE	UNK	UNK	UNK	6"	1/1/1978	CI-U	6"	1/1/1978	NONRES	UNK	CI-U	6"	UNK	FEEDS 1500,1502,1504,1506 & 1508	Installation Record	Y	1/1/1978	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
10080	301 E 8TH ST	UNK	C	Y	1"	9/7/2021	C	1"	9/7/2021	SF	UNK	C	1"	UNK	9/7/2021 Maddrell Const. Installed 1" corp 2' north of abondoned corp. New 1" CS + Box .5' west of gas main. Connected to 3/4" copper .5' after gas main. Removed esisting lead service.	Installation Record	Y	9/7/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10087	919 MARTIN DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
10094	1315 W ARLINGTON ST	UNK	C	UNK	1"	8/16/2022	C	1"	8/16/2022	SF	UNK	C	1"	UNK	8/16/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/16/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10100	915 W 4TH ST	UNK	C	UNK	1"	10/5/2022	C	1"	10/5/2022	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	10/5/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10103	209 S STATE AVE	N	C	Y	UNK	1/1/2014	C	UNK	1/1/2014	SF	UNK	C	UNK	UNK	2014-REMOVED LEAD WIPES @ MAIN & INSTALLED 20' OF 3/4" COPPER, CONNECTED TO 1/2" COPPER	Installation Record	Y	1/1/2014	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10108	407 E 2ND ST	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER. SAN LAT IS 4' WEST OF WATER SERVICE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10114	805 S CEDAR AVE	N	C	UNK	1"	1/1/2022	P	1"	1/1/2022	SF	UNK	P	1"	UNK	2022: New 1" tap & 1" copper from main to cs, new 1" cs and reused box. 1" plastic on house side.	Installation Record	Y	1/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10118	1000 GEORGE DR	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10121	914 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS- ATTACHED TO 3/4" COPPER 15' PAST CURB VALVE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10126	715 W ADLER RD	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	MEWD/REPLACED CORP TO CURB BOX	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10135	311 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000: CURB BOX INSTALLED	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10138	307 S WISCONSIN AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10141	111 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10146	409 S CEDAR AVE	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	New 1" copper from main to curb valve. New 1" cs & box, hooked to 3/4" copper on owners side. Used existing corp.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10149	707 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	4/9/2015	Cross Connection Survey	
10152	1610 W ARLINGTON ST	UNK	C	UNK	1"	8/8/2022	C	1"	8/8/2022	SF	UNK	C	1"	UNK	8/8/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10155	1008 S CLARK AVE	UNK	C	Y	1"	8/6/2021	C	1"	8/6/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	8/6/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10159	1100 S CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	1/21/2022	Cross connection survey	
10159	1100 S CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1936	L	UNK	1/1/1936	SF	UNK	UNK	UNK		<Null>	Installation Record	N			Field inspection only	Y	2/13/2020		
10162	1401 W ARLINGTON ST	UNK	C	UNK	1"	8/15/2022	C	1"	8/15/2022	SF	UNK	C	1"	UNK	8/15/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/15/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10165	617 S CEDAR AVE	UNK	C	Y	1"	9/9/2021	C	1"	9/9/2021	SF	UNK	C	1"	UNK	9/9/2021 Maddrell Const. Installed 1" corp2' North of the abandoned corp. New 1" CS & Box connected to existing 3/4" copper .5' after CS. Removed existing lead service.	Installation Record	Y	9/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10168	1512 W ARLINGTON ST	UNK	C	UNK	1"	8/11/2022	C	1"	8/11/2022	SF	UNK	C	1"	UNK	8/11/22: Installed 1" tapping saddle, 1" copper and 1' cs & box. Connectd to 3/4" copper after cs.	Installation Record	Y	8/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10172	312 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	10/3/2017	Cross connection survey	
10175	1104 S CHESTNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1935	C	UNK	1/1/1935	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/9/2010	Cross Connection Survey	
10178	1109 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN. 8/5/2021: Removed lead wipe @ WM & replaced w/ 3/4" copper, connected to existing 3/4" copper 3' from WM.	Installation Record	Y	8/5/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10181	1101 W 5TH ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	CB/LV UNKNOWN	Installation record	N		Visual insp during install or repair	Previous eval	Y	12/17/2014	Cross connection survey	
10184	816 W ADLER RD	N	C	Y	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	3/4"	UNK	7/14/14 - Removed Lead wipe @ main, connected to existing 3/4" copper. 7/1/2021 - Gaffney dug & installed 3/4" CS & box. Found 3/4" copper from EOP - 15' East of EOP. Gaffney found Copper under conc. in basement. Galv. replaced from floor to meter.	Installation Record	Y	1/1/1926	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10187	918 W 8TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10191	200 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CURB VALVE CONNECTED TO 1" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10194	908 W 14TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10197	302 W MAGEE ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/19/22: Copper found @ the main	Installation Record	Y	5/18/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10200	409 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/14/2015	Cross Connection Survey	
10203	304 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/6/2016	Cross Connection Survey	
10206	406 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		LEAD WIPE REMOVED 11/22/99.	Installation Record	N			Field Inspection Only	Y	10/24/2014	Cross Connection Survey	
10209	1005 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO DITCH - CONNECTED TO EXISTING 3/4" COPPER AT DITCH	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10212	208 S CONCORD AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2011-INSTALLED NEW COPPER FROM MAIN TO CURB STOP/BOX. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10222	707 E 4TH ST	N	C	Y	1"	6/18/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/18/2024: Removed lead from wm-cs. Installed 1" corp. (3' East of old corp.), 1" copper, 1" cs & box connected to existing 3/4" copper 6" after cs.	SL repair/replace record	Y	6/18/2024	Visual insp during install or repair	Field Inspection Only	Y	6/18/2024	Visual Insp during install or repair	
10225	1008 S SEVERNS AVE	N	C	UNK	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	INSTALLED NEW 3/4" CU FROM CORP TO NEW 3/4" CS & BOX. CONNECTED TO EXISTING 3/4" CU ON CUSTOMER SIDE	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10228	514 W 13TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 10/10/97	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10233	314 W 4TH ST	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2011-CAL'S PLBG. INSTALLED CURB STOP/BOX. 1/2" COPPER PROP. SIDE.	SL repair/replace record	Y	2011	Mech excav	Field inspection only	Y	12/19/2014	Cross Connection Survey	
10240	809 S ASH AVE	N	C	Y	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	1985-REPLACED LEAD WHEN CITY REPLACED SEWER. 2014- INSTALLED CURB VALVE/BOX	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10243	1409 S ADAMS AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10246	1613 W ARLINGTON ST	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	SF	UNK	C	1"	UNK	SERVICED OFF OF LINCOLN. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10249	515 W 6TH ST	N	C	Y	3/4"	5/30/2018	C	3/4"	5/30/2018	SF	UNK	C	3/4"	UNK	SERVICE IS OFF W 6TH, ALL LEAD REMOVED FROM WM TO HOUSE, NEW CURB STOP AND BOX	Installation Record	Y	5/30/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10252	1008 S ADAMS AVE	UNK	UNK-LG	UNK	UNK	1/1/1947	C	UNK	1/1/1947	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	2/11/2013	Cross Connection Survey	
10256	412 W 7TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Service comes off of pine. 6/29/22: Lead wipe removed (TK/CH)	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10259	1511 W ARLINGTON ST	UNK	C	UNK	1"	8/10/2022	C	1"	8/10/2022	SF	UNK	C	1"	UNK	8/10/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10266	1103 S CEDAR AVE	N	C	UNK	1"	10/21/2022	C	1"	10/21/2022	SF	UNK	C	1"	UNK	2022: New 1" copper from main to curb valve. New 1" curb valve. Used existing corp and connected to existing 3/4" copper on owners side.	Installation Record	Y	10/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10273	1107 S CENTRAL AVE	N	C	UNK	1"	1/1/2014	P	1"	1/1/2014	SF	UNK	P	1"	UNK	THIS SERVICE COMES OFF MAPLE AND WAS BORED THROUGH BACK YARD.	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10277	608 S HIGHLAND AVE	N	C	UNK	1"	5/12/2022	C	1"	5/12/2022	SF	UNK	C	1"	UNK	5/12/22: New 1" tap and 1" copper from main to house	Installation Record	Y	5/12/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10280	202 S PEACH AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC. NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10283	1202 S CENTRAL AVE	N	C	UNK	1"	4/29/2022	C	1"	4/29/2022	NONRES	UNK	C	1"	UNK	4/29/22: Bored in new service 13' deep under cental. 1" copper to cs - 3/4" copper inside building. 1" Tap is on East side of main. Copper installed under main 13' deep.	Installation Record	Y	4/29/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10286	605 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1947	P	UNK	1/1/1947	SF	UNK	P	P		2013-C.B. INSTALLED. 3/4" HDPE on property side	Installation Record	N			Field Inspection Only	Y	10/24/2014	Cross Connection Survey	
10290	1113 S CEDAR AVE	N	C	UNK	1"	10/20/2022	L	1"	10/20/2022	SF	UNK	L	UNK	10/20/2022	2022: New 1" copper from main to curb valve. New 1" curb valve and box. Used existing corp and connected to lead on owners side.	SL repair/replace record	Y	10/20/2022	Visual insp during install or repair	Previous eval	Y	6/19/2017	Cross connection survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
10293	901 W ARLINGTON ST	N	C	Y	1"	5/4/2022	C	1"	5/4/2022	SF	UNK	C	1"	UNK	5/4/22: Replaced lead from main-cs w/ 1" tap, 1" copper, 1" cs & box. Removed old tap, retapped on DIP w/ 2-hymax connecting to cast. 1" copper on customers side.	Installation Record	Y	5/4/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10296	113 S CEDAR AVE	N	C	Y	1"	8/12/2022	C	1"	8/12/2022	SF	UNK	C	1"	UNK	8/12/22: Removed all lead. Installed new 1" copper from main to cs. Used existing corp., installed new box. Connected to existing 3/4" copper on customers side.	Installation Record	Y	8/12/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10299	304 S WALNUT AVE	N	L	UNK	UNK	1/1/1928	C	UNK	1/1/1928	NONRES	UNK	C	UNK	1/1/1928	2016-REMOVED LEAD WIPE @ CURB VALVE. INSTALLED NEW VALVE/BOX	SL repair/replace record	Y	2016	Mech excav	Field inspection only	Y	10/9/2014	Cross Connection Survey	
10302	713 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/22/2016	Cross Connection Survey	
10307	1005 W ARLINGTON ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/13/22: Dug @ wm, found 3/4" copper.	Installation Record	Y	5/13/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10310	313 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/5/2014	Cross Connection Survey	
10314	1506 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10323	810 S VINE AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2009- REMOVED LEAD WIPE @ MAIN.	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	6/6/2017	Cross Connection Survey	
10326	706 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/2/2016	Cross Connection Survey	
10330	504 W 13TH ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10333	911 S ASH AVE	N	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10336	406 W 6TH ST	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2007-INSTALLED NEW CURB STOP & REMOVED LEAD WIPE, 3/4" COPPER PROP. SIDE	SL repair/replace record	Y	2007	Mech excav	Field inspection only	Y	3/1/2016	Cross Connection Survey	
10339	1506 S CHESTNUT AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10343	1017 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS 1" COPPER INSIDE, RE-TAPPED PIPE BURST--2017	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10346	413 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1929	C	3/4"	1/1/1929	SF	UNK	UNK	UNK		4/5/2021: Notified customer the utility will vacuum excavate spring/summer 2021 to verify service. 12/23/24: Customer phone call verified copper service in the basement.	Installation Record	N			Field Inspection Only	Y	12/23/2024	Customer self id	
10349	512 E 8TH ST	UNK	UNK-LG	UNK	UNK	1/1/1941	C	UNK	1/1/1941	SF	UNK	C	C		REPLACED GOOSE NECK FOR REPAVING ASH ST	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
10352	106 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10355	917 W ADLER RD	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10358	1607 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10362	802 S CHERRY AVE	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	MEYERS. 3/4" copper on property side	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10365	700 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/23/2017	Cross Connection Survey	
10368	1100 W ARLINGTON ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	3/4 COPPER PROPERTY SIDE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10371	1206 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2005-REMOVED LEAD WIPE @ CURB VALVE. 1985-REMOVED GOOSENECK.	SL repair/replace record	Y	2005	Mech excav	Field inspection only	Y	10/14/2015	Cross Connection Survey	
10378	303 W PARK ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2013-REMOVED LEAD WIPE @ MAIN	Installation Record	N			Field Inspection Only	Y	9/10/2015	Cross Connection Survey	
10381	507 W 5TH ST	UNK	C	Y	1"	6/8/2023	C	1"	6/8/2023	SF	UNK	C	1"	UNK	6/8/23: Replaced lead from wm-cs w/ 1" copper. Conn to existing corp. using 18" - 3/4" copper. Meyers replaced lead from cs-meter w/ 1" copper and installed a new 1" cs & box.	Installation Record	Y	6/8/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10385	805 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/1/2014	Cross Connection Survey	
10393	907 S CENTRAL AVE	UNK	UNK	Y	3/4"	1/1/1966	C	3/4"	1/1/1966	NONRES	UNK	C	3/4"	UNK	2009- REMOVED LEAD WIPE @ MAIN. 3/4" copper on property side	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10396	605 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/22/2017	Cross Connection Survey	
10401	810 E 3RD ST	N	C	Y	3/4"	8/6/2020	C	3/4"	8/6/2020	SF	UNK	C	3/4"	UNK	8/6/2020 - REMOVED LEAD FROM MAIN TO C.S. - INSTALLED NEW C.S. & BOX CONNECTED TO EXISTING 3/4" COPPER ON CUSTOMER SIDE	Installation Record	Y	8/6/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10407	204 S CHERRY AVE	N	C	UNK	3/4"	5/8/2018	C	3/4"	5/8/2018	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	5/8/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10410	809 E 4TH ST	N	C	UNK	1"	10/20/2022	C	1"	10/20/2022	SF	UNK	C	1"	UNK	2022: New 1" tap and copper from main to curb valve, New 1" curb valve and box. 1" copper from curb to inside house.	Installation Record	Y	10/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10413	800 S DRAKE AVE	N	C	UNK	2"	1/1/2014	P	2"	1/1/2014	SF	UNK	P	2"	UNK	CALS PLUMBING	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10421	803 E 4TH ST	N	C	Y	1"	6/20/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/20/24: Removed lead from cs-wm. Replaced w/ 1" copper, 1" cs & box. connected to existing 3/4" copper after cs.	SL repair/replace record	Y	6/20/2024	Visual insp during install or repair	Field Inspection Only	Y	6/20/2024	Visual Insp during install or repair	
10424	1511 S CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10432	806 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		REMOVED GOOSENECK, INSULATED, PAVING 1985	Installation Record	N			Field Inspection Only	Y	6/8/2017	Cross Connection Survey	
10435	613 S ASH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	PAVING	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10438	812 W ADLER RD	UNK	UNK-LG	UNK	UNK	1/1/1938	C	UNK	1/1/1938	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/6/2014	Cross Connection Survey	
10442	1110 W ARLINGTON ST	N	C	UNK	3/4"	1/1/1993	C	3/4"	1/1/1993	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10445	705 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/18/2017	Cross Connection Survey	
10448	1001 W 4TH ST	N	C	UNK	3/4"	1/1/2009	P	3/4"	1/1/2009	SF	UNK	P	3/4"	UNK	2009- INSTALLED COPPER FROM MAIN TO CURB VALVE W/ BOX. MEYER INSTALLED NEW COPPER TO HOUSE.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10451	301 W 4TH ST	N	C	UNK	UNK	1/1/2002	C	UNK	1/1/2002	SF	UNK	C	UNK	UNK	REPLACED SERVICE FROM MAIN TO HOUSE WITH COPPER. INSTALLED NEW CURB STOP AND BOX. DUPLEX WITH 312A S. WALNUT	Installation Record	Y	1/1/2002	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10454	608 E 9TH ST	N	L	UNK	5/8"	1/1/1930	C	5/8"	1/1/1930	SF	UNK	C	UNK	1/1/1930	5/8" LEAD - STREET SIDE. 3/4" COPPER - PROPERTY SIDE. INSULATED 2X4 - 1981, NEW CURB VALVE & BOX - 2/3/2014. SERVICE IS 5' DEEP	SL repair/replace record	Y	2014	Mech excav	Field inspection only	Y	2/3/2016	Cross Connection Survey	
10457	904 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10460	505 W 5TH ST	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2022 - Replaced lead on customers side	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10464	501 W 7TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF PINE. 2022: Removed lead wipe. Replaced w/ 3/4" copper.	Installation Record	Y	11/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10468	610 S ASH AVE	N	L	UNK	5/8"	1/1/1927	C	5/8"	1/1/1927	SF	UNK	C	UNK	1/1/1927	MEYERS -2003- NEW CURB BOX- WIPES REMOVED ON BOTH SIDES OF VALVE	SL repair/replace record	Y	2003	Mech excav	Field inspection only	Y	6/2/2017	Cross Connection Survey	
10471	613 S OAK AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10471	613 S OAK AVE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10474	1012 W 14TH ST	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10478	514 W MAGEE ST	N	C	Y	1"	6/3/2022	C	1"	6/3/2022	SF	UNK	C	1"	UNK	6/3/22: Removed lead from main to cs, replaced w/ 1" copper. Installed new 1" tap and 1" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/3/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10482	813 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/13/2016	Cross Connection Survey	
10486	417 W MAGEE ST	N	C	Y	1"	5/26/2022	C	1"	5/26/2022	SF	UNK	C	1"	UNK	5/26/22: Removed lead from main-cs, replaced w/ 1" tap, 1" copper, 1" cs & box. Connected to existing 3/4" copper on property side	Installation Record	Y	5/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10492	301 E 2ND ST	N	C	Y	UNK	8/19/2022	C	UNK	8/19/2022	SF	UNK	C	UNK	UNK	8/19/22: All lead removed and replaced w/ 1" copper. Installed new 1" cs & box. Connected to existing 3/4" copper on customers side.	Installation Record	Y	8/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10497	212 S VINE AVE	N	C	UNK	3/4"	8/21/2019	C	3/4"	8/21/2019	SF	UNK	C	3/4"	UNK	INSTALLED 3-4" COPPER STREET SIDE AND PROPERTY SIDE W/ MEYERS	Installation Record	Y	8/21/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10500	1503 S CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10510	1111 S CEDAR AVE	N	C	Y	1"	10/13/2022	C	1"	10/13/2022	SF	UNK	C	1"	UNK	10/13/22: Removed lead and replaced w/ 1" copper from main to cs. Installed 1" cs & box, used existing corp., connected to existing 3/4" copper on owners side.	Installation Record	Y	10/13/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10513	1006 W 14TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYER STUB-OUT	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10516	605 W 14TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10519	603 W 5TH ST	UNK	C	UNK	1 1/2"	1/1/2007	C	1 1/2"	1/1/2007	NONRES	UNK	C	1 1/2"	UNK	1-1/2" COPPER INSIDE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10525	814 W 6TH ST	N	C	Y	1"	7/13/2023	P	1"	7/13/2023	SF	UNK	P	P		Lead and shared 'y' service removed. Installed 1" tap, 1" copper from main to 1" poly service. 1" cs & box.	Installation Record	Y	7/13/2023	Visual insp during install or repair	Field Inspection Only	Y	12/16/2014	Cross Connection Survey	
10530	608 S ASH AVE	N	UNK	Y	UNK	1/1/1985	C	UNK	1/1/1985	SF	UNK	C	UNK	UNK	REMOVED LEAD & INSULATED 1985	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
10536	804 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		REMOVED GOOSENECK & INSULATED, 1985 PAVING	Installation Record	N			Field Inspection Only	Y	6/6/2017	Cross Connection Survey	
10539	113 W 11TH ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10542	708 E 3RD ST	N	UNK	UNK	1"	6/22/1998	C	1"	6/22/1998	SF	UNK	C	1"	UNK	GAFFNEY PLUMBING	Installation Record	Y	6/22/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10545	312 S CONCORD AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 4'8" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10548	1008 S ASH AVE #A	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10551	203 S PEACH AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC. NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10557	511 E 2ND ST	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10560	505 S SPRUCE AVE	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	2011- NEW CURB STOP/BOX. COMES OFF OF 6TH	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10563	816 W 6TH ST	N	C	Y	1"	7/13/2023	P	1"	7/13/2023	SF	UNK	P	P		7/13/23: Removed lead and shared 'y' service. Installed 1" tap, 1" copper from main to 1" poly service.	Installation Record	Y	7/13/2023	Visual insp during install or repair	Field Inspection Only	Y	7/24/2017	Cross Connection Survey	
10570	611 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/23/2016	Cross Connection Survey	
10573	1011 S CEDAR AVE #A-REAR	N	C	Y	1"	10/26/2022	C	1"	10/26/2022	SF	UNK	C	1"	UNK	2022: Removed lead from wm-sidewalk. Replaced w/ 1" copper. Connected to 3/4" copper 6" East of the 1" cs. Connected to 3/4" copper 2' East of the wm. Curb valve is in the North edge of the driveway.	Installation Record	Y	10/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10577	1009 GEORGE DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10584	1306 S ADAMS AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10587	712 W 6TH ST	UNK	C	UNK	1"	7/25/2023	C	1"	7/25/2023	SF	UNK	C	1"	UNK	7/25/23: New 1" tap, 1" copper from main to cs. connected to existing 3/4" copper on customers side.	Installation Record	Y	7/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10592	1407 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10595	501 S VINE AVE	N	L	UNK	5/8"	1/1/1927	C	5/8"	1/1/1927	SF	UNK	C	UNK	1/1/1927	2009- REMOVED LEAD WIPE @ MAIN. 3/4" copper on property side	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	4/25/2014	Cross Connection Survey	
10598	300 W 14TH ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10601	904 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1943	C	UNK	1/1/1943	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/20/2017	Cross Connection Survey	
10604	419 W MAGEE ST	N	C	Y	3/4"	1/1/2022	C	3/4"	1/1/2022	SF	UNK	C	3/4"	UNK	2022: Removed lead from main-cs, replaced w/ 3/4"copper, 1" box. Connected to existing 3/4" copper on Utility side. Used existing cs.	Installation Record	Y	1/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10606	404 S CHERRY AVE	N	C	UNK	1"	1/1/2012	C	1"	1/1/2012	SF	UNK	C	1"	UNK	ABANDONDED CORP. 2'S.	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10610	812 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10620	410 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10623	312 S WISCONSIN AVE	N	UNK	Y	UNK	1/1/2016	C	UNK	1/1/2016	SF	UNK	C	UNK	UNK	2016-REMOVED LEAD FROM MAIN TO CURB VALVE REPLACING WITH 3/4" COPPER 2004-INSTALLED 3/4 CURB VALVE, REMOVED LEAD WIPES AT VALVE	Installation Record	Y	1/1/2016	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10626	409 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10630	1007 S CEDAR AVE	N	C	UNK	3/4"	4/13/2020	C	3/4"	4/13/2020	SF	UNK	C	3/4"	UNK	4/13/2020 - GAFFNEY installed 1" from CS - METER, MU installed 3/4" CU from MAIN - CS. 1"x3/4" fitting on customer side of CS. New CS & BOX. Sanitary lateral runs w/ serivce. Service insulated under Storm Sewer	Installation Record	Y	4/13/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10633	809 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/9/2017	Cross Connection Survey	
10639	603 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10642	814 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10645	706 S ASH AVE	N	C	UNK	3/4"	1/1/2008	P	3/4"	1/1/2008	SF	UNK	P	3/4"	UNK	2008-REPLACED SERVICE, USED EXISTING CORP, CALS PLBG.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10649	1000 W ARLINGTON ST	N	C	Y	1"	11/16/2021	C	1"	11/16/2021	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 10/13/97. 11/16/2021: Replaced lead service on treet side w/ new 1" corp. also. Conn. to existing 3/4" copper on home owner side. Installed new 1" CS & Box. 2022: Discovered service is also shared w/ 1002 Arlington South of cs & box	Installation Record	Y	11/16/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10652	408 W 6TH ST	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2010- REMOVED LEAD WIPE @ MAIN. INSTALLED 10' 3/4" COPPER CONNECTED TO EXISTING 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10661	212 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF PALMETTO	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10664	709 E 5TH ST	N	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	RETAPPED. ABANDONED OLD SERVICE	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10667	1010 S ASH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10670	610 S HIGHLAND AVE	N	C	Y	3/4"	9/27/2017	C	3/4"	9/27/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD AND INSTALLED NEW 3/4"COPPER FROM MAIN TO C.B./C.V.--2017	Installation Record	Y	9/27/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10674	1106 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	RETAPPED, LOWERED & INSULATED, 1983 PAVING	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10678	710 E 2ND ST	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003: NEW 1" CORP,COPPER,VALVE,BOX,3/4" COPPER INSIDE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10681	1000 S SEVERNS AVE	N	C	Y	1"	5/4/2022	C	1"	5/4/2022	SF	UNK	C	1"	UNK	5/4/22: Replaced lead from main-cs w/ 1" tap, 1" copper, 1" cs & box. Connected to existing 3/4" copper on customers side. Tap is 3' East of existing corp.	Installation Record	Y	5/4/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10685	701 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10690	305 E 2ND ST	N	C	Y	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	FROM CORP TO CURB VALVE - 11.5' OF 1" COPPER, 1' OF 3/4" COPPER, CURB VALVE, CONNECTED TO EXISTING 5/8" LEAD. CURB VALVE AND BOX IS 1"-2" SOUTH OF GAS MAIN. SAN LAT. IS 6'W OF WATER SERVICE.	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10698	712 S HIGHLAND AVE	UNK	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VACUUM EXCAVATED @ EOP, FOUND COPPER 9' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10707	714 E 3RD ST	N	C	Y	1"	8/4/2022	C	1"	8/4/2022	SF	UNK	C	1"	UNK	8/4/22: Removed lead from main to cs. Replaced w/ 1" copper. Installed 1" cs & box and connected to existing 3/4" copper 12" South of cs on private side.	Installation Record	Y	8/4/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10710	300 W PARK ST	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-INSTALLED NEW 3/4" COPPER FROM EXISTING CORP TO NEW CURB VALVE/BOX. 1/2" COPPER INSIDE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10714	208 S CHERRY AVE	UNK	C	Y	1"	5/24/2023	C	1"	5/24/2023	SF	UNK	C	1"	UNK	5/24/23: Replaced lead from wm-cs w/ 1" corp, 1" copper. Existing lead was connected to a main break sleeve w/ CC. MU abandoned the sleeve and retapped 3' to the North. Meyers replaced lead from cs-meter w/ 1" copper and installed new 1" cs & box.	Installation Record	Y	5/24/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10718	606 S VINE AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2009-REMOVED LEAD WIPE @ MAIN. 3/4" copper on property side	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	5/26/2017	Cross Connection Survey	
10721	410 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/22/2016	Cross Connection Survey	
10727	1103 S CLARK AVE	UNK	C	Y	1"	8/9/2021	C	1"	8/9/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	8/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10730	1001 W 5TH ST	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10736	707 E 17TH ST	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10741	820 W 6TH ST	N	C	Y	3/4"	10/17/2018	C	3/4"	10/17/2018	SF	UNK	C	3/4"	UNK	REMOVED ALL LEAD. INSTALLED 3/4" COPPER FROM WM TO HOUSE. REIGEL	Installation Record	Y	10/17/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
10745	901 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/18/2017	Cross Connection Survey	
10748	508 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2012-INSTALLED 3/4" COPPER FROM NEW CURB VALVE/BOX TO HOUSE. REMOVED LEAD WIPES AT CURB VALVE. 7/18/222: Removed lead wipe at main and replaced w/ 3/4" copper.	Installation Record	Y	7/18/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10751	406 W PARK ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10758	208 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REPLACED WITH B VALVE. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10760	405 S VINE AVE	N	C	Y	3/4"	7/18/2019	C	3/4"	7/18/2019	SF	UNK	C	3/4"	UNK	2001: REMOVED LEAD-WIPE AT MAIN. 2019: REMOVED LEAD FROM MAIN TO HOUSE AND INSTALLED 3/4" COPPER	Installation Record	Y	7/18/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10763	1408 S ERICKSON AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 8'2" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10770	1417 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10776	812 E 4TH ST	N	C	Y	1"	6/25/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/25/24: Removed lead from wm-cs. Replaced w/ 1" corp. (old corp is 3' west of new) 1" copper & 1" cs & box. Connected to existing 3/4" copper after cs.	SL repair/replace record	Y	6/25/2024	Visual insp during install or repair	Field Inspection Only	Y	6/25/2024	Visual Insp during install or repair	
10779	1411 W ARLINGTON ST	UNK	C	UNK	1"	8/11/2022	C	1"	8/11/2022	SF	UNK	C	1"	UNK	8/11/22: Installed 1" tapping saddle, 1" copper and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10782	404 W 7TH ST	UNK	C	Y	1"	6/9/2022	C	1"	6/9/2022	SF	UNK	C	1"	UNK	6/9/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10786	1211 S CHESTNUT AVE	N	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	IRON	Installation record	N		Visual insp during install or repair	Previous eval	Y	10/16/2015	Cross connection survey	
10789	701 W 14TH ST	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10795	511 W 14TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10797	701 S ASH AVE	UNK	C	Y	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	REPLACED LEAD WITH COPPER FROM WATERMAIN TO HOUSE 8-14-2018	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10804	506 W 13TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10807	910 S CENTRAL AVE	N	L	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2004-NEW 3/4" CURB VALVE W/ BOX, REMOVED LEAD WIPE @ CURB VALVE. 3/4" copper on property side	SL repair/replace record	Y	2004	Mech excav	Field inspection only	Y	8/1/2013	Visual insp at meter	
10810	1501 S CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10814	1015 W PARK ST	UNK	C	Y	1"	7/16/2021	C	1"	7/16/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/16/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10817	511 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	5/28/2016	Cross Connection Survey	
10820	309 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1932	G	3/4"	1/1/1932	SF	UNK	UNK	UNK		CB/LV UNKNOWN. 12/23/24: Verified galvanized before the meter by MU.	Installation Record	N			Previous eval	Y	12/23/2024	Visual insp at meter	
10829	610 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	SF	UNK	G	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	6/14/2017	Cross connection survey	
10832	614 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/15/2017	Cross Connection Survey	
10839	1614 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10842	706 S HIGHLAND AVE	N	C	UNK	3/4"	1/1/2003	C	3/4"	1/1/2003	SF	UNK	C	3/4"	UNK	2003-REIGEL PLBG.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10845	513 W PARK ST	N	C	UNK	3/4"	1/1/2013	L	3/4"	1/1/2013	SF	UNK	L	UNK	1/1/2013	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	SL repair/replace record	Y	1/1/2013	Visual insp during install or repair	Previous eval	Y	3/24/2015	Cross connection survey	
10848	300 W MAGEE ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE IS OFF OF MAGEE. 5/19/22: Found copper @ main.	Installation Record	Y	5/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10851	507 W 6TH ST	N	C	Y	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	REMOVED LEAD OUR SIDE AND GALVANIZED CUSTOMER SIDE, INSTALLED NEW SERVICE FROM MAIN TO HOUSE, NEW CURB STOP AND BOX 7-2018	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10862	915 MARTIN DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10865	703 E 4TH ST	N	C	Y	1"	6/18/2024	L	5/8"	UNK	SF	UNK	L	UNK	UNK	6/18/2024: Replaced lead from wm-cs. Installed new 1" corp (2' East of old corp), 1" copper, 1" cs & box. Connected to existing lead 6" from cs on customer side.	SL repair/replace record	Y	6/18/2024	Visual insp during install or repair	Field Inspection Only	Y	6/18/2024	Visual Insp during install or repair	
10870	1212 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	2005-REMOVED LEAD WIPE.INSTALLED NEW CURB VALVE & BOX	SL repair/replace record	Y	2005	Mech excav	Field inspection only	Y	10/16/2014	Cross Connection Survey	
10873	816 W 8TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10876	901 W ADLER RD	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	KALSCHED/PLUMBER, DUPLEX. 3/4" copper on property side	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10882	601 S CEDAR AVE	N	CI-U	UNK	6"	UNK	CI-U	6"	UNK	NONRES	UNK	CI-U	6"	UNK	MFLD PLB	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
10886	505 W 7TH ST	UNK	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS. 6/16/22: Dug and verified copper from main to terrace	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10889	806 W 4TH ST	UNK	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS INC	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10894	815 E 4TH ST	N	C	Y	1"	6/19/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/6/24: Removed lead from wm-cs. 3' - 3/4" copper at main. 1" copper the rest of the way to the cs.	SL repair/replace record	Y	6/19/2024	Visual insp during install or repair	Field Inspection Only	Y	6/19/2024	Visual Insp during install or repair	
10897	901 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
10902	303 S WISCONSIN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REPLACED 1997	Installation Record	Y	1/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10913	808 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2019-CURB STOP DOES NOT WORK; 2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10919	615 E 4TH ST	UNK	C	UNK	2"	1/1/1995	C	2"	1/1/1995	NONRES	UNK	C	2"	UNK	NEW 2" COPPER MAIN TO C.B., LOWERED SERVICE TO CLEAR NEW STORM SEWER, INSULATED BETWEEN WATER & STORM SEWER--2017	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10925	807 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2012- REMOVED LEAD WIPE @ CORP. INSTALLED 3/4" COPPER FROM CORP TO EAST SIDE OF ROAD.	Installation Record	N			Field Inspection Only	Y	7/23/2014	Cross Connection Survey	
10976	604 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1940	C	UNK	1/1/1940	SF	UNK	C	C		REMOVED LEAD WIPE @ MAIN.INSTALLED NEW COPPER FROM MAIN TO SOUTH SIDE OF ROAD1997-CB LOCATION VERIFIED	Installation Record	N			Field Inspection Only	Y	3/16/2016	Cross Connection Survey	
10979	704 S PALMETTO AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 5'4" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
10982	512 S PEACH AVE	UNK	C	UNK	1"	8/11/2022	C	1"	8/11/2022	SF	UNK	C	1"	UNK	8/11/22: Mark Meyers - ran new 1" copper into house. 1" copper on street side	Installation Record	Y	8/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
10986	404 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/17/2016	Cross Connection Survey	
10992	1505 S ERICKSON AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2008-CURB VALVE INSTALLED W/BOX	Installation Record	Y	1/1/2008	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11001	900 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/15/2017	Cross Connection Survey	
11004	911 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		9/90-WIPE REMOVE, New service ran in from CB	Installation Record	N			Field Inspection Only	Y	6/16/2017	Cross Connection Survey	
11007	901 S ASH AVE	N	C	UNK	3/4"	6/6/2019	C	3/4"	6/6/2019	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	6/6/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11010	903 S ASH AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/29/2016	Cross Connection Survey	
11013	515 W PARK ST	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11017	1010 S VINE AVE	N	C	Y	1"	11/19/2021	C	1"	11/19/2021	SF	UNK	C	1"	UNK	11/19/21: Removed lead from wm-cs, replaced w/ 1" copper, new 1" corp. (3' South of existing corp.), new 1" cs & box, conn. to existing 3/4" copper 12" West of the cs. Insulated @ main & cs. 4" pvc san. lat crosses over main 4' North of new corp.	Installation Record	Y	11/19/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11019	813 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/6/2017	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
11025	402 S PEACH AVE	N	L	UNK	5/8"	1/1/1922	C	5/8"	1/1/1922	SF	UNK	C	UNK	1/1/1922	2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 7'1" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	3/7/2014	Visual Insp during install or repair	
11031	709 E 6TH ST	N	C	UNK	3/4"	UNK	L	3/4"	UNK	SF	UNK	L	UNK	UNK	3/4" copper in R-O-W, Lead on Property side. MEYERS	SL repair/replace record	Y			Previous eval	Y	3/21/2016	Cross connection survey	
11034	811 W 4TH ST	UNK	C	Y	1"	5/22/2023	C	1"	5/22/2023	SF	UNK	C	1"	UNK	5/22/23: Removed lead from wm-cs. Installed 1" tap, 1" copper from wm-cs, 1" cs & box. Conn. to 3/4" copper on private side.	Installation Record	Y	5/22/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11038	1104 S OAK AVE	UNK	UNK	UNK	1 1/2"	1/1/1974	C	1 1/2"	1/1/1974	NONRES	UNK	C	1 1/2"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11042	508 E 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1943	C	UNK	1/1/1943	SF	UNK	C	C		PRIVATE LINE DOWN THE CENTER OF 6TH	Installation Record	N			Field Inspection Only	Y	6/2/2017	Cross Connection Survey	
11044	905 S VINE AVE	N	C	Y	1"	12/1/2022	C	1"	12/1/2022	SF	UNK	C	1"	UNK	12/1/22: Removed lead street side, 3/4" @ main for a foot then switches to 1" copper to the curb box. Hooked up to existing 3/4" copper by curb box on street side. 9/18/24: Meyers replaced 1/2" cu from cs-meter w/ 1" HDPE. Also relocated meter.	Installation Record	Y	12/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11047	811 S DRAKE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/5/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11050	1107 W 6TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	INSULATED, 1983 PAVING	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11053	509 E 6TH ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	LINE DOWN THE CENTER OF 6TH ST. REPLACE 1" PRIVATE LINE 9-24-98	Installation record	N	9/27/1998	Visual insp during install or repair	Previous eval	Y	6/20/2017	Cross connection survey	
11056	506 S ASH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED GOOSE NECK & INSULATED 1985 PAVING	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11068	1307 W ARLINGTON ST	UNK	C	UNK	1"	8/17/2022	C	1"	8/17/2022	SF	UNK	C	1"	UNK	8/17/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/17/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11071	406 W MAGEE ST	N	C	Y	1"	5/23/2022	C	1"	5/23/2022	SF	UNK	C	1"	UNK	5/23/22: Removed lead from main-cs replaced w/ 1" tap, 1" copper, 1" cs & box. Connected to existing 1" copper on property side.	Installation Record	Y	5/23/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11074	412 S WALNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/25/2016	Cross Connection Survey	
11077	400 S WALNUT AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/19/2014	Cross Connection Survey	
11080	707 W 4TH ST	N	C	Y	3/4"	5/1/2023	C	3/4"	5/1/2023	SF	UNK	C	3/4"	UNK	5/23: Removed Lead gooseneck @ wm. Replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	5/1/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11089	408 E 2ND ST	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER. SAN. LAT. IS DIRECTLY BELOW WATER SERVICE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11096	505 E 5TH ST	N	C	UNK	1"	5/24/2022	C	1"	5/24/2022	SF	UNK	C	1"	UNK	5/24/22: Abandoned 3/4" corp is 7' East of new 1" corp. Installed 12' - 1" copper from main to cs. Reigel Plbg. installed new 1" copper from cs-meter inside	Installation Record	Y	5/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11099	805 W OMAHA ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11099	805 W OMAHA ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11104	410 W 7TH ST	UNK	C	Y	1"	6/14/2022	C	1"	6/14/2022	SF	UNK	C	1"	UNK	6/14/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/14/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11110	507 S CHESTNUT AVE	N	C	UNK	1"	1/1/2013	L	1"	1/1/2013	NONRES	UNK	L	UNK	1/1/2013	ATTACHED TO EXISTING 5/8 LEAD 2'E OF VALVE	SL repair/replace record	Y	1/1/2013	Visual insp during install or repair	Previous eval	Y	8/17/2016	Cross connection survey	
11113	604 S CHESTNUT AVE	UNK	C	UNK	2"	1/1/1990	C	2"	1/1/1990	NONRES	UNK	C	2"	UNK	REIGEL PLB	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11116	710 E 17TH ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	TAPPED ON 17TH	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11124	703 S CEDAR AVE	UNK	C	Y	1"	9/8/2021	C	1"	9/8/2021	SF	UNK	C	1"	UNK	9/8/2021 Maddrell Const. Installed 1" corp 2' North of abandoned corp. New CS & Box connected to existing 3/4" copper .5' after CS. Removed existing lead service.	Installation Record	Y	9/8/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11127	1416 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11130	1106 S CHERRY AVE	N	L	UNK	5/8"	1/1/1936	C	5/8"	1/1/1936	SF	UNK	C	UNK	1/1/1936	2009-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	9/10/2016	Cross Connection Survey	
11138	1107 W ARLINGTON ST	UNK	C	UNK	3/4"	1/1/1990	C	3/4"	1/1/1990	SF	UNK	C	3/4"	UNK	MEYER: CB LOCATION VERIFIED 6/5/97. 8/4/2021: Dug & verified 3/4" copper @ the WM.	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11141	1206 S CHESTNUT AVE	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000: REMOVED LEAD WIPE BY MAIN.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11145	1607 S ERICKSON AVE	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11148	500 W MAGEE ST	N	C	Y	1"	5/26/2022	C	1"	5/26/2022	SF	UNK	C	1"	UNK	5/26/22: Removed lead from main-cs, replaced w/ 1" copper, 1" tap, 1" box. Connected to exisitng copper on Utility side. Used existing cs.	Installation Record	Y	5/26/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11155	806 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/30/2016	Cross Connection Survey	
11160	716 E 4TH ST	N	C	Y	1"	6/20/2024	L	5/8"	1/1/1926	SF	UNK	C	C		6/20/24: Removed lead and replaced w/ 1" corp, 1" cs & box, and 1" copper from wm-cs. Connected to lead at the back of walk.	SL repair/replace record	Y	6/20/2024	Visual insp during install or repair	Field Inspection Only	Y	6/20/2024	Visual Insp during install or repair	
11163	804 E 5TH ST	N	C	UNK	3/4"	1/1/1991	C	3/4"	1/1/1991	SF	UNK	C	3/4"	UNK	RON MEYERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11168	608 S PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	STUB OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11171	304 S CONCORD AVE	UNK	C	Y	1"	4/26/2023	C	1"	4/26/2023	SF	UNK	C	1"	UNK	4/26/23: Removed lead wipe, replaced w/ 3/4" copper. Installed new 3/4" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	4/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11177	504 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/13/2017	Cross Connection Survey	
11184	1210 W ARLINGTON ST	UNK	C	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	8/9/2021: Verified 3/4" copper @ the watermain	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11188	101 E 11TH ST	N	C	Y	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	2009- RETAPED & INSTALLED 1" COPPER 50' TO REROUTE FOR STORM SEWER CONFLICT. CONNECTED TO 5/8" LEAD W OF STORM SEWER.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11191	907 S PINE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/29/2021 - Property owner called and said they have 1" copper in the house. 5/10/2021 - Found copper from main to house, no curb box.	Installation Record	Y	5/10/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11195	203 S CHERRY AVE	N	C	UNK	1"	1/1/2010	P	1"	1/1/2010	SF	UNK	P	1"	UNK	CONNECTED TO 1" PLASTIC @ CURB VALVE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11198	109 W 12TH ST #A	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	FEEDS 109/112 W.12TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11209	1108 S CHERRY AVE	N	C	Y	1"	8/6/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 11.5' of 1" copper from cs to existing 3/4" copper. See sheet 30 of the construction report.	SL repair/replace record	Y	8/6/2024	Mech excav	Field Inspection Only	Y	8/6/2024	Cross Connection Survey	
11213	501 S CHERRY AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	1" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11217	312 W MAGEE ST	UNK	C	Y	3/4"	7/1/2022	C	3/4"	7/1/2022	SF	UNK	C	3/4"	UNK	Installed a new curb stop and box, removed all lead and replaced with 3/4" copper from wm to the house.	Installation Record	Y	7/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11223	704 S SPRUCE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	DUPLEX 704 & 706	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11227	314 W 3RD ST	N	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11230	803 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/4/2016	Cross Connection Survey	
11238	1201 S CHESTNUT AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11252	713 E 3RD ST	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11259	507 W 12TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11262	606 W 12TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11267	1200 S LOCUST AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11271	607 W 12TH ST	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11279	514 W 12TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11283	513 W 12TH ST	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11286	1006 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/8/2017	Cross Connection Survey	
11298	404 E 8TH ST	UNK	C	UNK	3/4"	3/29/2023	C	3/4"	3/29/2023	SF	UNK	C	3/4"	UNK	3/29/23: Installed 3/4" copper from wm-cs. Installed 3/4" cs & box. Connected to existing 3/4" copper on customers side.	Installation Record	Y	3/29/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11314	1110 S LOCUST AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11331	517 W 12TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11334	501 W 11TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11337	1200 S CHESTNUT AVE	N	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11340	314 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/19/2014	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
11343	1604 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11347	1033 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11350	600 W 12TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11356	106 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1945	C	UNK	1/1/1945	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/26/2015	Cross Connection Survey	
11361	1110 S CLARK AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11363	604 E 3RD ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	NONRES	UNK	C	1"	UNK	SPENCER-RON MEYER	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11367	601 W 12TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11372	600 W 11TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11376	710 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/11/2017	Cross Connection Survey	
11378	311 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CUT-IN CURBBOX-8-16-02	Installation Record	N			Field Inspection Only	Y	3/16/2016	Cross Connection Survey	
11384	107 W 14TH ST	UNK	C	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	FEEDS LAUNDRY : REIGEL PLUMBING	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11387	1300 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	C	1 1/2"	1/1/2009	NONRES	UNK	C	1 1/2"	UNK	FEEDS "THE STORE" & SUB SHOP	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11390	510 W 12TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11394	1116 S LOCUST AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11399	1111 S CLARK AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11400	800 S SPRUCE AVE	N	C	Y	3/4"	5/5/2020	C	3/4"	5/5/2020	SF	UNK	C	3/4"	UNK	DUPLEX WITH 800A. 2012 CURB BOX VERIFIED. 5/5/2020 - Replaced both sides w/ copper (removed lead)	Installation Record	Y	5/5/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11404	609 S CHERRY AVE	N	L	UNK	UNK	UNK	HDPE	UNK	1/1/2013	SF	UNK	UNK-LG	UNK	1/1/2013	2013-INSTALLED NEW SERVICE ON PROP. SIDE. INSTALLED CURB VALVE \BOX	SL repair/replace record	Y	2013	Mech excav	Field inspection only	Y	1/1/2013	Mech excav	
11407	709 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/19/2017	Cross Connection Survey	
11433	1809 WOODSVIEW DR	UNK	UNK	UNK	1 1/2"	1/1/1997	C	1 1/2"	1/1/1997	SF	UNK	C	1 1/2"	UNK	DUPLEX	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11442	1809 W ARLINGTON ST	UNK	C	UNK	1 1/2"	1/1/1997	C	1 1/2"	1/1/1997	SF	UNK	C	1 1/2"	UNK	DUPLEX	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11445	1808 WOODSVIEW DR	UNK	C	UNK	1 1/2"	1/1/1997	C	1 1/2"	1/1/1997	SF	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11453	506 W 12TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11459	1000 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/25/2017	Cross Connection Survey	
11466	806 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/2/2017	Cross Connection Survey	
11470	816 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11473	608 W 11TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11476	711 E 3RD ST	UNK	UNK	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	GAFFNEY PLUMBING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11479	1204 S OAK AVE	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	NONRES	UNK	C	1"	UNK	2006-NEW TAP W/ SADDLE	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11482	510 W 11TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11487	900 E 4TH ST	UNK	UNK	UNK	4"	1/1/1998	CI-U	4"	1/1/1998	NONRES	UNK	CI-U	4"	UNK	IS UNKNOWN. SERVICE IS FOR JUNIOR HIGH SCHOOL	Installation Record	Y	1/1/1998	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
11491	1814 W ARLINGTON ST	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11497	1214 S CHESTNUT AVE	N	C	Y	3/4"	8/31/2020	C	3/4"	8/31/2020	SF	UNK	C	3/4"	UNK	REMOVED WIPE FROM MAIN TO APPROX. 7'E OF CURB VALVE. 8/31/2020 - ALL LEAD REMOVED & REPLACED W/ 3/4" COPPER FROM MAIN - HOUSE. NEW C.S. (MEYERS)	Installation Record	Y	8/31/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11506	1810 W ARLINGTON ST	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11511	1105 S LOCUST AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	REDETKZE: STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11522	802 S COLUMBUS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11527	707 E 3RD ST	N	C	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	RON MEYER	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11554	911 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11557	1806 W ARLINGTON ST	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11560	901 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11564	509 W 11TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11568	309 E 2ND ST	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER, CURB VALVE AND BOX IS 1'-2" SOUTH OF GAS MAIN. SAN. LAT. IS DIRECTLY BELOW WATER SERVICE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11571	701 W 11TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11574	913 S CEDAR AVE	N	C	Y	1"	10/12/2022	C	1"	10/12/2022	SF	UNK	C	1"	UNK	10/12/22: Removed lead from wm-cs and replaced w/ 1" copper and new 1" cs & box. Used existing corp., connected to existing 3/4" copper on customers side.	Installation Record	Y	10/12/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11583	1101 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11586	1804 W 8TH ST	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	RON MEYERS	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11589	1701 WOODSVIEW DR	UNK	DI	UNK	6"	1/1/1997	DI	6"	1/1/1997	SF	UNK	DI	6"	UNK	WOODSVIEW BLOCK 1	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
11600	1001 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11606	310 S CONCORD AVE	UNK	C	Y	1"	5/2/2023	C	1"	5/2/2023	SF	UNK	C	1"	UNK	5/2/23: Removed lead from wm-cs, replaced w/ 1" copper. Installed new 1" tap, 1" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	5/2/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11608	315 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000: CURB BOX INSTALLED.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11619	1516 W ARLINGTON ST	UNK	C	UNK	1"	8/1/2022	C	1"	8/1/2022	SF	UNK	C	1"	UNK	8/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11622	807 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11624	201 S STATE AVE	N	UNK	UNK	UNK	1/1/2001	C	UNK	1/1/2001	SF	UNK	C	UNK	UNK	MEWD/REPLACED CORP TO CURB BOX	Installation Record	Y	1/1/2001	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11627	907 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11630	811 S CEDAR AVE	N	C	Y	3/4"	9/14/2020	C	3/4"	9/14/2020	SF	UNK	C	3/4"	UNK	9/14/2020 - Removed lead and replaced w/ 3/4" copper from corp to c.s. Pulled across street with 303 E. 9TH ST. water line at same time. Gaffney removed galvanized and replaced w/ 3/4" copper from new CS & BOX to Meter	Installation Record	Y	9/14/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11633	1008 S CHERRY AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Replaced the lead with copper & cut in a curb box - locking vlave inside	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11637	306 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER INSIDE	Installation Record	N			Field Inspection Only	Y	5/20/2016	Cross Connection Survey	
11640	1005 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11643	800 E 7TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE OFF OF APPLE. 7/20/22: Removed lead gooseneck at main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	7/20/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11646	1004 W 4TH ST	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/25/23: Dug and found 3/4" copper at water main	Installation Record	Y	5/25/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11652	1106 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	Removed lead wipe on main & lowered from main to center of road, connected to copper	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11658	801 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11664	612 W 12TH ST	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11667	611 W 12TH ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11673	612 W 11TH ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11676	1113 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11679	521 W MAGEE ST	UNK	C	UNK	1"	6/27/2022	C	1"	6/27/2022	SF	UNK	C	1"	UNK	6/27/22: Installed new copper from main to the house. 1" copper on the utility side, 3/4" copper on the customer side.	Installation Record	Y	6/27/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11682	507 W 7TH ST	UNK	C	Y	1"	6/20/2022	C	1"	6/20/2022	SF	UNK	C	1"	UNK	6/20/22: Removed lead from main to cs, replaced w/ 1" copper. Installed new 1" tap and 1" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/20/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11684	409 S CHESTNUT AVE	UNK	DI	UNK	4"	1/1/2013	DI	4"	1/1/2013	NONRES	UNK	DI	4"	UNK	CLOW VALVE	Installation Record	Y	1/1/2013	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
11688	1115 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11693	1107 W 11TH ST	UNK	C	UNK	1"	1/1/1998	P	1"	1/1/1998	SF	UNK	P	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11703	106 S PEACH AVE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	MEWD-2003	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11706	711 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11711	703 W ADLER RD	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/11/2014	Cross Connection Survey	
11713	818 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11721	809 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11729	1201 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
11733	1708 W 8TH ST	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11749	1515 W ARLINGTON ST	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STRATFORD PLBG	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11752	1801 W ARLINGTON ST	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11761	200 S LINCOLN AVE	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK	FLEWELLEN PLUMBING	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11764	1013 S CHERRY AVE	N	C	Y	1"	3/17/2024	L	5/8"	UNK	SF	UNK	C	UNK	UNK	3/17/24: Removed lead from wm-cs and replaced w/ 3/4" copper and a new 3/4" cs & box. Connect to lead after cs.	SL repair/replace record	Y	3/17/2024	Visual insp during install or repair	Previous eval	Y	3/17/2024	Mech excav	
11764	1013 S CHERRY AVE	N	C	Y	1"	3/17/2024	C	3/4"	1/1/1926	SF	UNK	C	C		3/17/24: Removed lead from wm-cs and replaced w/ 3/4" copper and a new 3/4" cs & box. Connect to lead after cs.	SL repair/replace record	Y	3/17/2024	Visual insp during install or repair	Field Inspection Only	Y	3/17/2024	Visual Insp during install or repair	
11767	510 E 3RD ST	UNK	UNK	UNK	3/4"	1/1/1962	P	3/4"	1/1/1962	SF	UNK	P	3/4"	UNK	3/4" HDPE on property side	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11770	1009 W 5TH ST	N	C	UNK	1"	1/1/2007	L	1"	1/1/2007	SF	UNK	L	UNK	1/1/2007	HAAS 1" LEAD INSIDE	SL repair/replace record	Y	1/1/2007	Visual insp during install or repair	Previous eval	Y	1/1/2007	Visual Insp during install or repair	
11773	1611 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11776	201 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER. SAN LAT. COME OFF 2ND ST.	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11781	907 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	EARTH INC. JO#5344	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11784	505 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		1/2" COPPER L.V. - L.V. REMOVED 3-7-90 AND REPLACED WITH A BALL VALVE	Installation Record	N			Field Inspection Only	Y	4/15/2015	Cross Connection Survey	
11787	503 S CHESTNUT AVE	UNK	C	UNK	1 1/2"	1/1/2013	C	1 1/2"	1/1/2013	NONRES	UNK	C	1 1/2"	UNK	VALVE ATTACHED TO EXISTING 1-1/2" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11793	511 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/1/2015	Cross Connection Survey	
11798	505 W 11TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11804	1009 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11810	809 E 3RD ST	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	STRATFORD PLB.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11813	513 W 11TH ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11816	1109 S LOCUST AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11824	1803 W ARLINGTON ST	UNK	UNK	UNK	1"	1/1/1997	P	1"	1/1/1997	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11833	215 S WISCONSIN AVE	N	L	UNK	UNK	1/1/1941	C	UNK	1/1/1941	SF	UNK	C	UNK	1/1/1941	3/4" LEAD, REPLACED CORPORATION REMOVED LEAD WIPE & 2' OF LEAD, INSULATED 3-3-92	SL repair/replace record	Y	1992	Mech excav	Field inspection only	Y	3/2/2015	Cross Connection Survey	
11838	800 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/12/2016	Cross Connection Survey	
11842	305 S VINE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED ALL LEAD	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11845	110 S CHERRY AVE	UNK	C	Y	1"	5/10/2023	C	1"	5/10/2023	SF	UNK	C	1"	UNK	5/10/23: Removed lead from wm-cs. Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	5/10/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11847	400 E 3RD ST	UNK	C	UNK	1"	6/5/2023	C	1"	6/5/2023	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	6/5/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11852	810 E 4TH ST	N	C	Y	1"	6/25/2024	C	1/2"	1/1/1926	SF	UNK	C	C		6/25/24:Removed lead from wm-cs. Replaced w/ 1" corp (Old corp is 2' East of new corp.), 1" copper, 1" cs & box. Connected to 1/2" copper 3' South of cs. 1/2" copper is inside of galvanized pipe.	SL repair/replace record	Y	6/25/2024	Visual insp during install or repair	Field Inspection Only	Y	6/25/2024	Visual Insp during install or repair	
11858	812 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/15/2017	Cross Connection Survey	
11861	1621 S ERICKSON AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	9/7/23: No lead, put in new 3/4" cs.	Installation Record	Y	9/7/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11866	706 E 4TH ST	N	C	Y	1"	6/18/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/18/2024: Removed lead from wm-cs. Replaced w/ 1" corp. (2' East of old corp), 1" copper, connected to existing 3/4" copper 5' from cs (street side of cs)	SL repair/replace record	Y	6/18/2024	Visual insp during install or repair	Field Inspection Only	Y	6/18/2024	Visual Insp during install or repair	
11886	605 E 8TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11889	410 W 6TH ST	N	C	Y	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	LEAD REPLACED IN STREET 7-25-2018 WITH 3/4" COPPER	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11892	1003 GEORGE DR	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11898	513 W 13TH ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	DUPLEX WITH 513 W 13TH	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11901	507 W 13TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11904	906 S CHERRY AVE	N	C	Y	3/4"	1/1/2009	C	3/4"	1/1/2009	SF	UNK	C	3/4"	UNK	2009-INSTALLED 3/4" COPPER IN STREET. REMOVED LEAD WIPE @ MAIN.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11908	801 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	4/18/2016	Cross Connection Survey	
11911	506 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/2/2016	Cross Connection Survey	
11919	606 E 10TH ST	UNK	UNK-LG	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	2/29/2016	Cross Connection Survey	
11922	1208 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	UNK-LG	5/8"	1/1/1926	SF	UNK	UNK	UNK	1/1/1926	2009-REMOVED LEAD WIPE @ MAIN.	SL repair/replace record	Y	2011	Mech excav	Field inspection only	Y	6/3/2015	Cross Connection Survey	
11925	1502 S CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11929	1007 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO DITCH, CONNECTED TO EXISTING 3/4" COPPER TO DITCH	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11933	206 S STATE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11937	406 E 6TH ST	N	UNK	UNK	UNK	5/20/1997	C	UNK	5/20/1997	SF	UNK	C	UNK	UNK	100% COPPER	Installation Record	Y	5/20/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11940	712 E 3RD ST	N	C	Y	1"	8/9/2022	C	1"	8/9/2022	SF	UNK	C	1"	UNK	8/9/22: All lead removed. Replaced with 1" copper from main to new 1" cs & box. Used existing corp. Connected to existing 3/4" copper on customers side.	Installation Record	Y	8/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11947	1205 S CHESTNUT AVE	N	UNK	Y	UNK	8/21/2000	C	UNK	8/21/2000	SF	UNK	C	UNK	UNK	LEAD WIPE @ CURB STOP REMOVED. LEAD WIPE AT MAIN & 27' OF LEAD REMOVED. 8/21/00	Installation Record	Y	8/21/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11950	1104 W 7TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
11957	309 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1941	C	UNK	1/1/1941	SF	UNK	C	C		CB/LV UNKNOWN. 5/8" copper on property side	Installation Record	N			Field Inspection Only	Y	5/25/2017	Cross Connection Survey	
11960	1411 S APPLE AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11973	907 S CEDAR AVE	Y	C	Y	1"	10/5/2022	C	1"	10/5/2022	SF	UNK	C	1"	UNK	10/5/22: New 1" copper from main to 1" curb valve and new box. Used existing corp. Lead on owners side. 2023: Gaffney replaced lead w/ 3/4" copper from cs-meter.	Installation Record	Y	10/5/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
11976	1301 S ADAMS AVE	UNK	C	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11981	808 S ASH AVE	N	UNK	Y	UNK	1/1/1985	C	UNK	1/1/1985	SF	UNK	C	UNK	UNK	REMOVED LEAD 1985 PAVING	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
11987	607 W 4TH ST	UNK	C	Y	1"	5/1/2023	C	1"	5/1/2023	SF	UNK	C	1"	UNK	5/23: Removed lead from wm-cs replaced w/ 1" copper, 1" tap, 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	5/1/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12000	611 W 13TH ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 10/10/97	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12003	203 W 14TH ST	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/28/2015	Cross Connection Survey	
12006	408 S WALNUT AVE	N	C	UNK	1/2"	UNK	C	1/2"	UNK	SF	UNK	C	1/2"	UNK	3/4" COPPER FROM BOX TO MAIN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12013	605 E 4TH ST	UNK	UNK	UNK	1 1/2"	1/1/1984	C	1 1/2"	1/1/1984	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12019	1004 GEORGE DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12022	206 S CONCORD AVE	UNK	UNK	UNK	UNK	1/1/1978	C	UNK	1/1/1978	SF	UNK	C	UNK	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12025	509 E 3RD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/22/2016	Cross Connection Survey	
12029	406 W 7TH ST	UNK	C	Y	1"	6/9/2022	C	1"	6/9/2022	SF	UNK	C	1"	UNK	6/9/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12033	908 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1937	C	5/8"	1/1/1937	SF	UNK	C	UNK	1/1/1937	2006-INSTALLED CURB VALVE W/BOX. 2014-VERIFIED 1/2 COPPER INSIDE	SL repair/replace record	Y	2006	Mech excav	Field inspection only	Y	11/4/2015	Cross Connection Survey	
12039	909 S ASH AVE	N	L	UNK	3/4"	1/1/1946	C	3/4"	1/1/1946	SF	UNK	C	UNK	1/1/1946	2010-INSTALLED CURB BOX & 1" POLY CURB VALVE TO HSE. REMOVED LEAD WIPES. REIGEL PLMG.	SL repair/replace record	Y	2010	Mech excav	Field inspection only	Y	2/26/2016	Cross Connection Survey	
12043	313 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/30/2015	Cross Connection Survey	
12046	213 W 3RD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	6/8/2015	Cross Connection Survey	
12049	513 E 3RD ST #A	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	2/25/2015	Cross Connection Survey	
12056	1101 S CEDAR AVE	N	C	Y	1"	10/24/2022	C	1"	10/24/2022	SF	UNK	C	1"	UNK	2022: Removed lead, installed new 1" copper from main to curb valve. New curb valve and box. Used existing corp and connected to existing 3/4" copper on owners side.	Installation Record	Y	10/24/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
12059	205 W 14TH ST	UNK	UNK-LG	UNK	3/4"	1/1/1929	C	3/4"	1/1/1929	SF	UNK	C	C		REIGEL PLUMBING	Installation Record	N			Field Inspection Only	Y	9/18/2015	Cross Connection Survey	
12062	309 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	10/30/2014	Cross Connection Survey	
12070	512 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER LOCKING VALVE. 3/4" Copper locking valve	Installation Record	N			Field Inspection Only	Y	6/29/2017	Cross Connection Survey	
12074	806 E 3RD ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12074	806 E 3RD ST	N	C	Y	1"	8/1/2022	C	1"	8/1/2022	SF	UNK	C	1"	UNK	8/1/22: Replaced lead from wm-cs w/ 1" copper. Abandoned old corp (5' West), installed new 1" corp 5' west (mainbreak sleeve is 18" West of new corp) Installed 1" cs & box. Conn. to exist. 3/4" copper 16" South of cs. Swr lateral replaced @ the same time.	Installation Record	Y	8/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12079	401 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB LOCATION VERIFIED 3/25/97. Copper through basement floor via email from customer (4/6/2121)	Installation Record	N			Field Inspection Only	Y	2/24/2015	Cross Connection Survey	
12083	913 W 4TH ST	N	C	Y	1"	10/31/2022	C	1"	10/31/2022	SF	UNK	C	1"	UNK	2022: Removed lead and installed 1" copper from main to house w/ Meyers. New curb stop and box.	Installation Record	Y	10/31/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12087	303 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		NEW CURB VALVE INSTALLED 5-21-99,REMOVED LEAD WIPES BOTH SIDES OF VALVE; 2014-REMOVED LEAD WIPE @ MIAN	Installation Record	N			Field Inspection Only	Y	5/21/1999	Cross Connection Survey	
12094	1005 S CEDAR AVE	N	C	Y	1"	10/27/2022	C	1"	10/27/2022	SF	UNK	C	1"	UNK	2022: Removed lead from wm-curb, replaced w/ 1" copper. Connected to existing corp w/ 2' - 3/4" copper. Installed new 1" cs & box. Connected to existing 3/4" copper 6" East of the cs. Used vavle box top as frost sleeve in driveway	Installation Record	Y	10/27/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12097	1013 S CEDAR AVE	N	C	Y	1"	10/25/2022	C	1"	10/25/2022	SF	UNK	C	1"	UNK	2022: Removed lead from wm-sidwalk. pulled in 1" copper. Installed 1" cs & box. Connected to 3/4" copper 2' East of the cs. Connected to existing corp @ the main. 3/4"x1" cu-cu 2' east of the watermain	Installation Record	Y	10/25/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12101	603 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	UNK-LG	UNK	1/1/1926	SF	UNK	UNK	UNK		<Null>	Installation Record	N			Field Inspection Only	Y	9/18/2023	Cross Connection Survey	
12104	313 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/23/2016	Cross Connection Survey	
12107	116 W 14TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		COMES OFF OF 14TH	Installation Record	N			Field Inspection Only	Y	7/5/2016	Cross Connection Survey	
12110	309 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12113	1012 S SEVERNS AVE	UNK	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO NEW CB. CONNECTED TO EXISTING 3/4" COPPER ON CUSTOMERS SIDE. SEWER LATERAL IS 1.5' BELOW WATER SERVICE	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12127	409 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/12/2017	Cross Connection Survey	
12131	1100 W 4TH ST	UNK	C	UNK	1"	7/23/2019	C	1"	7/23/2019	SF	UNK	C	1"	UNK	USED STAINLESS SERVICE SADDLE, TAPPED 1" CORP, RAN 4' OF 1" COPPER, CONNECTED TO EXISTING 1" COPPER	Installation Record	Y	7/23/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12134	315 S CONCORD AVE	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB/LV UNKNOWN REMOVE THE WIPE ON 5/12/93 - 3/4" COPPER. 5/3/23: Verified copper @ wm. Installed 3/4" cs & box.	Installation Record	Y	5/3/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12141	407 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB VERIFIED. 2022: Removed lead wipes - Service is 100% copper	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12149	401 W 7TH ST	N	C	UNK	1"	1/1/1965	C	1"	1/1/1965	SF	UNK	C	1"	UNK	GAFFENY. 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 8'6" DEEP	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12152	513 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/23/2017	Cross Connection Survey	
12155	616 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	3/12/2010	Cross Connection Survey	
12158	609 S HIGHLAND AVE	UNK	C	Y	1"	5/30/2023	C	1"	5/30/2023	SF	UNK	C	1"	UNK	5/30/23: replaced lead w/ 1" copper from wm-cs. Conn to existing corp. w/ 18" - 3/4" copper. Installed 1" cs & box. Conn to existing 1/2" copper after cs. 1/31/24: Reigle replaced 1/2" copper to 3/4" copper cs-meter.	Installation Record	Y	5/30/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12161	512 S WALNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	NEW COPPER FROM MAIN TO 5' PAST WALK.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12165	815 W 6TH ST	N	C	N	3/4"	1/1/1932	C	3/4"	1/1/1932	SF	UNK	C	C		3/4" copper @ main to under curb. dug and verified 7/14/23	Installation Record	N			Field Inspection Only	Y	12/2/2014	Cross Connection Survey	
12168	901 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/13/2017	Cross Connection Survey	
12171	116 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO EXISTING 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12174	308 S VINE AVE	N	L	UNK	UNK	1/1/1926	P	UNK	1/1/1926	SF	UNK	P	UNK	1/1/1926	2009- REMOVE LEAD WIPE @ MAIN	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	4/29/2016	Cross Connection Survey	
12181	1407 W ARLINGTON ST	UNK	C	UNK	1"	8/11/2022	C	1"	8/11/2022	SF	UNK	C	1"	UNK	8/11/22: Installed 1" tapping saddle, 1" copper and 1" cs & box. Connected to 1" copper after cs.	Installation Record	Y	8/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12184	502 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1929	C	UNK	1/1/1929	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/2/2015	Cross Connection Survey	
12187	405 S CHESTNUT AVE	N	C	UNK	1"	1/1/2013	C	1"	1/1/2013	SF	UNK	C	1"	UNK	CONNECTED TO EXISTING 1/2" COPPER	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12190	806 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS 1" PLASTIC INSIDE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12197	703 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/23/2013	Cross Connection Survey	
12209	1009 W 8TH ST	N	C	Y	3/4"	5/9/2018	C	3/4"	5/9/2018	SF	UNK	C	3/4"	UNK	5/2018 - ALL LEAD BOTH SIDES REMOVED, NEW COPPER FROM MAIN TO HOUSE AND CURB STOP	Installation Record	Y	5/9/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12216	402 W 7TH ST #A	UNK	C	Y	1"	6/8/2022	C	1"	6/8/2022	SF	UNK	C	1"	UNK	6/8/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12220	911 S COLUMBUS AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE OFF OF ARLINGTON. 8/9/2021: Removed Lead gooseneck @ WM & replaced w/ 3/4" copper. Connected to existing 3/4" copper 2' from WM	Installation Record	Y	8/9/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12223	307 S VINE AVE #A	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12227	309 E 8TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	GAFFNEY - SERVICE COMES OFF OF CHERRY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12232	802 W 5TH ST	N	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	HAAS 1" PLASTIC INSIDE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12239	403 W 7TH ST	N	C	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12245	405 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		1/2" COPPER & LOCKING VAVLE	Installation Record	N			Field Inspection Only	Y	12/7/2016	Cross Connection Survey	
12249	801 S CHERRY AVE	Y	UNK	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 8TH ALSO SERVICE IS Y CONNECTED WITH 404 E 8TH	Installation Record	Y	1/1/1926	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12249	801 S CHERRY AVE	UNK	C	UNK	3/4"	3/29/2023	C	3/4"	3/29/2023	SF	UNK	C	3/4"	UNK	3/29/23: Installed 3/4" copper from wm-cs. Installed 3/4" cs & box. Connected to existing 3/4" copper on customers side.	Installation Record	Y	3/29/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12255	716 E 3RD ST	N	C	Y	1"	8/17/2022	C	1"	8/17/2022	SF	UNK	C	1"	UNK	2003-REMOVED LEAD WIPE & INSTALLED CURB VALVE W/ BOX 2022- Removed lead from wm-house. New 1" copper (main-cs), new 1" tap, copper on customer side	Installation Record	Y	8/17/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12257	312 W PARK ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED. 2021 - 1" copper property side	Installation Record	Y	1/1/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12260	411 W MAGEE ST	N	C	Y	1"	5/23/2022	C	1"	5/23/2022	SF	UNK	C	1"	UNK	5/23/22: Removed lead from wm-cs. Replaced with 1" tap, 1" copper, 1" cs & box. Connected to existing 1/2" copper on property side.	Installation Record	Y	5/23/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12266	405 S WISCONSIN AVE	N	L	UNK	5/8"	1/1/1928	C	5/8"	1/1/1928	SF	UNK	C	UNK	1/1/1928	2009- REMOVED LEAD WIPE @ MAIN. 1" copper on property side	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	10/31/2014	Cross Connection Survey	
12270	300 E 4TH ST	N	C	Y	1"	1/1/2022	G	1"	UNK	SF	UNK	G	UNK	UNK	2022: New 1" copper from main to curb valve, used existing corp. New 1" cs & box - hooked to galvanized on owners side	SL repair/replace record	Y	1/1/2022	Visual insp during install or repair	Previous eval	Y	8/10/2017	Cross connection survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
12274	1001 S CEDAR AVE	N	C	Y	1"	10/28/2022	C	1"	10/28/2022	SF	UNK	C	1"	UNK	2022: Removed lead from wm-sidewalk, replaced w/ 1" copper. Connected to existing corp w/ 12" - 3/4" copper. Installed new 1" cs & box. Connected to existing 3/4" copper 2' East of the cs.	Installation Record	Y	10/28/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12281	407 W 7TH ST	UNK	C	Y	1"	6/9/2022	C	1"	6/9/2022	SF	UNK	C	1"	UNK	6/9/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	6/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12286	714 E 9TH ST	N	C	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	NEW ALL THE WAY TO HOUSE.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12291	1017 W ARLINGTON ST	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	3/4 COPPER PROPERTY SIDE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12298	501 W MAGEE ST	N	C	Y	3/4"	10/24/2018	C	3/4"	10/24/2018	SF	UNK	C	3/4"	UNK	REMOVED ALL LEAD MAIN TO HOUSE	Installation Record	Y	10/24/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12301	308 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		CB/LV UNKNOWN. copper on property side	Installation Record	N			Field Inspection Only	Y	11/26/2014	Cross Connection Survey	
12304	305 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	CB LOCATION VERIFIED 12/5/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12307	1312 W ARLINGTON ST	UNK	C	UNK	1"	8/10/2022	C	1"	8/10/2022	SF	UNK	C	1"	UNK	8/10/22: Installed 1" tapping saddle, 1" corp. and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12310	302 S CONCORD AVE	UNK	C	Y	1"	4/25/2023	C	1"	4/25/2023	SF	UNK	C	1"	UNK	4/25/23: Removed lead from wm-cs, replaced w/ 1" copper. Installed new 1" tap, 1" cs & box. Connected to existing 3/4" copper on customer side.	Installation Record	Y	4/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12315	207 W 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB VERIFIED 3-97. REMOVED LEAD WIPE ON CURB STOP. REPLACED CURB STOP & BOX 6-9-1997 JT	Installation Record	N			Field Inspection Only	Y	11/19/2014	Cross Connection Survey	
12321	511 E 6TH ST	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	PRIVATE LINE DOWN THE CENTER OF 6TH ST. REPLACED 1" PRIVATE LINE 9-24-98 (LEAD LOCKING VALVE)	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12324	311 W 5TH ST	N	C	Y	UNK	1/1/2015	P	UNK	1/1/2015	SF	UNK	P	UNK	UNK	2015-LEAD WIPE REMOVED ON OUR SIDE- NEW 3/4" POLY ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12327	1600 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12330	1006 W 8TH ST	UNK	C	Y	1"	5/23/2023	C	1"	5/23/2023	SF	UNK	C	1"	UNK	5/23/23: Removed lead & replaced w/ 1" copper (wm-cs), 1" tap (2.5' West of old tap). Meyers replaced lead w/ 1" copper from cs - meter. Installed new 1" cs & box	Installation Record	Y	5/23/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12337	1501 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12340	900 E 4TH ST	UNK	UNK	UNK	2"	1/1/1998	C	2"	1/1/1998	NONRES	UNK	C	2"	UNK	FEEDS BEELL STADIUM	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12344	300 S CONCORD AVE	UNK	C	Y	1"	4/26/2023	C	1"	4/26/2023	SF	UNK	C	1"	UNK	4/26/23: Removed lead from wm-cs, replaced w/ 1" copper. Installed new 1" tap, 1" cs & box. Meyers replaced lead w/ 3/4" copper from cs-meter	Installation Record	Y	4/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12347	1420 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12356	911 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		pex on property side (per Brian Dillinger)	Installation Record	N			Field Inspection Only	Y	3/6/2014	Visual insp at meter	
12359	408 E 3RD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB VERIFIED 3-97	Installation Record	N			Field Inspection Only	Y	6/30/2017	Cross Connection Survey	
12365	306 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1942	C	UNK	1/1/1942	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/28/2014	Cross Connection Survey	
12375	1009 S CEDAR AVE	N	C	Y	1"	10/31/2022	C	1"	10/31/2022	SF	UNK	C	1"	UNK	10/31/22: Removed lead from wm-cs. Replaced w/ 1" copper. Connected to existing corp. w/ 12" x 3/4" copper. Installed new cs & box, connected to existing 3/4" copper 12" East of the cs. Broke san. wye @ swr main. Dalton Tysver repaired.	Installation Record	Y	10/31/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12378	512 S ASH AVE	N	UNK	Y	UNK	1/1/1985	C	UNK	1/1/1985	SF	UNK	C	UNK	UNK	REMOVED LEAD & INSULATED 1985 PAVING	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12385	400 W 6TH ST	N	C	UNK	3/4"	9/13/2018	C	3/4"	9/13/2018	SF	UNK	C	3/4"	UNK	9/13/18 - NEW COPPER FROM MAIN TO HOUSE WITH NEW CURB STOP AND BOX, WORKED WITH REIGEL	Installation Record	Y	9/13/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12388	1201 S CENTRAL AVE	UNK	C	Y	1"	4/29/2022	C	1"	4/29/2022	NONRES	UNK	C	1"	UNK	2009- removed lead wipe at main. 4/29/22: Bored in new 1" copper from main to cs. Service is 13' deep to get under storm sewer. Installed new 1" cs & box. Service is not in a straight line, a big loop and bend at cs coming up from 13' deep.	Installation Record	Y	4/29/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12394	603 E 3RD ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	NONRES	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12397	607 E 3RD ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12400	710 E 9TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12403	710 S PEACH AVE	N	L	UNK	UNK	1/1/1940	P	UNK	1/1/1940	SF	UNK	P	UNK	1/1/1940	REMOVED WIPE BY BOX COPPER INSIDE, 2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 6'3" DEEP	Previous eval	Y	2020	Mech excav	Field inspection only	Y	3/15/2016	Visual Insp during install or repair	
12406	906 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12409	907 W 4TH ST	Y	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/24/23: Removed 4' lead gooseneck at the water main and replaced w/ 3/4" copper.	Installation Record	Y	5/24/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12413	720 S HIGHLAND AVE	UNK	C	Y	1"	6/12/2023	C	1"	6/12/2023	SF	UNK	C	1"	UNK	6/12/23: Replaced lead from wm-cs, replaced w/ 1" copper and installed 1" cs & box. Connected to existing 3/4" copper after cs. Conn. to existing corp. using 18" - 3/4" copper @ wm.	Installation Record	Y	6/12/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12417	807 W 4TH ST	UNK	C	Y	1"	5/18/2023	C	1"	5/18/2023	SF	UNK	C	1"	UNK	5/18/23: Removed lead wm-cs. Installed w/ 1" tap, 1" copper, 1" cs & box. 6/18/23: Meyers replaced lead w/ 1" copper cs-meter. Plgb. Permit #20230822	Installation Record	Y	5/18/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12420	402 S WISCONSIN AVE	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	10/10/2014	Cross connection survey	
12428	406 W 5TH ST	N	C	UNK	1"	9/1/2022	C	1"	9/1/2022	SF	UNK	C	1"	UNK	9/22: Meyers & Utility installed 1" copper from main to the house.	Installation Record	Y	9/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12440	805 S SPRUCE AVE	UNK	UNK-LG	UNK	1/2"	1/1/1926	C	1/2"	1/1/1926	SF	UNK	C	C		1/2" COPPER INSIDE	Installation Record	N			Field Inspection Only	Y	4/27/2018	Cross Connection Survey	
12443	713 E 15TH ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12446	1200 W ARLINGTON ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	8/5/2021: Removed Lead gooseneck @ WM & Replaced w/ 3/4" copper. Connected to existing 3/4" copper 2.5' from WM	Installation Record	Y	8/5/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12449	809 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12452	711 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12455	303 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB/LV UNKNOWN	Installation Record	N			Field Inspection Only	Y	5/24/2017	Cross Connection Survey	
12458	1010 W PARK ST	UNK	C	Y	1"	7/23/2021	C	1"	7/23/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/23/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12461	509 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB LOCATION VERIFIED 6/10/97	Installation Record	N			Field Inspection Only	Y	1/15/2015	Cross Connection Survey	
12464	504 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	8/26/20: Reigel plgg replaced 6' of 3/4" copper from middle of sidewalk to house. Verified copper on customer side. 2 - 3/4" compression fittings installed. 7/18/22: Removed lead wipe at main, replaced with 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	8/26/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12468	1102 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	<Null>	Installation Record	Y	2009	Mech excav	Field inspection only	Y	10/21/2015	Cross Connection Survey	Internal Notes
12472	100 S STATE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12485	112 S VINE AVE	N	C	UNK	1"	1/1/2010	P	1"	1/1/2010	SF	UNK	P	1"	UNK	CONNECTED TO 1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12488	305 E 9TH ST	N	C	Y	1"	11/9/2021	C	1"	11/9/2021	SF	UNK	C	1"	UNK	11/9/21: MU Abandonded exist. tap & re-tapped 16" East w/ 1" Corp. Replaced exist. lead w/ 1" copper from wm-cs. Meyers installed 1" cs & box & replaced lead w/ 1" copper from cs-meter. New tap is 2' West of tap for 306 E. 9th. Pulled service under curb.	Installation Record	Y	11/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12491	1608 S ERICKSON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
12494	605 W 13TH ST #A	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12501	411 E 14TH ST	N	C	Y	1"	8/6/2024	C	3/4"	1/1/1926	SF	UNK	C	C		Earth Inc. 6' of 1" copper from cs to existing 3/4" copper. See sheet 30 of the construction report.	SL repair/replace record	Y	8/6/2024	Mech excav	Field Inspection Only	Y	8/6/2024	Visual Insp during install or repair	
12511	411 S CEDAR AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2008-REMOVED LEAD WIPE @ CURB VALVE. 2022: Removed lead, service is 3/4" copper. No Lead	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12517	515 W 5TH ST	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC JO35344. 3/4" copper on property side	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12519	510 W 13TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS-VIC & TOM	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12529	907 MARTIN DR	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12532	512 W 14TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	1993-REPLACED WIPES INSTALLED NEW COPPER FROM Y TO HOUSE	Installation Record	Y	1/1/1993	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12538	304 W 4TH ST	UNK	C	Y	3/4"	5/16/2018	C	3/4"	5/16/2018	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO HOUSE INSTALLED 3/4" COPPER, REIGEL INTALLED NEW CURB STOP AND BOX	Installation Record	Y	5/16/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12541	1000 W PARK ST	UNK	C	Y	1"	7/26/2021	C	1"	7/26/2021	SF	UNK	C	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/26/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12546	712 E 15TH ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12555	415 W MAGEE ST	N	C	Y	1"	6/6/2022	C	1"	6/6/2022	SF	UNK	C	1"	UNK	6/6/22: Removed full lead, replaced with 1" copper from main to cb, New 1" tap and 1" cs & box. Conn. to 3/4" copper after cs.	Installation Record	Y	6/6/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12558	900 W 4TH ST	UNK	C	Y	1"	8/30/2023	C	1"	8/30/2023	SF	UNK	C	1"	UNK	8/30/23: Mark Meyers - Lead replacement - 1' - 1" copper from cs to 1"x3/4" fitting - Conn. to existing 3/4" copper. Old corp. is 15" South of new corp.	Installation Record	Y	8/30/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12560	1101 S CHERRY AVE	N	C	Y	3/4"	5/15/2020	C	3/4"	5/15/2020	SF	UNK	C	3/4"	UNK	5/15/2020 Replaced lead from main to CS. Verified Lead from cs to house 2022-Replaced lead on customer side	Installation Record	Y	5/15/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12574	308 S WISCONSIN AVE	UNK	C	UNK	3/4"	10/1/2023	C	3/4"	10/1/2023	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	10/1/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12579	702 S PALMETTO AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 6' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12582	702 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/20/22: Removed lead gooseneck at main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	7/20/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12585	912 S PEACH AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2009-NEW CURB VALVE & BOX	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12594	1505 S CHESTNUT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12603	1019 W PARK ST	UNK	C	Y	1"	7/15/2021	C	1"	7/15/2021	SF	UNK	C	1"	UNK	Meyers replaced lead service from house to where we left off. Also replaced remaining sewer. Installed 13' of 1" copper from CS to 8' behind walk. Clay sewer over old watermain, removed & repaired w/ 6" PVC. Water service tapped w/ S.S. 8" saddle w/ 1" CC	Installation Record	Y	7/15/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12620	204 S ASH AVE	N	P	UNK	1"	1/1/2019	C	1"	1/1/2019	SF	UNK	C	1"	UNK	1/2" COPPER INSIDE - J&R DIRECTIONAL DRILLED 1" POLY FROM 3RD STREET TO CURB STOP	Installation Record	Y	1/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12623	304 S PALMETTO AVE	N	C	Y	1"	6/1/2024	C	3/4"	1/1/1926	SF	UNK	C	C		2024: Removed lead from wm-cs. Replaced w/ 3/4" copper, 3/4" cs & box, connected to existing 3/4" copper after cs.	SL repair/replace record	Y	6/1/2024	Visual insp during install or repair	Field Inspection Only	Y	6/1/2024	Visual Insp during install or repair	
12629	710 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF APPLE 7/21/22: Removed lead wipe @ main, connected to existing 3/4" copper.	Installation Record	Y	7/21/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12632	605 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12641	1007 W 6TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	RETAPPED LOWERED & INSULATED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12644	908 W 4TH ST	UNK	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS. 3/4" copper on property side. 5/24/23: Dug and found 3/4" copper w/ flaired fitting at the water main.	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12647	813 W 4TH ST	UNK	C	Y	1"	5/22/2023	C	1"	5/22/2023	SF	UNK	C	1"	UNK	5/22/23: Removed lead from wm-cs. Installed 1" tap, 1" copper, 1" cs & box. Meyers replaced lead with 1" copper from cs-meter.	Installation Record	Y	5/22/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12653	601 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12656	1002 GEORGE DR	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12661	214 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	UNK-NOLG	UNK	1/1/1928	O	UNK	UNK	UNK		Vacant Lot. No building to service.	Installation Record	N			Field Inspection Only	Y	10/24/2006	Other - describe in notes	Vacant Lot
12669	113 S CHERRY AVE	UNK	C	UNK	1"	5/10/2023	C	1"	5/10/2023	SF	UNK	C	1"	UNK	5/10/23: Removed 3/4" copper from wm-cs. Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	5/10/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12672	310 S PALMETTO AVE	N	C	Y	1"	6/1/2024	C	3/4"	1/1/1925	SF	UNK	C	C		2024: Removed lead from wm-cs. Installed 1" copper w/ 45" fitting @ main (used existing corp), Installed 1" cs & box, connected to existing 3/4" copper after cs.	SL repair/replace record	Y	6/1/2024	Visual insp during install or repair	Field Inspection Only	Y	6/1/2024	Visual Insp during install or repair	
12680	815 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12683	1100 S VINE AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2008-REPAIRED LEAK ON 45 ON CORP. 1995-INSTALLED VALVE & BOX FOR PAVING PROJECT.	Installation Record	Y	1/1/2008	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12692	206 W 3RD ST	N	C	UNK	3/4"	7/18/2022	C	3/4"	7/18/2022	NONRES	UNK	C	3/4"	UNK	7/18/22: Intalled new 3/4" corp w/ 2' - 3/4" copper off the main then transitioned to 1" copper going South to the cs. Conn. to existing 3/4" copper 12" South of the cs. (There are 7 abandoned corps (tapped on top) East of this corp.	Installation Record	Y	7/18/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12695	813 E 4TH ST	N	C	Y	1"	6/26/2024	L	5/8"	UNK	SF	UNK	L	UNK	UNK	6/26/24: Old corp is 2' West of new corp. From cs, 8" of 1" copper to 8" of 3/4" copper connected to lead under the sidewalk.	SL repair/replace record	Y	6/26/2024	Visual insp during install or repair	Field Inspection Only	Y	6/26/-2024	Visual Insp during install or repair	
12698	406 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		LEAK REPAIRED, NEW C.B. INSTALLED-2016	Installation Record	N			Field Inspection Only	Y	4/29/2016	Cross Connection Survey	
12703	903 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	NEW CURB VALVE & 3/4 COPPER LINE PUT IN ON PROPERTY SIDE 2-15-93 - 5/8" LEAD ON STREET SIDE, DID NOT REMOVE ANY LEAD WIPES	SL repair/replace record	Y	1993	Mech excav	Field inspection only	Y	7/18/2023	Visual insp at meter	
12709	1610 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12712	606 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/19/22: Removed lead gooseneck at main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	7/19/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12715	600 S HIGHLAND AVE	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12720	912 W 4TH ST	UNK	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS. 5/24/23: Dug and found 3/4" copper w/ flaired fitting at water main.	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12723	801 W 4TH ST	N	L	UNK	UNK	1/1/1942	C	UNK	1/1/1942	SF	UNK	C	UNK	1/1/1942	6/11/18 - 5/8" LEAD OUR SIDE, INTALLED BOX ON EXISTING CURB STOP	SL repair/replace record	Y	2018	Mech excav	Field inspection only	Y	3/16/2016	Cross Connection Survey	
12732	1012 S CHERRY AVE	UNK	C	Y	3/4"	3/17/2024	C	3/4"	3/17/2024	SF	UNK	C	3/4"	UNK	3/17/24: Removed lead from wm-cs and replaced w/ 3/4" copper and new 3/4" cs & box. Connect to exisitng 3/4" copper after cs.	Installation Record	Y	3/17/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12735	308 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	10/21/2016	Cross Connection Survey	
12744	500 W 6TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2019 - Removed Lead, Installed Copper from main to c.b. - Copper installed on Customer side	Installation Record	Y	1/1/2019	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12749	217 W 14TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	NONRES	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/11/2017	Cross Connection Survey	
12752	112 W 14TH ST	N	C	Y	3/4"	5/7/2021	C	3/4"	5/7/2021	SF	UNK	C	3/4"	UNK	2018- CONFIREMED LEAD GOING INTO HOME. 5/7/2021 - Installed 3' of 3/4" copper from main to 3/4" x 1" fitting, then 1" copper to curb valve. Gaffney installed 3/4" copper to house.	Installation Record	Y	5/7/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
12752	112 W 14TH ST	UNK	C	UNK	3/4"	5/7/2021	C	3/4"	5/7/2021	SF	UNK	C	3/4"	UNK	3' of 3/4" copper from WM to 1" x 3/4" fitting, then 1" copper to CS. Gaffney - May 2021 - 1" CS - 5' of 1" CU, then 3/4" Copper into the house.	Installation Record	Y	5/7/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12757	609 W 14TH ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	DUPLEX WITH 609 W 14TH	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12762	109 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12771	1404 W ARLINGTON ST	UNK	C	UNK	1"	8/11/2022	C	1"	8/11/2022	SF	UNK	C	1"	UNK	8/11/22: Installed 1" tapping saddle, 1" copper and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/11/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12776	312 S PALMETTO AVE	N	C	Y	1"	6/26/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/26/24: Removed lead from wm-cs, replaced w/ 1" corp (5' west of old corp), 1" copper, and 1" cs & box. Connected to existing 3/4" copper 12" North of cs.	SL repair/replace record	Y	6/26/2024	Visual insp during install or repair	Field Inspection Only	Y	6/26/2024	Visual Insp during install or repair	
12779	511 S PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12786	1210 W 8TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/17/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12791	409 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12801	615 S CEDAR AVE	UNK	C	Y	1"	9/9/2021	C	1"	9/9/2021	SF	UNK	C	1"	UNK	9/9/2021 Maddrell Const. Installed 1" corp 2' North of abandoned corp. New CS & Box connected to existing 3/4" copper .5' after box. Removed existing lead service.	Installation Record	Y	9/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12808	912 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/12/2017	Cross Connection Survey	
12811	512 S DRAKE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12814	807 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12818	408 W 5TH ST	N	C	UNK	1"	4/29/2022	C	1"	4/29/2022	O	UNK	C	1"	UNK	4/29/22: New 1" copper from main to cs. 3/4" copper inside the house.	Installation Record	Y	4/29/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12822	310 W 3RD ST	N	UNK	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12826	407 W MAGEE ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	5/23/22: copper was found @ main	Installation Record	Y	5/23/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12840	217 W 11TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12843	1000 S CENTRAL AVE	UNK	C	UNK	1 1/4"	1/1/1984	C	1 1/4"	1/1/1984	NONRES	UNK	C	1 1/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12847	915 S CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2009-REMOVED LEAD WIPE @ MAIN	Installation Record	N			Field Inspection Only	Y	10/26/2015	Cross Connection Survey	
12850	704 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/20/22: Removed lead gooseneck at main and replaced w/ 3/4" copper. Connected to existing 3/4" copper.	Installation Record	Y	7/20/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12853	906 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1974	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12857	711 E 4TH ST	N	C	Y	1"	6/19/2024	C	3/4"	1/1/1926	SF	UNK	C	C		6/19/2024: Removed lead gooseneck @ wm. Installed 4'-3/4" copper connected to existing 3/4" copper @ wm. Installed new 3/4" cs & box.	SL repair/replace record	Y	6/19/2024	Visual insp during install or repair	Field Inspection Only	Y	6/19/2024	Visual Insp during install or repair	
12860	301 S PALMETTO AVE	N	C	UNK	3/4"	1/1/2005	C	3/4"	1/1/2005	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12863	400 S PEACH AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM SAN TRENCH TO CB, NEW COPPER & CB INSTALLED-2017	Installation Record	Y	1/1/2017	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12867	611 W 4TH ST	N	C	UNK	3/4"	12/7/2018	C	3/4"	12/7/2018	SF	UNK	C	3/4"	UNK	INSTALLED COPPER FROM WM TO HOUSE	Installation Record	Y	12/7/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12872	912 S CENTRAL AVE #A	UNK	UNK-LG	UNK	2"	1/1/1926	C	2"	1/1/1926	O	UNK	C	C		2009- REMOVED LEAD WIPES @ MAIN. 2" LINE 3-1" TAPS. SERVICE FOR MIDDLE & NORTH STORE. THERE IS TO CURB VALVES ONLY ONE BOX	Installation Record	N			Field Inspection Only	Y	2009	Cross Connection Survey	
12875	814 E 3RD ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12887	108 S CHERRY AVE	UNK	C	Y	1"	5/9/2023	C	1"	5/9/2023	SF	UNK	C	1"	UNK	5/9/23: Removed lead from wm-cs. Installed new 1" corp, 1" copper, 1" cs & box. 5/15/23: Meyers replaced lead w/ 1" copper from cs-meter.	Installation Record	Y	5/9/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12896	207 S PEACH AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC. NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12899	307 S PALMETTO AVE	N	C	UNK	3/4"	10/30/2018	C	3/4"	10/30/2018	SF	UNK	C	3/4"	UNK	3/4" COPPER PRIVATE (REIGEL), 3/4" COPPER STREET	Installation Record	Y	10/30/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12902	407 S PEACH AVE	UNK	UNK-LG	UNK	3/4"	1/1/1922	C	3/4"	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	4/15/2016	Cross Connection Survey	
12906	712 S PEACH AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" COPPER & LOCKING VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12909	109 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	12/11/2015	Cross Connection Survey	
12912	804 W 6TH ST	UNK	C	Y	1"	7/18/2023	C	1"	7/18/2023	SF	UNK	C	1"	UNK	7/18/23: Lead removed and replaced w/ 1" copper from main to cs, 1" cs & box, conn. to existing 3/4" copper on customers side. Repair sleeve installed 3' East of corp.	Installation Record	Y	7/18/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12915	1200 W 5TH ST	Y	UNK	Y	UNK	UNK	L	5/8"	UNK	SF	UNK	L	5/8"	UNK	SERVICE COMES OFF OF DRAKE. MU verified lead service before the meter in the home 5/30/2025	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12918	300 W 5TH ST	N	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	NEW COPPER FROM MAIN - 5' PAST SIDEWALK	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12924	512 W 5TH ST	Y	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC. J	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12927	637 W ADLER RD	N	C	UNK	3/4"	1/1/2005	C	3/4"	1/1/2005	SF	UNK	C	3/4"	UNK	2005-REPLACED FROM CORP TO CURB VALVE	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12937	800 S VINE AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2009-REMOVED LEAD WIPE @ MAIN	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	5/22/2017	Cross Connection Survey	
12942	811 E 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/20/2016	Cross Connection Survey	
12944	908 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12947	1004 S SEVERNS AVE	N	C	Y	3/4"	8/1/2019	C	3/4"	8/1/2019	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO DITCH - CONNECTED TO EXISTING 3/4" COPPER AT DITCH	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12953	601 W 14TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1968	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12962	1011 W PARK ST	UNK	C	Y	1"	7/19/2021	UNK	1"	7/19/2021	SF	UNK	UNK	1"	UNK	Tap at main using 8" S.S. saddle w/ 1" C.C. Connected to existing 3/4" Copper on customers side. (Removed Lead Gooseneck from retired 6" watermain-2021)	Installation Record	Y	7/19/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12965	708 W 6TH ST	N	C	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	LOWERED IN STREET 1983 PAVING, CURB VALVE/BOX INSTALLED-2014, VERIFIED COPPER IN ROAD--2017	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
12968	807 W 6TH ST	N	C	UNK	1"	7/14/2023	C	3/4"	1/1/1926	SF	UNK	C	C		REMOVED WIPE & INSULATED 1983 PAVING	Installation Record	Y	7/14/2023	Visual insp during install or repair	Field Inspection Only	Y	2/27/2015	Cross Connection Survey	
12972	301 S VINE AVE	UNK	C	Y	1"	5/6/2021	C	1"	5/6/2021	SF	UNK	C	1"	UNK	5/6/21 - Removed all lead in street, Installed 1" tap and 1" CU from main to cs. Connected to 3/4" copper in terrace. Found existing cs under West edge of sidewalk and Fiber Optic connected to galvanized steel going to house. Copper in basement. See Card	Installation Record	Y	5/6/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
12975	308 S PALMETTO AVE	N	C	Y	3/4"	6/1/2024	C	3/4"	1/1/1926	SF	UNK	C	UNK	1/1/1926	6/24: Lead removed from wm-cs, replaced w/ 3/4" copper. Installed cs & box. Connected to existing 3/4" copper after the cs.	SL repair/replace record	Y	6/1/2024	Visual insp during install or repair	Field inspection only	Y	6/1/2024	Visual Insp during install or repair	
12978	300 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
12981	413 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/9/2017	Cross Connection Survey	
12990	211 S STATE AVE	UNK	UNK-LG	UNK	UNK	1/1/1937	C	UNK	1/1/1937	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	10/31/2014	Cross Connection Survey	
12993	707 E 6TH ST	UNK	UNK	UNK	3/4"	1/1/1996	C	3/4"	1/1/1996	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13000	132 W 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		REMOVED LEAD WIPES, INSTALLED CURB STOP - 1/2" LEAD TO HOUSE	Installation Record	N			Field Inspection Only	Y	3/18/2009	Cross Connection Survey	
13004	605 S ADAMS AVE	N	C	Y	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	RETAPPED W/ 1" CORP, REMOVED LEAD WIPES @ MAIN, INSTALLED 20' OF 1" COPPER-2014. 1" copper on property side	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13007	705 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/17/2017	Cross Connection Survey	
13013	309 S CEDAR AVE	N	C	UNK	1"	9/1/2022	G	1"	9/1/2022	SF	UNK	G	UNK	9/1/2022	9/1/22: New 1" copper used existing corp, new 1" curb valve & box. Hooked up to existing galvanized on customers side	SL repair/replace record	Y	9/1/2022	Visual insp during install or repair	Previous eval	Y	7/22/2017	Cross connection survey	
13016	505 W 13TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13019	1204 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	NONRES	UNK	C	UNK	1/1/1926	Y SERVICE FOR 1106 & 1108 S. CENTRAL. 2009-RENOVED LEAD WIPE @ MAIN.	SL repair/replace record	Y	2009	Mech excav	Field inspection only	Y	10/16/2014	Cross Connection Survey	
13022	906 S CENTRAL AVE	N	L	UNK	5/8"	1/1/1937	UNK-LG	5/8"	1/1/1937	SF	UNK	UNK-LG	UNK	1/1/1937	2020- Verified Lead on Streetside via vac excavate	Installation Record	Y	2020	Mech excav	Field inspection only	Y	10/16/2015	Visual insp at meter	
13027	801 S OAK AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
13031	400 S OAK AVE	N	C	Y	3/4"	9/4/2020	C	3/4"	9/4/2020	SF	UNK	C	3/4"	UNK	1999 - REPLACED C.S. & BOX. REMOVED LEAD WIPE @ CURB STOP. NEW COPPER FROM C.S. TO HOUSE. 9/4/2020 - Removed lead from C.S. to MAIN. Replaced w/ 3/4" copper. Insalled new curb box.	Installation Record	Y	9/4/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13034	800 W 4TH ST	UNK	C	Y	1"	5/17/2023	C	1"	5/17/2023	SF	UNK	C	1"	UNK	5/17/23: Removed lead wm-cs. Installed 1" tap, 1" copper, 1" cs & box. Meyers Replaced lead from cs-meter w/ 1" copper.	Installation Record	Y	5/17/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13040	308 W 4TH ST	N	C	UNK	3/4"	1/1/2002	C	3/4"	1/1/2002	SF	UNK	C	3/4"	UNK	3/4 COPPER FROME MAIN TO CURBLINE-8-19-02	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13050	813 S CHERRY AVE #A	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/17/2017	Cross Connection Survey	
13053	206 S VINE AVE	Y	L	Y	3/4"	UNK	L	3/4"	UNK	SF	UNK	L	3/4"	UNK	2007-REMOVED LEAD WIPE BY CURB STOP (COPPER INSIDE)	Installation Record	Y	1/1/2007	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13061	707 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		LOCKING VALVE HAS BEEN REMOVED AND CURB BOX WAS INSTALLED ON 6/11/91	Installation Record	N			Field Inspection Only	Y	3/18/2016	Cross Connection Survey	
13067	613 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		6-7-02- REMOVED BOTH WIPES AND INSTALLED CURB BOX. DUPLEX WITH 613A	Installation Record	N			Field Inspection Only	Y	3/18/2016	Cross Connection Survey	
13073	402 W 6TH ST	UNK	UNK-LG	UNK	3/4"	1/1/1926	C	3/4"	1/1/1926	SF	UNK	C	C		CB LOCATION VERIFIED 3/25/97. 2/21/2022: JN verified 3/4" copper in the basement and feeds 402, 402A and 402B	Installation Record	N			Field Inspection Only	Y	8/5/2014	Cross Connection Survey	
13079	609 W 5TH ST	N	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13088	711 W ADLER RD	N	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	MEWD/REPLACED CORP TO CURB BOX	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13091	312 W 3RD ST	N	UNK	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13100	811 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICES 811 & 813 ADLER	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13110	601 W 13TH ST	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 10/10/97	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13116	500 W 5TH ST #A	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LEAD WIPE REMOVED AT MAIN 9/19/2000. Verified copper at main to 2' south of main. 3-15-2022. Corp is 3.5' west of valve #314.	Installation Record	Y	3/15/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13119	504 S ASH AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
13122	512 E 2ND ST	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 1/2" COPPER USING 1" x 1/2" CU-CU, 1/2" COPPER RUNS INSIDE OF 3/4" GAVL/IRON PIPE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13130	209 S VINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		IN SIDEWALK	Installation Record	N			Field Inspection Only	Y	5/10/2016	Cross Connection Survey	
13132	508 E 3RD ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		DUPLEX WITH 508A, 3/4 inch copper on property side	Installation Record	N			Field Inspection Only	Y	7/7/2016	Cross Connection Survey	
13135	701 E 9TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		CB/LV UNKNOWN. 3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	3/31/2016	Cross Connection Survey	
13138	208 W 14TH ST	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		CB LOCATION VERIFIED 10/13/97	Installation Record	N			Field Inspection Only	Y	10/27/2015	Cross Connection Survey	
13156	304 E 10TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	3/4" COPPER LOCKING VALVE. 11/10/2022: Removed lead wipe at main, replaced w/ copper and hooked to existing. Verified copper in ditch in front of home.	Installation Record	Y	1/10/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13159	1104 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	6/23/2017	Cross Connection Survey	
13166	805 S ASH AVE	N	C	UNK	UNK	1/1/1983	C	UNK	1/1/1983	SF	UNK	C	UNK	UNK	2020- HOMEOWNER VERIFIED COPPER IN BUILDING. 1983-INSTALLED 3/4" COPPER WHEN CITY REPLACED SEWER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13170	107 S CEDAR AVE	N	C	Y	1"	8/18/2022	C	1"	8/18/2022	SF	UNK	C	1"	UNK	8/18/22: 1" copper new C.B.V. All lead removed. Connected to existing 3/4" copper on customers side.	Installation Record	Y	8/18/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13173	1006 S VINE AVE	N	C	Y	3/4"	1/1/2016	C	3/4"	1/1/2016	SF	UNK	C	3/4"	UNK	INSTALLED 3/4" COPPER FROM MAIN TO C.V., 3/4" COPPER ON PROP SIDE-2016. 12/1/2020 - Meyers replaced Lead on property side w/ copper	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13179	405 S SPRUCE AVE	N	C	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	PRIVATE SERVICE OFF 4TH ST.	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13182	201 W 11TH ST	UNK	UNK-LG	UNK	UNK	1/1/1936	C	UNK	1/1/1936	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	11/23/2015	Cross Connection Survey	
13185	809 S APPLE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/26/2022: Removed lead wipe at main, Connected to existing 3/4" copper 18" from main.	Installation Record	Y	7/26/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13195	308 E 2ND ST	N	C	UNK	1"	1/1/2010	P	1"	1/1/2010	SF	UNK	P	1"	UNK	CONNECTED TO 1" PLASTIC, SANITARY LATERAL DIRECTLY BELOW WATER SERVICE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13210	114 W 14TH ST	N	C	Y	3/4"	8/4/2020	C	3/4"	8/4/2020	SF	UNK	C	3/4"	UNK	COPPER 3/4" STREET SIDE - 3/4" COPPER PROP. SIDE - REMOVED LEAD SERVICE PROP. SIDE 2020	Installation Record	Y	8/4/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13212	508 W 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	DUPLEX: CB/LV UNKNOWN. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13219	600 E 2ND ST	UNK	C	UNK	1 1/4"	1/1/2003	C	1 1/4"	1/1/2003	NONRES	UNK	C	1 1/4"	UNK	FEEDS 600, 602, 604, 606 (NEW CORP, CURB STOP AND BOX AND COPPER FROM CORP TO CURB STOP, CONNECTED TO 1 1/4" COPPER	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13222	715 E 4TH ST	UNK	C	Y	3/4"	6/19/2024	C	3/4"	6/19/2024	SF	UNK	C	3/4"	UNK	6/19/2024: Removed lead gooseneck @ wm. Replaced w/ 3/4" copper (18") Connected to existing 3/4" copper.	Installation Record	Y	6/19/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13228	200 S PEACH AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- EARTH INC. . NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13231	807 E 3RD ST	N	C	UNK	1"	7/28/2022	C	1"	7/28/2022	SF	UNK	C	1"	UNK	7/28/22: New 1" copper from main to cs. New 1" tap, and new 1" cs & box. Connected to existing 3/4" copper on owners side. 100% copper service. Old corp is 3' West	Installation Record	Y	7/28/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13234	411 S VINE AVE	N	C	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13237	809 S PEACH AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	UNK	1/1/1922	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	2/9/2015	Cross Connection Survey	
13243	508 S WALNUT AVE	N	C	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	2000 - NEW COPPER FROM MAIN - 5' PAST SIDEWALK, 8/2018 - NEW COPPER ON HOMEOWNER SIDE CS TO METER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13255	307 S CHERRY AVE #A	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/15/2017	Cross Connection Survey	
13258	117 S CHERRY AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13261	105 S VINE AVE	N	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	CONNECTED TO 5/8" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13264	706 S VINE AVE	N	C	UNK	UNK	1/1/2001	C	UNK	1/1/2001	SF	UNK	C	UNK	UNK	2001: NEW SERVICE FROM MAIN TO HOUSE.	Installation Record	Y	1/1/2001	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13267	604 W 13TH ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13270	405 W 7TH ST	UNK	C	Y	1"	6/8/2022	C	1"	6/8/2022	SF	UNK	C	1"	UNK	6/8/22: Removed lead from main to cs and replaced w/ 1" copper. Installed new 1" corp and connected to existing 3/4" cs	Installation Record	Y	6/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13273	414 W 6TH ST	N	L	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	UNK	1/1/1926	CB/LV UNKNOWN, INSTALLED NEW 1" CORP AND 8' OF 1" COPPER TO EXISTING LEAD-2014. 1" copper on property side	SL repair/replace record	Y	2014	Mech excav	Field inspection only	Y	3/17/2015	Cross Connection Survey	
13276	1408 S APPLE AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
13279	900 S PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
13288	1001 S CHERRY AVE	N	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	1001 & 1005 ARE CLOSE TOGETHER. 3/4" copper on property side	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13293	1108 S CENTRAL AVENUE	N	L	UNK	5/8"	1/1/1926	C	5/8"	1/1/1926	SF	UNK	C	UNK	1/1/1926	2 5/8" LINES. NEW 1-1/4 VALVE IS 1'E OF 2ND VALVE	SL repair/replace record	Y	2008	Mech excav	Field inspection only	Y	2/9/2011	Cross Connection Survey	
13297	509 W 14TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13302	510 W PARK ST	UNK	C	UNK	3/4"	1/1/1987	C	3/4"	1/1/1987	SF	UNK	C	3/4"	UNK	2013-NEW 3/4" COPPER FROM MAIN TO NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13314	606 S CHERRY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/1/2017	Cross Connection Survey	
13322	1310 W ARLINGTON ST	UNK	C	UNK	1"	8/10/2022	C	1"	8/10/2022	SF	UNK	C	1"	UNK	8/10/22: Installed 1" tapping saddle, 1" copper and 1" cs & box. Connected to 1" copper after cs.	Installation Record	Y	8/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13329	310 W 14TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	CB LOCATION VERIFIED 12/04/97. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13338	402 W 4TH ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	NONRES	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13344	503 S CHERRY AVE #1	UNK	UNK	UNK	1 1/2"	1/1/1988	C	1 1/2"	1/1/1988	NONRES	UNK	C	1 1/2"	UNK	STRATFORD	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
13368	1205 S LOCUST AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13376	920 W ARLINGTON ST	N	C	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	STUB-OUT. 1-1-2020 J&R VACUUM EXCAVATED @ CURB, FOUND COPPER 7' DEEP. 5/11/22: Ripped corp., installed 6"x12" sleeve w/ 1" C.C. Tapped on top. 3/4" copper is slip lined through a 1-1/4" galvanized steel line. Conn. to 3/4" copper @ main. (see card)	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13379	700 S HIGHLAND AVE	N	C	Y	3/4"	10/17/2018	C	3/4"	10/17/2018	SF	UNK	C	3/4"	UNK	REMOVED ALL LEAD FROM MAIN TO CURB VALVE	Installation Record	Y	10/17/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13385	1117 S LOCUST AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13393	1121 S LOCUST AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13399	1113 S LOCUST AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13415	900 W OMAHA ST	N	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13418	1120 S LOCUST AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	CURB BOX IS ON SW CORNER OF CU	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13421	203 W 11TH ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
13424	2801 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13428	207 W 2ND ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		2 SERVICES - SERVICE INFRONT OF BLDG 207 W 2ND IS LIVE, SERIVICE TO WEST OF BLDG 207 W 2ND IS ABANDONED. 07-23-10 AB	Installation Record	N			Field Inspection Only	Y	8/14/2014	Cross Connection Survey	
13430	305 W 3RD ST	N	P	Y	2"	2/1/2023	P	2"	2/1/2023	NONRES	UNK	P	2"	UNK	1/12/23: Jackel plbg replaced cast water service w/ poly from cs to meter. 2/1/23: MU removed and replaced lead w/ 2" poly from wm-cs. Used existing 8"x2" tapping saddle and 2" corp. Installed new 2" cs and box. WM is 4.5' deep, insulated. Tracer Wire	Installation Record	Y	2/1/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13434	206 W 1ST ST	UNK	UNK	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	NONRES	UNK	C	3/4"	UNK	TAPPED ON END OF ENDCAP.	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13440	106 S CHESTNUT AVE	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	ATTACHED TO EXISTING 3/4" COPPER 2' PAST VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13443	110 S CHESTNUT AVE	UNK	C	UNK	1 1/4"	1/1/2013	C	1 1/4"	1/1/2013	NONRES	UNK	C	1 1/4"	UNK	ATTACHED TO EXISTING 1-1/4" COPPER 3' PAST VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13447	215 W DEPOT ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/6/2014	Cross Connection Survey	
13449	301 W DEPOT ST	N	C	Y	UNK	8/25/2021	C	UNK	8/25/2021	SF	UNK	C	UNK	UNK	All Lead removed from WM to CS and replaced with 3/4" copper with new 3/4" CS & Box. Connected to existing 3/4" copper behind CB. Lowered service 18" from WM to curb.	Installation Record	Y	8/25/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13452	303 W DEPOT ST	N	C	Y	1"	9/21/2021	C	1"	9/21/2021	SF	UNK	C	1"	UNK	REMOVED WIPE & 6' OF LEAD @ MAIN 5/97. 9/21/21: Replaced w/ 1" copper from wm-cs and installed new cs & box.	Installation Record	Y	9/21/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13457	307 W DEPOT ST	N	C	Y	3/4"	8/24/2021	C	3/4"	8/24/2021	SF	UNK	C	3/4"	UNK	CUT IN CURB BOX 11/19/96. REMOVED WIPE & 6' OF LEAD & INSULATED 5/97. 8/24/2021: All lead removed & replaced w/ 3/4" copper and new 3/4" cs & box.	Installation Record	Y	8/24/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13460	311 W DEPOT ST	UNK	C	Y	3/4"	8/19/2021	C	3/4"	8/19/2021	SF	UNK	C	3/4"	UNK	All Lead removed (5' lead under curb), New 3/4" copper installed from main to existing CB. Insulated. Installed a tapping sleeve w/ a 3/4" corp. over the existing corp hole.	Installation Record	Y	8/19/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13463	313 W DEPOT ST	UNK	C	Y	3/4"	8/20/2021	C	3/4"	8/20/2021	SF	UNK	C	3/4"	UNK	8/20/2021: Removed lead under curb & gutter & installed 3/4" copper from wm - cs with a new 3/4" cs. connected to existing 1/2" copper. Insulated. 1-12-22 - MU found cracked 90 bend at the corp. Replaced and installed 3/4" compression 2' from corp.	Installation Record	Y	8/20/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13466	405 W DEPOT ST	UNK	C	Y	1"	1/1/2021	C	1"	1/1/2021	SF	UNK	C	1"	UNK	Private service off of Spruce. 2021 - Removed Lead wipe at the watermain. 1" copper to curb, 3/4" copper to house. (See City of Marhsfield Sewer Lateral/Water Service Inspection Report # 20221126 & 20221127)	Installation Record	Y	1/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13468	22 N CHESTNUT AVE	UNK	UNK-LG	UNK	2"	1/1/1926	C	2"	1/1/1926	NONRES	UNK	C	C		2" FROM MAIN CURB TO BOX, 1" INSIDE. OFF DEPOT	Installation Record	N			Field Inspection Only	Y	1/20/2015	Cross Connection Survey	
13471	200 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13474	204 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1/2" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13477	206 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13480	212 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13484	308 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13487	404 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER OF PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13490	408 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13493	109 N PINE AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED 15' OF LEAD, REPLACED W/ COPPER & RECONNECTED TO LEAD. 6/1/2021 - Verified 3/4" copper from centerline of road to sidewalk.	Installation Record	Y	6/1/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13496	504 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13499	506 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13502	508 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13505	104 N OAK AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CURB BOX LOCATION VERIFIED 1/6/97. 5/18/20 - Removed lead main to cs. Gaffeny installed 3/4" copper cs to meter	Installation Record	Y	5/18/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13508	108 N OAK AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	3/4"	1/1/1926	O	UNK	UNK	UNK			Installation Record	N			Field Inspection Only	Y	7/21/2017	Cross Connection Survey	
13511	110 N OAK AVE	UNK	UNK-LG	UNK	UNK	1/1/1935	C	UNK	1/1/1935	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/25/2016	Cross Connection Survey	
13515	605 W DEPOT ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2001: 1-1/2" LINE COMING OFF OF OAK STREET	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13518	704 W ARNOLD ST	UNK	C	Y	1"	7/27/2023	C	1"	7/27/2023	SF	UNK	C	1"	UNK	7/27/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 1/2" copper (+/- 12") Proj. #5878 pg. 13 of const. report.	Installation Record	Y	7/27/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13521	712 W ARNOLD ST	UNK	C	Y	1"	7/28/2023	C	1"	7/28/2023	SF	UNK	C	1"	UNK	7/28/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper (+/- 12") Proj. #5878 pg. 14 of const. report.	Installation Record	Y	7/28/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13524	714 W ARNOLD ST	UNK	C	Y	1"	7/25/2023	C	1"	7/25/2023	SF	UNK	C	1"	UNK	7/25/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper (+/- 12"). Corp for 715 is 4' East. Swr. lat. is West of service. Proj. #5878 pg. 11 of const. report.	Installation Record	Y	7/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13527	716 W ARNOLD ST	UNK	C	Y	1"	7/31/2023	C	1"	7/31/2023	SF	UNK	C	1"	UNK	7/31/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Gaffney replaced 3/8" copper w/ 3/4" copper (cs-meter) Proj. #5878 pg. 15 of const. report.	Installation Record	Y	7/31/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13530	800 W ARNOLD ST	UNK	C	Y	1"	7/24/2023	C	1"	7/24/2023	SF	UNK	C	1"	UNK	7/24/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper after the cs (+/- 12") Proj. #5878 pg. 10 of const. report.	Installation Record	Y	7/24/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13533	902 W ARNOLD ST	UNK	C	Y	1"	7/21/2023	C	1"	7/21/2023	SF	UNK	C	1"	UNK	7/21/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper after the cs (+/- 12") Proj. #5878 pg. 9 of const. report.	Installation Record	Y	7/21/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13536	911 W ARNOLD ST	N	C	UNK	1"	1/1/2002	G	1"	1/1/2002	SF	UNK	G	UNK	1/1/2002	NEW 1' CORP & COPPER & CURB VALVE	SL repair/replace record	Y	1/1/2002	Visual insp during install or repair	Previous eval	Y	7/9/2016	Cross connection survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
13539	907 W ARNOLD ST	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	NEW 1" CORP & COPPER 3/4 COPPER INSIDE. 2023: Curb box & rod replaced w/ project #5878	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13542	905 W ARNOLD ST	UNK	C	Y	1"	7/21/2023	C	1"	7/21/2023	SF	UNK	C	1"	UNK	7/21/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper after the cs (+/- 12") Proj. #5878 pg. 9 of const. report.	Installation Record	Y	7/21/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13545	805 W ARNOLD ST	UNK	C	Y	1"	7/24/2023	C	1"	7/24/2023	SF	UNK	C	1"	UNK	7/24/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper after the cs (+/- 12") Proj. #5878 pg. 10 of const. report.	Installation Record	Y	7/24/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13548	803 W ARNOLD ST	UNK	C	Y	1"	7/26/2023	C	1"	7/26/2023	SF	UNK	C	1"	UNK	7/26/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 1/2" copper after the cs (+/- 12") Proj. #5878 pg. 12 of const. report.	Installation Record	Y	7/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13551	709 W ARNOLD ST	UNK	C	Y	1"	7/27/2023	C	1"	7/27/2023	SF	UNK	C	1"	UNK	7/27/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper (+/- 12") Proj. #5878 pg. 13 of const. report.	Installation Record	Y	7/27/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13554	613 W ARNOLD ST	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	NEW FROM CORP. TO CURB VALVE, EXISTING 3/4 COPPER FROM CURB VALVE TO HOUSE.	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13557	607 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13560	515 W ARNOLD ST	N	C	UNK	1"	1/1/2011	L	1"	1/1/2011	SF	UNK	L	UNK	1/1/2011	PEMBER. 5/8" LEAD ON PROP. SIDE	SL repair/replace record	Y	1/1/2011	Visual insp during install or repair	Previous eval	Y	7/20/2016	Cross Connection Survey	
13563	509 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 5/8" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13567	403 W ARNOLD ST	N	C	UNK	1"	1/1/2011	P	1"	1/1/2011	SF	UNK	P	1"	UNK	PEMBER. 1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13573	204 N SPRUCE AVE	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. SERVICE COME OFF OF ARNOLD. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13576	315 W ARNOLD ST	N	C	UNK	1"	1/1/2011	P	1"	1/1/2011	SF	UNK	P	1"	UNK	PEMBER. 1" PLASTIC PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13579	307 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13582	200 N WALNUT AVE	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER 1" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13587	212 N WALNUT AVE	N	C	Y	1"	6/2/2021	C	1"	6/2/2021	SF	UNK	C	1"	UNK	6/2/2021 - New 1" tap 4' East of old corp. Removed corp to 301 W. Blodgett (3' West of corp. to 212 Walnut) Removed lead across road & replaced with 1" copper, new cs & box connected to existing 1/2" copper that is inside steel line.	Installation Record	Y	6/2/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13591	306 W BLODGETT ST	N	C	UNK	3/4"	10/2/2017	C	3/4"	10/2/2017	SF	UNK	C	3/4"	UNK	INSTALLED NEW 3/4" COPPER FROM MAIN TO INSDIE HOUSE--2017	Installation Record	Y	10/2/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13594	310 W BLODGETT ST	UNK	C	Y	1"	6/10/2021	C	1"	6/10/2021	SF	UNK	C	1"	UNK	6/10/2021: Removed Lead from WM-CS & replaced w/ 1" copper. New tap is 3' East of abandoned tap. Connected to existing 3/4" copper behind CS. Power Pole held by electric dept. while excavating for CS.	Installation Record	Y	6/10/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13597	314 W BLODGETT ST	UNK	C	Y	3/4"	6/22/2018	C	3/4"	6/22/2018	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO CURB BOX AND REPLACED WITH 3/4" COPPER	Installation Record	Y	6/22/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13600	400 W BLODGETT ST	UNK	C	Y	1"	6/14/2021	C	1"	6/14/2021	SF	UNK	C	1"	UNK	6/14/2021: Removed Lead from WM-CS with 1" copper. Abandoned old tap and retapped 3' East of existing tap. Pulled 3/4" copper under sidewalk. Reduced to 3/4" after CS and connected to 3/4" copper just South of the sidewalk	Installation Record	Y	6/14/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13603	406 W BLODGETT ST	N	C	Y	3/4"	8/11/2020	C	3/4"	8/11/2020	SF	UNK	C	3/4"	UNK	DUPLEX WITH 406A. 2020 - REMOVED LEAD FROM MAIN TO CS & REPLACED W/ 3/4" COPPER & NEW CS. LOWERED SERVICE TO 7' DEEP, 4' DEEP AFTER CS	Installation Record	Y	8/11/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13606	410 W BLODGETT ST	N	C	UNK	3/4"	8/15/2019	C	3/4"	8/15/2019	SF	UNK	C	3/4"	UNK	RAN COPPER FROM MAIN TO CURB VALVE & MEYERS INSTALLED COPPER FROM VAVLE TO HOUSE	Installation Record	Y	8/15/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13609	414 W BLODGETT ST	N	C	Y	3/4"	10/11/2018	C	3/4"	10/11/2018	SF	UNK	C	3/4"	UNK	10/11/18 REMOVED LEAD FROM MAIN TO CS, REPLACED WITH 3/4" (TYPE K) COPPER - MEYERS RAN 3/4" COPPER TO HSE	Installation Record	Y	10/11/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13612	500 W BLODGETT ST	N	C	UNK	3/4"	5/22/1985	C	3/4"	5/22/1985	SF	UNK	C	3/4"	UNK	Tap is 86' S. & 20' E of the SW Prop. Corner of Blodgett & Pine. Service is 6' deep in the driveway, was changed from 1/2" copper to 3/4" copper on 5/22/85	Installation Record	Y	5/22/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13615	502 W BLODGETT ST	UNK	C	Y	1"	6/28/2021	C	1"	6/28/2021	SF	UNK	C	1"	UNK	6/28/2021: Retapped 3' East of abandoned tap. Replaced all Lead in the road with 1" copper w/ 1" CS & Box. Connected to existing 3/4" copper to house.	Installation Record	Y	6/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13618	504 W BLODGETT ST	UNK	C	Y	1"	6/29/2021	C	1"	6/29/2021	SF	UNK	C	1"	UNK	6/29/2021: All Lead removed. Retapped 3' West of abandoned tap. Installed 1" copper from WM-CS w/ new 1" CS & Box. Connected to existing 1/2" copper slip lined through 3/4" steel to house.	Installation Record	Y	6/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13621	506 W BLODGETT ST	UNK	C	Y	1"	6/30/2021	C	1"	6/30/2021	SF	UNK	C	1"	UNK	6/30/2021: All Lead removed. Insulated in roadway. Retapped 1" corp. 3' West of abandoned tap. Installed new 1" CS & Box	Installation Record	Y	6/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13624	512 W BLODGETT ST	UNK	C	Y	1"	7/6/2021	C	1"	7/6/2021	SF	UNK	C	1"	UNK	7/6/2021: Retapped 1" corp. 3' West of abandoned tap. Pulled 1" copper to replace lead from WM-CS. Connected to existing 1/2" copper South of CS. Reduced from 1" to 3/4" to 1/2" after CS.	Installation Record	Y	7/6/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13629	606 W BLODGETT ST	UNK	C	Y	1"	7/13/2021	C	1"	7/13/2021	SF	UNK	C	1"	UNK	7/13/2021: Retapped 4' West of abandonded tap. Pulled 1" copper & removed lead from WM-CS. (crosses over san. lateral for house 607 W. Blodgett 5' South of WM. Conn. to existing 3/4" copper 6" South of CB. Installed new 1" CS & Box	Installation Record	Y	7/13/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13632	612 W BLODGETT ST	UNK	C	Y	1"	7/21/2021	C	1"	7/21/2021	SF	UNK	C	1"	UNK	7/1988: Meyers installed new line. 7/21/2021: Pulled in 1" copper to replace lead from wm-cs. Retapped 3' East of abandoned tap. Installed 1" cs & box & connected to existing 3/4" copper 6" South of cs.	Installation Record	Y	7/21/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13636	210 N ST JOSEPH AVE	UNK	DI	UNK	4"	9/16/2021	CI-U	4"	9/16/2021	O	UNK	CI-U	4"	UNK	A-1 Installed 8"x4" tee angled 45 degrees up, 2' - 4" dip out of tee to 45 bend fitting then 3' dip to 4" valve. Extended 4" dip for 25' to connect to exist. 3" cast using 3"x4" reducer. 4" top elev. @ center of road = 1292.03	Installation Record	Y	9/16/2021	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
13658	704 W BLODGETT ST	UNK	C	Y	1"	9/16/2021	C	1"	9/16/2021	SF	UNK	C	1"	UNK	9/15/2020: Removed lead in road up to lead-cu fitting near wm. Meyers installed 3/4" cu from cs to hse, new cs & box. 9/16/21: A-1 removed 12' lead & 3' cu from wm-san swr. Installed new 1" corp. & cu conn. to exist. 3/4" cu @ san. sewer main	Installation Record	Y	9/16/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13661	710 W BLODGETT ST	UNK	C	Y	1"	9/27/2021	C	1"	9/27/2021	SF	UNK	C	1"	UNK	9/27/2021: A-1 removed lead from wm - cs and installed 1" corp., 31' - 1" copper and 1" cs & box. Connected to existing 3/4" copper at the sidewalk.	Installation Record	Y	9/27/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
13664	712 W BLODGETT ST	UNK	C	Y	1"	9/27/2021	C	1"	9/27/2021	SF	UNK	C	1"	UNK	9/27/2021: A-1 removed existing lead between wm & cs. Installed 1" corp., 31' - 1" copper,1" cs & box. Connected to existing 3/4" copper under the sidewalk.	Installation Record	Y	9/27/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13667	804 W BLODGETT ST	UNK	C	Y	1"	9/28/2021	C	1"	9/28/2021	SF	UNK	C	1"	UNK	2020: 1" HDPE on customers side, 3/4" copper on utilty side. Service runs under the driveway (removed all the lead) 9/28/2021: A-1 removed existing service from wm-cs & replaced w/ 1" corp., 32' - 1" copper, and 1" cs & box and connected to ex. 1" HDPE	Installation Record	Y	9/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13670	808 W BLODGETT ST	UNK	C	Y	1"	9/30/2021	C	1"	9/30/2021	SF	UNK	C	1"	UNK	8/28/2018: Lead removed from wm-house & replaced w/ 3/4" copper, new cs & box. 9/30/2021: A-1 connected to existing 3/4" copper w/ 1" copper, 2' from wm. Installed 1" corp.	Installation Record	Y	9/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13673	812 W BLODGETT ST	UNK	C	Y	1"	9/29/2021	C	1"	9/29/2021	SF	UNK	C	1"	UNK	9/29/2021: A-1 removed lead gooseneck at the water main w/ 3/4" copper from wm-cs. replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper, 1' south of curb box	Installation Record	Y	9/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13676	900 W BLODGETT ST	UNK	C	Y	1"	9/30/2021	C	1"	9/30/2021	SF	UNK	C	1"	UNK	2005: Removed lead wipe @ cs. Installed new cs & box. 9/30/2021: A-1 removed lead gooseneck at wm w/ copper service, replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 5' South of new cs.	Installation Record	Y	9/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13679	904 W BLODGETT ST	UNK	C	Y	1"	9/29/2021	C	1"	9/29/2021	SF	UNK	C	1"	UNK	7/20/2005: Replaced lead w/ 1" copper to 7' North of the cs, tied to existing 3/4" copper. 9/29/2021: A-1 removed lead from wm-cs and replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper, 3' after cs.	Installation Record	Y	9/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13682	910 W BLODGETT ST	UNK	C	Y	1"	10/1/2021	C	1"	10/1/2021	SF	UNK	C	1"	UNK	10/1/2021: A-1 removed lead from wm-cs and replaced w/ 1" corp., 1" copper and 1" cs & box. Connected to existing 1" copper at the cs.	Installation Record	Y	10/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13685	914 W BLODGETT ST	UNK	C	UNK	1"	10/4/2021	C	1"	10/4/2021	SF	UNK	C	1"	UNK	10/4/2021: A-1 removed 3/4" copper from wm-cs and replaced w/ 1" copr., 1" copper, and 1" cs & box. Installed 1'-1" copper after cs to connect to existing 3/4" copper at the sidewalk.	Installation Record	Y	10/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13688	209 N WOOD AVE	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	NEW 1" CORP, COPPER AND CURBVALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13692	208 N WOOD AVE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	*STUB-OUT*- NEW 1" CORP, CURBVALVE, COPPER	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13692	208 N WOOD AVE	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	NEW 1" CORP, COPPER AND CURBVALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13695	210 N WOOD AVE	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	NEW 1" CORP. COPPER AND CURBVALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13698	927 W BLODGETT ST	UNK	C	UNK	1"	10/5/2021	C	1"	10/5/2021	SF	UNK	C	1"	UNK	2017: replaced service w/ 15' - 3/4" copper, found 3/4" copper on customers side. 10/5/2021: A-1 installed 1" corp., 1" copper and 5' - 1" copper, connected to existing 3/4" copper 5' from water main. Insulated @ water main	Installation Record	Y	10/5/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13701	915 W BLODGETT ST	UNK	C	Y	1"	10/4/2021	C	1"	10/4/2021	SF	UNK	C	1"	UNK	10/4/2021: A-1 removed lead from wm-cs and replaced w/ 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper @ the sidewalk.	Installation Record	Y	10/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13704	907 W BLODGETT ST	UNK	C	UNK	1"	9/29/2021	C	1"	9/29/2021	SF	UNK	C	1"	UNK	9/29/2021: A-1 removed existing 3/4" copper and replaced w/ 1" corp., 1" copper, and 1" cs & box. Connected to existing 3/4" copper @ the sidewalk.	Installation Record	Y	9/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13707	903 W BLODGETT ST	UNK	C	Y	1"	10/4/2021	C	1"	10/4/2021	SF	UNK	C	1"	UNK	10/4/2021: A-1 removed lead from wm-cs and replaced w/ 1" corp., 1" cs & box, 1" copper. Connected to existing 3/4" copper, 5' after cs. (1"x3/4" reducer 5' after cs)	Installation Record	Y	10/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13710	901 W BLODGETT ST	UNK	C	Y	1"	9/30/2021	C	1"	9/30/2021	SF	UNK	C	1"	UNK	9/30/2021: A-1 removed existing lead gooseneck w/ copper service & replaced w/ 1" corp., 16' - 1" copper, 1" cs & box. Connected to existing 3/4" copper 5' from cs.	Installation Record	Y	9/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13713	805 W BLODGETT ST	UNK	C	Y	1"	9/28/2021	C	1"	9/28/2021	SF	UNK	C	1"	UNK	2020: Removed lead from wm - sidewalk, new cs & box installed. 9/28/2021: A-1 removed 3/4" copper from wm-cs & replaced w/ 1" corp, 12' - 1" copper, 1" cs & box & connected to existing 3/4" copper @ the sidewalk.	Installation Record	Y	9/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13716	717 W BLODGETT ST	UNK	C	Y	1"	9/24/2021	C	1"	9/24/2021	SF	UNK	C	1"	UNK	10/15/04: New service from CB to house, lead wipe removed in terrace. 9/24/21: A-1 Removed lead from wm-cs & Installed 1" corp., 14' - 1" copper, 1" cs & box & connected to existing 3/4" copper @ the sidewalk.	Installation Record	Y	9/24/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13719	617 W BLODGETT ST	UNK	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	NONRES	UNK	C	3/4"	UNK	COMES OFF OF ST.JOSEPH	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13722	615 W BLODGETT ST	N	C	Y	1"	7/20/2021	C	1"	7/20/2021	SF	UNK	C	1"	UNK	7/20/2021: Pulled 1" copper to replace lead from wm to 2' N. of sidewalk. Installed 6"x12" w/ 1" C.C. & 1" corp. 6' East of abandoned tap. 2022-replaced lead on customer side Plbg. Permit 20220445	Installation Record	Y	7/20/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13726	300 N OAK AVE	N	C	Y	3/4"	1/31/2019	C	3/4"	1/31/2019	SF	UNK	C	3/4"	UNK	1-31-19 - INTALLED NEW 3/4" CURB STOP & BOX, CONNECTED TO EXISTING LEAD ON STREET SIDE AND 3/4" COPPER ON PROPETY SIDE --- 2019 - Removed all Lead in street & replaced with Copper	Installation Record	Y	1/31/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13729	509 W BLODGETT ST	UNK	C	Y	1"	7/2/2021	C	1"	7/2/2021	SF	UNK	C	1"	UNK	7/2/2021: All lead removed. 1/2" existing copper to house slip line in 3/4" steel. New tap is 3' West of old tap. New 1" CS & Box installed	Installation Record	Y	7/2/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13732	405 W BLODGETT ST	UNK	C	Y	1"	6/17/2021	C	1"	6/17/2021	SF	UNK	C	1"	UNK	6/17/2021: Full Lead replaced from WM-CS. Replaced w/ 1" copper. New tap is 3' East of abandoned tap. Connect to existing 3/4" copper 6" behind CS.	Installation Record	Y	6/17/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13735	313 W BLODGETT ST	UNK	C	Y	1"	6/14/2021	C	1"	6/14/2021	SF	UNK	C	1"	UNK	6/14/2021: Removed Lead from WM-CS & replaced w/ 1" copper & new 1" tap 3" East of abandoned tap. Connected to existing 3/4" copper 12" behind CS.	Installation Record	Y	6/14/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13738	307 W BLODGETT ST	N	C	Y	1"	6/4/2021	C	1"	6/4/2021	SF	UNK	C	1"	UNK	2010 - Installed 1" HDPE on property side & 3/4" curb valve installed. 6/4/2021 - New 1" tap 4.5' East of existing corp (left in place). Removed lead and installed 1" copper. Connected to existing 3/4" copper 12" before cs. Found 3/4" copper after cs.	Installation Record	Y	6/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13741	300 W CLEVELAND ST	N	C	UNK	1"	7/31/2020	C	1"	7/31/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, 10.5' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 39 of Const. Report)	Installation Record	Y	7/31/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13744	304 W CLEVELAND ST	N	C	UNK	1"	7/31/2020	C	1"	7/31/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, 9' - 1" past cs to connect to existing 3/4" copper. (Pg. 39 of Const. Report)	Installation Record	Y	7/31/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13747	306 W CLEVELAND ST	N	C	UNK	1"	8/3/2020	C	1"	8/3/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, 21.5' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 40 of Const. Report)	Installation Record	Y	8/3/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
13750	314 W CLEVELAND ST	N	C	UNK	1"	7/29/2020	C	1"	7/29/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs. (Pg. 37 of Const. Report)	Installation Record	Y	7/29/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13753	307 W CLEVELAND ST	N	C	UNK	1"	8/3/2020	C	1"	8/3/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, 10.5' past cs to connect to existing 3/4" copper. (Pg. 40 of Const. Report)	Installation Record	Y	8/3/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13761	115 W CLEVELAND ST	N	C	UNK	1"	6/5/2020	C	1"	6/5/2020	SF	UNK	C	1"	UNK	Earth INC. - Connected to existing 3/4" Copper 11.5' behind CS, San. sewer lateral & Water service are approx. 6' apart after CS. (Pg. 10 of Const. Report)	Installation Record	Y	6/5/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13764	313 N CHESTNUT AVE	UNK	C	UNK	1"	6/8/2020	C	1"	6/8/2020	SF	UNK	C	1"	UNK	Earth INC. - Installed 6" - 1" copper after CS, connected to existing 5/8" copper. (Pg. 11 of Const. Report)	Installation Record	Y	6/8/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13769	307 N WALNUT AVE	N	CI-U	UNK	4"	1/1/1926	CI-U	4"	1/1/1926	NONRES	UNK	CI-U	CI-U		<Null>	Installation Record	N			Field Inspection Only	Y	2/16/2023	Cross Connection Survey	
13771	201 W BLODGETT ST	N	C	N	1"	4/1/2022	C	UNK	1/1/1926	NONRES	UNK	C	C		1" copper on property side	SL repair/replace record	Y	4/1/2022	Visual insp during install or repair	Field Inspection Only	Y	4/1/2022	Visual Insp during install or repair	
13774	211 N CHESTNUT AVE	UNK	C	Y	1"	4/19/2024	C	1"	4/19/2024	SF	UNK	C	1"	UNK	4/19/24: Replaced lead w/ 1" copper (wm-cs) Connected @ wm w/ 2' of 3/4" copper (used existing corp.) Installed new 1" cs & box. Connected to existing 3/4" copper 2' East of cs.	Installation Record	Y	4/19/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13777	205 N CHESTNUT AVE	N	C	Y	1"	4/1/2024	C	3/4"	1/1/1926	SF	UNK	C	C		4/2024: 1" copper to existing 3/4" curb stop from main. Lead removed.	SL repair/replace record	Y	4/1/2024	Visual insp during install or repair	Field Inspection Only	Y	4/1/2024	Visual Insp during install or repair	
13780	108 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13783	110 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 5/8" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13786	114 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13789	401 N ST JOSEPH AVE	N	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	NEW 3/4" CORP & CURB STOP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13804	613 WESTERN ST	N	DI	UNK	6"	1/1/1992	DI	6"	1/1/1992	NONRES	UNK	DI	6"	UNK	WATER & FORE SERVICE COMB.	Installation Record	Y	1/1/1992	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
13806	510 N ST JOSEPH AVE	UNK	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	NONRES	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13809	510 N ST JOSEPH AVE	UNK	C	UNK	1 1/4"	1/1/1999	C	1 1/4"	1/1/1999	NONRES	UNK	C	1 1/4"	UNK	<Null>	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13816	811 W NORTH ST	N	C	UNK	1"	1/1/2014	L	1"	1/1/2014	SF	UNK	L	UNK	1/1/2014	<Null>	SL repair/replace record	Y	1/1/2014	Visual insp during install or repair	Previous eval	Y	8/20/2016	Cross connection survey	
13819	821 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13822	827 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13825	901 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13828	903 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13831	907 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13834	913 W NORTH ST	N	C	UNK	1"	6/1/2014	P	1"	6/1/2014	SF	UNK	P	1"	UNK	1" HDPE on Customer side 2021	Installation Record	Y	6/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13837	919 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13840	925 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13843	700 N WOOD AVE	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13853	612 N WOOD AVE	N	C	UNK	1"	1/1/2017	P	1"	1/1/2017	SF	UNK	P	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13856	606 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13859	602 N WOOD AVE	N	C	UNK	1"	7/5/2017	C	1"	7/5/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	7/5/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13862	600 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13865	1017 W LAUREL ST	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	NONRES	UNK	C	1"	UNK	RE-TAPPED--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13868	1008 W LAUREL ST	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	RE-TAPPED--2017, CONN. TO 3/4"	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13871	504 N WOOD AVE	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13874	500 N WOOD AVE	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13877	511 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13880	605 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13883	916 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13886	914 W NORTH ST	N	C	UNK	1"	1/1/2014	L	1"	1/1/2014	SF	UNK	L	UNK	1/1/2014	<Null>	SL repair/replace record	Y	1/1/2014	Visual insp during install or repair	Previous eval	Y	8/5/2016	Cross connection survey	
13889	912 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13892	906 W NORTH ST	UNK	C	UNK	1"	1/1/2014	P	1"	1/1/2014	SF	UNK	P	1"	UNK	DUPLEX	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13895	900 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13899	604 N BROADWAY AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/27/2016	Cross Connection Survey	
13902	512 N BROADWAY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LV/CB UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13908	511 N BROADWAY AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7'6" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
13911	513 N BROADWAY AVE	UNK	UNK-LG	UNK	UNK	1/1/1944	C	UNK	1/1/1944	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/22/2016	Cross Connection Survey	
13914	907 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13917	911 WESTERN ST	N	C	UNK	1"	1/1/2008	P	1"	1/1/2008	SF	UNK	P	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13920	915 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13923	925 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13926	410 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC. Meyers Replaced Galvanized w/ 1" copper on Property side.	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13929	406 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC. Meyers replaced galvanized with 1" copper on property side	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13932	411 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13935	924 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13938	920 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13941	918 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-SANITARY DOES NOT RUN WITH WATER	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13944	914 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13947	912 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13950	910 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13953	412 N BROADWAY AVE	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13956	827 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13959	817 WESTERN ST	N	C	UNK	1"	1/1/2008	P	1"	11/25/2024	SF	UNK	G	UNK	1/1/2008	HAAS-INSULATION OVER CORP. 11/25/24: Cals Plumbing replaced leaking galvanized water service w/ 1" HDPE from cs-meter. Cal also replaced clay san. lat. from stub in terrace to house w/ 4" SDR-35 PVC.	SL repair/replace record	Y	1/1/2008	Visual insp during install or repair	SL repair/replace record	Y	11/25/2024	Mech excav	
13966	809 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP-SANITARY DOES NOT RUN W/ WATER. 3/4" copper on property side	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13969	411 N BROADWAY AVE	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13972	814 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	2008-INSTALLED COPPER /COPPER 2' FROM CORP. DUE TO DAMAGED CORP.HAAS. 8/2021: New 3/4" copper service customer side	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13975	810 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13978	412 N ST JOSEPH AVE	N	C	Y	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	NEW 3/4" CORP & CURB STOP. 6/7/23: Meyers replaced lead w/ 3/4" copper from cs-meter.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13981	410 N ST JOSEPH AVE	N	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	NEW 3/4" CORP. & CURB STOP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13984	614 W CLEVELAND ST	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	LAKELAND-REPLACED FROM MAIN TO BACKSIDE OF VALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13987	612 W CLEVELAND ST	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	LAKELAND-REPLACED FROM MAIN TO BACKSIDE OF VALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13990	608 W CLEVELAND ST	N	C	UNK	1"	8/12/2020	C	1"	8/12/2020	SF	UNK	C	1"	UNK	Earth INC. - Installed copper from main to cs, connected to existing 1" copper	Installation Record	Y	8/12/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
13993	606 W CLEVELAND ST	N	C	UNK	1"	8/25/2020	C	1"	8/25/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs and 10'1" - 1" copper past cs to existing 3/4" copper. (Pg. 54 of Const. Report)	Installation Record	Y	8/25/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
13996	600 W CLEVELAND ST	N	C	UNK	1"	8/25/2020	C	1"	8/25/2020	SF	UNK	C	1"	UNK	Earth INC. - installed copper from main to cs, 11' - 1" copper past cs to connect to existing 3/4" . (Pg. 54 of Const. Report)	Installation Record	Y	8/25/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14002	308 N OAK AVE	N	C	UNK	1"	5/22/2020	C	1"	5/22/2020	SF	UNK	C	1"	UNK	EARTH INC. - CONN. TO EXIST. 3/4" CU 1' BEHIND CS. CU-CU COMPRESSION IS 10' NORTH & 66' EAST OF THE N.E.C. OF PORCH AT 600A W. CLEVELAND. (Pg. 53 of Const. Report)	Installation Record	Y	5/22/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14005	508 W CLEVELAND ST	N	C	Y	1"	8/26/2020	P	1"	8/26/2020	SF	UNK	P	1"	UNK	2009 - Removed lead wipe @ main, customer installed plastic w/ new CS. 8/26/2020 Earth INC. installed copper from main to cs, 9' - 1" copper past cs to connect to existing 1" poly. (Pg. 55 of Const. Report)	Installation Record	Y	8/26/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14008	504 W CLEVELAND ST	N	C	Y	1"	8/27/2020	C	1"	8/27/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, Meyers replaced lead on customers side w/ 1" copper (Lead Replacment Program) (Pg. 56 of Const. Report)	Installation Record	Y	8/27/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14010	500 W CLEVELAND ST	N	C	UNK	1"	7/13/2020	C	1"	7/13/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, connected to new 1" copper (Meyers installed to meter) (Pg. 27 of Const. Report)	Installation Record	Y	7/13/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14013	308 N PINE AVE	N	C	UNK	1"	7/13/2020	C	1"	7/13/2020	SF	UNK	C	1"	UNK	Earth INC installed copper from main to cs, connected to new 1" copper (Meyers installed to meter. (Pg. 27 of Const. Report)	Installation Record	Y	7/13/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14016	412 W CLEVELAND ST	N	C	UNK	1"	7/13/2020	C	1"	7/13/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 6.5' - 1" copper past cs to connect to existing 3/4" copper. (Customer side replaced in 2019 Meyers) (Pg. 27 of Const. Report)	Installation Record	Y	7/13/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14019	408 W CLEVELAND ST	N	C	UNK	1"	8/11/2020	C	1"	8/11/2020	SF	UNK	C	1"	UNK	Earth INC. - Installed copper from main to cs, Meyers installed copper from cs to house. (Pg. 46 of Const. Report)	Installation Record	Y	8/11/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14022	406 W CLEVELAND ST	N	C	UNK	1"	8/15/2020	C	1"	8/15/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 2' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 49 of Const. Report)	Installation Record	Y	8/15/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14025	400 W CLEVELAND ST	N	C	UNK	1"	7/31/2020	C	1"	7/31/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, 16' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 39 of Const. Report)	Installation Record	Y	7/31/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14031	413 W CLEVELAND ST	N	C	UNK	1"	8/14/2020	C	1"	8/14/2020	SF	UNK	C	1"	UNK	Earth INC installed copper from main to cs, 10.5' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 48 of Const. Report)	Installation Record	Y	8/14/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14043	600 W DOEGE ST	N	C	Y	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	LAKELAND-REPLACED FROM MAIN TO BACKSIDE OF VALVE 2022-Customer replaced lead w/ 1" copper (Gaffney)	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14046	507 W DOEGE ST	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	LAKELAND- REPLACED FROM MAIN TO BACKSIDE OF VALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14049	521 W IVES ST	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14052	516 W IVES ST	UNK	UNK	UNK	3/4"	1/1/1971	UNK	3/4"	1/1/1971	SF	UNK	UNK	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14055	522 W IVES ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14061	809 N PINE AVE	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	8/16/2016	Cross connection survey		
14064	711 N PINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	7/27/2016	Cross Connection Survey		
14067	410 N PINE AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 4'9" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14070	410 W DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1971	UNK	3/4"	1/1/1971	NONRES	UNK	UNK	3/4"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14070	410 W DOEGE ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey		
14073	408 W DOEGE ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14076	1808 E MCMILLAN ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14086	2500 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14089	2410 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL PLB	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14092	2404 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14095	2312 E HINTZ ST	N	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14098	2212 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14101	2204 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14104	2200 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14107	701 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14110	2411 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14113	2511 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14116	2408 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14119	2312 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1977	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14122	2306 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14125	2300 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14128	2204 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14131	623 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14134	615 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14137	607 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14140	600 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14143	612 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14146	616 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14149	700 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14152	706 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS(SPRENCER)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14155	710 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14158	714 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1974	P	3/4"	1/1/1974	SF	UNK	P	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14161	718 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1974	P	3/4"	1/1/1974	SF	UNK	P	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14164	2201 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14167	2213 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14170	2303 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1988	C	3/4"	1/1/1988	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14173	2305 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1977	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14176	2413 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	BILL REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14179	2507 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14182	2408 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14185	2404 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14188	2310 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14191	2212 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14194	2022 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1974	P	3/4"	1/1/1974	SF	UNK	P	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14197	2000 E BECKER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14200	2011 E BECKER RD	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14203	2015 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14206	2019 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14209	2014 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14212	2005 E EMERALD ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey		
14221	2203 E BECKER RD	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey		
14224	1815 E BECKER RD	N	UNK	UNK	UNK	1/1/1967	C	UNK	1/1/1967	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1967	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey		
14227	1805 E BECKER RD	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	SPENCER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey		
14230	1804 E BECKER RD	N	UNK	UNK	UNK	1/1/1967	C	UNK	1/1/1967	SF	UNK	C	UNK	UNK		Installation Record	Y	1/1/1967	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey		
14233	1706 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS. WATER TAP ONLY	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey		

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
14236	1604 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14239	1600 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14244	1106 E BECKER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	8/11/98: INSULATED IN STREET.	Installation Record	Y	8/11/1998	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14247	717 N PALMETTO AVE	UNK	C	UNK	1"	7/7/2023	C	1"	7/7/2023	SF	UNK	C	1"	UNK	1' of 1" copper from CS to existing 3/4" copper. (pg. 16 of construction report)	Installation Record	Y	7/7/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14249	1401 E BECKER RD	N	DI	UNK	6"	UNK	DI	6"	UNK	NONRES	UNK	DI	6"	UNK	SENIOR HIGH AUTO SHOP	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
14252	1411 N OAK AVE	N	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14255	1601 N OAK AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14264	1504 N ST JOSEPH AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14267	1500 N ST JOSEPH AVE	UNK	UNK	UNK	3/4"	1/1/1994	C	3/4"	1/1/1994	SF	UNK	C	3/4"	UNK	BORED & RETAPPED	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14270	1416 N ST JOSEPH AVE	N	UNK	UNK	3/4"	1/1/1994	C	3/4"	1/1/1994	SF	UNK	C	3/4"	UNK	BORED & RETAPPED	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14273	1406 N ST JOSEPH AVE	N	UNK	UNK	3/4"	1/1/1993	C	3/4"	1/1/1993	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14276	1308 N ST JOSEPH AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14279	1208 N ST JOSEPH AVE	N	UNK	UNK	UNK	1/1/1993	C	UNK	1/1/1993	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14282	1200 N ST JOSEPH AVE	N	UNK	UNK	UNK	1/1/1963	C	UNK	1/1/1963	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14285	807 W UPHAM ST	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14288	1313 N SHAWANO DR	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14291	1407 N SHAWANO DR	UNK	C	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14294	1507 N SHAWANO DR	UNK	C	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SHUH	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14297	1511 N SHAWANO DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14300	1515 N SHAWANO DR	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14303	1500 N SHAWANO DR	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14306	1412 N SHAWANO DR	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14309	1408 N SHAWANO DR	N	C	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	SCHREINERS. 1-1-2020 J&R VACUUM EXCAVATED 4' FROM CB, FOUND 3/4" COPPER 8'2" DEEP	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14312	1320 N SHAWANO DR	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1966	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14315	1310 N SHAWANO DR	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14318	1306 N SHAWANO DR	N	C	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	SCHUH. 1-1-2020 J&R VACUUM EXCAVATED 2' OFF ROAD, FOUND 1" COPPER 6'10" DEEP	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14321	1300 N SHAWANO DR	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14324	1301 N BROADWAY AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14327	1415 N BROADWAY AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SPENCER PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14330	1510 N BROADWAY AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14333	1400 N BROADWAY AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14336	1312 N BROADWAY AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14339	1320 N WOOD AVE	UNK	C	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL PLB	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14342	909 W UPHAM ST	UNK	C	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14345	1008 W LAIRD ST	UNK	C	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	ABBY PLB	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14348	1035 W LAIRD ST	UNK	C	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	ABBY PLB	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14351	1001 W UPHAM ST	UNK	C	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14354	1019 W UPHAM ST	UNK	C	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14357	1025 W UPHAM ST	UNK	C	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14360	1031 W UPHAM ST	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14363	822 W UPHAM ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14366	808 W UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14369	800 W UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14372	721 W UPHAM ST	UNK	C	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	LINED WATER MAIN, MICHELS-2016. 1-1-2020 J&R VACUUM EXCAVATED @ BOC, FOUND 3/4" COPPER 8'8" DEEP	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14378	705 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 8" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14381	629 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 20" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14384	621 W UPHAM ST	UNK	UNK	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 20" OF 1" COPPER FROM CORP CONN TO EXIST 1" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14387	615 W UPHAM ST	UNK	C	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	LINED WATER MAIN, MICHELS-2016	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14392	1000 N OAK AVE	UNK	CI-U	UNK	8"	UNK	CI-U	8"	UNK	NONRES	UNK	CI-U	8"	UNK	LOCATED ON PRIVATE PROPERTY	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
14406	1001 W KALSCHED ST	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	O	UNK	C	3/4"	UNK	3/4" copper in house	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14418	1600 SAWYER DR #A	UNK	UNK	UNK	UNK	1/1/1970	C	UNK	1/1/1970	NONRES	UNK	C	UNK	UNK	MFLD PLB	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14431	1609 SAWYER DR	UNK	DI	UNK	4"	UNK	DI	4"	UNK	SF	UNK	DI	4"	UNK	<Null>	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
14447	400 W 29TH STREET	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	FEEDS HANGER DUE SOUTH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14451	500 E 29TH STREET	N	C	UNK	1 1/2"	UNK	C	1 1/2"	UNK	NONRES	UNK	C	1 1/2"	UNK	1-1/2" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14457	309 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	NONRES	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14462	301 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	NONRES	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14465	2705 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14468	2607 S PEACH AVE	UNK	C	UNK	3/4"	2/17/2020	C	3/4"	2/17/2020	SF	UNK	C	3/4"	UNK	NEW CS/CB	Installation Record	Y	2/17/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14471	1209 E 29TH ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14474	1213 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1974	P	3/4"	1/1/1974	SF	UNK	P	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14477	1221 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	HELLER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14480	1301 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	RON MEYERS: CB LOCATION VERIFIED 8/27/97	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14483	1305 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14486	1319 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14489	1323 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14492	1401 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14495	1419 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14498	1423 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14501	1427 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14504	1431 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14507	1811 E 29TH ST	UNK	DI	UNK	8"	1/1/1973	DI	8"	1/1/1973	NONRES	UNK	DI	8"	UNK	FIRE SERVICE AND POTABLE LINE COMBINE	Installation Record	Y	1/1/1973	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
14509	2608 S HUME AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	NONRES	UNK	C	1"	UNK	NO CB FOUND 4/29/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14515	1920 E 26TH ST	UNK	UNK	UNK	1"	1/1/1970	C	1"	1/1/1970	NONRES	UNK	C	1"	UNK	SPENCER	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14518	1915 E 29TH ST	UNK	UNK	UNK	1 1/2"	1/1/1969	C	1 1/2"	1/1/1969	NONRES	UNK	C	1 1/2"	UNK	MEL SPENCER. 1-1/2" copper on property side	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14523	2800 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14526	1318 E 28TH ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14529	1314 E 28TH ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14532	1300 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14532	1300 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14535	1222 E 28TH ST	UNK	UNK	UNK	UNK	1/1/1972	C	UNK	1/1/1972	SF	UNK	C	UNK	UNK	RON MEYERS WATER ONLY	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14538	1218 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14541	1210 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL PLB	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14544	1213 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14550	2710 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14553	2700 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SCHUH	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14556	1212 E 27TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14559	1206 E 27TH ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14562	2710 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14565	2706 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14568	2608 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14571	2604 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14574	2600 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14577	2508 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
14580	2504 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14583	2807 S FELKER AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	Spencer	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14586	2801 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1976	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14589	1200 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHULTZ	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14592	1212 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(STRATFORD 1973) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14595	1200 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(GAFFNEY 1970) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14598	1207 E 27TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14601	1213 E 27TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14604	1301 E 27TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14607	1307 E 27TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14610	1307 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(MEYER 1973) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14613	1319 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(REIGEL 1972) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14616	1325 E 26TH ST	UNK	C	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	(REIGEL 1974) 2020 - NEW TAP (5813)	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14619	1214 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14622	2500 BUTTERNUT PKWY	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14625	2512 BUTTERNUT PKWY	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14628	2522 BUTTERNUT PKY	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14631	2601 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14634	2701 S TAMARACK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14637	2705 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14640	2711 S TAMARACK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14643	2710 S WASHINGTON AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	SCREINERS	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14646	2706 S WASHINGTON AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14649	2612 S WASHINGTON AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14652	2703 S WASHINGTON AVE	N	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14655	2711 S WASHINGTON AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14658	1405 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14661	1425 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14664	1430 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14667	1426 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14670	1418 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14673	1414 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14676	1410 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14679	2801 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14682	2406 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14685	2400 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14690	2313 S WASHINGTON AVE	UNK	UNK	UNK	UNK	1/1/1968	C	UNK	1/1/1968	NONRES	UNK	C	UNK	UNK	SCHREINERS; NEW 1 1/2" CURB STOP 2015 REIGEL PLUMBING	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14694	2307 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1968	P	3/4"	1/1/1968	SF	UNK	P	3/4"	UNK	HELLER	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14697	2306 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14700	2300 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14703	2200 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14706	2210 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14709	2110 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14712	2104 S WASHINGTON AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14719	1406 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	NONRES	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	9/26/2013	Cross Connection Survey	
14725	1514 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	5/11/2017	Cross Connection Survey	
14732	1607 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		2006-INSTALLED NEW CURB VALVE W/BOX NORTH OF SIDEWALK	Installation Record	N			Field Inspection Only	Y	4/27/2017	Cross Connection Survey	
14735	1613 E 4TH ST	N	C	Y	3/4"	7/11/2018	C	3/4"	7/11/2018	SF	UNK	C	3/4"	UNK	7/11/2018, REMOVED LEAD WIPE @ MAIN AND CONNECTED TO 3/4" COPPER	Installation Record	Y	7/11/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14738	1614 E 4TH ST	UNK	C	UNK	1"	7/1/2018	C	1"	7/1/2018	NONRES	UNK	C	1"	UNK	MEYERS SLID COPPER THROUGH 4" ABANDONED SERVICE, CUT OUT 6X4 TEE, INSTALLED 3' DIP WITH 2 · 6" HYMAX SLEEVES, 1" CORP TAPPED	Installation Record	Y	7/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14743	1803 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/21/2017	Cross Connection Survey	
14747	1802 E 4TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	IN ROADWAY. RE-TAPPED ALSO. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14754	1811 E 4TH ST	N	C	Y	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003- NEW CORP COPPER VALVE AND BOX *RUNS PARALLEL WITH HYD. LEAD	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14757	1903 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	3/30/2017	Cross Connection Survey	
14760	1904 E 4TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14763	1914 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	NONRES	UNK	C	C		CB VERIFIED 4-97	Installation Record	N			Field Inspection Only	Y	11/22/2013	Cross Connection Survey	
14782	2400 E 5TH ST	UNK	UNK	UNK	6"	1/1/1976	CI-U	6"	1/1/1976	NONRES	UNK	CI-U	6"	UNK	SPRINKLER/MEYERS & MFLD PLB	Installation Record	Y	1/1/1976	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
14787	1011 E 4TH ST	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	7/5/2022: Lead wipe removed	Installation Record	Y	7/5/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14790	1101 E 4TH ST	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	7/8/2022: Lead wipe removed. copper inside home.	Installation Record	Y	7/8/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14793	1109 E 4TH ST	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	7-7-2022: Lead wipe removed	Installation Record	Y	7/7/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14796	1111 E 4TH ST	N	C	UNK	1"	7/7/2022	C	1"	7/7/2022	SF	UNK	C	1"	UNK	7/7/2022: 1" tap to 3/4" copper - separated combined service with 1113 4th	Installation Record	Y	7/7/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14799	1113 E 4TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ BOC, FOUND COPPER 6'6" DEEP. Separated combined services with 1111 4th.	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14802	1115 E 4TH ST	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	7-8-2022: Lead wipe removed, connected to copper.	Installation Record	Y	7/8/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14805	1117 E 4TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	10/1/2021: Removed lead gooseneck at the watermain and replaced with 6' - 3/4" copper. Connected to existing copper @ the watermain.	Installation Record	Y	10/1/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14810	1119 E 4TH ST	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" COPPER & LOCKING VALVE. 3/4" copper main to new box & cv.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14812	1203 E 4TH ST	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2009-REIGELS INSTALLED CURB STOP W/ BOX. 7/11/2022: lead wipe removed	Installation Record	Y	7/11/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14815	406 S WASHINGTON AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14820	501 S WASHINGTON AVE	UNK	UNK	UNK	UNK	1/1/1976	C	UNK	1/1/1976	NONRES	UNK	C	UNK	UNK	1-1/2 SER MFLD PLB	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14824	500 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14827	1231 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14830	608 S WASHINGTON AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/13/22: Lead wipe removed.	Installation Record	Y	7/13/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14833	616 S WASHINGTON AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/13/22: Lead wipe removed @ the main	Installation Record	Y	7/13/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14836	1326 E 8TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF WASHINGTON	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14839	1410 S WASHINGTON AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14842	1414 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	INSULATED FROM MAIN TO CURB STOP/GAFFNEY	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14845	1400 S TAMARACK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14848	1300 E 14TH ST	N	UNK	UNK	UNK	1/1/1964	C	UNK	1/1/1964	SF	UNK	C	UNK	UNK	SCHREINERS. 3/4" copper in house	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14851	1413 S FELKER AVE	UNK	UNK	UNK	UNK	1/1/1962	C	UNK	1/1/1962	NONRES	UNK	C	UNK	UNK	2 - 1"	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14854	1205 E 14TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14857	1309 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14860	1206 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14863	1208 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14866	1212 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14869	1216 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14872	1300 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14876	1310 E 8TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	SERVICE COMES OFF 14TH ST	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14879	1324 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14882	1311 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
14885	1307 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14888	1301 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14891	1219 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14894	1217 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14897	1215 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14900	707 S FELKER AVE	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000- REMOVED LEAD WIPE @ MAIN. LOWERED FROM MAIN TO CL INSULATED OVER CORP	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14903	701 S FELKER AVE	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000-REMOVED LEAD WIPE @ MAIN, LOWERED SERVICE FROM MAIN TO CL. INSULATED OVER CORP.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14906	613 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14909	607 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14912	605 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14915	1200 E 6TH ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF FELKER. 2011-REPLACED LEAD WIPE AT MAIN. CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2011	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14918	1208 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN. 1999: CURB BOX INSTALLED.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14921	1212 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14924	1218 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14927	1220 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14930	1224 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14933	1213 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14936	511 S FELKER AVE	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2000-REMOVED LEAD WIPE @ MAIN, LOWERED SERVICE FROM MAIN TO CL. INSULATED OVER CORP	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14939	501 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14942	1203 WASHINGTON CT	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB VERIFIED 2-97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14945	1201 WASHINGTON CT	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB VERIFIED 2-97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14948	407 S FELKER AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	OVER CORP.3-31-00.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14951	1200 E 4TH ST	N	UNK	UNK	UNK	7/2/1997	C	UNK	7/2/1997	SF	UNK	C	UNK	UNK	NEW SERVICE FROM MAIN TO PROP. LINE ON 7-2-1997. WAS FORMERLY FREEZE-UP SERVICE	Installation Record	Y	7/2/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14956	1010 E 4TH ST	UNK	UNK	UNK	1 1/4"	1/1/1996	C	1 1/4"	1/1/1996	NONRES	UNK	C	1 1/4"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14960	1108 E 4TH ST	N	C	Y	1 1/4"	7/8/2022	C	1 1/4"	7/8/2022	SF	UNK	C	1 1/4"	UNK	7-8-2022: Removed 3 - 1" manifold. retapped with 1-1/4" service saddle and new tap. 6/29/23: Replaced 1-1/4" lead from cs-center of road w/ 1" copper. Installed 1" cs & box. 1" copper on private side.	Installation Record	Y	7/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14963	504 S FELKER AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VAC EXCAVATED @ BOC, FOUND COPPER 7' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14966	506 S FELKER AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ BOC, FOUND COPPER 6'6" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
14969	512 S FELKER AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14972	600 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14975	604 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14978	606 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14981	608 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14984	612 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14987	706 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14990	708 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14993	714 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
14996	1108 WEISTER CT	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP AND 3/4" COPPER FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
14999	1408 S FELKER AVE	N	UNK	UNK	5/8"	1/1/1961	C	5/8"	1/1/1961	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15002	1412 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15005	1416 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF 15TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15008	1113 E 15TH ST	N	C	UNK	5/8"	1/1/1959	C	5/8"	1/1/1959	SF	UNK	C	5/8"	UNK	1-1-2020 J&R VACUUM EXCAVATE @ CB, FOUND COPPER 6' DEEP	Installation Record	Y	1/1/1959	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15011	1109 E 15TH ST	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15014	1101 E 15TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15017	1411 S HEMLOCK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15020	1104 WEISTER CT	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP AND 3/4" COPPER FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15023	1109 WEISTER CT	N	C	UNK	3/4"	1/1/2016	C	3/4"	1/1/2016	SF	UNK	C	3/4"	UNK	2016-INSTALLED 3/4" TAP AND 3/4" COPPER FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15026	1107 WEISTER CT	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP AND 3/4" COPPER FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15029	1105 WEISTER CT	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP AND 3/4" COPPER FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15032	1401 S HEMLOCK AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INTALLED 1" TAP & CONNECTED TO 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15035	800 S HEMLOCK AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE COMES OFF OF 8TH ST.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15038	804 S HEMLOCK AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP & CONNECTED TO 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15041	1400 S HEMLOCK AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP AND CONNECTED TO 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15044	1404 S HEMLOCK AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP & CONNECTED TO 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15047	210 S COLUMBUS DR	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	CB/LV UNKNOWN. 2018 - 3' OF 1" CU CONNECTED TO 3/4" CU IN THE ROAD	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15050	1412 S HEMLOCK AVE	N	C	UNK	3/4"	1/1/2016	C	3/4"	1/1/2016	SF	UNK	C	3/4"	UNK	2016-TAPPED 3/4" 5' NORTH OF VALVE ON DIP. CONNECTED TO 3/4" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15053	1007 E 15TH ST	N	C	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	1-1-2020 J&R VACUUM EXCAVATED 2' FROM CB, FOUND 3/4" COPPER 5'3" DEEP	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15056	1417 S PALMETTO AVE	N	UNK	Y	3/4"	6/1/1997	C	3/4"	6/1/1997	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE FROM MAIN TO CURB STOP 6/97	Installation Record	Y	6/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15059	1409 S PALMETTO AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15062	1407 S PALMETTO AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD FROM MAIN TO CURB STOP 6/97	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15065	1401 S PALMETTO AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15068	1406 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15071	1408 S PALMETTO AVE	N	UNK	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN 6/97	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15074	1416 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15077	1418 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15079	1420 S PALMETTO AVE	Y	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED LEAD WIPE @ MAIN 6/97.	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15082	1500 S PALMETTO AVE	N	UNK	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN 6/97	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15085	1600 S PALMETTO AVE	N	UNK	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN 6/97.	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15088	1602 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	& REMOVED LEAD WIPE @ MAIN 6/97.	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15091	1608 S PALMETTO AVE	N	UNK	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2008- REIGELS INSTALLED CURB VALVE W/ BOX. 1997-RETAPPED & REMOVED LEAD WIPE @ MAIN	Installation Record	Y	1/1/2008	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
15094	1612 S PALMETTO AVE	N	UNK	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	RETAPPED WITH 3/4" CORP., & REMOVED LEAD WIPE @ MAIN 6/97.	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15097	1614 S PALMETTO AVE	N	UNK	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15100	1620 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF E 17TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15103	1001 E 17TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15106	1615 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	D WIPE @ MAIN 6/97	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15109	1611 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	RETAPPED WITH 3/4" CORP. 6/97.	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15112	1607 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	RETAPPED WITH 3/4" CORP. 6/97.	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15115	1603 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	RETAPPED WITH 3/4" CORP. 6/97.	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15118	1601 S PALMETTO AVE	N	UNK	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN 6/97.	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15121	1604 S HEMLOCK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15124	1608 S HEMLOCK AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15127	1612 S HEMLOCK AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15130	1101 E 17TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF HEMLOCK	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15133	1619 S HEMLOCK AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15136	1615 S HEMLOCK AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 8/13/97	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15139	1609 S HEMLOCK AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15142	1605 S HEMLOCK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/13/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15145	1100 E 15TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15148	1104 E 15TH ST	N	C	UNK	1"	1/1/1961	C	1"	1/1/1961	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED 1' FROM CB, FOUND 1" COPPER 6'4" DEEP	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15151	1110 E 15TH ST	N	UNK	UNK	UNK	1/1/1964	C	UNK	1/1/1964	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15154	1500 S FELKER AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF 15TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15157	2701 S APPLE AVE	N	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15160	2700 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	BILL REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15163	2610 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15166	2606 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15169	2512 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15172	2506 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15175	716 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15178	700 E 25TH ST	UNK	C	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	2015- NEW CURB VALVE/BOX INSTALLED	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15181	606 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15184	600 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15190	611 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15193	711 E 25TH ST	N	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15196	717 E 25TH ST	UNK	C	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	2005-INSTALLED 1" CURB VALVE WITH BOX	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15199	801 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15202	2408 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15207	2322 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15210	2314 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15213	2300 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15216	2216 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15219	2208 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15222	2204 WALLONNIE DR	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL PLB	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15225	2205 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15228	2209 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15231	2213 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15234	2305 WALLONNIE DR	UNK	UNK	UNK	1"	1/1/1970	C	1"	1/1/1970	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15237	2313 WALLONNIE DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15240	2212 S PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	2012-RETAPPED DURING LINING PROJECT	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15243	2300 S PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15246	2307 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15249	2115 S PALMETTO AVE	Y	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15252	2104 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15255	2013 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15258	2009 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15261	2005 S PALMETTO AVE	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED LEAD WIPE AT MAIN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15264	2001 S PALMETTO AVE	N	C	UNK	3/4"	1/1/1960	C	3/4"	1/1/1960	SF	UNK	C	3/4"	UNK	4-30-21: 3/4" Copper	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15267	1915 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15270	1909 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15273	1807 S PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1973	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15276	1711 S PALMETTO AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REIGEL PLUMBING, TAP 1970	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15279	1908 S PALMETTO AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15282	1811 S APPLE AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE IS OFF OF 19TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15285	805 E 19TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15288	809 E 19TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15291	816 E 18TH ST	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15294	812 E 18TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15297	808 E 18TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15300	801 E 18TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 18TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15303	805 E 18TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15306	809 E 18TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15309	817 E 18TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15312	1702 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15317	1700 S PALMETTO AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAC EXCAVATED @ BOC, FOUND COPPER 8'3" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15319	808 E 17TH ST	N	UNK	Y	UNK	8/9/1994	C	UNK	8/9/1994	SF	UNK	C	UNK	UNK	REMOVED LEAD, INSTALLED 90 DEG BEND. 8/9/94	Installation Record	Y	8/9/1994	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15322	1701 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15325	1109 E 17TH ST	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-JO#5358 MEWD NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15328	1622 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15331	1618 S FELKER AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15334	1614 S FELKER AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	CB IN SIDEWALK, 2014-INSTALLED NEW CURB BOX	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15337	1610 S FELKER AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15340	1604 S FELKER AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15343	1419 S FELKER AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15346	1213 E 15TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15349	1217 E 15TH ST	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15352	1221 E 15TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15355	1227 E 15TH ST	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15358	1301 E 15TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15361	1311 E 15TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15364	1504 S WASHINGTON AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15367	1508 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15371	1600 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15374	1601 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15377	1603 S WASHINGTON AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15380	1608 S WASHINGTON AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15383	1612 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15386	1323 E 17TH ST	N	UNK	UNK	3/4"	1/1/1960	C	3/4"	1/1/1960	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15389	1317 E 17TH ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15392	1803 S WASHINGTON AVE	N	C	UNK	3/4"	1/1/2009	C	3/4"	1/1/2009	NONRES	UNK	C	3/4"	UNK	2009-NEW 3/4" COPPER FROM CORP TO NEW CURB STOP & BOX W/ INSULATION	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15395	1809 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
15398	1901 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15401	1907 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15404	2004 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15407	1904 S WASHINGTON AVE	N	C	Y	3/4"	8/20/2019	C	3/4"	8/20/2019	SF	UNK	C	3/4"	UNK	LEAD REPLACEMENT WITH MARK MEYERS - MAIN IS 6' DEEP, TAPPED ON TOP	Installation Record	Y	8/20/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15410	1808 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15413	1320 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15416	1617 S TAMARACK AVE	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15419	1615 S TAMARACK AVE	UNK	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15422	1609 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15425	1616 S TAMARACK AVE	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15428	1614 S TAMARACK AVE	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15431	1612 S TAMARACK AVE	UNK	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15434	1312 E 15TH ST	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15437	1300 E 15TH ST	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15440	1609 S MADISON AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15443	1615 S MADISON AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15446	1312 E 17TH ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15449	1308 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15452	1304 E 17TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15455	1701 S MADISON AVE	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15458	1317 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	HELLER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15461	1316 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15464	1308 E 18TH ST	UNK	C	UNK	1"	1/1/1970	C	1"	1/1/1970	SF	UNK	C	1"	UNK	MEYER. 1-1-2020 J&R VACCUM EXCAVATE, LOCATED 1" COPPER 6'2" DEEP 4' FROM CB	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15467	1226 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	STRATFORD PLB. CB LOCATION VERIFIED 10/16/97	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15473	1214 E 18TH ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB ID IN DRIVEWAY 10/16/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15476	1210 E 18TH ST	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 10/16/97	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15479	1204 E 18TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB IS IN DRIVEWAY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15482	1207 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15485	1211 E 18TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 10/16/97	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15488	1219 E 18TH ST	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15491	1221 E 18TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 10/16/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15491	1221 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15494	1224 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15497	1218 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15502	1214 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15504	1208 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15507	1200 E 17TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 J&R VACUUM EXCAVATED @ BOC, FOUND COPPER 6'7" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15511	1201 E 17TH ST	UNK	C	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15516	1219 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15519	1227 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15522	1301 E 19TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 12/4/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15525	1307 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15528	1900 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15531	2107 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15534	2209 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15537	2312 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15540	1301 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15543	1311 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15546	1310 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	BUCKS PLB	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15549	1300 E 21ST ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15552	1111 E 21ST ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	SPENCER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15555	1310 E 22ND ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15558	1311 E 22ND ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15561	1907 PECAN PKWY	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15564	1913 PECAN PKWY	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15567	2207 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15570	2301 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15573	1515 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15576	1601 W 5TH ST	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	REIGEL PLBG.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15579	1609 W 5TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15582	1613 W 5TH ST	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15585	1701 W 5TH ST	UNK	C	UNK	1"	9/19/2023	C	1"	9/19/2023	SF	UNK	C	1"	UNK	9/19/23: Earth INC. installed 1" corp, 18'-1" copper (wm-cs), 1" cs & box, 4'-1" copper (cs-existing 3/4" copper). Project # 5876. See pg. 15 of Const. Report	Installation Record	Y	9/19/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15588	2001 W 5TH ST	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SPENCER PLB.	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15591	512 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15594	600 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	3/4" copper on property side	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15598	606 S SYCAMORE AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15601	610 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15604	700 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15607	706 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15610	712 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15613	716 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	KALSCHED. 3/4" copper on property side	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15616	720 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15619	721 S SYCAMORE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15622	717 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15625	707 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15628	701 S SYCAMORE AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15631	613 S SYCAMORE AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15634	607 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15637	513 S SYCAMORE AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15640	501 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15643	1900 W 5TH ST	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15646	606 S CYPRESS AVE	UNK	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15649	700 S CYPRESS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	THE SOUTH SIDE OF 7TH ST.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15652	706 S CYPRESS AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1970	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15655	714 S CYPRESS AVE	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15659	1811 W 8TH ST	N	C	UNK	3/4"	12/24/2020	C	3/4"	12/24/2020	SF	UNK	C	3/4"	UNK	GAFFNEY. 12-23-2020 - replaced existing corporation, ilnstalled 6" mainbreak sleeve w/ 1" CC. Sized down for 3/4" corp. and connected to existing 3/4" copper 2.5' from main. San. Lateral crosses over top of watermain 1.5' West of tap.	Installation Record	Y	12/24/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15662	715 S CYPRESS AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15665	711 S CYPRESS AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15668	707 S CYPRESS AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15671	601 S CYPRESS AVE	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15676	504 S BIRCH AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	HAD OWN WELL & 3/4" COPPER LV	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15679	510 S BIRCH AVE	N	UNK	UNK	UNK	1/1/1963	C	UNK	1/1/1963	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15682	602 S BIRCH AVE	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	SERVICE IS A RUN IN.	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15685	606 S BIRCH AVE	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	SERVICE IS RUN IN.	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
15688	700 S BIRCH AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15691	704 S BIRCH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15694	714 S BIRCH AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15697	717 S BIRCH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15700	707 S BIRCH AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15703	701 S BIRCH AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15706	609 S BIRCH AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15709	607 S BIRCH AVE	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15712	601 S BIRCH AVE	N	UNK	UNK	UNK	1/1/1968	C	UNK	1/1/1968	SF	UNK	C	UNK	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15715	1710 W 5TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15718	500 S LINCOLN AVE	N	UNK	UNK	5/8"	1/1/1961	C	5/8"	1/1/1961	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15721	600 S LINCOLN AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1968	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15724	606 S LINCOLN AVE	N	C	UNK	3/4"	7/24/1961	C	3/4"	7/24/1961	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	7/24/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15727	706 S LINCOLN AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1968	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15730	1701 W 8TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15733	903 S LINCOLN AVE	N	C	UNK	1"	1/1/2009	C	1"	1/1/2009	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15738	815 S MARYKNOLL AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15741	801 S MARYKNOLL AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15744	1500 W 8TH ST	N	UNK	UNK	UNK	1/1/1981	C	UNK	1/1/1981	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/17/97. INSULATED 2' X 8'	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15747	810 S SCHMIDT AVE	N	C	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	KALSCHED. 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND COPPER 8'10" DEEP. 3/4" copper on property side	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15750	814 S SCHMIDT AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15753	1408 W 8TH ST	N	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	SERVICE COMES ACROSS INTERSECTION	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15756	1400 W 8TH ST	N	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15759	708 S SCHMIDT AVE	N	C	Y	3/4"	9/16/2020	C	3/4"	9/16/2020	SF	UNK	C	3/4"	UNK	9/16/2020 - Removed 6' of Lead from main to driveway, replaced w/ 3/4" copper. Conected to existing 3/4" copper under driveway. 3/4" copper on property side	Installation Record	Y	9/16/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15762	1501 W 8TH ST	N	UNK	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	TAPPED TO NEW MAIN / CURB STOP INSTALLED	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15765	1507 W 8TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15768	1511 W 8TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15771	713 S MARYKNOLL AVE	N	UNK	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15774	714 S MARYKNOLL AVE	N	UNK	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15777	1613 W 8TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15780	701 S LINCOLN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 7TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15783	1604 W 7TH ST	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	3/4" copper on property side	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15786	700 S MARYKNOLL AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2020 - Street Dept. hit service, replaced damaged section from centerline to 5' south with 2 - 3/4" compression and 18" - 3/4" copper	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15789	701 S MARYKNOLL AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15792	1504 W 7TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15795	700 S SCHMIDT AVE	N	C	Y	3/4"	1/1/2020	C	3/4"	1/1/2020	SF	UNK	C	3/4"	UNK	2020 - removed lead wipe @ watermain, connected to existing 3/4" copper	Installation Record	Y	1/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15798	614 S SCHMIDT AVE	N	C	UNK	5/8"	1/1/1959	P	5/8"	1/1/1959	SF	UNK	P	5/8"	UNK	1" PEX ON CUSTOMERS SIDE - PIONEER PLUMBING NEW CB 2017	Installation Record	Y	1/1/1959	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15801	1505 W 7TH ST	N	C	Y	3/4"	1/1/1950	C	3/4"	1/1/1950	SF	UNK	C	3/4"	UNK	10/2/2020 - Removed 2' of lead @ main replaced w/ 3/4" copper. Connected to existing 3/4" copper in ditch	Installation Record	Y	1/1/1950	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15804	1507 W 7TH ST	N	C	Y	3/4"	1/1/1952	C	3/4"	1/1/1952	SF	UNK	C	3/4"	UNK	11/3/2020 - Removed 2.5' of Lead @ main, connected to 3/4" copper 3' from main. *ALL COPPER SERVICE*	Installation Record	Y	1/1/1952	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15807	614 S MARYKNOLL AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	OLD CORP-36'W & 7'S OF HYD. NEW- 54'W & 4'N OF HYD @ 7TH & MARYKNOLL	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15810	1605 W 7TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15813	1607 W 7TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15816	1611 W 7TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15819	615 S LINCOLN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF 7TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15822	1614 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15825	1604 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15828	600 S MARYKNOLL AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15831	601 S MARYKNOLL AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15834	1510 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15837	1506 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED GOOSE NECK @ MAIN. DEPTH 6'6". 6/27/89	Installation Record	Y	6/27/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15840	1504 W 6TH ST	UNK	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15843	1507 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN - REMOVED GOOSE NECK AT MAIN 6-27-89. DEPTH 6'6"	Installation Record	Y	6/27/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15846	1513 W 6TH ST	N	UNK	UNK	5/8"	UNK	C	5/8"	UNK	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15849	1605 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15852	1607 W 6TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15855	1614 W 5TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15858	1610 W 5TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB VERIFIED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15861	1604 W 5TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15864	500 S MARYKNOLL AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15867	1500 W 5TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE COMES OFF OF SCHMIDT	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15870	1414 W 5TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	SERVICE COMES OFF OF SCHMIDT. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15873	1410 W 5TH ST	N	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	NONRES	UNK	C	3/4"	UNK	SCHREINERS FOUR 3/4" Copper taps to 1-1/2" copper. 1-1/2" on property side. Dug and verified 10/7/2022	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15877	1300 W 5TH ST	N	C	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	VALVE IS IN PP-FOR OLD CHURCH & SCHOOL - Retapped and connected to existing 2" copper in the terrace	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15877	1300 W 5TH ST	N	C	Y	2"	7/14/2022	C	2"	7/14/2022	NONRES	UNK	C	2"	UNK	7/14/22: Removed 4-1" lead gooseneck manifold to 2 copper. Retapped North of abandoned corps. (3'). Used 8" service sleeve w/ 2" C.C. Ran 10'-2" copper & conn. to existing 2" copper @ East edge of the sidewalk. Insulated over copper & abandoned corps.	Installation Record	Y	7/14/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15888	1507 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15891	1403 W 5TH ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15894	1301 W 5TH ST	N	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15897	1209 W 5TH ST	UNK	UNK	UNK	1"	1/1/1974	P	1"	1/1/1974	SF	UNK	P	1"	UNK	RON MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15900	403 S COLUMBUS DR	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 6/17/97. 8/12/2021: Dug & verified at the watermain, found 3/4" copper. No lead	Installation Record	Y	8/12/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15903	313 DRAKE CT	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	2006-INSTALLED NEW 3/4" CORP	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15906	305 DRAKE CT	N	C	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	2006-INSTALLED NEW 3/4" CORP	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15909	301 DRAKE CT	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2006-INSTALLED NEW 3/4" CORP	Installation Record	Y	1/1/2006	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15912	308 DRAKE CT	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2006-INSTALLED NEW 3/4" CORP	Installation Record	Y	1/1/2006	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15915	300 DRAKE CT	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2006-INSTALLED NEW 3/4" CORP	Installation Record	Y	1/1/2006	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
15918	303 S COLUMBUS DR	N	C	UNK	1"	7/11/2018	C	1"	7/11/2018	SF	UNK	C	1"	UNK	2018 - 3' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN STREET	Installation Record	Y	7/11/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15921	301 S COLUMBUS DR	N	C	UNK	1"	7/11/2018	C	1"	7/11/2018	SF	UNK	C	1"	UNK	SERVICE IS OFF OF COLUMBUS. 2018 - 2' OF 1" CU CONNECTED TO TO EXISTING 3/4" CU IN THE STREET	Installation Record	Y	7/11/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15924	217 COLUMBUS CT	UNK	C	UNK	1"	7/17/2018	C	1"	7/17/2018	SF	UNK	C	1"	UNK	20' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN THE MIDDLE OF THE CUL-DE-SAC (1" CU CROSSES OVER SANITARY SEWER)	Installation Record	Y	7/17/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15927	215 COLUMBUS CT	N	C	UNK	1"	7/17/2018	C	1"	7/17/2018	SF	UNK	C	1"	UNK	TAP IS 14' SOUTH OF HYDRANT. 12' OF 1" CU CONNECTED TO EXISTING 3/4" CU @ EDGE OF THE ROAD	Installation Record	Y	7/17/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15930	209 S COLUMBUS DR	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - 2' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN ROAD	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15933	205 S COLUMBUS DR	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - 2" OF 1" CU CONNECTED TO EXISTING 3/4" CU IN THE ROAD. 3/4" copper on property side	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15936	203 S COLUMBUS DR	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - 4' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN THE ROAD	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15939	1312 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
15942	1104 W ADLER RD	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2010-CAL'S INSTALLED NEW CURB VALVE W/ BOX	Installation Record	Y	1/1/2010	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15945	216 S ADAMS AVE	N	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	RE-TAPPED 1" PIPE BURST--2017. 1" copper on property side	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15948	300 S ADAMS AVE	N	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	RE-TAPPED 1" PIPE BURST--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15951	308 S ADAMS AVE	N	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	RE-TAPPED 1" PIPE BURST--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15954	314 S ADAMS AVE	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	2011-INSTALLED NEW 1" CORP, NEW 1" COPPER FROM CORP TO NEW 1" CURB STOP/BOX; RE-TAPPED 1" PIPE BURST--2017	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15957	1016 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15960	1012 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN. 4/19/21: Customer emailed photo to verify service material (copper)	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15963	1006 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15966	1002 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15969	217 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15972	213 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15975	209 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR PROP. LINE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15978	205 WESTVIEW DR	UNK	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER @ MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15981	217 S ADAMS AVE	N	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	RE-TAPPED 1" PIPE BURST--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15984	201 S ADAMS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2007-CURB BOX INSTALLED SERVICE IS OFF ADLER	Installation Record	Y	1/1/2007	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15987	210 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15990	206 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER @ MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
15993	1101 W ADLER RD	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SPENCER. 3/4" copper on property side	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15996	1209 W ADLER RD	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	NO CURB BOX	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
15999	1213 W ADLER RD	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16002	1217 W ADLER RD	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2013- INSTALLED CURB VALVE/ BOX	Installation Record	Y	1/1/2013	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16005	1405 W ADLER RD	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16008	1407 W ADLER RD	UNK	UNK-LG	UNK	UNK	1/1/1930	C	UNK	1/1/1930	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/28/2014	Cross Connection Survey	
16011	216 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16014	1410 W ADLER RD	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHUH	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16017	1406 W ADLER RD	N	UNK	UNK	5/8"	1/1/1989	C	5/8"	1/1/1989	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16020	202 S COLUMBUS DR	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - 1' OF 1" CU CONNECTED TO 3/4" CU IN THE ROAD	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16023	212 S COLUMBUS DR	N	C	UNK	2"	1/1/2018	P	2"	1/1/2018	SF	UNK	P	2"	UNK	CALS PLUMBING. 2018 - 30' OF 2" CU CONNECTED TO EXISTING CURB STOP	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16026	300 S COLUMBUS DR	N	C	UNK	1"	7/11/2018	C	1"	7/11/2018	SF	UNK	C	1"	UNK	CB/LV UNKNOWN. 2018 - 3' OF 1" CU CONNECTED TO EXISTING 1" CU IN THE STREET	Installation Record	Y	7/11/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16029	400 S COLUMBUS DR	UNK	C	UNK	3/4"	1/1/2018	C	3/4"	1/1/2018	SF	UNK	C	3/4"	UNK	MEYERS. 2018 - 3' OF 3/4" CU CONNECTED TO EXISTING 3/4" CU IN THE STREET	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16031	2601 E 34TH ST	UNK	DI	UNK	4"	1/1/1998	DI	4"	1/1/1998	NONRES	UNK	DI	4"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
16031	2601 E 34TH ST	UNK	DI	UNK	8"	1/1/1998	DI	8"	1/1/1998	NONRES	UNK	DI	8"	UNK	8" VALVE WITH VALVE BOX.	Installation Record	Y	1/1/1998	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
16033	511 S LINCOLN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/17/97	Installation Record	Y	6/17/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16422	2306 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16425	2508 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16433	1306 E 22ND ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16436	510 W IVES ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16443	1607 N WOOD AVE	UNK	C	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS. 1" copper on property side	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16443	1607 N WOOD AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON. 1" copper on property side	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16446	1408 S HEMLOCK AVE	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP CONNECTING TO 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16450	802 W BLODGETT ST	UNK	C	Y	1"	9/30/2021	C	1"	9/30/2021	SF	UNK	C	1"	UNK	9/30/2021: A-1 removed lead gooseneck @ water main and copper from wm-cs, replaced w/ 1" corp, 1" copper and 1" cs & box. Connected to existing 1/2" copper 7' from cs. Reducer is property side of cs. (see service card)	Installation Record	Y	9/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16455	1614 S HEMLOCK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16461	2600 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	RON MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16464	1611 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	NONRES	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16467	1222 E 19TH ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16474	2804 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16479	509 S SYCAMORE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16482	1911 W 5TH ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16488	1709 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	NONRES	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16492	1306 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16495	206 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL PLB. CB LOCATION VERIFIED 6/17/97	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16501	1600 E 4TH ST	UNK	UNK	UNK	1"	1/1/1968	C	1"	1/1/1968	NONRES	UNK	C	1"	UNK	CB VERIFIED 4-97. 1" copper on property side	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16503	315 W CLEVELAND ST	N	C	UNK	1"	7/29/2020	C	1"	7/29/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 13' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 37 of Const. Report)	Installation Record	Y	7/29/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16507	1308 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16510	826 W UPHAM ST	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16514	916 W BLODGETT ST	UNK	C	Y	1"	10/4/2021	C	1"	10/4/2021	SF	UNK	C	1"	UNK	10/4/2021: A-1 removed lead from wm-cs and replaced w/ 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper at the sidewalk.	Installation Record	Y	10/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16517	622 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16520	808 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16529	2707 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
16533	1218 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16536	1901 S TAMARACK AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16542	2304 S GALVIN AVE	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	NONRES	UNK	C	1"	UNK	2016-INSTALLED NEW CURB BOX	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16545	610 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16552	510 W BLODGETT ST	UNK	C	Y	1"	7/1/2021	C	1"	7/1/2021	SF	UNK	C	1"	UNK	7/1/2021: All lead removed. New 1" tap is 34' East of N.E.C.H. Connected to existing 3/4" copper.	Installation Record	Y	7/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16555	2205 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16558	110 N SPRUCE AVE	UNK	Unk	UNK	1"	9/17/2021	UNK	1"	9/17/2021	SF	UNK	UNK	1"	UNK	New tap - New Curbvalve. New tap is 4' North of old tap, New 1" copper hooked to 3/4" copper inside	Installation Record	Y	9/17/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16561	1316 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16564	1306 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(MEYER 1974) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16567	2601 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16572	705 S FELKER AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VACUUM EXCAVATED @ BOC, FOUND COPPER 8' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16575	1311 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYER. 3/4" copper on property side	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16578	2011 PECAN PKWY	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16582	1421 E 28TH ST	UNK	C	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16585	514 S SCHMIDT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16588	513 S FELKER AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2000-REMOVED LEAD W/PW @ MAIN, LOWERED MAIN TO CL. INSULATED OVER CORP. 2020 J&R VAC EXCAVATED @ BOC, FOUND COPPER 6'6" DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16594	2201 WALLONNIE DR	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16597	1814 E 4TH ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	NONRES	UNK	C	1"	UNK	1998: RE-TAPPED (REIGEL)	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16601	1007 W KALSCHED ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	O	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16605	1412 N WOOD AVE	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16610	209 W CLEVELAND ST	N	C	Y	1"	6/25/2020	C	1"	6/25/2020	SF	UNK	C	1"	UNK	Earth INC. - Installed Copper from corp. to main, Reigel Plbg. replaced lead with copper from CS to house. (Pg. 19 of Const. Report)	Installation Record	Y	6/25/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16618	610 W BLODGETT ST	UNK	C	Y	1"	7/21/2021	C	1"	7/21/2021	SF	UNK	C	1"	UNK	7/21/2021: Worked w/ Mark Meyer to remove lead on utility & customer side. Meyer also replaced San. Lateral from curb to house. Installed 1" copper from wm-meter. Retapped 3' East from abandoned tap.	Installation Record	Y	7/21/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16622	1610 S HUME AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16625	1615 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16628	512 S LINCOLN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16631	2701 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16639	2301 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1978	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16642	1500 W ADLER RD	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16645	900 W ARNOLD ST	UNK	C	Y	1"	7/25/2023	C	1"	7/25/2023	SF	UNK	C	1"	UNK	7/25/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper after the cs (+/- 12") Proj. #5878 pg. 11 of const. report.	Installation Record	Y	7/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16648	2501 E LAWRAINE ST	UNK	UNK	UNK	UNK	1/1/1978	C	UNK	1/1/1978	SF	UNK	C	UNK	UNK	REIGEL	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16651	1209 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16654	504 N ST JOSEPH AVE	UNK	C	UNK	1 1/2"	1/1/2008	C	1 1/2"	1/1/2008	NONRES	UNK	C	1 1/2"	UNK	HAAS-6x1-1/2 STAINLESS SADLE. 1-1/2" copper on property side	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16657	1206 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(STRATFORD 1973) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16661	1402 W ADLER RD	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	MEYERS. 2018 - 3' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN THE STREET	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16664	625 W UPHAM ST	UNK	C	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	LINED WATER MAIN, MICHELS--2016	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16670	1500 N BROADWAY AVE	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16673	2305 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16676	304 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16679	310 W ARNOLD ST	N	C	UNK	1"	1/1/2011	P	1"	1/1/2011	SF	UNK	P	1"	UNK	PEMBER. 1" PLASTIC PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16683	920 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16686	1207 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16689	2306 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16692	2121 PECAN PKWY	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16695	1411 E 29TH ST	UNK	C	UNK	3/4"	2/19/2019	C	3/4"	2/19/2019	SF	UNK	C	3/4"	UNK	NEW 3/4" TAP & COPPER FROM WM - CS	Installation Record	Y	2/19/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16699	510 W CLEVELAND ST	UNK	C	UNK	1"	8/26/2020	C	1"	8/26/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 12' - 1" copper past cs to connect to existing 1" copper. (Pg. 55 of Const. Report)	Installation Record	Y	8/26/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16702	2800 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16706	1210 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REPLACED 3' OF 3/4" COPPER, JUST NORTH OF STORM SEWER-2014	Installation Record	Y	1/1/2014	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16713	1410 N BROADWAY AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16716	1309 E 18TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 12/4/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16719	113 W BLODGETT ST	UNK	P	Y	1"	7/26/2023	C	1"	7/26/2023	SF	UNK	C	1"	UNK	7/26/23: J&R bored in 2 - 1" plastic lines from N. Chestnut on South side fo stop sign & 3" behind curb to cs. Abandoned old lead line to the street behind the curb.	Installation Record	Y	7/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16722	2608 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16725	1403 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	TO CURB STOP 6/97.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16728	908 E 19TH ST	UNK	UNK	UNK	1 1/2"	UNK	C	1 1/2"	UNK	SF	UNK	C	1 1/2"	UNK	MEYERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16731	1510 W 7TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16737	2206 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16742	1606 W 5TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16745	309 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16748	115 W BLODGETT ST	UNK	C	y	3/4"	6/1/2020	C	3/4"	6/1/2020	SF	UNK	C	3/4"	UNK	MAP ON CARD Replace 2020, Removed Lead 2020	Installation Record	Y	6/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16751	1821 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16754	1601 E 29TH ST	UNK	C	UNK	1 1/2"	1/1/1979	C	1 1/2"	1/1/1979	NONRES	UNK	C	1 1/2"	UNK	2008-REPLACED SADDLE CLAMP AND CORP	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16757	700 WESTERN ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LV/CB UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16760	1316 N WOOD AVE	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16763	2516 BUTTERNUT PKWY	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16766	1422 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16770	1819 E BECKER RD	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16773	1202 WASHINGTON CT	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB VERIFIED 2-97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16776	500 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16779	1313 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	NEW 1" CURB VALVE AND NEW BOX	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16783	2301 WALLONNIE DR	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16786	1015 W UPHAM ST	UNK	C	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16789	3600 S CENTRAL AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	WATER DEPT	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16792	3606 S CENTRAL AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	PRIVATE LINE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16792	3606 S CENTRAL AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	WATER DEPT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16795	2406 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16798	2001 S TAMARACK AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16802	310 W CLEVELAND ST	N	C	UNK	1"	7/30/2020	C	1"	7/30/2020	SF	UNK	C	1"	UNK	Earth INC. insalled copper from main to cs, 12' - 1" copper past cs to connect to existing 3/4" copper (Pg. 38 of Const. Report)	Installation Record	Y	7/30/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16808	1201 E 6TH ST	N	UNK	UNK	3/4"	1/1/1960	C	3/4"	1/1/1960	SF	UNK	C	3/4"	UNK	SERVICE IS FED FROM 6" ON FELKER.	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16812	2508 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
16815	1018 W CHAPEL ST	UNK	C	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16818	1408 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16821	709 W BLODGETT ST	UNK	C	UNK	1"	7/27/2021	C	1"	7/27/2021	SF	UNK	C	1"	UNK	9/27/21: A-1 Installed 1" corp., 12' - 1" cu, & 1" cs & box. 10/5/21: Gaffney ran 3/4" cu from where A-1 left off (ran to house w/ new san. lateral).	Installation Record	Y	7/27/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16824	2315 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16828	1406 N WOOD AVE	UNK	C	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16831	1107 E 4TH ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16834	108 N CHESTNUT AVE	N	C	Y	1"	5/8/2024	C	3/4"	1/1/1929	SF	UNK	C	C		5/8/2024: Removed lead from wm-cs. Replaced w/ 1" corp, 1" copper & 1" cs & box. Conn. to exist 3/4" cu 12" west of new cs. Old corp is 4' South of the new one. San Lateral is above wm and inbetwenn new and old corp. (pvc inside clay tile)	SL repair/replace record	Y	5/8/2024	Visual insp during install or repair	Field Inspection Only	Y	5/8/2024	Visual Insp during install or repair	
16837	405 S FELKER AVE	N	UNK	UNK	3/4"	1/1/1994	C	3/4"	1/1/1994	SF	UNK	C	3/4"	UNK	ENTIRE STREET	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16840	1111 W 4TH ST	UNK	C	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	2006-INSTALLED NEW 3/4" CORP	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16843	2316 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16846	1511 W 7TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16849	1025 W LAIRD ST	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16853	612 E 25TH ST	UNK	C	UNK	1 1/2"	1/1/2012	P	1 1/2"	1/1/2012	SF	UNK	P	1 1/2"	UNK	DISCONNECTED OLD 3/4" SERVICE @ MAIN LOCATED 3' WEST OF 1-1/2" SADDLE & TAP. TYPE K COPPER	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16856	406 E 29TH ST	UNK	UNK	UNK	6"	1/1/2003	DI	6"	1/1/2003	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
16859	1300 N BROADWAY AVE	UNK	C	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16863	715 W BLODGETT ST	UNK	C	Y	1"	9/27/2021	C	1"	9/27/2021	SF	UNK	C	1"	UNK	9/27/2021: A-1 removed existing lead service from wm -cs. Replaced w/ 1" copper, 1" corp., and 1" cs & box. Connected to existing 3/4" copper @ the sidewalk. Corp. is 4.5' East of curb stop.	Installation Record	Y	9/27/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16866	1820 E 26TH ST	UNK	UNK	UNK	UNK	1/1/1965	C	UNK	1/1/1965	NONRES	UNK	C	UNK	UNK	MEL SPENCER	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16870	706 W BLODGETT ST	UNK	C	UNK	1"	9/28/2021	C	1"	9/28/2021	SF	UNK	C	1"	UNK	9/28/2021: A-1 Removed 3/4" copper from wm - cs, replaced with 32' - 1" copper, 1" corp., and 1" cs & box. Connected to existing 1/2" copper 4' East of the curb valve. (see service card for sketch)	Installation Record	Y	9/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16873	613 S MARYKNOLL AVE	N	UNK	UNK	5/8"	1/1/1959	C	5/8"	1/1/1959	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1959	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16876	2307 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16879	1808 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16882	1600 N BROADWAY AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16885	918 W BLODGETT ST	UNK	C	UNK	1"	10/5/2021	C	1"	10/5/2021	SF	UNK	C	1"	UNK	10/5/2021: A-1 removed existing 3/4" copper from wm-cs and replaced w/ 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper at the sidewalk. Insulated @ water main, water main is 6.5' bury to top of pipe.	Installation Record	Y	10/5/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16888	2702 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16892	1205 E 15TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16895	610 S LINCOLN AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16898	1201 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16900	1101 W UPHAM ST	UNK	DI	UNK	8"	UNK	DI	8"	UNK	NONRES	UNK	DI	8"	UNK	2002	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
16900	1101 W UPHAM ST	UNK	DI	UNK	8"	UNK	DI	8"	UNK	NONRES	UNK	DI	8"	UNK	2002	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
16900	1101 W UPHAM ST	UNK	UNK	UNK	8"	1/1/1979	UNK	8"	1/1/1979	NONRES	UNK	UNK	8"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
16900	1101 W UPHAM ST	UNK	UNK	UNK	8"	1/1/1979	DI	8"	1/1/1979	NONRES	UNK	DI	8"	UNK	Copper service through the floor; tapped off of 8" private main	Installation Record	Y	1/1/1979	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
16904	504 W IVES ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16907	912 E 19TH ST	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	1" OFF 1-1/2" LINE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16911	304 W BLODGETT ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2011-COPPER AT MAIN. REPLACED 90 DEG. FITTING AT MAIN & INSULATED	Installation Record	Y	1/1/2011	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16914	1508 S POPPLE AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	NONRES	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16917	507 S FELKER AVE	UNK	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	CB VERIFIED 8-97	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16924	2008 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16927	1309 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	Service material is copper on customer side confirmed from phot submitted via email 4/13/2021	Installation Record	Y	4/13/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16931	1822 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16934	727 N IRENE AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16937	915 W ARNOLD ST	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	2010-CURB VALVE NOT OPERABLE DUE TO ROUNDED OPERATING SHAFT. 2002-NEW 1" CORP & COPPER & CURB BOX.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16940	1409 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16943	1226 E 19TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/26/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16946	626 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16949	813 E 18TH ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16952	502 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1/2" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16955	1901 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL PLB	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16958	2809 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16961	1210 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011- CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN. '97-CB LOCATION VERIFIED	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16964	506 W CLEVELAND ST	N	C	Y	1"	8/27/2020	C	1"	8/27/2020	SF	UNK	C	1"	UNK	2003-REMOVED WIPE @ CURB VALVE. INSTALLED NEW CURB VALVE W/ BOX. 8/27/2020 Earth INC. installed copper form main to cs, Meyers replaced lead on customer side (Lead Replacement Program) (Pg. 56 of Const. Report)	Installation Record	Y	8/27/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16967	315 W DEPOT ST	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/23/97 - Removed lead wipe from CS. 3/4" COPPER LOCKING VALVE. 8/23/21: No lead, Installed new CB	Installation Record	Y	8/23/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16970	1200 E 27TH ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16974	1911 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16977	1610 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16980	1610 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
16983	1113 W ADLER RD	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
16986	1230 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16989	1219 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
16991	619 LAUREL CT	UNK	C	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	NONRES	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1968	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17000	509 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17003	400 N ST JOSEPH AVE	N	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	NEW 3/4" CORP & CURB STOP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17006	2021 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17009	1007 E 4TH ST	N	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	7/5/2022: Lead wipe removed, connected to copper	Installation Record	Y	7/5/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17012	111 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17018	705 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17021	2800 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17024	2306 S PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17030	2401 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17034	1505 W 6TH ST	UNK	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17037	2101 W 5TH ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
17041	1405 E 29TH ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17044	1103 WEISTER CT	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- INSTALLED 1" CORP, 3/4" COPPER FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17047	1301 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF 17TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17050	1214 W ADLER RD	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	6/6/2014	Cross Connection Survey	
17055	1710 E 29TH ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17058	415 W BLODGETT ST	N	C	Y	1"	7/8/2020	C	1"	7/8/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 8' - 1" copper past cs to connect to existing Lead (Customer refuses to eliminate the lead service to house) Pg 25 & 26 Const. Report. 4/15/23: Reigle plbg. replaced lead w/ 1" copper from cs-meter.	Installation Record	Y	7/8/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17062	723 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17067	1606 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17070	630 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17073	601 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17076	710 N GALVIN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17079	2304 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17082	1301 E 14TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17085	509 W IVES ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17088	600 S SCHMIDT AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17092	608 W BLODGETT ST	UNK	C	Y	1"	7/19/2021	C	1"	7/19/2021	SF	UNK	C	1"	UNK	7/19/2021: Pulled 1" copper to replace lead from WM-CS. Retapped 7' East of abandonded tap. Dalton Tysver connected to existing 3/8" copper 18" S. of CS by brazing. Reduced from 1" to 3/8" S. of CS. repaired San. Lateral in driveway as well.	Installation Record	Y	7/19/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17095	2711 S FELKER AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17101	1219 E 20TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/12/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17107	619 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17110	500 E 29TH ST	N	C	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	5 CORP MANIFOLD WITH 3/4" COPPER	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17110	500 E 29TH ST	UNK	UNK	UNK	8"	7/25/2022	P	8"	7/25/2022	NONRES	UNK	P	8"	UNK	7/25/22: Installed 12"x8" stainless cut-in tee w/ 8" valve. (See Plumber inspector notes and pictures permit number 20220366). Customer installed 8" pvc c900 after valve.	Installation Record	Y	7/25/2022	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
17113	501 S HUME AVENUE	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1980	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17116	2306 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17120	501 S MARYKNOLL AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	INSULATED @ MAIN & CENTERLINE 11/97	Installation Record	Y	11/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17126	501 E 25TH ST-BACK	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	NONRES	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17132	1201 E 21ST ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17135	1105 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	MEWD - NEW 2" COPPER FROM MAIN TO CURB VALVE AND BOX	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17138	1305 E 18TH ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1969	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17145	2310 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17148	1810 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17151	610 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17154	2808 S HUME AVE	UNK	UNK	UNK	UNK	1/1/1969	C	UNK	1/1/1969	NONRES	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17154	2808 S HUME AVE	UNK	P	UNK	8"	6/7/2023	P	8"	6/7/2023	NONRES	UNK	P	8"	UNK	6/7/23: MU installed 8" cut-in valve (Live tap) 8" valve bolted to sleeve. Suda installed 8" PVC to new building to the West.	Installation Record	Y	6/7/2023	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
17163	2607 S TAMARACK AVE	N	C	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SCHREINERS. 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 3/4" COPPER 5'3" DEEP	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17167	309 N CHESTNUT AVE	UNK	C	UNK	1"	6/16/2020	C	1"	6/16/2020	SF	UNK	C	1"	UNK	EARTH INC. - Corp. located 34' West of Valve #1746 & 9' North of Center of Sanitary Manhole, Installed 154' - 1" copper and corp., Meyers installed CS & Box (Pg. 8 & 14 of Const. Report)	Installation Record	Y	6/16/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17170	1713 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	NONRES	UNK	C	C		3/4" Copper & Locking valve	Installation Record	N			Field Inspection Only	Y	3/19/2015	Cross Connection Survey	
17176	1905 S TAMARACK AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17179	2506 BUTTERNUT PKWY	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1973	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17182	215 S ADAMS AVE	N	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	RE-TAPPED 1" PIPE BURST--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17185	207 N CHESTNUT AVE	UNK	C	Y	1"	4/23/2024	C	1"	4/23/2024	SF	UNK	C	1"	UNK	4/23/24: Removed lead. 1" copper installed from main to curb stop	Installation Record	Y	4/23/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17194	1905 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17200	1500 E BECKER RD	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17203	1221 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17206	1700 S WASHINGTON AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17209	1206 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17212	1207 E 21ST ST	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17215	2210 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL-PLASTIC INSIDE	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17218	1406 N BROADWAY AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17221	801 S LINCOLN AVE	N	C	UNK	1"	1/1/2009	C	1"	1/1/2009	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17228	2319 ANTON CT	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17231	514 S FELKER AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17234	412 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17237	204 S COLUMBUS DR	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	JOSEPH SCHUH. 2018 - 1' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN THE ROAD	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17243	700 S LINCOLN AVE	N	UNK	UNK	UNK	1/1/1970	C	UNK	1/1/1970	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1970	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17246	1311 E 27TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17249	308 W CLEVELAND ST	N	C	UNK	1"	8/3/2020	C	1"	8/3/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, 16' - 1" copper past cs to connect to existing 3/4" copper. (Pg.) 40 of Const. Report)	Installation Record	Y	8/3/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17256	600 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1/2" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17260	214 W 2ND ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	NONRES	UNK	C	C		3/4" copper on property side	Installation Record	N			Field Inspection Only	Y	6/7/2013	Cross Connection Survey	
17263	413 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17266	2300 ANTON CT	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17269	1825 E BECKER RD	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17272	1606 E 4TH ST	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	O	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	8/18/2017	Cross Connection Survey	
17275	1605 S MADISON AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17280	2001 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17283	1307 E 22ND ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17286	212 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17289	2211 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17296	1626 S HEMLOCK AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17299	600 W BLODGETT ST	UNK	C	Y	UNK	7/28/2021	C	UNK	7/28/2021	NONRES	UNK	C	UNK	UNK	7/28/2021: Retapped 3' West of abandonded tap. Pulled in new 1" copper, removed lead from wm-cs. Connected to existing 3/4" copper 6" South of new 1" cs & box.	Installation Record	Y	7/28/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17302	2505 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17305	2010 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17308	1300 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17311	808 W MCMILLAN ST	UNK	C	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17314	302 W CLEVELAND ST	N	C	UNK	1"	7/31/2020	C	1"	7/31/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, 9.5' past cs to connect to existing 3/4" copper. (Pg. 39 of Const. Report)	Installation Record	Y	7/31/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17318	1419 S PALMETTO AVE	UNK	UNK-LG	UNK	UNK	1/1/1927	C	UNK	1/1/1927	SF	UNK	C	C		REMOVED LEAD WIPE @ MAIN 6/97	Installation Record	N			Field Inspection Only	Y	3/3/2017	Cross Connection Survey	
17326	2510 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
17329	821 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17332	601 E 29TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	THIS SERVICE COMES OFF A 2" PRIVATE LINE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17335	200 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER @ MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17349	1901 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17353	814 E 19TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17364	2807 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	RON MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17369	919 W BLODGETT ST	UNK	C	Y	1"	10/5/2021	C	1"	10/5/2021	SF	UNK	C	1"	UNK	10/5/2021: A-1 removed lead from wm-cs and replaced w/ 1" corp., 1" copper and 1" cs & box. Connected to existing 1" HDPE on the back (North) side of the sidewalk.	Installation Record	Y	10/5/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17372	1800 E MCMILLAN ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17377	1307 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	BUCK'S PLB.	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17383	2101 S PALMETTO AVE	N	C	UNK	3/4"	1/1/2013	C	3/4"	1/1/2013	SF	UNK	C	3/4"	UNK	2013-INSTALLED NEW COPPER FROM MAIN TO CURB VALVE. INSTALLED NEW CURB VALVE/BOX	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17386	601 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	NONRES	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17389	401 W BLODGETT ST #A	UNK	C	Y	1"	6/17/2021	C	1"	6/17/2021	SF	UNK	C	1"	UNK	6/17/2021: Full Lead Replacement from WM-CS. Replaced w/ 1" copper. New tap is 3' East of abandoned tap. Connected to existing 3/4" copper 6" North of CS. Hit gas service w/ breaker. Most gas services on 300-600 BLK of W. Blodgett are 1" under conc.	Installation Record	Y	6/17/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17392	716 W BLODGETT ST	UNK	C	Y	1"	9/28/2021	C	1"	9/28/2021	SF	UNK	C	1"	UNK	7/28/2021: A-1 Removed lead from wm-cs and replaced w/ 1" corp., 32' - 1" copper, 1" cs & box. 9/30/2021: Mark Meyers removed galv. from cs - house & replaced w/ 1" copper from the cs to the meter.	Installation Record	Y	9/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17396	802 S HEMLOCK AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP AND CONNECTED TO 3/4" COPPER AT MAIN.	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17399	1707 S PALMETTO AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17408	1004 E 15TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17411	409 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17417	2112 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17423	221 HICKORY CT	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17427	1222 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17431	2212 ANTON CT	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17435	1507 N BROADWAY AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17438	109 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17441	832 W UPHAM ST	UNK	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17444	700 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17447	610 S CYPRESS AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17450	511 S MARYKNOLL AVE	UNK	C	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 6/17/97	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17453	714 S LINCOLN AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1968	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17457	604 W BLODGETT ST	UNK	C	Y	1"	7/22/2021	C	1"	7/22/2021	SF	UNK	C	1"	UNK	7/22/2021: Removed 3/4" copper & lead from WM-CS & replaced w/ 1" copper. Retapped 3' West of abandonded tap. Installed 1" CS & Box. Connected to existing 3/4" copper 3' South of new CS.	Installation Record	Y	7/22/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17460	215 W CLEVELAND ST	N	C	Y	1"	6/29/2020	C	1"	6/29/2020	SF	UNK	C	1"	UNK	2019 - MU & Meyers removed lead both sides, installed copper from main to house. 6/29/2020 - Earth INC. installed new 1" copper from main to CS, and 15' - 1" copper past CS to connect to Existing 3/4" Copper. (Pg. 21 of Const. Report)	Installation Record	Y	6/29/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17464	302 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER 1" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17467	2301 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17470	1309 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	TWO CURB BOXES, FERPAL REPAIRED 1-12-15 SEE CARD	Installation Record	Y	1/12/2015	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17473	2301 ANTON CT	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17476	1511 N BROADWAY AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SHUH	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17480	1209 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17484	1703 SAWYER DR #A	UNK	UNK	UNK	1 1/2"	1/1/1980	C	1 1/2"	1/1/1980	NONRES	UNK	C	1 1/2"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17494	1811 S PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL: CB IS IN TH CURB LINE	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17497	404 N ST JOSEPH AVE	N	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	NEW 3/4" CORP & CURB STOP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17500	2405 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17503	1009 E 4TH ST	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED LEAD WIPE AT CORP 11-06-2007. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17506	1006 E 15TH ST	N	C	UNK	1"	1/1/1964	C	1"	1/1/1964	SF	UNK	C	1"	UNK	GAFFNEY. 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 5'3" DEEP	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17510	708 W ARNOLD ST	UNK	C	Y	1"	7/27/2023	C	1"	7/27/2023	SF	UNK	C	1"	UNK	7/27/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper (+/- 12") San. lat. is East of service. Proj. #5878 pg. 13 of const. report.	Installation Record	Y	7/27/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17516	506 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17519	818 W UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17521	3005 S CHERRY AVE UNIT B	N	C	UNK	1"	4/28/1982	C	1"	4/28/1982	NONRES	UNK	C	1"	UNK	MEYER	Installation Record	Y	4/28/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17525	2407 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	BILL REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17531	817 E 19TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17534	1801 S PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17537	2200 WALLONNIE DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	COULD NOT LOCATE CB 8-97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17543	923 W BLODGETT ST	UNK	C	UNK	1"	10/5/2021	C	1"	10/5/2021	SF	UNK	C	1"	UNK	10/5/21: A-1 Removed exist. 3/4" copper from wm-cs & replaced w/ 1" corp., 16' - 1" copper, 1" cs & box. Connected to existing 3/4" copper after cs	Installation Record	Y	10/5/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17546	809 W BLODGETT ST	UNK	C	UNK	1"	9/30/2021	C	1"	9/30/2021	SF	UNK	C	1"	UNK	11/17/1981: Gaffney/B&K Builders. 9/30/21: A-1 Installed 1" corp., 13' - 1" copper, 1" cs & box & connected to existing 1" copper.	Installation Record	Y	9/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17551	1803 W VETERANS PKWY	UNK	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	NONRES	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17554	1822 E 24TH ST	UNK	UNK	UNK	2"	1/1/1982	C	2"	1/1/1982	NONRES	UNK	C	2"	UNK	STRATFORD - RETAPPED 2019	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17557	606 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17560	1825 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17570	409 W DEPOT ST	N	C	Y	1"	1/1/2021	C	1"	1/1/2021	SF	UNK	C	1"	UNK	Private service off of Spruce. 2021 - Removed Lead wipe at the watermain. 1" copper to curb, 3/4" copper to house. (See City of Marhsfield Sewer Lateral/Water Service Inspection Report # 20221126 & 20221127)	Installation Record	Y	1/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17574	603 W BLODGETT ST	UNK	C	UNK	1"	1/1/1968	C	1"	1/1/1968	NONRES	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED AT CB, FOUND 1" COPPER 7' DEEP. 1" copper on property side. 7/28/2021: Dug @ wm and field verified copper.	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17579	1324 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(MEYER 1974) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17582	807 W BLODGETT ST	UNK	C	UNK	1"	9/30/2021	C	1"	9/30/2021	SF	UNK	C	1"	UNK	11/17/81: Gaffeny/B&K Builders. 9/30/2021: A-1 removed existing copper from wm-cs & replaced w/ 1" corp., 1" copper and 1" cs & box. Connected to existing 1" copper after cs	Installation Record	Y	9/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
17587	1501 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17590	311 W BLODGETT ST	UNK	C	Y	1"	6/9/2021	C	1"	6/9/2021	SF	UNK	C	1"	UNK	6/9/2021:Replaced Lead w/ 1" copper from WM-CS. Installed new 1" CS & Box. retapped 10' West of abandoned corp. Dalton Tysver replaced san. lateral from sewer main to curb w/ 6" PVC & conn. to clay tile at curb. Lateral runs over wm 2.5' East of new corp.	Installation Record	Y	6/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17597	1300 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17600	1015 W COLONIAL ST	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17603	803 W BLODGETT ST	UNK	C	Y	1"	10/1/2021	UNK	1"	10/1/2021	SF	UNK	UNK	1"	UNK	10/1/2021: A-1 removed copper (lead gooseneck) from wm-cs and replaced with 1" corp., 29' - 1" copper and 1" cs & box. Connected to existing 3/4" copper after the cs @ the sidewalk.	Installation Record	Y	10/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17606	1009 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17610	705 W ARNOLD ST	UNK	C	Y	1"	7/31/2023	C	1"	7/31/2023	SF	UNK	C	1"	UNK	7/31/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper (+/- 12") San. lat. x's over wm. Proj. #5878 pg. 15 of const. report.	Installation Record	Y	7/31/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17613	1211 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17616	1223 E 14TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17619	1110 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17622	1604 S WASHINGTON AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17626	1006 W CHAPEL ST	UNK	C	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17629	402 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1/2" COPER PRP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17635	1306 E 27TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17638	800 E 19TH ST	N	UNK	Y	3/4"	1/1/1960	C	3/4"	1/1/1960	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE @ MAIN CONNECTING TO 3/4" COPPER, COPPER RUNS THROUGH 1-1/4" STEEL PIPE FOR UNKNOWN DISTANCE-2016	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17643	606 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17646	1704 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS. WATER TAP ONLY	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17650	201 W DEPOT ST	UNK	C	Y	1"	5/13/2024	C	1"	5/13/2024	NONRES	UNK	C	1"	UNK	Old corp. is 4' South of new corp. San. lateral is resting directly on top of water main. Replaced lead line with 1" copper from main to cs. 1" cs and box installed, connected to existing 3/4" copper after cs.	Installation Record	Y	5/13/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17652	102 N CHESTNUT AVE	UNK	C	Y	1"	5/13/2024	C	1"	5/13/2024	NONRES	UNK	C	1"	UNK	Replaced lead w/ 1" copper from main to cs. New tap is 3' South of old corp. Mark Meyers installed new 1" copper and cs & box. Sanitary lateral is directly on top of water main.	Installation Record	Y	5/13/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17658	411 W BLODGETT ST	UNK	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2000: New curb box, removed lead wipe by box. 6/18/2021: Removed Lead gooseneck @ WM and replaced w/ 3/4" copper. Connected to existing 3/4" copper in the street.	Installation Record	Y	6/18/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17661	1416 N WOOD AVE	UNK	C	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17664	2700 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17667	508 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	INSULATED OVER MAIN 7/16/97	Installation Record	Y	7/16/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17670	1323 E 18TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	DUPLEX WITH 1323A CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17674	2405 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17678	2219 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17682	1412 N OAK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LV/CB UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17685	2603 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17688	1117 W ADLER RD	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17698	1531 N SHAWANO DR	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17705	803 W NORTH ST	UNK	C	UNK	2"	1/1/2014	C	2"	1/1/2014	NONRES	UNK	C	2"	UNK	CURB BOX INSTALLED	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17715	2309 E HINTZ ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17718	1201 E 27TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17724	2611 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17727	512 S CYPRESS AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17732	2600 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17740	601 N WOOD AVE	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17747	712 S FELKER AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17750	1618 S HEMLOCK AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFEID 8/13/97. 3/4" copper on property side	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17753	105 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17756	1316 N SHAWANO DR	N	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS. 1-1-2020 J&R VACUUM EXCAVATED EAST OF CULVERT, FOUND 3/4" COPPER 8'8" DEEP	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17759	208 N WALNUT AVE	N	C	Y	3/4"	9/21/2017	C	3/4"	9/21/2017	SF	UNK	C	3/4"	UNK	REMOVED LEAD, INSTALLED NEW 3/4" COPPER FROM W.M. TO NEW C.V./C.B.--2017	Installation Record	Y	9/21/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17762	207 W CLEVELAND ST	N	C	UNK	1"	6/29/2020	C	1"	6/29/2020	SF	UNK	C	1"	UNK	Earth INC. - Installed copper from main to CS, ran 12.5' - 1" copper after cs to connect to existing 3/4" copper. (Pg. 21 of Const. Report)	Installation Record	Y	6/29/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17772	1811 E BECKER RD	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	SPENCER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17775	412 S CYPRESS AVE	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17778	800 S MARYKNOLL AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/17/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17784	711 W BLODGETT ST	N	C	UNK	1"	9/27/2021	P	1"	9/27/2021	SF	UNK	P	1"	UNK	GAFFNEY PLUMBING, OLD CORP IS SHUT OFF @ MAIN. 1" HDPE on property side. 9/27/21: A-1 Installed new 1" corp., 1" copper 6' from water main and connected to existing 1" copper.	Installation Record	Y	9/27/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17787	513 W BLODGETT ST	UNK	C	Y	1"	7/7/2021	C	1"	7/7/2021	SF	UNK	C	1"	UNK	1/16/04: removed 3/4" lead wipe. 7/7/2021: Retapped 1" corp. 3' East of abandonded tap. Replaced full lead w/ 1" copper from WM-CS. Connected to exisitng 3/4" copper North of CS. Dalton Tysver replaced clay san. lat. from sewer main to WM w/ 4" PVC.	Installation Record	Y	7/7/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17791	1414 S HEMLOCK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17794	1509 S PALMETTO AVE	Y	UNK	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	REMOVED LEAD WIPE @ MAIN 6/97	Installation Record	Y	6/1/1997	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17801	1312 E 18TH ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17805	1310 E 26TH ST	N	C	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	(SCHREINERS 1969)	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17808	2115 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 8/12/97	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17812	1705 W VETERANS PKWY	UNK	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	NONRES	UNK	C	3/4"	UNK	3/4" copper on property side	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17818	1010 SAWYER DR #101	UNK	CI-U	UNK	4"	1/1/1979	CI-U	4"	1/1/1979	NONRES	UNK	CI-U	4"	UNK	HUSKY PLB	Installation Record	Y	1/1/1979	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
17824	1301 E 21ST ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17827	514 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17830	703 S FELKER AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	ROAD, INSULATED OVER CORP. (2000)	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17833	812 S HEMLOCK AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP & CONNECTED TO 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17836	2401 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1976	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17839	1503 N SHAWANO DR	UNK	C	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17843	1415 E 29TH ST	UNK	UNK	UNK	UNK	1/1/1971	C	UNK	1/1/1971	SF	UNK	C	UNK	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17846	1307 E 15TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17850	2611 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
17853	308 W BLODGETT ST	N	C	Y	1"	6/8/2021	C	1"	6/8/2021	SF	UNK	C	1"	UNK	6/8/2021 - Removed lead & replaced w/ 1" copper. New tap 8' East of cs @ wm. Connected to 3/4" copper on customer side. Installed new cs & box	Installation Record	Y	6/8/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17856	2504 E HINTZ ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17861	1611 N BROADWAY AVE	UNK	C	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17865	1516 N WOOD AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17897	902 N IRENE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17903	1041 W LAIRD ST	UNK	C	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	WEIGEL	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17909	612 S WASHINGTON AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/14/22: Dug and verified copper @ the main	Installation Record	Y	7/14/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17913	810 N IRENE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17916	401 S ANTON AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	SERVICE COMES OFF OF 5TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17926	911 N IRENE AVE #1	UNK	UNK	UNK	1 1/2"	1/1/1990	C	1 1/2"	1/1/1990	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17935	1018 W LAIRD ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17951	1207 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	MEWD - NEW 2" COPPER FROM MAIN TO NEW 2" CURB VALVE AND BOX	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17954	2510 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17964	2405 MONIQUE LN #1	UNK	UNK	UNK	1 1/2"	1/1/1990	C	1 1/2"	1/1/1990	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17970	1706 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17973	1601 N ADAMS AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17977	1402 N SHAWANO DR	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
17982	1706 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
17985	1031 W LAIRD ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17992	1101 E 26TH ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
17999	3600 DOWNWIND DR	UNK	UNK	UNK	1"	UNK	C	1"	UNK	NONRES	UNK	C	1"	UNK	WATER DEPT.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18002	1300 E 27TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18006	2517 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18015	2401 MONIQUE LN #1	UNK	UNK	UNK	1 1/2"	UNK	C	1 1/2"	UNK	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18021	912 N IRENE AVE #1	UNK	UNK	UNK	1 1/2"	1/1/1990	C	1 1/2"	1/1/1990	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18033	2506 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18036	1100 E 25TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18039	1000 W CHAPEL ST	UNK	C	UNK	1"	1/1/1983	C	1"	1/1/1983	O	UNK	C	1"	UNK	SERVICE COMES OFF OF N. HILLS. 2015-CURB VALVE/BOX LOCATION VERIFIED	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18042	1909 S TAMARACK AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18045	1000 W COLONIAL ST	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18049	1218 E 18TH ST	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	RON MEYER	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18055	604 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. /4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18057	1707 E 4TH STREET	N	CI-U	UNK	8"	UNK	CI-U	8"	UNK	NONRES	UNK	CI-U	8"	UNK	FIRE PROTECTION	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
18062	1004 N IRENE AVE #1	UNK	UNK	UNK	1 1/2"	1/1/1990	C	1 1/2"	1/1/1990	NONRES	UNK	C	1 1/2"	UNK	SAWDUST CITY	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18076	1411 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18079	1606 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18091	2411 MONIQUE LN #1	UNK	UNK	UNK	1 1/2"	1/1/1991	C	1 1/2"	1/1/1991	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18100	601 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1966	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18106	312 W BLODGETT ST	UNK	C	Y	1"	6/11/2021	C	1"	6/11/2021	SF	UNK	C	1"	UNK	6/11/2021: Removed Lead from WM-CS, replaced w/ 1" copper. Corp. blew out and replaced w/ 6"x12" sleeve w/ 1" C.C. Connected to existing 3/4" copper 12" S. of CS. Insulated @ main.	Installation Record	Y	6/11/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18109	1009 W LAIRD ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18112	1005 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18118	2700 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18121	1622 S HEMLOCK AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18124	705 N WOOD AVE	UNK	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	THIS IS A PRIVATE SERVICE THAT COMES OFF OF NORTH ST.	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18128	1607 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18142	1101 W VETERANS PKWY #1	UNK	C	UNK	2"	1/1/2017	C	2"	1/1/2017	SF	UNK	C	2"	UNK	TAPPED OFF WOOD AVE--EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18148	1910 E MCMILLAN ST	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18154	1806 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18160	1601 N WOOD AVE	UNK	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18163	1202 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18166	1227 E 14TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18170	2300 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18178	1906 E MCMILLAN ST	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18182	1312 E 21ST ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18185	1523 E 29TH ST	UNK	C	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	NONRES	UNK	C	3/4"	UNK	MEYERS: STUB-OUT	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18188	1601 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18191	1606 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18195	904 CHAPEL CT	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SERVICE COMES OFF OF NORTH HILLS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18199	1401 E 25TH ST	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	2013-MAINBREAK ON 1" SERVICE INSTALLED MAINBREAK SLEEVE & NEW 1" CORP & 12" OF COPPER. CB LOCATION VERIFIED 12/4/97	Installation Record	Y	1/1/2013	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18202	111 W CLEVELAND ST	UNK	C	UNK	1 1/2"	6/5/2020	C	1 1/2"	6/5/2020	NONRES	UNK	C	1 1/2"	UNK	Earth INC. - Type K Copper, 1 - SS 16"x1-1/2" Tapping Saddle, Connected to Existing 1-1/2" Copper. (Pg. 10 of Const. Report)	Installation Record	Y	6/5/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18207	2417 MONIQUE LN #1	UNK	C	UNK	1 1/2"	1/1/1991	C	1 1/2"	1/1/1991	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18220	1600 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18223	2412 E BECKER RD	UNK	C	UNK	1 1/2"	UNK	C	1 1/2"	UNK	SF	UNK	C	1 1/2"	UNK	3-1" TAPS W/ MANIFOLD	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18226	3716 DOWNWIND DR	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	WATER DEPT.	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18232	2401 E 5TH ST	UNK	UNK	UNK	1"	1/1/1993	C	1"	1/1/1993	NONRES	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18235	1111 W VETERANS PKWY	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18241	212 S ADAMS AVE	UNK	C	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	RE-TAPPED 1" PIPE BURST--2017	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18247	1820 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18250	1510 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18254	2329 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18257	206 S ADAMS AVE	UNK	C	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	RE-TAPPED 1" PIPE BURST--2017	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18261	2416 E BECKER RD	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18279	111 W BLODGETT ST	Y	C	Y	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	6/1/23: Gaffney replaced lead w/ 1" copper from cs-meter and installed 1" cs & box	Installation Record	Y	6/1/2023	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18279	111 W BLODGETT ST	UNK	P	Y	1"	7/26/2023	C	1"	7/26/2023	SF	UNK	C	1"	UNK	6/1/23: Gaffney replaced lead w/ 1" copper from cs-meter and installed 1" cs & box. 7/26/23: J&R bored in 2 - 1" plastic lines from N. Chestnut on South side fo stop sign & 3" behind curb to cs. Abandoned old lead line to the street behind the curb.	Installation Record	Y	7/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18283	215 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	NONRES	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18286	1315 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18294	2710 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINERS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18297	2801 E 21ST ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	NONRES	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18299	605 W KALSCHED ST	UNK	DI	UNK	4"	1/1/2016	DI	4"	1/1/2016	NONRES	UNK	DI	4"	UNK	SERVICE COMES OFF OF UPHAM, HYMAX SLEEVE 2'S OF TEE	Installation Record	Y	1/1/2016	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
18302	2206 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18327	618 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18330	1301 E 22ND ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18333	1207 W 4TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18349	202 N WALNUT AVE	N	L	UNK	UNK	1/1/1939	P	UNK	1/1/1939	SF	UNK	P	UNK	1/1/1939		Installation Record	Y	2020	Mech excav	Field inspection only	Y	11/18/2016	Cross Connection Survey	Internal Notes

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
18353	2210 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18356	2200 S PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18362	823 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18368	615 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18371	1012 E 15TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18378	604 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18381	2107 S PALMETTO AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18384	2109 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18388	1711 W VETERANS PKWY	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	12/17/24: Dug and verified 3/4" copper at the water main	Installation Record	Y	12/14/2024	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18392	717 W ARNOLD ST	UNK	C	Y	1"	7/26/2023	C	1"	7/26/2023	SF	UNK	C	1"	UNK	7/26/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper after the cs (+/- 12") Proj. #5878 pg. 12 of const. report.	Installation Record	Y	7/26/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18400	1421 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18406	2209 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18409	2201 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18413	405 N BROADWAY AVE	UNK	C	UNK	1"	9/29/2021	C	1"	9/29/2021	SF	UNK	C	1"	UNK	9/29/2021: A-1 removed existing 1" copper from wm-cs and replaced w/ new 1" corp., 1" copper, 1" cs&box. Connected to existing 1" copper just after the cs.	Installation Record	Y	9/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18422	505 W CLEVELAND ST	UNK	C	UNK	1"	8/27/2020	C	1"	8/27/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 12' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 56 of Const. Report)	Installation Record	Y	8/27/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18425	2511 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1975	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18428	2311 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18431	1610 N BROADWAY AVE	UNK	C	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18440	1306 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18443	2601 S FELKER AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS (GAFFNEY)	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18446	1409 S HEMLOCK AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP & CONNECTED TO 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18449	1801 S APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF 18TH	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18452	1701 S APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18455	1606 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18458	2301 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18461	213 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18468	1506 W 7TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18474	1300 E 22ND ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18479	401 N BROADWAY AVE	UNK	C	UNK	1"	9/29/2021	C	1"	9/29/2021	SF	UNK	C	1"	UNK	9/29/2021: A-1 installed 1" corp., 1" copper, 1" cs & box and extended copper 5' North from cs. Mark Meyers continued service with 3' - 1" copper then reduced to 3/4" and connected to existing 3/4" copper at the edge of the house.	Installation Record	Y	9/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18486	1413 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18495	309 W BLODGETT ST	N	C	Y	1"	6/8/2021	C	1"	6/8/2021	SF	UNK	C	1"	UNK	Removed lead from wm - cs. Installed new 1" tap, 3' East of old tap (left in place). Connected to existing 3/4" copper on customers side.	Installation Record	Y	6/8/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18507	1102 WEISTER CT	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016-INSTALLED 1" TAP & 3/4" COPPER FROM MAIN TO CURB VALVE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18510	1715 W 6TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF OF BIRCH. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7' DEEP	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18513	1200 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18516	1018 W LAUREL ST	UNK	C	UNK	2"	1/1/2017	C	2"	1/1/2017	NONRES	UNK	C	2"	UNK	RE-TAPPED--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18519	2206 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18522	407 S SCHMIDT AVE	UNK	UNK	UNK	1 1/4"	1/1/1984	C	1 1/4"	1/1/1984	SF	UNK	C	1 1/4"	UNK	REIGEL PLB	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18525	106 N OAK AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		<Null>	Installation Record	N			Field Inspection Only	Y	5/23/2016	Cross Connection Survey	
18529	1401 N WOOD AVE	UNK	C	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18535	1310 E 28TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18538	502 S WASHINGTON AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/13/22: Lead wipe removed	Installation Record	Y	7/13/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18541	1226 E 14TH ST	N	UNK	UNK	5/8"	1/1/1964	C	5/8"	1/1/1964	SF	UNK	C	5/8"	UNK	SCHREINERS	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18547	2503 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	EACH SIDE HAS ITS OWN CURB BOX	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18547	2503 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	EACH SIDE HAS ITS OWN CURB BOX	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18550	607 W BLODGETT ST	UNK	C	Y	1"	7/13/2021	C	1"	7/13/2021	SF	UNK	C	1"	UNK	7/13/2021: Retapped 4.5' West of abandoned tap. Pulled in 1" copper to replace full lead (cs-wm). Connected to existing 3/4" copper under sidewalk. Installed 1" cs & box between sidewalk and curb. Sanitary lateral is above the watermain.	Installation Record	Y	7/13/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18553	820 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18557	2511 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18557	2511 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18560	1411 W 5TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	GAFFNEY. 3/4" copper on property side	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18563	1410 N ST JOSEPH AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	WIRE OF SERVICE 87'E & 7'S OF NE COR. OF GARAGE	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18566	202 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18572	713 S SYCAMORE AVE	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18575	506 S LINCOLN AVE	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/13/2022: Confirmed 3/4" copper from main to back of curb - confirmed copper at curb valve.	Installation Record	Y	7/12/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18578	221 S SCHMIDT AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/19/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18582	2001 PECAN PKWY	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18585	1429 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	P	1"	1/1/1990	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18591	1012 W CHAPEL ST	UNK	C	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18595	1103 E 4TH ST	N	C	Y	3/4"	5/17/2018	P	3/4"	5/17/2018	SF	UNK	P	3/4"	UNK	2018-REMOVED LEAD FROM MAIN TO HOUSE. INSTALLED 3/4" COPPER STREETSIDE, 1" PEX PRIVATE SIDE	Installation Record	Y	5/17/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18598	1311 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1971	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18601	1407 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1958	C	3/4"	1/1/1958	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1958	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18606	409 N PINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		OUT/MAIN IS 4'DEEP 10/81	Installation Record	N			Field Inspection Only	Y	8/8/2016	Cross Connection Survey	
18609	1042 W LAIRD ST	UNK	C	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18615	110 N PINE AVE	Y	UNK	UNK	3/4"	1/1/1993	C	3/4"	1/1/1993	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18628	901 MONIQUE LN	UNK	UNK	UNK	1 1/2"	1/1/1991	C	1 1/2"	1/1/1991	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18631	1606 S POPPLE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18639	1806 E 4TH ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	2003- NEW COR,COPPER,VALVE & BOX.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18643	1400 NORTH HILLS AVE	UNK	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CURB BOX VEREIFIED 1/14/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18651	1222 E 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18652	913 W BLODGETT ST	UNK	C	UNK	1"	10/4/2021	P	1"	10/4/2021	SF	UNK	P	1"	UNK	10/27/2009: Plastic on inside. 10/4/2021: A-1 installed 1" corp. and 8' - 1" copper to connect to existing 1" copper using a copper-copper compression coupling.	Installation Record	Y	10/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18658	406 N SPRUCE AVE	N	C	UNK	1"	7/30/2020	C	1"	7/30/2020	SF	UNK	C	1"	UNK	Earch INC. installed 62' copper from main to Existing copper, connected using 1"x3/4" CU-CU compression. (Pg. 38 of Const. Report)	Installation Record	Y	7/30/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18661	1508 E BECKER RD	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18667	1812 BUTTERNUT PKWY	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18673	2101 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
18677	407 W BLODGETT ST	N	C	Y	3/4"	7/8/2020	P	3/4"	7/8/2020	SF	UNK	P	3/4"	UNK	DUPLEX WITH 407A - ALL LEAD REMOVED - 1" PLASTIC ON CUSTOMERS SIDE	Installation Record	Y	7/8/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18680	1414 N BROADWAY AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18687	507 W CLEVELAND ST	N	C	UNK	1"	8/27/2020	C	1"	8/27/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 10' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 56 of Const. Report)	Installation Record	Y	8/27/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18690	2020 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18693	1824 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18696	1313 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(HELLER 1973) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18702	1307 N WOOD AVE	UNK	C	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18706	1527 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18709	1423 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	P	1"	1/1/1990	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18713	1204 WASHINGTON CT	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18716	2101 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18723	306 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP.SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18726	510 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18730	115 W ARNOLD ST	N	C	UNK	1"	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		CB LOCATION VERIFIED 3-26-97. 4/2024: Dug and verified 1" copper from main to sidewalk (no lead) New 1" curb stop was installed.	Installation Record	Y	4/1/2024	Mech excav	Field Inspection Only	Y	4/1/2024	Mech excav	
18742	106 N CHESTNUT AVE	N	C	Y	3/4"	9/11/2017	C	3/4"	9/11/2017	SF	UNK	C	3/4"	UNK	LEAD REMOVED FROM MAIN TO INSIDE HOUSE, INSTALLED NEW 3/4" COPPER -- 2017	Installation Record	Y	9/11/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18745	1406 E 28TH ST	UNK	C	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18751	1508 W 8TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS INC. CB LOCATION VERIFIED 6/17/97. INSULATED 2' X 8'	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18755	317 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	NONRES	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18760	1813 W 5TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	HAS OWN WELL	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18763	1601 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18771	2505 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18775	1916 E 29TH ST	UNK	UNK	UNK	2"	1/1/1993	C	2"	1/1/1993	NONRES	UNK	C	2"	UNK	REIGEL PLUMB	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18775	1916 E 29TH ST	UNK	UNK	UNK	2"	1/1/1993	C	2"	1/1/1993	NONRES	UNK	C	2"	UNK	REIGEL PLUMB	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18780	2205 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18786	823 W NORTH ST	UNK	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18789	2806 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	Schreiner	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18795	2800 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18801	1109 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18814	909 MONIQUE LN	UNK	UNK	UNK	1 1/2"	1/1/1991	C	1 1/2"	1/1/1991	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18824	113 N PINE AVE	N	C	UNK	3/4"	4/20/2020	C	3/4"	4/20/2020	SF	UNK	C	3/4"	UNK	4/20/2020 - Removed all leave & replaced w/ 3/4" copper from main to CS. Installed new CS & BOX. Connected to 1/2" copper on customer side	Installation Record	Y	4/20/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18834	1300 E 18TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18838	309 N PINE AVE	N	C	UNK	1"	7/15/2020	C	1"	7/15/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 8.5' - 1" copper past cs to 1"x3/4" fitting and 6" of 3/4" copper to 3/4"x1/2" fitting connected to existing 1/2" copper. (1/2" copper is fed inside galvanized line to house. (Pg. 22 & 29 of Const. Report)	Installation Record	Y	7/15/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18841	214 W ARNOLD ST	N	C	UNK	1"	1/1/2011	P	1"	1/1/2011	SF	UNK	P	1"	UNK	PEMBER. 1" PLASTIC PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18844	1910 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18847	1011 E 15TH ST	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18852	501 W BLODGETT ST	N	C	UNK	1"	7/13/2020	C	1"	7/13/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 11' - 1" copper past cs to connect to existing 3/4" copper (Pg. 27 of Const. Report)	Installation Record	Y	7/13/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18862	2310 S PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18865	1200 E 21ST ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18873	1615 N WOOD AVE	UNK	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18882	2000 BUTTERNUT PKWY	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 8/12/97	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18892	1811 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18898	804 N IRENE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	DUPLEX	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18901	715 W ARNOLD ST	UNK	C	Y	1"	7/25/2023	C	1"	7/25/2023	SF	UNK	C	1"	UNK	7/25/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper (+/- 12"). Corp for 714is 4' West. Swr. lat. is East of service. Proj. #5878 pg. 11 of const. report.	Installation Record	Y	7/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18904	2300 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18907	2022 E EMERALD ST #A	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18910	1506 S PALMETTO AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18914	401 S HUME AVE	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	NONRES	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18924	800 W BLODGETT ST	UNK	C	Y	1"	9/29/2021	C	1"	9/29/2021	SF	UNK	C	1"	UNK	9/29/2021: A-1 removed lead from wm-cs & replaced w/ 1" corp., 1" copper, & 1" cs & box. Connected to existing 3/4" copper @ the sidewalk.	Installation Record	Y	9/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18927	901 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18937	512 S MARYKNOLL AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
18949	302 N ST JOSEPH AVE	UNK	C	UNK	1"	9/25/2021	C	1"	9/25/2021	NONRES	UNK	C	1"	UNK	9/28/2021: A-1 removed copper/galvanized existing line & replaced w/ 1" corp., 14' - 1" copper & 1" cs & box and connected to existing 3/4" copper @ the front edge of the sidewalk. (1' behind cs)	Installation Record	Y	9/25/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18954	1521 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18958	1006 W KALSCHED ST	UNK	UNK	UNK	1"	1/1/1966	C	1"	1/1/1966	NONRES	UNK	C	1"	UNK	KALSCHED	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18964	312 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18967	213 N CHESTNUT AVE	N	C	Y	3/4"	5/22/2018	C	3/4"	5/22/2018	SF	UNK	C	3/4"	UNK	REMOVED ALL LEAD AND REPLACED WITH COPPER FROM WATERMAIN TO HOUSE WITH NEW CURB VALVE & BOX	Installation Record	Y	5/22/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18970	1707 E 4TH ST #A-METER 1791-SHOP	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003: NEW CORP,COPPER,VALVE,BOX. EXISTING 3/4" COPPER INTO BUILDING	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18974	2308 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18977	2201 PECAN PKWY	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/12/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18980	319 W 29TH ST	UNK	UNK	UNK	6"	1/1/1993	DI	6"	1/1/1993	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
18987	510 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
18994	2010 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
18998	100 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS/102 S ADAMS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19001	2111 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19004	1801 S HUME AVE	UNK	UNK	UNK	8"	1/1/1994	DI	8"	1/1/1994	NONRES	UNK	DI	8"	UNK	MEYERS	Installation Record	Y	1/1/1994	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
19007	305 S COLUMBUS DR	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - 2" OF 1" CU CONNECTED TO EXISTING 3/4" CU IN THE ROAD. 3/4" copper on property side	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19013	2015 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19016	303 W CLEVELAND ST	N	C	UNK	1"	7/31/2020	C	1"	7/31/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs. Meyers replaced/installed copper from cs to meter. (Pg. 39 of Const. Report)	Installation Record	Y	7/31/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19022	1401 N SHAWANO DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19028	1407 N WOOD AVE	UNK	C	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19034	2401 E 21ST ST	UNK	DI	UNK	8"	1/1/2001	DI	8"	1/1/2001	NONRES	UNK	DI	8"	UNK	REIGELS/FIRE SERVICE ONLY	Installation Record	Y	1/1/2001	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
19042	2505 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19045	1711 SAWYER DR #A	UNK	UNK	UNK	1 1/2"	1/1/1984	C	1 1/2"	1/1/1984	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19053	2206 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	2012-RETAPPED DURING LINING PROJECT	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
19056	505 S BIRCH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CITY WATER 2/17/89	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19067	1602 S WASHINGTON AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19070	809 E 25TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19073	2307 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19077	514 E 29TH ST	UNK	UNK-LG	UNK	UNK	UNK	G	UNK	UNK	NONRES	UNK	G	UNK	UNK	<Null>	Installation record	N		Visual insp during install or repair	Previous eval	Y	9/23/2013	Cross connection survey	
19082	1810 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19088	605 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19091	1001 SAWYER DR	UNK	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	NONRES	UNK	C	3/4"	UNK	ARNOLD/STUB-OUT	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19091	1001 SAWYER DR	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	2002: NEW CORP AND CURB STOP INSTALLED	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19097	2006 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19100	2001 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19103	1211 E 14TH ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19106	1402 S PALMETTO AVE	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/1946	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	3/1/2017	Cross Connection Survey	
19121	712 S LINCOLN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19124	1607 W 8TH ST	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19127	1626 S FELKER AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-JO#5358 MEWD NEW 1" CORP,COPPER,3/4-1 COPPER TO COPPER BEFORE VALVE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19130	1215 E 18TH ST	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19133	2414 E LAWRAINE ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19143	2711 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19146	500 S BIRCH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN HAS OWN WELL	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19150	809 N IRENE AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	DUPLEX - FACING TWO STREETS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19154	400 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1/2" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19157	1027 W CHAPEL ST	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19157	1027 W CHAPEL ST	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19163	901 W ARNOLD ST	UNK	C	Y	1"	7/24/2023	C	1"	7/24/2023	SF	UNK	C	1"	UNK	7/24/23: Earth Inc. replaced copper w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper after the cs (+/- 12") Proj. #5878 pg. 10 of const. report. 2017:Meyers replaced lead w/ 3/4" copper (cs-meter)	Installation Record	Y	7/24/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19169	920 W BLODGETT ST	UNK	C	UNK	1"	10/5/2021	UNK	1"	10/5/2021	SF	UNK	UNK	1"	UNK	10/5/2021: A-1 removed 1" copper from wm-cs and replaced w/ 1" corp., 1" copper and 1" cs & box. Connected to existing 1" copper @ the back side of the cs.	Installation Record	Y	10/5/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19178	818 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS-INSULATION OVER CORP.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19181	404 W CLEVELAND ST	N	C	UNK	1"	8/15/2020	C	1"	8/15/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 16' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 49 of Const. Report)	Installation Record	Y	8/15/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19184	2405 E LAWRAINE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19190	1517 W VETERANS PKWY	UNK	C	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19194	2708 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19197	1300 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(STRATFORD 1974) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19200	400 S WASHINGTON AVE	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2018-INSIDE SERVICE MATERIAL VERIFIED; 2003-3/4 CORP & 1" COPPER,VALVE & BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19203	1228 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19206	609 S FELKER AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19212	815 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19222	1511 N ADAMS AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19226	2100 E 29TH STREET	UNK	UNK	UNK	2"	1/1/1994	C	2"	1/1/1994	NONRES	UNK	C	2"	UNK	MEYER-GAFFNEY	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19229	1519 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19246	1201 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19249	401 S COLUMBUS DR	N	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SERVICE IS OFF OF 4TH ST. - 3' OF 3/4" CU CONNECTED TO EXISTING 3/4" CU IN STREET. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19252	302 S COLUMBUS DR	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	REIGEL. 2018 - 4' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN THE ROAD	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19255	1601 S LAEMLE AVE	UNK	UNK	UNK	3/4"	1/1/1992	C	3/4"	1/1/1992	NONRES	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19255	1601 S LAEMLE AVE	UNK	UNK	UNK	6"	1/1/2018	DI	6"	1/1/2018	NONRES	UNK	DI	6"	UNK	CUT-IN TEE - DIP RUNS UNDER ROAD AND SWITCHES TO PVC TO BLDG (REIGEL/FERGUSON TAP)	Installation Record	Y	1/1/2018	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
19259	2410 MONIQUE LN	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	DUPLEX	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19268	2109 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19272	403 N WOOD AVE	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19278	1509 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19281	1035 W COLONIAL ST	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19281	1035 W COLONIAL ST	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS. 3/4" copper on property side	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19284	2311 ANTON CT	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19291	1509 N WOOD AVE	UNK	C	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19294	1401 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19302	305 W BLODGETT ST	N	C	UNK	1"	6/3/2021	C	1"	6/3/2021	SF	UNK	C	1"	UNK	6/3/2021: Removed exist corp. installed 6"x12" S.S. repair w/ 1" CC. Installed 1" CU to 12" South of existing CS. Connected to existing 3/4" CU on street side of CS. Dalton Tysver replaced san. lat with 6" PVC. Sewer lateral crosses over WM @ Corp.	Installation Record	Y	6/3/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19305	1809 SAWYER DR #A	UNK	UNK	UNK	1 1/2"	1/1/1983	C	1 1/2"	1/1/1983	NONRES	UNK	C	1 1/2"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19308	1605 S TAMARACK AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19317	1024 W COLONIAL ST	UNK	C	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19320	1311 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MAIN & LOOPS UNDNEATH	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19329	1709 S MADISON AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19332	1307 E 21ST ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19347	919 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19353	1807 W VETERANS PKWY	UNK	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	NONRES	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19356	1215 E 14TH ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19360	1012 SAWYER DR	UNK	C	UNK	1 1/4"	1/1/1985	C	1 1/4"	1/1/1985	SF	UNK	C	1 1/4"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19369	106 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS/108 S ADAMS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19376	801 W UPHAM ST	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19379	2313 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19382	1801 E BECKER RD	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	SPENCER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19385	1429 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19388	1821 E 26TH ST	UNK	UNK	UNK	6"	UNK	CI-U	6"	UNK	NONRES	UNK	CI-U	6"	UNK	CB LOCATION VERIFIED 4/22/97	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
19391	809 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19394	1703 S WASHINGTON AVE #A	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19400	1311 N WOOD AVE	UNK	C	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19403	300 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19406	815 E 19TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LV	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19409	1807 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19421	1108 E 15TH ST	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	2020 J&R VAUUM EXCAVATED @ CB, FOUND COPPER, SERVICE IS DENTED	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
19427	505 W BLODGETT ST	UNK	C	Y	1"	6/30/2021	C	1"	6/30/2021	SF	UNK	C	1"	UNK	6/30/2021: Insulated in roadway. All Lead removed. Existing 3/4" C.B.V. installed 9/05 Reigel Plumbing. New tap is 3' West of abandonded corp. Installed new CB & rod.	Installation Record	Y	6/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19433	205 W CLEVELAND ST	N	C	Y	1"	6/24/2020	C	1"	6/24/2020	SF	UNK	C	1"	UNK	Earth INC. - Installed 9' - 1" copper from CORP.-CS, Meyers Replaced CS & Box and replaced lead w/ copper to house. (Pg. 18 of Const. Report)	Installation Record	Y	6/24/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19437	1204 W 4TH ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19442	309 N ST JOSEPH AVE	N	UNK	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19448	514 W CLEVELAND ST	N	C	UNK	1"	8/27/2020	C	1"	8/27/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 13' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 56 of Const. Report)	Installation Record	Y	8/27/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19453	2717 S CEDAR AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	NONRES	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19456	1311 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19460	2500 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19463	805 E 25TH ST	UNK	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19466	402 S COLUMBUS DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1971	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19469	305 W CLEVELAND ST	N	C	UNK	1"	8/3/2020	C	1"	8/3/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, 12.5' - 1" copper past cs to existing 3/4" copper. (Pg. 40 of Const. Report)	Installation Record	Y	8/3/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19472	400 N WOOD AVE	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19481	1225 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19484	2207 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19489	622 LAUREL CT	UNK	C	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	NONRES	UNK	C	3/4"	UNK	DARRETT	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19491	620 LAUREL CT #B1	UNK	C	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	NONRES	UNK	C	3/4"	UNK	DARRETT	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19493	617 LAUREL CT	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	DARRETT. 2" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19502	1411 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19506	701 S CYPRESS AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19509	405 W CLEVELAND ST	N	C	UNK	1"	8/14/2020	C	1"	8/14/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, Meyers intalled 1" copper. (Pg. 48 of Const. Report)	Installation Record	Y	8/14/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19512	909 W BLODGETT ST	UNK	C	Y	1"	10/4/2021	C	1"	10/4/2021	SF	UNK	C	1"	UNK	10/4/2021: A-1 removed lead from wm-cs and replaced w/ 1" corp., 1" copper, and 1" cs & box. Installed 5' - 1" copper after cs to connect to existing 3/4" copper.	Installation Record	Y	10/4/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19521	2211 E 5TH ST	UNK	UNK	UNK	2"	1/1/1995	C	2"	1/1/1995	NONRES	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19528	611 W DEPOT ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2001: 1-1/2" LINE COMING OFF OAK STREET	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19531	714 W BLODGETT ST	UNK	C	Y	1"	9/27/2021	C	1"	9/27/2021	SF	UNK	C	1"	UNK	9/27/2021: A-1 removed existing lead service and installed 1" corp, 32' - 1" copper, 1" cs & box. Connected to existing 3/4" copper @ the sidewalk	Installation Record	Y	9/27/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19537	1211 E 6TH ST	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN. 2003-REIGEL PLBG.,CURB BOX INSTALLED	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19544	2312 ANTON CT	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19547	2700 S MAYWOOD AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19553	505 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19556	2313 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19559	2509 S PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19564	1515 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19583	211 W CLEVELAND ST	N	C	Y	1"	6/26/2020	C	1"	6/26/2020	SF	UNK	C	1"	UNK	Earth INC. - Installed copper from main to CS, ***CONNECTED TO EXISTING LEAD*** (Pg. 20 of Const. Report) 2022 - Customer replaced lead w/ 3/4" copper Plbg. Permit 20220334	Installation Record	Y	6/26/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19586	1000 WESTVIEW DR	N	C	UNK	3/4"	1/1/2011	C	3/4"	1/1/2011	SF	UNK	C	3/4"	UNK	2011-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19594	1300 W ADLER RD	N	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	NO CURB BOX. 2020 J&R VACUUM EXCAVATED @ BOC, FOUND COPPER 8' DEEP. 3/4" copper on property side	Installation Record	Y	1/1/2020	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19597	2311 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19602	109 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19608	604 W CLEVELAND ST	N	C	UNK	1"	8/26/2020	C	1"	8/26/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 10'1" - 1" copper past cs to 1x3/4 fitting, 4" - 3/4" copper to 3/4x1/2 fitting, connect to existing 1/2" copper. (Pg. 55 of Const. Report)	Installation Record	Y	8/26/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19612	713 S BIRCH AVE	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19615	220 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19620	2507 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19623	2608 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19626	1623 S HEMLOCK AVE	N	C	UNK	1"	1/1/1969	C	1"	1/1/1969	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 8/13/97. 1-1-2020 J&R VACUUM EXCAVATED 1' FROM CB, FOUND 1" COPPER 4'6" DEEP (MEASURED FROM BOTTOM OF DITCH)	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19639	2400 E LAWRAINE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19642	2411 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19652	611 W UPHAM ST	UNK	C	UNK	3/4"	1/1/2003	C	3/4"	1/1/2003	SF	UNK	C	3/4"	UNK	2004-NEW COPPER FROM CORP TO VALVE BOX.MAIN IS UNDER CURB 7' DEEP, LINED WATER MAIN, MICHELS--2016	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19658	2600 S GALVIN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	NONRES	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19675	1411 N WOOD AVE	UNK	C	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19678	1001 W LAIRD ST	UNK	C	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19682	1300 S FELKER AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19687	713 W ARNOLD ST	UNK	C	Y	1"	7/28/2023	C	1"	7/28/2023	SF	UNK	C	1"	UNK	7/28/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Meyers replaced 3/8" copper w/ 1" copper (cs-meter). Proj. #5878 pg. 14 of const. report.	Installation Record	Y	7/28/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19690	601 W ARNOLD ST #A	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 4/17/2020 - 3/4" GALVANIZED ON PROP. SIDE REMOVED & REPLACED W/ 1" COPPER (MARK MEYERS)	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19697	2407 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19700	2011 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19703	1301 N SHAWANO DR	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19713	3115 S CENTRAL AVE	UNK	P	UNK	2"	7/11/2023	P	2"	7/11/2023	NONRES	UNK	P	2"	UNK	7/11/23: cut out main and replaced with 10" DIP for a 2" tap, ran 2" poly through the old 10" pipe under Central ave.	Installation Record	Y	7/11/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19720	1417 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19727	303 W BLODGETT ST	N	C	Y	1"	6/2/2021	C	1"	6/2/2021	SF	UNK	C	1"	UNK	8/18/97 - Removed lead wipe from box into house. 6/2/2021 - new 1" tap 4' east of old corp (abandonded old corp in place) replace lead with 1" copper from wm-cs. connected to existing 3/4" copper 12" before cs.	Installation Record	Y	6/2/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19733	2325 ANTON CT	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	SCHREINERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19736	800 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1974	P	3/4"	1/1/1974	SF	UNK	P	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19739	1800 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
19742	725 W UPHAM ST	UNK	UNK	UNK	1"	1/1/1974	P	1"	1/1/1974	SF	UNK	P	1"	UNK	REIGEL PLASTIC, LINED WATER MAIN, MICHELS--2016	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19745	1403 N BROADWAY AVE	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19760	1225 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19777	609 S CYPRESS AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19780	1110 W 4TH ST	N	C	UNK	3/4"	7/24/2019	C	3/4"	7/24/2019	SF	UNK	C	3/4"	UNK	USED 1" SERVICE SADDLE, TAPPED 1" CORP, RAN 36" OF 1" COPPER, CONNECTED TO EXISTING 3/4" COPPER	Installation Record	Y	7/24/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19785	1705 S LAEMLE AVE	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	NONRES	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19793	315 W BLODGETT ST	N	C	Y	3/4"	6/20/2018	C	3/4"	6/20/2018	SF	UNK	C	3/4"	UNK	ALL LEAD REMOVED FROM MAIN TO HOME, REPLACED WITH 3/4" COPPER	Installation Record	Y	6/20/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19802	506 N BROADWAY AVE	N	C	UNK	3/4"	8/26/1985	C	3/4"	8/26/1985	SF	UNK	C	3/4"	UNK	8/26/1985 - replaced gooseneck with 3/4" copper to 1/2" copper. 1/2" copper goes all the way	Installation Record	Y	8/26/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19805	927 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19808	407 W CLEVELAND ST	N	C	UNK	1"	8/14/2020	C	1"	8/14/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 12' - 1" copper past cs to connect to existing 3/4" copper. (Pg. 48 of Const. Report)	Installation Record	Y	8/14/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19814	1508 N SHAWANO DR	UNK	C	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19817	1315 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19820	1505 W 8TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LOCKING VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19823	1610 W 7TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19826	1508 W 5TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/17/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19829	217 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19837	1309 W ADLER RD #B	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	TWO CURB BOXES	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19840	1914 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19843	1217 E 29TH ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19846	1009 W UPHAM ST	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19849	1814 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19854	103 N PINE AVE	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		DUPLEX WITH 413 W DEPOT	Installation Record	N			Field Inspection Only	Y	6/21/2016	Cross Connection Survey	
19857	208 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 5/8" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19860	1113 E 25TH ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19865	1019 W LAIRD ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19868	1019 W COLONIAL ST	UNK	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
19873	1415 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19878	503 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	3/4" COPPER CUST. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19892	2404 MONIQUE LN	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19898	2414 MONIQUE LN	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19904	2402 S GALVIN AVE	UNK	UNK	UNK	1 1/2"	1/1/1997	C	1 1/2"	1/1/1997	NONRES	UNK	C	1 1/2"	UNK	CURB BOX IS 4'W OF THE WATERMAIN	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19923	603 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19926	1800 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19929	814 W LAIRD ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19932	810 W LAIRD ST	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19947	1501 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19954	1801 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19959	1400 S LAEMLE AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	NONRES	UNK	C	3/4"	UNK	CORNER OF 5TH & LAEMLE	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19965	1504 E 25TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19968	1426 E 25TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19978	515 W BLODGETT ST	N	C	UNK	3/4"	1/1/1991	C	3/4"	1/1/1991	SF	UNK	C	3/4"	UNK	1991 - Meyers removed iron from meter to cs replaced w/ copper, installed 3/4" from CS - Main	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
19986	1301 E 28TH ST	N	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
19990	1703 E 4TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" CURB VALVE INSTALLED WITH NO CURB BOX, VALVE IS UNDER NORTH EDGE OF TELEPHONE SLURRY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20002	1215 E 19TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20005	2705 S FELKER AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20011	1226 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20014	1311 W 5TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20019	2603 S FELKER AVE	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20022	2211 ANTON CT	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20026	1201 E 26TH ST	UNK	C	UNK	3/4"	7/1/2020	C	3/4"	7/1/2020	SF	UNK	C	3/4"	UNK	(GAFFNEY 1973) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20035	802 W ARNOLD ST	UNK	C	Y	1"	7/25/2023	C	1"	7/25/2023	SF	UNK	C	1"	UNK	7/25/23: Earth Inc. replaced lead w/ 1" corp., 1" copper (buried 7.5' deep), 1" cs & box. Conn. to existing 3/4" copper after the cs (+/- 12') Proj. #5878 pg. 11 of const. report.	Installation Record	Y	7/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20041	924 W NORTH ST	N	C	UNK	1"	7/5/2017	P	1"	7/5/2017	SF	UNK	P	1"	UNK	EARTH INC	Installation Record	Y	7/5/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20050	2000 E EMERALD ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20053	1711 W 5TH ST	UNK	C	UNK	1"	9/27/2021	C	1"	9/27/2021	SF	UNK	C	1"	UNK	9/27/2021: Earth connected to existing 3/4" copper service 23' East of CS, (Pg 13 Daniels Addition inspection notes)	Installation Record	Y	9/27/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20056	710 S BIRCH AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20059	1311 W ADLER RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" COPPER LOCKING VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20065	400 W 29TH ST	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	NONRES	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1980	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20068	2611 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20072	2014 E BECKER RD	UNK	UNK	UNK	UNK	UNK	P	UNK	UNK	SF	UNK	P	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20076	720 S BIRCH AVE	N	UNK	UNK	UNK	1/1/1968	C	UNK	1/1/1968	SF	UNK	C	UNK	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20079	1206 W ADLER RD	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20082	1205 WASHINGTON CT	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20085	818 E 19TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20088	806 E 19TH ST	N	UNK	UNK	5/8"	1/1/1961	C	5/8"	1/1/1961	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20091	1706 S PALMETTO AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	C.B. VEREFIED 12/97. 3/4" copper in the house	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20094	806 E 17TH ST	N	UNK	Y	UNK	8/9/1994	C	UNK	8/9/1994	SF	UNK	C	UNK	UNK	REMOVED LEAD, INSTALLED 90 DEG 8/9/94	Installation Record	Y	8/9/1994	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20113	812 W UPHAM ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20116	1504 W 5TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/17/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20123	2500 S APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	JOE SCHUH	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20126	1806 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20132	1600 N ADAMS AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20138	314 W ARNOLD ST	N	C	UNK	1"	1/1/2022	C	1"	1/1/2022	SF	UNK	C	1"	UNK	2022: New 1" tap - old corp 2' South, new 1" copper from main to curb valve, new 1" cs & box. 1" copper from curb valve to meter.	Installation Record	Y	1/1/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20150	611 W BLODGETT ST	UNK	C	Y	1"	7/20/2021	C	1"	7/20/2021	SF	UNK	C	1"	UNK	7/13/98: New CB, new copper from house to CB & removed lead wipe on our side. 7/20/2021: Replaced lead from wm-cs w/ 1" copper. Retapped 4' East of abandonded tap. Conn. to exist. 3/4" copper 6" S. of CB. San. Lateral x-ing over wm 2' W. of new tap.	Installation Record	Y	7/20/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20153	407 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20160	1031 LAUREL ST #1	UNK	C	UNK	1 1/4"	1/1/1981	C	1 1/4"	1/1/1981	NONRES	UNK	C	1 1/4"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20169	2513 S WASHINGTON AVE	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20172	2313 S PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20175	206 S COLUMBUS DR	N	C	UNK	3/4"	7/16/2018	C	3/4"	7/16/2018	SF	UNK	C	3/4"	UNK	2018 - 5' OF 1" CU CONNECTED TO 3/4" EXISTING CU IN THE STREET. 3/4" copper on property side	Installation Record	Y	7/16/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20181	1413 S HEMLOCK AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
20187	402 W BLODGETT ST	UNK	C	Y	1"	6/15/2021	C	1"	6/15/2021	SF	UNK	C	1"	UNK	6/15/2021: Full Lead replaced w/ 1" copper from WM-CS. Installed new tap 6' East of abandoned tap. Installed new 1" CS & Box, connected to exisiting 3/4" copper 6" behind CS. Gas service (1/2" Plastic) runs with water service approx. 4.5' deep.	Installation Record	Y	6/15/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20190	611 W ARNOLD ST	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	NONRES	UNK	C	3/4"	UNK	NEW FROM CORP TO CURB VALVE.	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20197	1206 W 4TH ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20201	109 N WALNUT AVE	UNK	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. SERVICE COME OFF ARNOLD. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20210	1214 E 28TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20213	313 S ADAMS AVE	UNK	UNK	UNK	3/4"	1/1/1969	UNK	3/4"	1/1/1969	SF	UNK	UNK	3/4"	UNK	STUB-OUT	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20213	313 S ADAMS AVE	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20218	2511 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20218	2511 E BECKER RD	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20228	903 WESTERN ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS- INSOLATION OVER CORP	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20231	707 W UPHAM ST	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20234	1301 N WOOD AVE	UNK	C	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20237	1503 W VETERANS PKWY	UNK	C	UNK	1 1/4"	1/1/1985	C	1 1/4"	1/1/1985	SF	UNK	C	1 1/4"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20240	1815 E EMERALD ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20243	1801 W 5TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20246	1613 W 6TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20252	101 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20256	600 S WASHINGTON AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	7/13/22: Lead wipe removed	Installation Record	Y	7/13/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20259	605 E 29TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20262	2701 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20265	309 W DEPOT ST	UNK	C	Y	3/4"	8/19/2021	C	3/4"	8/19/2021	SF	UNK	C	3/4"	UNK	8/19/2021: All lead removed from wm-cs. New 3/4" copper installed from main to new 3/4" CB. Insulated	Installation Record	Y	8/19/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20274	2400 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20280	501 W CLEVELAND ST	N	C	UNK	1"	8/26/2020	C	1"	8/26/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs, 13' - 1" copper to connecto to existing 3/4" copper. (Pg. 55 of Const. Report)	Installation Record	Y	8/26/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20283	2704 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20291	1013 W KALSCHED ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	O	UNK	C	3/4"	UNK	SCHREINER (MEYERS)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20304	2401 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20307	2304 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20315	709 N WOOD AVE	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20322	917 W ARNOLD ST	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	NEW 1" CORP,COPPER. CURBBOX	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20330	1218 E 20TH ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20342	1400 N WOOD AVE	UNK	C	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20345	1025 W COLONIAL ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20348	2320 ANTON CT	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20354	2318 WALLONNIE DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20357	1617 S MADISON AVE	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20361	1512 E 25TH ST	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20373	1318 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. INSTALLED CURB BOX	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20376	2405 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	BILL REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20379	1104 E BECKER RD	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	8/11/98: INSULATED IN STREET.	Installation Record	Y	8/11/1998	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20383	305 N PINE AVE	N	C	Y	1"	7/15/2020	C	1"	7/15/2020	SF	UNK	C	1"	UNK	Earth INC. installed copper from main to cs. Meyers replaced lead from cs to house (Lead Replacement Program) (Pg. 29 of Const. Report)	Installation Record	Y	7/15/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20388	417 E 29TH STREET	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	NONRES	UNK	C	1"	UNK	REIGEL PLMB. FEEDS OFFICE BLDG.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20394	3313 S CHERRY AVE	UNK	UNK	UNK	1 1/2"	1/1/2002	C	1 1/2"	1/1/2002	NONRES	UNK	C	1 1/2"	UNK	A 2ND CURB BOX IS LOCATED 19'W & 11'N OF S.W COR. OF BLDG.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20399	1209 E 25TH ST	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20404	2323 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20407	908 SAWYER DR	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	SF	UNK	C	2"	UNK	CURB VALVE, NEW 2" CURB VALVE AND BOX	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20408	908 SAWYER DR	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	908/910 SAWYER	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20412	1501 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20420	1035 W UPHAM ST	UNK	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20426	1201 E 8TH ST	N	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	HAAS. CURB BOX INSTALLED	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20430	311 S SCHMIDT AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20433	910 SAWYER DR	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	908/910 SAWYER	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20437	4001 S BUSINESS PARK AVE	UNK	DI	UNK	6"	1/1/1997	DI	6"	1/1/1997	NONRES	UNK	DI	6"	UNK	1998	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
20440	1507 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20444	307 W 2ND ST	UNK	UNK-LG	UNK	UNK	UNK	L	UNK	UNK	NONRES	UNK	L	UNK	UNK	FEEDS 307 309 311	Installation record	N		Visual insp during install or repair	Previous eval	Y	7/31/2014	Cross connection survey	
20448	1415 E 26TH ST	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20453	507 W ARNOLD ST #A	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20462	1312 N WOOD AVE	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20466	1611 S ANTON AVE	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	NONRES	UNK	C	1"	UNK	FLEWELLEN	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20479	2206 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20482	1307 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20485	1518 E 25TH ST	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20490	1507 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20492	2601 E 34TH STR	UNK	C	UNK	2"	1/1/1999	C	2"	1/1/1999	NONRES	UNK	C	2"	UNK	J.S. AHERN CO.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20494	1203 W ADLER RD	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHULTZ	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20500	1016 TREMMEL CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20507	311 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20510	924 W BLODGETT ST	UNK	C	Y	1"	10/1/2021	C	1"	10/1/2021	SF	UNK	C	1"	UNK	10/1/2021: A-1 removed lead from wm - cs and replaced w/ 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper 18' South of the cs w/ a 1"x3/4" copper-copper compression coupling. Insulated @ water main, 6'8" bury top of wm	Installation Record	Y	10/1/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20520	2412 E HINTZ ST	N	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20531	1009 LAUREL ST	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	NONRES	UNK	C	1"	UNK	RE-TAPPED--2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20546	2220 WALLONNIE DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20549	410 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20563	1425 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20566	1513 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20570	2300 S GALVIN AVE	UNK	UNK	UNK	1 1/2"	1/1/1996	C	1 1/2"	1/1/1996	NONRES	UNK	C	1 1/2"	UNK	4' FROM MAIN TO CURB STOP	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20573	2418 MONIQUE LN	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20576	1201 E 25TH ST	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20581	1508 E 25TH ST	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20588	2207 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20601	612 W ARNOLD ST	N	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	SF	UNK	C	3/4"	UNK	CORP TO CURB VALVE, 1/2 COPPER FROM CURB VALVE TO HOUSE	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20613	603 W UPHAM ST	UNK	C	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	LINED WATER MAIN, MICHELS--2016 4/15/2021: Customer emailed photo of copper service entering basement by meter.	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
20616	1515 N WOOD AVE	UNK	C	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20619	1000 SAWYER DR	UNK	C	UNK	1 1/2"	UNK	C	1 1/2"	UNK	SF	UNK	C	1 1/2"	UNK	900, 902, 904, AND 906 SAWYER DR	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20625	1501 W VETERANS PKWY	UNK	C	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20628	1315 E 29TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20634	600 N BROADWAY AVE	N	C	UNK	1/2"	UNK	C	1/2"	UNK	SF	UNK	C	1/2"	UNK	1985-REMOVED GOOSENECK & INSTALLED 3/4 COPPER CONNECTED TO 1/2	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20637	2007 E BECKER RD	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20644	720 S CYPRESS AVE	N	C	UNK	1 1/2"	1/1/2011	P	1 1/2"	1/1/2011	SF	UNK	P	1 1/2"	UNK	REIGEL PLBG. 1-1/2" PLASTIC PROP. SIDE.	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20647	307 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20653	1105 W ADLER RD	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	Spencer - shared service - copper on property side for both 1105 & 1107 Adler Rd.	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20655	1415 S PALMETTO AVE	N	C	Y	3/4"	1/1/1997	C	3/4"	1/1/1997	SF	UNK	C	3/4"	UNK	REMOVED LEAD WIPE FROM MAIN TO CURB STOP 6/97	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20664	1026 W LAIRD ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20667	2802 S FELKER AVE	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20671	1031 W COLONIAL ST	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20677	301 S SCHMIDT AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20679	403 W BLODGETT ST	UNK	C	Y	1"	6/16/2021	C	1"	6/16/2021	SF	UNK	C	1"	UNK	6/16/2021: Full Lead replaced from WM-CS w/ 1" copper. New tap is 3' East from old tap. Installed new 1" CS & Box. Connected to existing 3/4" copper 6" behind CS.	Installation Record	Y	6/16/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20688	1807 S LAEMLE AVE	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	NONRES	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20692	209 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20696	2319 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20700	1412 E 26TH ST	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20702	514 W BLODGETT ST	UNK	C	Y	1"	7/7/2021	C	1"	7/7/2021	SF	UNK	C	1"	UNK	7/7/2021: Retapped 1" corp. 3' West of abandoned corp. Pulled 1" copper & removed lead from WM-CS. Connected to existing 3/4" copper on customer side. Service turns East after curb & runs towards driveway.	Installation Record	Y	7/7/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20709	2211 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20712	2604 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20715	1612 N BROADWAY AVE	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHULTZ	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20718	2333 PECAN PKWY	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20721	1308 E 21ST ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20727	2710 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20730	1028 W CHAPEL ST	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20738	1329 NORTH HILLS AVE	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20741	1800 S APPLE AVE	UNK	UNK	UNK	UNK	1/1/1985	C	UNK	1/1/1985	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20744	2608 S FELKER AVE	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20747	2706 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20750	1206 E 25TH ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYERS. 1" copper on property side	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20768	3712 S CENTRAL AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	WATER DEPT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20774	1800 BUTTERNUT PKWY	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20779	2406 E 21ST ST	UNK	UNK	UNK	6"	1/1/1998	DI	6"	1/1/1998	NONRES	UNK	DI	6"	UNK	CUT-IN : VALVE BOX IN STREET.	Installation Record	Y	1/1/1998	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
20781	1501 N BROADWAY AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20784	1213 E 26TH ST	UNK	C	UNK	1"	7/1/2020	C	1"	7/1/2020	SF	UNK	C	1"	UNK	(MEYER 1988) 2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20788	1601 E 4TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	CB VERIFIED 4-97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20791	2011 S TAMARACK AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20795	1016 W COLONIAL ST	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20800	501 S HUME AVE	UNK	UNK	UNK	1 1/4"	1/1/1988	C	1 1/4"	1/1/1988	NONRES	UNK	C	1 1/4"	UNK	REIGEL	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20803	2408 S GALVIN AVE	UNK	UNK	UNK	1 1/4"	1/1/1988	C	1 1/4"	1/1/1988	NONRES	UNK	C	1 1/4"	UNK	STRATFORD	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20808	1200 WASHINGTON CT	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYER/CB VERIFIED 2-97	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20811	304 DRAKE CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	2006-INSTALLED NEW 3/4" CORP	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20814	105 N OAK AVE	UNK	UNK	UNK	1 1/2"	1/1/1988	C	1 1/2"	1/1/1988	NONRES	UNK	C	1 1/2"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20822	1900 BUTTERNUT PKWY	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20825	3715 DOWNWIND DR	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	WATER DEPT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20828	2500 E 5TH ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	NONRES	UNK	C	1"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20834	1600 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON. 1" copper on property side	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20834	1600 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON. 1" copper on property side	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20834	1600 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON/CURB BOX VERIFIED 1/14/97. 1" copper on property side	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20861	2501 E HINTZ ST	N	UNK	UNK	UNK	UNK	UNK	UNK	UNK	SF	UNK	UNK	UNK	UNK	CB LOCATION VEREFIED 5/2/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20870	1600 N WOOD AVE	UNK	C	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20873	1501 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20897	109 N OAK AVE	UNK	UNK	UNK	1 1/2"	1/1/1988	C	1 1/2"	1/1/1988	NONRES	UNK	C	1 1/2"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20905	1510 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20908	2106 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20911	210 AIRPARK RD	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	WATER DEPT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20914	1207 E 26TH ST	UNK	C	UNK	1"	7/1/2020	C	1"	7/1/2020	SF	UNK	C	1"	UNK	2020 - NEW TAP (5813)	Installation Record	Y	7/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20917	2700 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20919	201 W ARNOLD ST	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20922	1040 W COLONIAL ST	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20926	2308 E HINTZ ST	UNK	UNK	UNK	3/4"	1/1/1989	C	3/4"	1/1/1989	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20929	1511 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20933	1509 NORTH HILLS AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20938	1710 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20941	2612 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 8/21/97	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20944	200 AIRPARK RD	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	WATER DEPT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20950	1036 W LAIRD ST	UNK	C	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CURB BOX VERIFIED 1/14/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
20950	1036 W LAIRD ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20954	1608 N WOOD AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20957	2407 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
20960	1219 E 14TH ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20966	700 W KALSCHED ST	UNK	CI-U	UNK	8"	UNK	CI-U	8"	UNK	NONRES	UNK	CI-U	8"	UNK	CUT-IN VALVE ON PRIVATE PROPERTY	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
20973	900 CHAPEL CT	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20976	1408 N ADAMS AVE	UNK	C	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20979	1028 W COLONIAL ST	UNK	C	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20982	1040 W CHAPEL ST	UNK	C	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20985	1306 N BROADWAY AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20991	905 W CHAPEL ST	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON/CURB BOX VERIFIED 1/14/97	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
20997	1111 E 25TH ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21003	1015 W CHAPEL ST	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21006	1510 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	1" copper on property side	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21006	1510 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON. 1" copper on property side	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21009	1700 BUTTERNUT PKWY	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21012	1607 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21016	1034 W COLONIAL ST	UNK	C	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21019	1223 E 19TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	CB LOCATION VERIFIED 8/26/27	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21022	1012 W LAIRD ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21025	1906 BUTTERNUT PKWY	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21028	1215 W 14TH ST	N	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21034	1511 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21034	1511 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON. 1" copper on property side	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
21037	1423 N BROADWAY AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21040	2600 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21044	2501 E 5TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	NONRES	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21048	1034 W CHAPEL ST	UNK	C	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21051	1101 E 25TH ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21058	1041 W UPHAM ST	UNK	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21061	1208 E 22ND ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD. CB LOCATION VERIFIED 12/4/97	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21064	1510 N ADAMS AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21069	1409 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21076	1411 W VETERANS PKWY	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK	MEWD- NEW 2" COPPER FROM MAIN TO NEW 2" CURB VALVE AND BOX	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21086	1503 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21089	701 W KALSCHED STREET	UNK	DI	UNK	6"	1/1/1996	DI	6"	1/1/1996	NONRES	UNK	DI	6"	UNK	1996-10X6 CUT-IN VALVE, HYD W. OF SERVICE IS 10X6 CUT-IN VALVE ALSO	Installation Record	Y	1/1/1996	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21093	1208 W 14TH ST	UNK	C	UNK	2"	6/4/2018	C	2"	6/4/2018	NONRES	UNK	C	2"	UNK	4-3/4" TAPS:SCHREINERS	Installation Record	Y	6/4/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21096	1501 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21100	1417 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21102	213 W CLEVELAND ST	N	C	UNK	1"	6/25/2020	C	1"	6/25/2020	SF	UNK	C	1"	UNK	Earth INC. - Installed 1" copper from main to CS, 10.8' - 1" copper after CS to connect to existing 3/4" copper 4' behind walk. (Pg. 19 of Const. Report)	Installation Record	Y	6/25/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21111	1000 TREMMEL CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21115	1607 N ADAMS AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21121	1526 E 25TH ST	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21124	1416 E 26TH ST	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21135	609 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21138	1407 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21141	1510 S ANTON AVE	UNK	UNK	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	REIGELS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21149	1932 E 26TH ST	UNK	UNK	UNK	8"	1/1/2001	DI	8"	1/1/2001	NONRES	UNK	DI	8"	UNK	POTABLE COMBINED W/ FIRE SERVICE	Installation Record	Y	1/1/2001	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21152	611 W DOEGE ST	UNK	UNK	UNK	6"	1/1/2002	DI	6"	1/1/2002	NONRES	UNK	DI	6"	UNK	LAKELAND	Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21158	2106 S HUME AVE	UNK	C	UNK	1 1/2"	1/1/2002	C	1 1/2"	1/1/2002	NONRES	UNK	C	1 1/2"	UNK	LAKELAND CONSTRUCTION	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21162	1421 E 26TH ST	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21166	1503 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21177	1426 E 26TH ST	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21183	1411 E 26TH ST	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21187	2210 S MADISON AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21192	818 E 25TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21195	1614 N WOOD AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21200	1613 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21206	2603 S APPLE AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21209	2503 S APPLE AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	NORTHDALE	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21213	1500 N ADAMS AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21216	1502 N ADAMS AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21220	3512 S CENTRAL AVE	UNK	UNK	UNK	8"	1/1/2000	DI	8"	1/1/2000	NONRES	UNK	DI	8"	UNK	MACHINE CUT-IN	Installation Record	Y	1/1/2000	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21223	1000 W LAIRD ST	UNK	C	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1980	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21231	2204 S HUME AVE	UNK	C	UNK	1 1/2"	1/1/2002	C	1 1/2"	1/1/2002	NONRES	UNK	C	1 1/2"	UNK	LAKELAND CONSTRUCTION	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21240	3700 DOWNWIND DR	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	STUB-OUT:	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21243	1612 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21250	1500 IMMANUEL CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21252	201 W CLEVELAND ST	N	C	UNK	1"	6/25/2020	P	1"	6/25/2020	SF	UNK	P	1"	UNK	Earth INC. - Installed Corp., CS & BOX, ran 2' - 1" copper after CS to connect to existing 1" poly, insert was installed in plastic. (Pg. 19 of Const. Report)	Installation Record	Y	6/25/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21261	210B S PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21266	812 E 25TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	NORTHDALE	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21269	1024 W CHAPEL ST	UNK	C	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21272	1008 TREMMEL CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21278	2507 S APPLE AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21281	2511 S APPLE AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21288	901 CHAPEL CT	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	RON MEYERS	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21294	1419 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21300	813 MONIQUE LN	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21303	2422 MONIQUE LN	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21310	908 W NORTH ST	UNK	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	DUPLEX	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21318	100 S CHESTNUT AVE	UNK	C	UNK	1 1/2"	1/1/2013	C	1 1/2"	1/1/2013	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21351	713 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21353	1612 LUTHER CT	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21357	1033 W CHAPEL ST	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21364	511 E 25TH ST #G	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	NONRES	UNK	C	1"	UNK	RON MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21371	106 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21374	615 E 25TH ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21377	617 E 25TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21380	2300 S HUME AVE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21384	706 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21386	1001 N OAK AVE	UNK	DI	UNK	6"	1/1/2002	DI	6"	1/1/2002	NONRES	UNK	DI	6"	UNK		Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21389	1000 CORPORATE DR	UNK	C	UNK	1 1/2"	1/1/2003	C	1 1/2"	1/1/2003	NONRES	UNK	C	1 1/2"	UNK	GAFFNEY	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21393	2406 S PEACH AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21400	1001 N OAK AVE	UNK	DI	UNK	6"	1/1/2002	DI	6"	1/1/2002	NONRES	UNK	DI	6"	UNK		Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21404	110 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21407	213 AIRPARK RD	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21422	101 S SCHMIDT AVE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21442	1033 LAUREL ST #1	UNK	C	UNK	1 1/2"	1/1/1981	C	1 1/2"	1/1/1981	NONRES	UNK	C	1 1/2"	UNK	BLDG 1033	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21448	2010 BUTTERNUT PKWY	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21453	107 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21458	3707 CORPORATE DR	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK	LAKELAND ENT. JOI#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21466	2113 S NIKOLAI AVE	UNK	DI	UNK	8"	1/1/2002	DI	8"	1/1/2002	NONRES	UNK	DI	8"	UNK	MEWD & GAFFNEY PLG.	Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21468	112 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 5/8" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21471	907 N PINE AVE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	SUDA	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21475	505 W DEPOT ST	UNK	C	UNK	1 1/2"	1/1/2002	C	1 1/2"	1/1/2002	NONRES	UNK	C	1 1/2"	UNK	STRATFORD PLB.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21478	100 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21486	809 MONIQUE LN	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21501	2305 S PEACH AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21508	2711 S APPLE AVE	UNK	DI	UNK	4"	1/1/2000	DI	4"	1/1/2000	NONRES	UNK	DI	4"	UNK	WELLS INVESTMENTS	Installation Record	Y	1/1/2000	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21514	1902 E MCMILLAN ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21519	1012 TREMMEL CT	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21522	1413 S WASHINGTON AVE	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	NONRES	UNK	C	1"	UNK	STOP/GAFFNEY	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21527	2109 W 5TH ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21531	909 WESTERN ST	N	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK	RON MEYERS	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21536	1422 E 26TH ST	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21540	2500 S FELKER AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21543	305 W DEPOT ST	UNK	C	Y	1"	8/17/2021	C	1"	8/17/2021	SF	UNK	C	1"	UNK	8/17/2021: Removed all lead from WM-CS and replaced with 1" copper and new CS & Box. Old tap is 3' East of new tap.	Installation Record	Y	8/17/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21548	2107 W 5TH ST	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
21551	1523 E 25TH ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21556	3516 DOWNWIND DR	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21562	2401 S PEACH AVE	UNK	UNK	UNK	6"	1/1/2001	DI	6"	1/1/2001	NONRES	UNK	DI	6"	UNK	REIGEL	Installation Record	Y	1/1/2001	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21571	1513 S WASHINGTON AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21574	211 W 2ND ST	UNK	UNK	UNK	3/4"	1/1/1989	C	3/4"	1/1/1989	NONRES	UNK	C	3/4"	UNK	REIGEL PLUMBING	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21577	1522 E 25TH ST	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21581	212 N WOOD AVE	UNK	C	UNK	1"	1/1/2017	C	1"	1/1/2017	SF	UNK	C	1"	UNK	EARTH INC	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21584	1039 W CHAPEL ST	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21586	313 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1/2" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21588	417 E 29TH ST	UNK	C	UNK	2"	1/1/1997	C	2"	1/1/1997	NONRES	UNK	C	2"	UNK	THERE IS A 1" LINE TAPPED OFF THE 2" LINE BEHIND METER. IT THEN RUNS BACK OUT THE BUILDING PAST THE CURB VALVE TO THE BLDG. TO THE NORTH	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21588	417 E 29TH ST	UNK	UNK	UNK	12"	UNK	DI	12"	UNK	NONRES	UNK	DI	12"	UNK	NO SERVICE VALVE AT THIS TIME	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21595	2611 S FELKER AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	STUB-OUT CB LOCATION VERIFIED 8/21/97	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21598	2006 BUTTERNUT PKWY	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21600	511 W ARNOLD ST #A	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 3/4" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21602	1507 S ANTON AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	NONRES	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21614	1600 N CHESTNUT AVE	UNK	DI	UNK	6"	UNK	DI	6"	UNK	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
21622	1906 N PEACH AVE	UNK	UNK	UNK	2 - 3/4"	1/1/1964	C	2 - 3/4"	1/1/1964	O	UNK	C	2 - 3/4"	UNK	1 1/4 LINE	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21628	600 N WEBER AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21631	1600 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS(SPENCER)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21634	1612 E BLODGETT ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21637	1620 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SPENCER/INSULATED 1982	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21640	1804 E BLODGETT ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21643	422 MEADOW LN	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21646	416 MEADOW LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21649	400 MEADOW LN	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21652	423 MEADOW LN	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21655	427 MEADOW LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21658	401 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	RON MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21661	411 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21664	417 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21667	423 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21670	501 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21673	520 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21676	518 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21679	418 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21682	410 N ANTON AVE	N	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21685	400 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21688	2001 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21691	1911 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1976	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21694	401 N AUBURN AVE	N	UNK	UNK	UNK	1/1/1969	C	UNK	1/1/1969	SF	UNK	C	UNK	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21697	411 N AUBURN AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21700	417 N AUBURN AVE	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21703	423 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21706	501 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21709	509 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MFLD PLB(MEYER)	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21712	517 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21715	521 N AUBURN AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21718	1821 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21721	526 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	SPENCER MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21724	416 N AUBURN AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21727	411 N HUME AVE	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21730	421 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21733	527 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21736	528 N HUME AVE	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21739	1607 HUME CT	UNK	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	RE-TAPPED IN 2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21742	1610 HUME CT	UNK	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	RE-TAPPED IN 2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21745	516 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21748	510 N HUME AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1998: C.B. LOCATION VERIFIED.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21751	500 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21754	1719 E BLODGETT ST	N	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21757	1717 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	1982-RETAPPED & LOWERED	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21760	1715 E BLODGETT ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21763	1713 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1975	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21766	1619 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1973	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21766	1619 E BLODGETT ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21769	1611 E BLODGETT ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21772	401 N WILLOW AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21775	413 N WILLOW AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21778	1606 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21781	1610 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21784	1710 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21787	1707 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21790	1613 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21793	501 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21796	509 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21799	515 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21802	519 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21805	527 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21808	1606 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21812	611 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21815	617 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21818	707 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21821	711 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21824	715 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21827	721 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21830	718 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21833	700 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21836	1500 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21839	1504 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21842	526 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21845	1505 WILLOW CT	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21848	518 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21851	510 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21854	500 N WILLOW AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21857	1501 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21860	410 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21863	400 N WILLOW AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
21866	206 N WILLOW AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	1980-BOX MOVED FOR STORM SEWER	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21869	106 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	ABBY PLB	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21872	100 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21875	201 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	ABBOTTSFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
21878	115 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21881	111 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	ABBY PLB	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21884	1100 W MCMILLAN ST	UNK	C	UNK	3/4"	1/1/1990	C	3/4"	1/1/1990	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
21975	1150 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21978	1024 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21981	908 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21984	907 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21987	1023 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21990	301 MARATHON ST	UNK	UNK	UNK	1"	1/1/1974	P	1"	1/1/1974	SF	UNK	P	1"	UNK	MEYER	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21993	309 MARATHON ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21996	607 MARATHON ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
21999	1101 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22002	1125 W RIDGE RD	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22005	1129 W RIDGE RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22008	1133 W RIDGE RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22011	1141 W RIDGE RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22014	807 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22017	1201 W IVES ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22020	1201 W RIDGE RD	N	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	SERVICE RUNS DIAGNOL FROM WATER MAIN TO HOUSE. 2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22023	1136 W RIDGE RD	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22026	1132 W RIDGE RD	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22029	1124 W RIDGE RD	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22032	1116 W RIDGE RD	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22035	1112 W RIDGE RD	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22038	1104 W RIDGE RD	N	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	GAFFNEY 11/30/22: Verified copper @ main will fixing main break	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22041	608 MARATHON ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS INC	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22044	600 MARATHON ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22047	1105 W BRIARWOOD ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22050	1125 W BRIARWOOD ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22053	1133 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22056	1141 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22059	1140 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22062	1136 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22065	1132 W BRIARWOOD ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22068	1128 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22071	1124 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22074	1120 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22077	1112 W BRIARWOOD ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22080	1108 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22083	1104 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1968	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22086	1102 W BRIARWOOD ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22089	1101 FAIRVIEW DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22092	1105 FAIRVIEW DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22095	1117 FAIRVIEW DR	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22098	1121 FAIRVIEW DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22105	502 FAIRVIEW CT	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22108	511 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER 3' FROM MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22112	501 N SCHMIDT AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22115	1112 FAIRVIEW DR	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22118	1100 FAIRVIEW DR	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22121	1105 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22124	1117 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22127	301 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	MEYER/CURB BOX VERIFIED 1/14/97. 2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER AT MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22130	1116 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22133	1106 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22136	1107 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22139	1115 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22142	1125 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22145	1150 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1976	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22148	1120 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22151	1100 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22155	403 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4'' COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22159	407 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4'' COPPER NEAR WATER MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22162	409 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22165	412 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22168	420 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22171	422 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22174	424 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22177	426 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22180	428 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22183	1800 S BALBOA AVE	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	30' OF 1" COPPER CONNECTED TO EXISTING 1" COPPER @ THE OLD WATERMAIN	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22186	1012 W 17TH ST	UNK	UNK	UNK	1"	1/1/1974	P	1"	1/1/1974	SF	UNK	P	1"	UNK	SERVICE LOWERED TO 8' TO CENTER OF ROAD. DEPTH @ THAT POINT IS 6' 10". MEYER	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22189	1100 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22192	1106 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22195	1110 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22198	1114 W 17TH ST	UNK	UNK	UNK	1"	1/1/1976	UNK	1"	1/1/1976	SF	UNK	UNK	1"	UNK	REIGEL: CB LOCATION VERIFIED 6/5/97	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22201	1200 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22204	1206 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22207	1105 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22210	1113 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22213	1207 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22216	1011 W 17TH ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
22219	409 W 17TH ST	UNK	C	UNK	1"	8/22/2018	C	1"	8/22/2018	SF	UNK	C	1"	UNK	CONNECTED 1" COPPER TO EXISTING 3/4" APPROX 4' FROM WEST SIDE OF HOUSE. SERVICE FED THROUGH 4" ABANDONED WM APPROX. 2.5' NORTH OF CURB STOP, TYPE 'K' COPPER, NEW 1" CORP, CURB STOP & BOX	Installation Record	Y	8/22/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22219	409 W 17TH ST	N	C	UNK	1"	8/22/2018	C	1"	8/22/2018	SF	UNK	C	1"	UNK	CONNECTED 1" COPPER TO EXISTING 3/4" COPPER APPROX 4' FROM EAST SIDE OF HOUSE. SERVICE RUNS THROUGH ABANDONED 4" WM TO HOUSE	Installation Record	Y	8/22/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22222	405 W 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22225	442 WILDWOOD CT	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22231	303 W 17TH ST	UNK	CI-U	UNK	UNK	1/1/1965	CI-U	UNK	1/1/1965	NONRES	UNK	CI-U	UNK	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22238	1601 S LOCUST AVE	UNK	DI	UNK	4"	1/1/2015	CI-U	4"	1/1/2015	NONRES	UNK	CI-U	4"	UNK	2016-SERVICE 45 DEG UP AND NORTH TO ATTACHED TO EXISTING 3" CAST 6' NE OF MAIN	Installation Record	Y	1/1/2015	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
22245	1500 S LOCUST AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22248	1502 S LOCUST AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22251	1506 S LOCUST AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22254	1512 S LOCUST AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22257	1518 S LOCUST AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22260	1520 S LOCUST AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22263	441 WILDWOOD CT	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22266	431 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22269	427 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22272	425 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22275	423 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22278	419 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22281	417 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22284	415 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN.	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22287	408 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECT TO EXISTING 3/4" COPPER NEAR WATER MAIN. 3/4" copper on property side	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22292	1800 S RODDIS AVE	UNK	UNK	UNK	4"	1/1/1984	CI-U	4"	1/1/1984	NONRES	UNK	CI-U	4"	UNK	CONTROL SEPARATELY.	Installation Record	Y	1/1/1984	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
22295	608 W 17TH ST	UNK	UNK	UNK	4"	UNK	CI-U	4"	UNK	NONRES	UNK	CI-U	4"	UNK	BEAR PEN	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
22298	211 E DEPOT ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22300	206 E DEPOT ST	UNK	UNK-LG	UNK	UNK	1/1/1920	C	UNK	1/1/1920	NONRES	UNK	C	C		CB/LV UNKNOWN. 1" copper on property side	Installation Record	N			Field Inspection Only	Y	3/12/2018	Cross Connection Survey	
22306	1100 N ST JOSEPH AVENUE	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	NONRES	UNK	C	1"	UNK	2008	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22312	201 S OAK AVE	UNK	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	NONRES	UNK	C	3/4"	UNK	STUB-OUT	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22317	407 W 2ND STREET	UNK	UNK	UNK	4"	1/1/1999	DI	4"	1/1/1999	NONRES	UNK	DI	4"	UNK	6" SERVICE REDUCED TO 4".	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
22493	311 W KALSCHED ST	UNK	UNK	UNK	4"	UNK	CI-U	4"	UNK	NONRES	UNK	CI-U	4"	UNK	<Null>	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
22505	1305 N CENTRAL AVE	UNK	C	UNK	1"	1/1/1972	C	1"	1/1/1972	NONRES	UNK	C	1"	UNK	NEW CURB VALVE AND BOX INSTALLED IN 2000.	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22508	1400 N CENTRAL AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	NONRES	UNK	C	3/4"	UNK	2000- LOWERED & INSULATED.	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22510	1306 N CENTRAL AVE	N	CI-U	UNK	8"	1/1/1967	CI-U	8"	1/1/1967	NONRES	UNK	CI-U	8"	UNK	CUT-IN	Installation Record	Y	1/1/1967	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
22519	307 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22522	309 W UPHAM ST	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 12" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22525	405 W UPHAM ST	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 10" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22528	407 W UPHAM ST	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 30" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22535	1602 N CENTRAL AVE	UNK	UNK	Y	3/4"	1/1/1960	C	3/4"	1/1/1960	NONRES	UNK	C	3/4"	UNK	2000: LEAD WIPES REMOVED.	Installation Record	Y	1/1/1960	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22539	1620 N CENTRAL AVE	UNK	C	UNK	1"	1/1/1963	C	1"	1/1/1963	NONRES	UNK	C	1"	UNK	2006-INSTALLED NEW 1" COPPER SERVICE WITH NEW CORP AND CURB-STOP	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22547	306 W MCMILLAN ST	UNK	DI	UNK	6"	1/1/1999	DI	6"	1/1/1999	NONRES	UNK	DI	6"	UNK	BOB NIKOLAY	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
22550	419 W MCMILLAN ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	6/24/2021: Dug at watermain and found 3/4" copper	Installation Record	Y	6/24/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22553	411 W MCMILLAN ST	N	C	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	6/24/2021: Dug at watermain and found 3/4" copper	Installation Record	Y	6/24/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22556	329 W MCMILLAN ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22561	305 W MCMILLAN ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	NEW 1" TAP, PEMBER--2017. 3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22564	223 W MCMILLAN ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	6/22/2021: Dug @ watermain and found 3/4" copper	Installation Record	Y	6/22/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22567	221 W MCMILLAN ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	6/22/2021: Dug @ watermain and found 3/4" copper	Installation Record	Y	6/22/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22579	1702 N PEACH AVE	N	UNK	UNK	5/8"	1/1/1960	UNK	5/8"	1/1/1960	SF	UNK	UNK	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22582	1705 N PEACH AVE	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22585	1703 N PEACH AVE	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22588	1701 N PEACH AVE	N	UNK	UNK	5/8"	1/1/1963	C	5/8"	1/1/1963	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22591	1619 N PEACH AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22594	1613 N PEACH AVE	N	C	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	11/1/2022: Dug service @ the main. Found flared fitting @ the corp was leaking. Removed flare fitting, conn. to existing corp and 3/4" copper @ main.	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22597	1600 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22603	1700 N APPLE AVE	UNK	UNK	UNK	1 1/2"	UNK	C	1 1/2"	UNK	NONRES	UNK	C	1 1/2"	UNK	2009- CAL'S PLMB INSTALLED NEW CURB STOP W/ BOX.	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22606	1710 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CATCH PRESENT LAND ON RM	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22612	1707 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22615	1607 N APPLE AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
22618	1601 N APPLE AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	NEW BOX	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22621	1600 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22624	1606 N PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22627	1616 N PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22630	1700 N PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22633	1706 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SPENCER. 3/4" copper on property side	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22636	1100 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22639	1713 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22642	1707 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22645	1701 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22648	1617 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22651	1609 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22656	1605 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22658	1115 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22661	1121 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22664	1110 CARMEN DR	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22667	1600 KATHERINE CT	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1973	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22670	1614 KATHERINE CT	UNK	UNK	UNK	3/4"	1/1/1974	P	3/4"	1/1/1974	SF	UNK	P	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22673	1615 KATHERINE CT	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22676	1619 KATHERINE CT	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22679	1115 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22682	1714 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22685	1122 E MCMILLAN ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22688	1531 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS. 3/4" copper on property side	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22691	1537 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS(GAFFNEY)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22694	1510 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1976	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22697	1507 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22700	1701 DEBRA LN	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22709	1507 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22712	1501 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22715	1532 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22718	1530 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22721	1524 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22724	1523 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22727	1517 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22730	1509 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22733	1520 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22736	1514 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22739	1508 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22742	1500 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS. 3/4" copper on property side	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22745	1118 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22748	1114 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22751	1507 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22754	1501 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22757	1109 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22760	1119 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS. 3/4" copper on property side	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22765	1500 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22768	1506 N PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22771	1510 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22774	1527 N APPLE AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22777	1523 N APPLE AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22780	1519 N APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22783	1516 N APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22786	1528 N APPLE AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MEL SPENCER	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22789	1529 N PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SCHUH	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22792	1521 N PEACH AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22795	1517 N PEACH AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22798	1511 N PEACH AVE	N	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey
22826	1407 N PEACH AVE	UNK	UNK	UNK	6"	1/1/1987	DI	6"	1/1/1987	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/1987	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter
22830	E KALSCHED ST- S ADDN	UNK	UNK	UNK	4"	1/1/1971	CI-U	4"	1/1/1971	NONRES	UNK	CI-U	4"	UNK	SCHREINER-TAPPED OFF E KALSCHED	Installation Record	Y	1/1/1971	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter
22833	1403 N PEACH AVE	N	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey
22835	1309 N PEACH AVE	N	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey
22838	1301 N PEACH AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22843	1211 N PEACH AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22846	200 W 25TH ST	N	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	CB LOCATION VERIFIED 8-4-97	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22849	204 W 25TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22852	212 W 25TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22855	218 W 25TH ST	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22858	224 W 25TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/4/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22861	225 W 26TH ST	N	UNK	UNK	5/8"	1/1/1961	C	5/8"	1/1/1961	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22864	219 W 26TH ST	N	UNK	UNK	5/8"	1/1/1961	C	5/8"	1/1/1961	SF	UNK	C	5/8"	UNK	INSULATED 2 X 4 X 81	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22867	215 W 26TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22870	211 W 26TH ST	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22873	209 W 26TH ST	N	UNK	UNK	5/8"	1/1/1960	C	5/8"	1/1/1960	SF	UNK	C	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22876	205 W 26TH ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22879	2508 S WITTMAN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22882	2600 S WITTMAN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22885	204 W 26TH ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22888	212 W 26TH ST	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22891	220 W 26TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 12/4/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22894	224 W 26TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22897	2609 S OAK AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22900	221 W 27TH ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1966	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22903	215 W 27TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22906	211 W 27TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/4/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22909	205 W 27TH ST	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	HILLER	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22912	2608 S WITTMAN AVE	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2011- REMOVED LEAD WIPE FROM MAIN. INSTALLED 10' 3/4" COPPER CONNECTED TO EXISTING 3/4" COPPER.	Installation Record	Y	1/1/2011	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22915	2700 S WITTMAN AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22918	225 W 28TH ST	N	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22921	221 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22924	211 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22927	205 W 28TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22930	201 W 28TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey
22933	208 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22936	216 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22939	228 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22942	309 W 29TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22945	221 W 29TH ST	N	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22948	211 W 29TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey
22951	201 W 29TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 8/6/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
22955	2701 S MAPLE AVE	UNK	C	UNK	1"	1/1/1965	C	1"	1/1/1965	NONRES	UNK	C	1"	UNK	2/5/2021 - Removed old 1" - 45 degree that was leaking at the flared end. replaced with new 1" - 45 degree bend w/ 3' - 1" copper 4/10/23: Gaffney installed new 1" cs & box and 1'-1" copper on customer side.	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22959	2525 S CENTRAL AVENUE	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	NONRES	UNK	C	1"	UNK	REIGEL PLUMBING	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
22976	2201 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22979	2109 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22982	210 E 21ST ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	3/4" copper on property side	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22985	214 E 21ST ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1966	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
22988	211 E 21ST ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22991	2007 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LOWERED & INSULATED 1988	Installation Record	Y	1/1/1988	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
22996	2100 S MAPLE AVE	UNK	UNK	UNK	1 1/2"	1/1/1980	C	1 1/2"	1/1/1980	NONRES	UNK	C	1 1/2"	UNK	DISCONNECT AT MAIN 5/88. 1-1/2" copper on property side	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23001	1507 W ADLER RD	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23004	1511 W ADLER RD	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	SF	UNK	C	C		2013-EXISTING CURB-BOX FOUND.	Installation Record	N			Field Inspection Only	Y	1/9/2014	Cross Connection Survey	
23007	1506 W ADLER RD	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23010	1512 W ADLER RD	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23013	1516 W ADLER RD	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23016	2100 W ADLER RD	N	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23019	1506 W 4TH ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23022	1512 W 4TH ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL PLB	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23025	2501 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23028	2509 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23031	407 S EVERGREEN AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23031	407 S EVERGREEN AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23037	2609 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23040	410 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23043	2701 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23046	2700 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23049	710 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23052	716 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23056	705 S HAWTHORN AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23063	712 S HAWTHORN AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 7/28/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23066	607 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23069	601 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23072	2808 HOLLY CT	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23075	2803 HOLLY CT	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23078	2809 HOLLY CT	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23081	2806 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23084	2800 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23088	2000 W 5TH ST	UNK	DI	UNK	6"	1/1/2016	DI	6"	1/1/2016	NONRES	UNK	DI	6"	UNK	2-6" 45 DEG. BENDS AFTER VALVE TO GO UNDER STORM SEWER	Installation Record	Y	1/1/2016	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
23099	1006 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23102	614 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SEEGAR	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23105	107 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23108	1605 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23113	1606 HUME CT	UNK	C	UNK	3/4"	1/1/2017	C	3/4"	1/1/2017	SF	UNK	C	3/4"	UNK	RE-TAPPED IN 2017	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23116	1118 FAIRVIEW DR	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23119	1201 E UPHAM ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS(GAFFNEY)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23124	2111 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	ATTACHED TO 3/4" COPPER @ CURB VALVE. CURB BOX MEASUREMENT FOR CURB VALVE NEXT TO BLDG. 6'N & 10'W OF THE NW CORNER OF BLDG	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23127	1154 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23130	1607 S LINCOLN AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23136	1513 S LINCOLN AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23139	207 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23143	1111 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1972	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23165	408 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23169	914 W STATE ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23172	1501 W 4TH ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23175	1101 N PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23183	812 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1976	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23186	1618 KATHERINE CT	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23193	1019 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23196	913 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23199	1511 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23202	1113 W BRIARWOOD ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23209	906 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23213	1529 RENEE LN	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23216	1141 W IVES ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23219	1517 S LINCOLN AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23222	1513 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1976	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23225	1513 N HINMAN AVE	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23229	1500 W 4TH ST	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	STRATFORD PLB	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23232	1507 W 4TH ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23235	700 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23238	1507 N HINMAN AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23242	1600 N FIG AVE	UNK	C	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23245	701 S HAWTHORN AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23248	401 MEADOW LN	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23270	1601 S LINCOLN AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23273	521 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS(GAFFNEY)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23276	514 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23279	1000 W STATE ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23282	1506 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23287	2800 S WITTMAN AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23290	1007 N PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23296	749 W 17TH STREET	UNK	UNK	UNK	4"	UNK	CI-U	4"	UNK	NONRES	UNK	CI-U	4"	UNK	MFLD PLUMBING	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
23304	1711 S LINCOLN AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23307	411 MEADOW LN	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23309	211 E DEPOT ST	UNK	UNK	Y	2"	1/1/1976	C	2"	1/1/1976	NONRES	UNK	C	2"	UNK	DON'T KNOW IF THIS IS LIVE. 6'E OF THIS LINE IS A 1-1/4 LEAD LINE THIS IS EITHER DISCONNECTED OR SHUT OFF AT MAIN	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23311	1107 W STATE ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23317	814 W 14TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23321	411 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23324	1612 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23330	1514 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS. 3/4" copper in the house	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23334	1600 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23337	511 MARATHON ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
23342	220 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23346	1229 W IVES ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23349	1709 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23352	1411 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016-2" TAP AND INSTALLED NEW 2" COPPER TO NEW CURB VALVE CONNECTING TO 2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23363	1510 RENEE LN	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23369	1108 FAIRVIEW DR	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1968	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23385	1116 E MCMILLAN ST	UNK	C	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23391	115 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 20" OF 1" COPPER CONN TO EXIST 1" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23403	900 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23406	1721 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23409	304 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23412	1126 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	SPENCER	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23418	1225 W IVES ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23426	1605 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1978	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23429	1016 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23433	1615 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23442	1500 S VINE AVE	UNK	C	UNK	1 1/2"	1/1/1979	C	1 1/2"	1/1/1979	NONRES	UNK	C	1 1/2"	UNK	REIGEL	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23444	211 E DEPOT ST	UNK	UNK	UNK	2"	1/1/1979	C	2"	1/1/1979	NONRES	UNK	C	2"	UNK	CB LOCATION VERIFIED 6/4/97	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23447	1704 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23450	600 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23454	901 W STATE ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23461	1300 N CENTRAL AVE	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	NONRES	UNK	C	3/4"	UNK	MEYERS: SERVICE COMES OFF KALSCHED.	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23466	1126 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23470	909 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23473	503 E IVES ST #300	UNK	UNK	UNK	2"	1/1/1979	C	2"	1/1/1979	NONRES	UNK	C	2"	UNK	MFLD PLB	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23477	503 E IVES ST	UNK	UNK	UNK	8"	1/1/1978	DI	8"	1/1/1978	NONRES	UNK	DI	8"	UNK	NORTHWAY MALL	Installation Record	Y	1/1/1978	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
23480	1515 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23488	1506 RENEE LN	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23493	1515 W 4TH ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23497	501 MARATHON ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS(GAFFNEY)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23500	1144 W STATE ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS. 1" copper on property side	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23515	121 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 10" OF 1" COPPER FROM CORP CONN TO EXIST 1" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23522	801 W 17TH ST	UNK	C	UNK	2"	1/1/2017	P	2"	1/1/2017	NONRES	UNK	P	2"	UNK	REMOVED 4-3/4" LINES AND RE-TAPPED 2"	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23529	407 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	MEYERS (REIGEL)	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23533	1129 W IVES ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	NONRES	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23537	1110 W ONSTAD DR	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23541	1107 N PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23546	301 S LINCOLN AVE	UNK	C	UNK	1"	9/19/2023	C	1"	9/19/2023	SF	UNK	C	1"	UNK	9/19/23 Earth Inc installed 1" corp., 35 LF - 1" copper (wm-cs), 1" cs & box, 5.5 LF - 1" copper (cs - existing 3/4" copper) See pg 15 of the constr. report.	Installation Record	Y	9/19/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23551	1607 E DOEGE ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB VERIFIED 3-97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23554	1610 N PALMETTO AVE	N	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23557	1710 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23560	1914 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23570	600 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23573	1610 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23577	506 FAIRVIEW CT	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23580	1613 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23587	220 W 27TH ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23591	1501 WILLOW CT	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23596	1514 S LOCUST AVE	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23600	1910 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23604	210 W 27TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23607	1111 N PEACH AVE	N	UNK-NOLG	UNK	UNK	UNK	L	UNK	UNK	SF	UNK	L	UNK	UNK	<Null>	SL repair/replace record	N		Visual insp during install or repair	Previous eval	Y	4/15/2014	Cross connection survey	
23610	700 E MCMILLAN ST	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23615	403 W MCMILLAN ST	UNK	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	O	UNK	C	3/4"	UNK	SCHREINERS. 6/22/2021: Dug at watermain and found 3/4" copper	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23619	1401 N PEACH AVE	N	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23622	510 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23627	406 MARATHON ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS(GAFFNEY)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23630	1615 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1980	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23633	1611 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	KOHL	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23637	412 MARATHON ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23642	1613 W 4TH ST	UNK	C	UNK	1"	9/29/2023	C	1"	9/29/2023	SF	UNK	C	1"	UNK	9/29/23 Earth Inc installed 1" corp., 33LF - 1" copper (wm-cs), 1" cs & box, 9.5 LF - 1" copper (cs - existing 1" copper) Project #5876 See pg. 19 of the const. report	Installation Record	Y	9/29/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23645	1706 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23648	1010 W STATE ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23652	1138 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23655	114 N WILLOW AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23658	217 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23664	1609 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23667	716 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23670	705 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23674	1011 N PEACH AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	STUBBED OUT WHEN PAVED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23677	1105 W RIDGE RD	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	KALSCHED PLB	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23680	707 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	O	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23688	410 MEADOW LN	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23696	1521 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016- 2" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 1-1/2"COPPER AFTER CURB VALVE	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23699	1517 S LOCUST AVE	UNK	C	UNK	1 1/2"	1/1/2016	C	1 1/2"	1/1/2016	NONRES	UNK	C	1 1/2"	UNK	2016-1-1/2" TAP AND INSTALLED NEW 1-1/2" COPPER TO NEW CURB VALVE CONNECTING TO 1-1/2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23702	1519 S LOCUST AVE	UNK	C	UNK	1 1/2"	1/1/2016	C	1 1/2"	1/1/2016	NONRES	UNK	C	1 1/2"	UNK	2016-1-1/2" TAP AND INSTALLED NEW 1-1/2" COPPER TO NEW CURB VALVE CONNECTING TO 1-1/2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23706	1511 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016-2" TAP AND INSTALLED NEW 2" COPPER TO NEW CURB VALVE CONNECTING TO 2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23709	1513 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016-2" TAP AND INSTALLED NEW 2" COPPER TO NEW CURB VALVE CONNECTING TO 2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23712	1509 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016-2" TAP AND INSTALLED NEW 2" COPPER TO NEW CURB VALVE CONNECTING TO 2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
23716	1505 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016-2" TAP AND INSTALLED NEW 2" COPPER TO NEW CURB VALVE CONNECTING TO 2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23719	1501 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016-2" TAP AND INSTALLED NEW 2" COPPER TO NEW CURB VALVE CONNECTING TO 2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23722	1503 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016-2" TAP AND INSTALLED NEW 2" COPPER TO NEW CURB VALVE CONNECTING TO 2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23726	1601 E UPHAM ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23730	1500 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23735	1101 W 17TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/5/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23738	1507 S LINCOLN AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	ABBY	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23741	1001 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23754	417 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23757	706 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23763	2025 W VETERANS PKWY	UNK	C	UNK	1 1/4"	1/1/1981	C	1 1/4"	1/1/1981	NONRES	UNK	C	1 1/4"	UNK	REIGEL PLB	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23773	1606 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1980	C	3/4"	1/1/1980	SF	UNK	C	3/4"	UNK	KOHLS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23776	509 MEADOW LN	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23780	1136 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23783	1201 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYER (GAFFNEY)	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23786	2000 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STARTFORD PLUMBING	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23789	1011 W STATE ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23794	1001 N PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23799	410 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23802	1617 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23805	1137 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23809	503 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23813	727 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23816	407 MARATHON ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23819	1711 N PEACH AVE	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	SAME FOR 1713	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23824	101 N ADAMS AVE	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23828	1616 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1973	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23832	1605 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23835	1601 W 4TH ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23838	2801 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23841	2805 HOLLY CT	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1977	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23846	505 W 17TH ST	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23850	527 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23853	1601 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23862	401 MARATHON ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23867	610 N WEBER AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 7/3/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23871	1614 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23875	510 MARATHON ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23880	405 N ADAMS AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23886	109 W UPHAM ST	UNK	C	UNK	2"	1/1/1981	C	2"	1/1/1981	NONRES	UNK	C	2"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23891	217 W UPHAM ST	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23895	1800 E BLODGETT ST	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
23903	1715 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23906	505 MARATHON ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23909	1503 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	SCHULTZ	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23912	1101 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23917	215 W UPHAM ST	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 12" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23922	403 W 17TH ST	UNK	C	UNK	1"	1/1/1970	C	1"	1/1/1970	SF	UNK	C	1"	UNK	1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 8'9" DEEP	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23926	416 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
23929	2011 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	LOWERED & INSULATED 1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23932	1140 W RIDGE RD	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23935	610 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	BROSTWITZ	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23938	419 MARATHON ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	GAFFNEY PLB	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23943	1149 W STATE ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23950	1112 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23957	224 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23965	100 N ADAMS AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF STATE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23971	1109 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1966	C	3/4"	1/1/1966	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23976	1130 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23984	209 W 29TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23992	1409 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	SCHULTZ	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
23997	1618 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24000	1014 W STATE ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24003	1121 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24011	1221 W IVES ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24019	1619 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24022	1136 W STATE ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER-GAFFNEY	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24026	1611 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24032	1611 DEBRA LN	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24035	305 MARATHON ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24038	403 N HUME AVE	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24043	1101 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24046	800 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24056	119 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 15" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24063	1619 E DEPOT ST	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24066	508 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	SPENCER(MEYERS)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24071	101 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24078	514 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24082	1007 W 17TH ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYER (GAFFNEY)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24087	600 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24090	904 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24093	411 MARATHON ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24120	211 MARATHON ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24127	806 S HAWTHORN AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 12/12/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24136	421 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24140	1136 W IVES ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24147	401 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24153	710 N WEBER AVE	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	NONRES	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24159	1707 E FILLMORE ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24163	616 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24168	1015 W STATE ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24171	1122 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
24175	1720 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24180	516 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24183	425 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24186	607 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24189	706 N WEBER AVE	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	NONRES	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24195	206 W 27TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24199	312 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24204	515 MARATHON ST	UNK	UNK	UNK	1"	1/1/1974	P	1"	1/1/1974	SF	UNK	P	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24207	1126 W STATE ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24212	1701 N APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24215	1500 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24218	204 W 28TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24224	416 N HUME AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24227	317 W MCMILLAN ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	L	UNK	UNK	6/22/2021: Dug @ watermain and found 3/4" copper	SL repair/replace record	Y	6/22/2021	Mech excav	Previous eval	Y	6/24/2014	Cross connection survey	
24233	701 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24236	808 W STATE ST	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24240	1511 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24243	315 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24246	410 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24256	1714 N APPLE AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24259	1116 W STATE ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24267	1110 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24270	1140 W STATE ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24278	404 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24286	1510 E BLODGETT ST	UNK	UNK	UNK	UNK	1/1/1973	C	UNK	1/1/1973	SF	UNK	C	UNK	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24294	1123 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24297	209 MARATHON ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24300	1510 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24303	1206 E UPHAM ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24308	808 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24316	606 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24319	410 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24323	522 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24329	430 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR WATER MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24343	1611 N APPLE AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24353	1604 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24358	308 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24361	416 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24366	1001 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	SPENCER	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24375	500 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24379	1113 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24382	1516 RENEE LN	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24396	1207 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24404	213 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24409	1217 W IVES ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS(GAFFNEY)	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24412	1610 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24422	303 W UPHAM ST #100	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	NEW 2" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 26" OF 2" COPPER FROM CORP CONN TO EXIST 2" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24426	1002 W BLODGETT ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	SERVICE IS OFF MARATHON	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24430	1316 N HUME AVE #B101	UNK	CI-U	UNK	6"	1/1/1960	CI-U	6"	1/1/1960	SF	UNK	CI-U	6"	UNK	R & C UNITY	Installation Record	Y	1/1/1960	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
24464	1518 N PEACH AVE	UNK	DI	UNK	6"	1/1/1990	CI-U	6"	1/1/1990	NONRES	UNK	CI-U	6"	UNK	FINCH BURG PLB MADISON	Installation Record	Y	1/1/1990	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
24470	701 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24496	307 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24502	410 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24505	1010 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24510	400 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24513	306 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24516	406 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24522	204 E 21ST ST	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24529	1200 W IVES ST	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24533	2413 BLUEBIRD CT	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24538	810 E HARRISON ST	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	NONRES	UNK	C	2"	UNK	DOINE-REIGEL	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24547	1708 E MCMILLAN ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24552	308 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24556	425 W UPHAM ST	UNK	DI	UNK	4"	1/1/2016	DI	4"	1/1/2016	NONRES	UNK	DI	4"	UNK	6X4 TEE 1'W OF VALVE, MJ SLEEVE 16" N OF TEE, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
24559	401 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24562	206 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24567	209 MEADOW LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24570	312 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24573	2313 W 4TH ST	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	LEWERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24577	2314 W 4TH ST	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	LEWERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24582	901 W 17TH ST #1	UNK	UNK	UNK	1 1/2"	1/1/1983	C	1 1/2"	1/1/1983	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24590	405 E 17TH ST	UNK	UNK	UNK	1 1/4"	1/1/1984	UNK	1 1/4"	1/1/1984	NONRES	UNK	UNK	1 1/4"	UNK	CITY GARAGE	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24590	405 E 17TH ST	Y	UNK	UNK	UNK	UNK	P	UNK	UNK	NONRES	UNK	P	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24590	405 E 17TH ST	UNK	C	UNK	1 1/2"	5/13/2022	C	1 1/2"	5/13/2022	NONRES	UNK	C	1 1/2"	UNK	Earth Inc. This is for Pat's Barn. 33' of copper from main to curb valve. 3' of copper from curb valve to existing copper. Curb box is 8" south of a 2" plastic gas line.	Installation Record	Y	5/13/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24590	405 E 17TH ST	UNK	UNK	UNK	1 1/2"	1/1/2000	C	1 1/2"	1/1/2000	NONRES	UNK	C	1 1/2"	UNK	MEYERS	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24590	405 E 17TH ST	UNK	C	UNK	1 1/2"	6/23/2022	C	1 1/2"	6/23/2022	NONRES	UNK	C	1 1/2"	UNK	Pg. 19 of construction report. Earth Inc. installed 1-1/2" corp., 1-1/2" copper, 1-1/2" cs & box. Conn. to existing 1-1/2" copper, 32.5' after the cs. (Feeds Restrooms & concession stand on SW side of bldg)	Installation Record	Y	6/23/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24590	405 E 17TH ST	UNK	C	UNK	2"	6/23/2022	P	2"	6/23/2022	NONRES	UNK	P	2"	UNK	Pg. 19 of construction report. Earth Inc. installed 2" corp., 2" copper, 2" cs & box. Conn. to existing 2" poly, 30" after the cs. Reduces to 1-1/2" poly at building footings. (Feeds Zamboni room, NW corner restrooms and showers.)	Installation Record	Y	6/23/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24628	2310 W 4TH ST	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	LEWERS	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24634	400 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STARTFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24637	1607 E ARNOLD ST	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24674	309 W MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24677	209 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24682	210 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24686	207 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY (ATHENS)	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24716	1810 S BALBOA AVE	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	30' OF 1" COPPER CONNECTED TO EXISTING 1" COPPER @ THE OLD WATERMAIN	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
24722	1522 S LOCUST AVE	N	C	UNK	1"	1/1/2016	P	1"	1/1/2016	SF	UNK	P	1"	UNK	2016- 1" TAP AND INSTALLED NEW COPPER CONNECTING TO EXISTING 3/4" COPPER AT WEST CURB LINE 2010- INSTALLED 1" PLASTIC FROM INSIDE TO NEW CURB VALVE W/ BOX.	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24725	300 S LARCH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 12/10/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24731	1708 N CENTRAL AVE	UNK	DI	UNK	8"	1/1/1991	DI	8"	1/1/1991	NONRES	UNK	DI	8"	UNK	REIGEL	Installation Record	Y	1/1/1991	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
24734	1413 E DEPOT ST	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24737	2401 W 4TH ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24743	1804 S BALBOA AVE	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	30' OF 1" COPPER CONNECTED TO EXISTING 1" COPPER @ THE OLD WATERMAIN	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24748	1900 S BALBOA AVE	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	30' OF 1" COPPER CONNECTED TO EXISTING 1" COPPER @ THE OLD WATERMAIN	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24756	300 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24759	201 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY (ATHENS)	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24762	1601 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24765	1620 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24768	200 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24772	313 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	LEWERS - NOTE: TAPPED 4' FROM END OF HYD TEE	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24783	2501 W 3RD ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	RON MEYER	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24789	309 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24796	500 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
24799	2306 W 4TH ST	UNK	UNK	UNK	1"	1/1/1991	C	1"	1/1/1991	SF	UNK	C	1"	UNK	LEWER	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24802	1212 W RIDGE RD	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24807	314 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 6" OF 1" COPPER FROM CORP CONN TO EXIST 1" COPPER, 1.5" COPPER FROM C.B. TO BLDG, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24813	2510 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24816	701 S HOLLY AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	TAP FOR 620 HOLLY IS 18"N	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24819	213 MEADOW LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24825	201 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24834	2414 BLUEBIRD CT	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24840	209 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24843	200 S MULBERRY AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 7/28/97 IN DRIVEWAY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24858	1508 N HINMAN AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	MEYER(GAFFNEY)	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24861	1112 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24864	900 W STATE ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24867	907 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24870	1608 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24874	1505 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24877	1106 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24880	212 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24883	1223 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24886	2605 W 3RD ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24889	310 S MARYKNOLL AVE	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24892	208 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - CONNECTED TO EXISTING 1" COPPER AT MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24895	300 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24899	1408 S BALBOA AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	SCHULTZ	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24902	904 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24910	1504 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24931	1316 N HUME AVE #A101	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24950	509 S HOLLY AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24953	306 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24959	522 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24962	1408 N HUME AVE	UNK	UNK	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24965	1700 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
24984	201 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	NEW MEASUREMENT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24988	910 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
24991	2601 W 3RD ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25000	2314 E FILLMORE ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25003	401 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25006	614 S HOLLY AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25009	1406 S APPLE AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25015	1112 E MCMILLAN ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25022	1401 E DEPOT ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25026	518 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25029	2709 W 8TH ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25032	310 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25035	1153 W STATE ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25038	1210 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25052	2101 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25059	1505 N HUME AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25068	606 S HOLLY AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25071	1121 CARMEN DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25074	1109 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25077	1723 S LINCOLN AVE	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25080	422 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25084	613 W 11TH ST	UNK	UNK	UNK	6"	1/1/2001	DI	6"	1/1/2001	NONRES	UNK	DI	6"	UNK	MECHANICAL CUT-IN: REIGELS	Installation Record	Y	1/1/2001	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
25087	1601 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25090	501 W 17TH ST	UNK	C	UNK	1"	8/22/2018	C	1"	8/22/2018	SF	UNK	C	1"	UNK	CONNECTED 1" COPPER TO EXISTING 3/4" APPROX 6' FROM EAST SIDE OF HOUSE, SERVICE FED THROUGH 4" ABANDONED WM APPROX. 2.5' NORTH OF CURB STOP, TYPE 'K' COPPER, NEW 1" CORP, CURB STOP & BOX	Installation Record	Y	8/22/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25090	501 W 17TH ST	N	C	UNK	1"	8/22/2018	C	1"	8/22/2018	SF	UNK	C	1"	UNK	CONNECTED 1" COPPER TO EXISTING 3/4" COPPER APPROX 6' FROM EAST SIDE OF HOUSE. SERVICE RUNS THROUGH ABANDONED 4" WM TO HOUSE	Installation Record	Y	8/22/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25093	201 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25097	1719 N PALMETTO AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25100	1704 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25103	1200 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25109	913 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25112	410 S EVERGREEN AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25115	504 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25121	423 W MCMILLAN ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	6/25/2021: Dug at watermain and found 3/4" copper	Installation Record	Y	6/25/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25124	111 W MCMILLAN ST	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	1" TAP W/ 2' OF 1" COPPER CONN. TO EXIST. 3/4" COPPER, PEMBER--2017	Installation Record	Y	1/1/2017	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25129	1130 W STATE ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25132	1504 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25135	1525 N PEACH AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25138	2511 W 3RD ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25159	1608 KATHERINE CT	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS. 3/4" copper on property side	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
25162	1521 RENEE LN	UNK	C	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25176	805 W STATE ST	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25179	115 E UPHAM ST	UNK	UNK	UNK	1 1/4"	1/1/1993	C	1 1/4"	1/1/1993	NONRES	UNK	C	1 1/4"	UNK	WHEN TAPPED	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25184	301 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25190	428 MEADOW LN	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25200	424 N ANTON AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25208	1710 N PALMETTO AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25216	2600 W 3RD ST	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25221	1504 WILLOW CT	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25224	1304 N CENTRAL AVE	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	NONRES	UNK	C	3/4"	UNK	NEW CURB BOX INSTALLED 2000.	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25235	422 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25238	209 HICKORY LN	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25242	1409 S LOCUST AVE	UNK	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	2016-2" TAP AND INSTALLED NEW C" COPPER TO NEW CURB VALVE CONNECTING TO 2" COPPER	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25249	200 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP CONNECTED TO EXISTING 1" COPPER AT MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25253	208 W 26TH ST	N	UNK	UNK	3/4"	1/1/1962	C	3/4"	1/1/1962	SF	UNK	C	3/4"	UNK	INSULATED 2x4	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25269	1626 N FIG AVE	UNK	CI-U	UNK	4"	UNK	CI-U	4"	UNK	NONRES	UNK	CI-U	4"	UNK	<Null>	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
25282	507 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25285	1615 E BLODGETT ST	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25288	310 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	1978-STOP REMOVED FOR STORM SEWER	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25294	1704 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	NONRES	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25303	1713 N HUME AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	DUPLEX	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25306	1514 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25309	700 N WEBER AVE	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	NONRES	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25316	1501 N FIG AVE	UNK	C	UNK	1 1/2"	1/1/1977	C	1 1/2"	1/1/1977	NONRES	UNK	C	1 1/2"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25319	2809 S OAK AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25322	2207 W 5TH ST	UNK	UNK	UNK	1 1/4"	1/1/1983	C	1 1/4"	1/1/1983	NONRES	UNK	C	1 1/4"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25334	712 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25337	1606 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25342	1612 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25346	1131 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25350	1006 N SCHMIDT AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25353	407 W MCMILLAN ST	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	6/22/2021: Dug at watermain and found 3/4" copper	Installation Record	Y	6/22/2021	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25357	1701 E FILLMORE ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25360	601 N WEBER AVE	UNK	UNK	UNK	1 1/2"	1/1/1979	C	1 1/2"	1/1/1979	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25363	814 W STATE ST	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25366	1113 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25370	1226 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25377	111 W UPHAM ST	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 29" OF 1" COPPER CONN TO 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25386	1407 N CENTRAL AVE	UNK	C	UNK	2"	1/1/1984	P	2"	1/1/1984	NONRES	UNK	P	2"	UNK	10/25/23: Kyle Kluck - 2" poly w/ insert on customers side	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25392	1217 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25396	307 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25410	316 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25413	403 W UPHAM ST	N	C	UNK	1"	1/1/2016	C	1"	1/1/2016	SF	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 15" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25420	1606 N HUME AVE	UNK	UNK	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25434	1410 N CENTRAL AVE	N	C	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	CURB BOX LOCATION VERIFIED 1/14/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25437	1220 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25440	1609 N HUME AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25446	1600 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25449	1106 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25452	1609 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25456	209 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON/2400 BLUEBIRD CT	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25462	1600 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25465	1405 E DEPOT ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25469	620 S HOLLY AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	TAP FOR 701 HOLLY IS 18"S	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25472	2508 W 3RD ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25475	213 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25490	200 N WILLOW AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25493	1100 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25496	1524 RENEE LN	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25499	810 E VILAS ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25504	2121 W VETERANS PKWY	UNK	DI	UNK	4"	1/1/2002	DI	4"	1/1/2002	NONRES	UNK	DI	4"	UNK	MEWD *NOTE*- THERE ARE 2-4" VALVES FOR THIS SERVICE	Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
25508	208 W 25TH ST	N	UNK	UNK	3/4"	1/1/1963	C	3/4"	1/1/1963	SF	UNK	C	3/4"	UNK	3/4" copper on property side	Installation Record	Y	1/1/1963	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25515	1121 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25530	912 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25534	1720 N APPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25538	719 N WEBER AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25541	720 N WEBER AVE #A	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	NONRES	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25545	1141 W STATE ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25548	1607 E UPHAM ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25551	1707 S LINCOLN AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25555	1601 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25577	617 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25580	329 S MARYKNOLL AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25583	400 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25586	511 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25593	1121 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25596	2314 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25604	1411 E DOEGE ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25610	206 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25613	2308 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25617	1007 W STATE ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25624	1506 E BLODGETT ST	UNK	C	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS 1975. 2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25650	1520 W ADLER RD	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25653	2809 W 5TH ST	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25656	1126 W ONSTAD DR	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25661	1128 W IVES ST	UNK	UNK	UNK	UNK	1/1/1984	C	UNK	1/1/1984	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25667	1501 N CENTRAL AVE	UNK	UNK	UNK	1 1/2"	1/1/1985	C	1 1/2"	1/1/1985	NONRES	UNK	C	1 1/2"	UNK	SERVICE COMES OFF UPHAM	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25667	1501 N CENTRAL AVE	UNK	UNK	UNK	4"	1/1/1984	CI-U	4"	1/1/1984	NONRES	UNK	CI-U	4"	UNK	REIGEL	Installation Record	Y	1/1/1984	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
25671	1609 W 4TH ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25674	501 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25678	1610 N APPLE AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25707	205 W 29TH ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
25713	1511 E BLODGETT ST	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 6' - 1" COPPER AND 1"3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25717	2711 S CENTRAL AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25724	1001 W STATE ST	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25727	707 N WEBER AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25730	1011 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25734	2701 S OAK AVE	N	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	SF	UNK	C	3/4"	UNK	SCHUH	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25739	1413 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1981	C	3/4"	1/1/1981	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25747	513 E 17TH STREET	UNK	UNK	UNK	2"	1/1/1985	C	2"	1/1/1985	NONRES	UNK	C	2"	UNK	RIEGEL PLB.	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25752	1006 W STATE ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25755	611 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25758	219 W 27TH ST	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25764	1601 N FIG AVE	UNK	C	UNK	1 1/2"	1/1/1977	C	1 1/2"	1/1/1977	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1977	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25768	1717 S LINCOLN AVE	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25782	207 E 21ST ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25794	205 MARATHON ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25797	415 MARATHON ST	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25800	1717 N PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	SF	UNK	C	3/4"	UNK	SAME FOR 1719	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25803	1500 N HUME AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25806	1116 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25809	406 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25815	201 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25821	1100 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25824	1701 E BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYERS/MAP ON CARD	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25830	210 S LEY AVE	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25833	208 S MULBERRY AVE	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25838	222 E UPHAM ST	UNK	UNK	UNK	6"	1/1/1994	DI	6"	1/1/1994	NONRES	UNK	DI	6"	UNK	GAFFNEY	Installation Record	Y	1/1/1994	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
25842	1722 N HUME AVE	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25849	1906 S BALBOA AVE	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	30' OF 1" COPPER CONNECTED TO EXISTING 1" COPPER @ THE OLD WATERMAIN	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25852	1604 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25855	2412 BLUEBIRD CT	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25858	2401 BLUEBIRD CT	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25864	2300 W 3RD ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 12/10/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25867	2507 W 3RD ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25879	822 S HAWTHORN AVE	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25882	201 S LEY AVE	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25887	1213 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25890	216 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25893	2409 MEADOWBROOK DR	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	TAPPED ON THE HYDRANT RUN	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25896	201 MARATHON ST	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25899	1020 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25902	1144 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25905	1129 W STATE ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25909	301 MEADOW LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25912	2308 W 3RD ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25915	900 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25925	2204 W 3RD ST	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	LOT 37	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
25934	1412 S BALBOA AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	3/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25944	1606 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25947	216 W 26TH ST	N	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25958	1807 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25963	507 W 17TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
25969	1700 E UPHAM ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25972	2601 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25975	1126 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25978	417 MEADOW LN	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25990	2008 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	LOWERED & INSULATED 1988	Installation Record	Y	1/1/1988	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
25993	2800 HOLLY CT	UNK	C	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26002	1129 W BRIARWOOD ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26010	1120 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26018	508 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26021	508 MEADOW LN	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26028	716 N WEBER AVE	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	NONRES	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26034	1135 W STATE ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26037	1115 E VILAS ST	UNK	C	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26048	2706 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26052	1108 WAUSHARA DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26059	709 N SCHMIDT AVE	N	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26090	506 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	BROSTOWITZ	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26105	1711 E BLODGETT ST	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	RETAPPED, LOWERED & INSULATED 1982	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26121	1505 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26125	1707 E UPHAM ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26137	1500 RENEE LN	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26140	1500 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1985	C	3/4"	1/1/1985	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26149	211 E DEPOT ST	UNK	UNK	UNK	4"	1/1/1977	DI	4"	1/1/1977	NONRES	UNK	DI	4"	UNK	CB LOCATION VERIFIED 6/4/97	Installation Record	Y	1/1/1977	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
26162	110 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26175	1701 E UPHAM ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26181	2107 S MAPLE AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1989- LOWERED & INSULATED 6-1/2' COVER @ STORM SEWER	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26197	401 N HUME AVE	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26202	1609 KATHERINE CT	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26214	407 W 17TH ST	N	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26227	2501 MEADOWBROOK DR	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	SF	UNK	UNK	UNK	UNK	1-1/2" LINE FROM FILLMORE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26227	2501 MEADOWBROOK DR	UNK	UNK	UNK	1 1/2"	UNK	C	1 1/2"	UNK	SF	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26230	422 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26236	713 N WEBER AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26249	610 S HOLLY AVE	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	RON MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26254	709 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	2017-INSTALLED 1" COPPER FROM MAIN 26' TO EAST	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26257	1700 E DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS(SPENCER)	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26263	1012 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26266	506 MARATHON ST	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26279	1701 N CHESTNUT AVE #201	UNK	C	UNK	2"	1/1/1983	C	2"	1/1/1983	NONRES	UNK	C	2"	UNK	35444	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26301	1608 W 4TH ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26307	406 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26310	417 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26316	1154 W BLODGETT ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26327	1137 W IVES ST	UNK	UNK	UNK	1"	1/1/1986	P	1"	1/1/1986	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26330	1109 FAIRVIEW DR	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1968	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26345	215 W 29TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	MFLD PLUMBING	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26348	401 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
26351	500 BLUEBIRD LN	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26356	1511 RENEE LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26359	1322 N HUME AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26373	203 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 23" OF 1" COPPER FROM CORP CONN TO EXIST 1" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26375	1013 W ONSTAD DR	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26378	1117 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26381	1125 W ONSTAD DR	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26384	1125 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26387	1139 W STATE ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26404	1617 N FIG AVE	UNK	C	UNK	2"	1/1/1977	C	2"	1/1/1977	NONRES	UNK	C	2"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26410	303 W MCMILLAN ST	UNK	C	UNK	3/4"	1/1/1989	C	3/4"	1/1/1989	O	UNK	C	3/4"	UNK	1" TAP & 3' OF 1" COPPER CONN. TO EXIST. 3/4" COPPER--2017, PEMBER	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26414	2005 S MAPLE AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1988 - REMOVED WIPE, LOWERED & INSULATED	Installation Record	Y	1/1/1988	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26417	504 N AUBURN AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26423	510 S HOLLY AVE	UNK	UNK	UNK	3/4"	1/1/1982	C	3/4"	1/1/1982	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26439	210 MAGNOLIA DR	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	LOT 30	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26442	211 S LEY AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 7/28/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26456	610 N WILLOW AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26459	1610 N HUME AVE	UNK	UNK	UNK	1"	1/1/1973	C	1"	1/1/1973	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1973	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26464	1701 N CHESTNUT AVE #101	UNK	DI	UNK	6"	UNK	DI	6"	UNK	NONRES	UNK	DI	6"	UNK	REIGEL, CURB BOX VERIFIED 1/14/97	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
26476	1709 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26480	501 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26483	1809 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26486	1210 W STATE ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26490	1701 MARCY CT	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	NONRES	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26506	1201 N PEACH AVE	N	UNK	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26509	1015 N CENTRAL AVE	N	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	1986: HOUSE TORN DOWN. 1-1/4" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26509	1015 N CENTRAL AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	NONRES	UNK	C	1"	UNK	FITTINGS.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26523	1714 N PALMETTO AVE	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26527	411 N ADAMS AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	REIGEL-MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26530	1140 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26536	1213 W STATE ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26539	1318 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1987	C	3/4"	1/1/1987	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26542	1601 N HUME AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26557	1224 W BRIARWOOD ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26560	1229 W BRIARWOOD ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26564	2515 MEADOWBROOK DR	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26567	2112 W 3RD ST	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	LOT 36	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26579	1710 MARCY CT	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26596	1708 DEBRA LN	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS: DUPLEX WITH 1710	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26599	1500 N HINMAN AVE	UNK	UNK	UNK	1"	1/1/1974	C	1"	1/1/1974	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26602	1211 W IVES ST	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26605	1115 W STATE ST	UNK	UNK	UNK	3/4"	1/1/1979	C	3/4"	1/1/1979	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26609	700 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26612	711 S HOLLY AVE	N	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26617	1401 E 4TH ST	N	CI-U	UNK	6"	UNK	UNK	6"	UNK	NONRES	UNK	UNK	6"	UNK	THIS SERVICE FEEDS MASONITE (MINERAL CORE)	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
26619	101 S OAK AVE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	NONRES	UNK	C	1"	UNK	CITY GARAGE	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26629	1109 W ONSTAD DR	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26632	500 FAIRVIEW CT	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26641	411 S EVERGREEN AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26644	1609 N FIG AVE	UNK	C	UNK	1 1/2"	1/1/1977	C	1 1/2"	1/1/1977	NONRES	UNK	C	1 1/2"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26648	313 W MCMILLAN ST	UNK	C	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	O	UNK	C	3/4"	UNK	SEGAR. 6/22/2021: Dug @ watermain and found 3/4" copper	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26660	2408 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26685	328 S MARYKNOLL AVE	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26688	516 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26691	706 S LINDEN AVE #A	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26694	2806 HOLLY CT	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26708	1818 N CENTRAL AVE	UNK	UNK	UNK	3/4"	1/1/1965	C	3/4"	1/1/1965	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26717	411 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26740	1517 RENEE LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26743	300 N ADAMS AVE	UNK	UNK	UNK	3/4"	1/1/1973	C	3/4"	1/1/1973	SF	UNK	C	3/4"	UNK	STERTZ	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26746	311 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26749	512 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26752	715 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1978	C	1"	1/1/1978	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26755	300 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26758	212 W 28TH ST	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26787	901 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26790	1133 W IVES ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26793	1106 W STATE ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	KOWALSCHED	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26796	400 S LINDEN AVE	UNK	UNK	UNK	3/4"	1/1/1978	C	3/4"	1/1/1978	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26803	1600 W 4TH ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26809	306 S LEY AVE	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26813	422 N GALVIN AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	2007-REMOVED LEAKING CURB STOP INSTALLED NEW CURB STOP	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26816	1120 W STATE ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26833	1207 W IVES ST	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26836	1104 FAIRVIEW DR	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26841	311 N WILLOW AVE	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26868	499 E 25TH ST	UNK	UNK	UNK	4"	1/1/1968	CI-U	4"	1/1/1968	NONRES	UNK	CI-U	4"	UNK	METER IS IN PIT	Installation Record	Y	1/1/1968	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
26874	2215 S MAPLE AVE	N	UNK	UNK	2"	1/1/2010	C	2"	1/1/2010	SF	UNK	C	2"	UNK	PARKVIEW TERRACE	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26878	2215 S MAPLE AVE	UNK	UNK	UNK	4"	1/1/1982	CI-U	4"	1/1/1982	NONRES	UNK	CI-U	4"	UNK	<Null>	Installation Record	Y	1/1/1982	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
26886	425 W MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26890	1305 N PEACH AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS-WATER TAP ONLY	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26914	306 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26921	1116 W BLODGETT ST	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26924	1409 N HINMAN AVE	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26932	1000 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	SERVICE IS 8' DEEP IN MIDDLE OF ROAD	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26958	1226 W IVES ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26961	517 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1974	C	3/4"	1/1/1974	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
26964	212 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
26977	110 W UPHAM ST #A	N	C	UNK	2"	1/1/2016	C	2"	1/1/2016	NONRES	UNK	C	2"	UNK	TAP DONE ON DIP BETWEEN SECTIONS OF LINED PIPE CONN W/ HYMAX SLEEVES ON EACH END, 2" CORP W/ 4' OF COPPER FROM CORP TO EXIST. 2" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26991	1128 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
26996	1220 W STATE ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27001	1221 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27020	313 MARATHON ST	UNK	UNK	UNK	3/4"	1/1/1983	C	3/4"	1/1/1983	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27023	1801 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
27029	1104 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27032	1526 N APPLE AVE	UNK	UNK	UNK	3/4"	1/1/1970	C	3/4"	1/1/1970	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27042	317 S LEY AVE	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27045	1227 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27048	1416 S BALBOA AVE	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	SF	UNK	C	3/4"	UNK	GAFFNEY	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27052	1610 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27057	1227 W STATE ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27061	301 MAGNOLIA DR	UNK	UNK	UNK	UNK	1/1/1994	C	UNK	1/1/1994	SF	UNK	C	UNK	UNK	LOT 35	Installation Record	Y	1/1/1994	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27067	1230 W STATE ST	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27074	1608 E MCMILLAN ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27078	1616 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27081	1126 W IVES ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27087	1715 DEVINE DR	UNK	UNK	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27093	115 W MCMILLAN ST #W	UNK	DI	UNK	4"	1/1/1984	C	4"	1/1/1984	O	UNK	C	4"	UNK	NEW SERVICE TEE & HOR. OFFSET INSTALLED, PEMBER--2017, ALSO FEEDS 115/11	Installation Record	Y	1/1/1984	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
27097	405 WILDWOOD CT	N	C	UNK	3/4"	1/1/2015	C	3/4"	1/1/2015	SF	UNK	C	3/4"	UNK	2015-CONNECTED TO EXISTING 3/4" COPPER NEAR MAIN	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27101	1412 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27104	1411 N HINMAN AVE	UNK	UNK	UNK	3/4"	1/1/1986	C	3/4"	1/1/1986	SF	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27107	513 N HUME AVE	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	STARTFORD	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27110	1819 N CENTRAL AVE #A	UNK	UNK	UNK	8"	1/1/1999	DI	8"	1/1/1999	O	UNK	DI	8"	UNK	OFF E.MCMILLAN.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
27118	1617 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27121	1711 E UPHAM ST	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27150	407 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27158	1401 E 4TH ST	N	DI	UNK	6"	1/1/2003	DI	6"	1/1/2003	NONRES	UNK	DI	6"	UNK	2003: Installed 6" service w/ veterans proj. 7/9/22: Removed 6" cast coupling 6' East of wm, installed 6" valve, 7.5' - 6" dip, 6" 22.5 Bend, 16.5' C900, 6" Hymax Grip, Conn to existing 6" cast. Removed existing 6" valve in parking lot. CH, AP, JW	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
27164	2300 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27167	400 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27189	307 W MCMILLAN ST	UNK	UNK	UNK	1"	UNK	C	1"	UNK	O	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27202	1614 N APPLE AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27217	1506 N HINMAN AVE	UNK	UNK	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27223	1001 W ONSTAD DR	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27227	322 S MARYKNOLL AVE	UNK	C	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27246	121 W MCMILLAN ST #2	UNK	UNK	UNK	1 1/4"	1/1/1986	C	1 1/4"	1/1/1986	O	UNK	C	1 1/4"	UNK	INSTALLED 2.5' OF 1-1/4" COPPER FROM CORP TO EXIST. 1-1/4" COPPER--2017, PEMBER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27257	206 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	LOT 31	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27269	305 S LINCOLN AVE	UNK	C	UNK	1"	9/19/2023	C	1"	9/19/2023	SF	UNK	C	1"	UNK	9/19/23 Earth Inc installed 1" corp., 35 LF - 1" copper (wm-cs), 1" cs & box, 10 LF - 1" copper (cs - existing 3/4" copper) Project #5876 See pg. 15 of the const. report	Installation Record	Y	9/19/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27279	1501 S SCHMIDT AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27282	2709 W 5TH ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27285	500 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27288	506 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27292	1613 N CENTRAL AVE	N	CI-U	UNK	6"	UNK	CI-U	6"	UNK	NONRES	UNK	CI-U	6"	UNK	THIS ALSO FEEDS 1617, 1619 & 1621 N CENTRAL	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
27302	907 N PEACH AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27305	512 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27308	600 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27322	509 BLUEBIRD LN	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27331	1409 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27334	1415 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27337	2301 MEADOWBROOK DR	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1-1/2" LINE FROM FILLMORE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27337	2301 MEADOWBROOK DR	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	FILLMORE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27337	2301 MEADOWBROOK DR	UNK	UNK	UNK	1 1/2"	UNK	C	1 1/2"	UNK	SF	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27337	2301 MEADOWBROOK DR	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	SF	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27340	1407 N HINMAN AVE	UNK	UNK	UNK	3/4"	1/1/1987	C	3/4"	1/1/1987	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27351	1419 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27354	314 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27358	508 BLUEBIRD LN	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27361	1511 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27367	502 W MCMILLAN ST	UNK	UNK	UNK	2"	1/1/1984	C	2"	1/1/1984	NONRES	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27371	1611 S LINCOLN AVE	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27374	304 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27377	2309 MEADOWBROOK DR	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	FILLMORE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27380	2502 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27383	1505 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27386	1601 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27389	400 N GALVIN AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 7/3/79	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27396	301 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27400	316 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27403	1407 N PEACH AVE	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	NONRES	UNK	C	2"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27409	415 W MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1985	C	1"	1/1/1985	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27414	2401 MEADOWBROOK DR	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27417	816 S HAWTHORN AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27421	1504 S BALBOA AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 6/5/97.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27491	310 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP CONNECTED TO EXISTING 1" COPPER AT MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27494	608 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP, CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27499	1401 E 4TH ST	N	DI	UNK	4"	UNK	P	4"	UNK	NONRES	UNK	P	4"	UNK	2003-MEWD,INSTALLED NEW 4" VALVE.NOT TIED INTO ANY FIRE PROTECTION	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
27507	200 E UPHAM STREET	UNK	UNK	UNK	4"	1/1/1987	C	4"	1/1/1987	NONRES	UNK	C	4"	UNK	206, 206A, 206B/STRATFORD	Installation Record	Y	1/1/1987	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
27511	1306 N HUME AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27514	801 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27523	411 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27526	810 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27529	1516 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27537	1304 N HUME AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27543	1605 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27546	500 N ANTON AVE	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27550	217 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27553	1508 S BALBOA AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27556	201 N ADAMS AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27560	508 N GALVIN AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	CB LOCATION VERIFIED 7/3/97	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27566	206 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27569	1606 N CENTRAL AVE	UNK	UNK	Y	3/4"	1/1/1962	C	3/4"	1/1/1962	NONRES	UNK	C	3/4"	UNK	2000: REMOVED LEAD WIPES.	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
27573	1206 W IVES ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27579	1609 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27585	813 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27588	803 W STATE ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27591	300 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW 1" COPPER FROM MAIN TO CURB VALVE - 4' NEW COPPER TO EXISTING. 1" COPPER ON HOMEOWNERS SIDE	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27596	300 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27599	1512 S BALBOA AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27606	2400 E FILLMORE ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27614	1706 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27618	2200 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MAIN IS 12'DEEP CENTER OF ROAD	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27621	1720 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27626	1711 N APPLE AVE	N	UNK	UNK	3/4"	1/1/1988	C	3/4"	1/1/1988	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27634	307 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27640	1700 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27644	1625 N CENTRAL AVE	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	THIS SERVICE ALSO FEEDS 1625, 1627, & 1631 N. CENTRAL. 2" copper on property side	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27649	1310 N HUME AVE	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27655	1629 N CENTRAL AVE	UNK	DI	UNK	8"	1/1/1999	DI	8"	1/1/1999	NONRES	UNK	DI	8"	UNK	DOINE- OFFICE MAX	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
27658	1600 S BALBOA AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27665	1300 N HUME AVE #A	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27671	311 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HAWTHORNE	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27678	1212 W IVES ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27681	313 N SCHMIDT AVE	UNK	C	UNK	1"	6/1/2019	C	1"	6/1/2019	SF	UNK	C	1"	UNK	2019 - NEW TAP CONNECTED TO EXISTING 1" COPPER NEAR MAIN	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27684	1604 S BALBOA AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27689	1616 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27695	1001 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27700	212 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27703	1712 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27717	1403 N HINMAN AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27720	1007 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27723	1315 N HINMAN AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27735	1917 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27738	401 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27741	1612 S BALBOA AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27744	1708 S BALBOA AVE	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	30' OF 1" COPPER CONNECTED TO EXISTING 1" COPPER @ THE OLD WATERMAIN	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27753	823 S HAWTHORN AVE	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27759	1604 E MCMILLAN ST	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27765	1716 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27778	1700 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27787	1011 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	NONRES	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27790	1000 N COLUMBUS AVE	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27795	1206 W BRIARWOOD ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27801	501 S HOLLY AVE	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27805	211 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27812	123 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 12" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27812	123 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 16" OF 1" COPPER FROM CORP CONN TO EXIST 3/4" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27815	200 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27819	302 W UPHAM ST	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	NONRES	UNK	C	1"	UNK	NEW 1" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 6" OF 1" COPPER FROM CORP CONN TO EXIST 1" COPPER, EARTH--2016	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27821	405 E 17TH STREET	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	NONRES	UNK	UNK	UNK	UNK	CUT OFF BELOW GRADE.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27821	405 E 17TH STREET	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	NONRES	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27821	405 E 17TH STREET	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	NONRES	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27821	405 E 17TH STREET	UNK	C	UNK	1"	5/13/2022	C	1"	5/13/2022	NONRES	UNK	C	1"	UNK	Earth Inc. Page 11 of construction reports.	Installation Record	Y	5/13/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27821	405 E 17TH STREET	N	C	UNK	2"	5/9/2022	C	2"	5/9/2022	NONRES	UNK	C	2"	UNK	Earth Inc. Page 7 of construction reports. 12' from main to curb valve. 11' from curb valve to existing 2" copper.	Installation Record	Y	5/9/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27821	405 E 17TH STREET	UNK	C	UNK	2"	5/10/2022	C	2"	5/10/2022	NONRES	UNK	C	2"	UNK	Earth Inc. Page 8 of construction reports. STUB-OUT FOR FUTURE USE. 33' from main to curb valve. 12' from curb valve to end of stub out smashed end of copper.	Installation Record	Y	5/10/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27826	311 S LEY AVE	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27829	1206 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27832	315 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27835	303 S LINCOLN AVE	UNK	C	UNK	1"	9/21/2023	C	1"	9/21/2023	SF	UNK	C	1"	UNK	9/21/23 Earth Inc installed 1" corp., 34 LF - 1" copper (wm-cs), 1" cs & box, 9 LF - 1" copper (cs - existing 1" copper) Project #5876. See const. report pg. 16	Installation Record	Y	9/21/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27841	1708 E UPHAM ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27844	101 W 29TH ST	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
27849	1708 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27857	1216 W BRIARWOOD ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27859	217 HICKORY CT	UNK	UNK	UNK	1"	1/1/1984	C	1"	1/1/1984	SF	UNK	C	1"	UNK	RON MEYER	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27864	1600 E MCMILLAN ST	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27868	1811 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27875	309 MEADOW LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27892	2600 W 5TH ST	UNK	DI	UNK	4"	1/1/1990	DI	4"	1/1/1990	NONRES	UNK	DI	4"	UNK	GAFFNEY	Installation Record	Y	1/1/1990	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
27906	407 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27910	1607 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27914	301 S LARCH AVE	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27917	1608 S BALBOA AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27922	2211 W 5TH ST #A	UNK	UNK	UNK	2"	1/1/1990	C	2"	1/1/1990	NONRES	UNK	C	2"	UNK	GAFFNEY	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27938	307 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27945	1217 W BRIARWOOD ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27948	1222 W IVES ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27951	1006 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27955	1814 S BALBOA AVE	UNK	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	30' OF 1" COPPER CONNECTED TO EXISTING 1" COPPER @ THE OLD WATERMAIN	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27958	2209 MEADOWBROOK DR	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1-1/2" LINE FROM FILLMORE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27958	2209 MEADOWBROOK DR	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	1-1/2" LINE FROM FILLMORE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27958	2209 MEADOWBROOK DR	UNK	C	UNK	1 1/2"	UNK	C	1 1/2"	UNK	SF	UNK	C	1 1/2"	UNK	SERVES TWO HOMES	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
27965	1702 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27968	1801 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27972	1706 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27975	1701 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27978	1705 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
27981	1218 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27985	210 MEADOW LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27993	811 E HARRISON ST	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	NONRES	UNK	C	2"	UNK	DOINE-REIGEL	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
27997	1610 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28000	313 S EVERGREEN AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28003	317 S EVERGREEN AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28006	813 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28010	300 MEADOW LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28014	1701 E DOEGE ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28019	1223 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28023	1230 W BLODGETT ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28026	1701 N FIG AVENUE	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	NONRES	UNK	C	2"	UNK	REDETZKE	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28029	1215 W BLODGETT ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28037	1409 N HUME AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28043	512 E 25TH ST	UNK	C	UNK	1 1/2"	1/1/2001	C	1 1/2"	1/1/2001	NONRES	UNK	C	1 1/2"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28046	1406 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28049	1410 E FILLMORE ST	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28052	1402 E FILLMORE ST	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28061	205 S OAK AVE	UNK	DI	UNK	4"	1/1/1999	DI	4"	1/1/1999	NONRES	UNK	DI	4"	UNK	4" DIP from main to valve in bullpen; At some point transitions to 2" copper coming into Hackman Fields concession stand	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28064	1700 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28068	701 N HUME AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28071	625 N HUME AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28078	1612 N JEAN AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28081	1109 DEVINE DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28084	209 S LINDEN AVE	UNK	UNK	UNK	1"	1/1/1979	C	1"	1/1/1979	SF	UNK	C	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
28089	308 W 26TH CIRCLE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28093	1618 RENEE LN	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28096	1124 W IVES ST	UNK	UNK	UNK	1 1/4"	1/1/1996	C	1 1/4"	1/1/1996	SF	UNK	C	1 1/4"	UNK	MEYERS	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28100	812 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28105	1230 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28109	309 W 26TH CIRCLE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28112	1716 DEVINE DR	UNK	UNK	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28115	2107 N CENTRAL AVE	UNK	UNK	UNK	8"	1/1/1999	DI	8"	1/1/1999	O	UNK	DI	8"	UNK	TRIERWEILER CONST.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28123	S BALBOA AVE	UNK	C	UNK	2"	1/1/2000	P	2"	1/1/2000	NONRES	UNK	P	2"	UNK	PLASTIC IS ON CUSTOMERS SIDE.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28129	1606 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28134	103 W MCMILLAN ST	UNK	UNK	UNK	2"	1/1/2000	C	2"	1/1/2000	O	UNK	C	2"	UNK	JAKEL PLUMBING	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28140	1813 N CENTRAL AVE	UNK	UNK	UNK	2"	1/1/2000	C	2"	1/1/2000	O	UNK	C	2"	UNK	JAKEL	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28144	1231 W STATE ST	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28147	1231 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28158	1230 W BRIARWOOD ST	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
28160	407 W 2ND ST	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	NONRES	UNK	C	1"	UNK	CITY GARAGE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28167	807 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28171	1014 N COLUMBUS AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28174	1212 W BLODGETT ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28179	1601 HEIDE LN	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28192	1805 S SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28196	312 S EVERGREEN AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28199	1712 HEIDE LN	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28215	2500 S CENTRAL AVE	UNK	UNK	UNK	2"	1/1/1995	C	2"	1/1/1995	NONRES	UNK	C	2"	UNK	REIGEL PLUMBING	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28225	1014 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28228	615 N HUME AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28234	307 S EVERGREEN AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28237	2504 S OAK AVE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28243	1226 W BLODGETT ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28246	621 N HUME AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28249	1223 W BLODGETT ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28253	1227 W BLODGETT ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28262	300 W 27TH CIRCLE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28265	2114 N CENTRAL AVE #273	UNK	DI	UNK	6"	1/1/2002	DI	6"	1/1/2002	O	UNK	DI	6"	UNK		Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28268	1627 RENEE LN	UNK	UNK	UNK	1"	UNK	C	1"	UNK	SF	UNK	C	1"	UNK		Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
28274	214 W 27TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28281	2010 E BLODGETT ST	UNK	UNK	UNK	1"	1/1/1982	C	1"	1/1/1982	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
28284	1710 DEVINE DR	UNK	UNK	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28291	1716 N HUME AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	2004-REPLACED CURB VALVE(MEYER)	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28298	316 S LEY AVE	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28301	1123 W ONSTAD DR	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	FLEWELLEN	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28309	1705 MARCY CT	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28313	1205 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28319	1717 N HUME AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28325	1609 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28329	808 E VILAS ST	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
28337	1206 W STATE ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28340	1200 W STATE ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28344	1515 HEIDE LN	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28348	1200 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETZKE-NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28358	316 S EVERGREEN AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28362	1018 N COLUMBUS AVE	UNK	C	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28368	1501 N HUME AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK	SCHREINERS: DUPLEX WITH 1503	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28379	1224 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28389	1704 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28395	1613 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28398	211 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	LOT 34	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28403	1020 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28406	1224 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28409	201 MEADOW LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28412	312 S LEY AVE	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28416	1015 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28422	1116 W BRIARWOOD ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28426	307 S LEY AVE	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28429	1206 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28432	1221 W STATE ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28435	200 S LEY AVE	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28438	1216 W STATE ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28441	500 N GALVIN AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28444	1631 RENEE LN	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28447	1619 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	THE SANITARY SEWER LATERAL IS ABOVE THE WATERMAIN	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28450	1503 N HUME AVE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK	SCHREINERS: DUPLEX WITH 1501	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28454	2600 S OAK AVE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28457	207 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	LOT 33	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28461	1605 HEIDE LN	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28464	200 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	LOT 32	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
28470	610 N GALVIN AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28473	2310 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28476	801 S HAWTHORN AVE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	FLEWELLEN	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28482	1217 FAIRVIEW DR	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28485	1708 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28488	401 S EVERGREEN AVE	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28491	516 MEADOW LN	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28494	1021 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28497	1232 W IVES ST	UNK	UNK	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28500	1110 DEVINE DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28521	1301 N HINMAN AVE	UNK	DI	UNK	6"	1/1/2002	P	6"	1/1/2002	SF	UNK	P	6"	UNK	WYNDHAM SENIOR VILLAS	Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28546	601 N PINE AVE	UNK	UNK	UNK	6"	1/1/1998	DI	6"	1/1/1998	NONRES	UNK	DI	6"	UNK	VALVE BOX - REDETZKE CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28550	1600 DEVINE DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28561	1605 RENEE LN	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28582	2406 E ARNOLD ST	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN CONST.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28585	1212 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28588	2508 S OAK AVE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28593	1106 DEVINE DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28603	2808 S OAK AVE	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	ALTERNATIVE PLB.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28608	1611 RENEE LN	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28611	322 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28614	1401 E FILLMORE ST	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28617	2415 E ARNOLD ST	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN CONST.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28626	319 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28632	305 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28643	1622 RENEE LN	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28646	2416 E ARNOLD ST	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN CONSTRUCTION	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28649	2400 E ARNOLD ST	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN CONST.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28657	1227 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETZKE-NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28660	206 S LEY AVE	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28667	1612 RENEE LN	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28670	1611 N JEAN AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28673	1606 N JEAN AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28676	1605 N JEAN AVE	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28681	1617 RENEE LN	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28687	1612 W 4TH ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	STRATFORD PLBG.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28690	313 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28694	301 W 27TH CIRCLE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28699	1213 W RIDGE RD	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28702	1701 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	THE SANITARY SEWER LATERAL IS ABOVE THE WATERMAIN.	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28706	1737 N CENTRAL AVE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	JAKEL PLBG.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28711	1000 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28715	1403 E FILLMORE ST	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28718	706 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1975	C	1"	1/1/1975	SF	UNK	C	1"	UNK	STRATFORD	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
28724	1615 N HUME AVE	UNK	UNK	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28729	1218 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETZKE-NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28737	1010 N SCHMIDT AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28743	218 W 27TH ST	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK	RON MEYERS	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28748	613 N HUME AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28752	1616 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28755	1823 N CENTRAL AVE #B	UNK	UNK	UNK	8"	1/1/1999	DI	8"	1/1/1999	O	UNK	DI	8"	UNK	TO TEE, WITH VALVE ON NORTH SIDE.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28765	314 MAGNOLIA DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28768	1621 RENEE LN	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28772	2410 E ARNOLD ST	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN CONST.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28776	410 N GALVIN AVE	UNK	UNK	UNK	1"	1/1/1986	C	1"	1/1/1986	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28778	2700 S CENTRAL AVE	UNK	DI	UNK	6"	1/1/2003	DI	6"	1/1/2003	NONRES	UNK	DI	6"	UNK	2003-FIRE SERVICE TO NEW ADDITION	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28787	2116 N CENTRAL AVE	UNK	DI	UNK	10"	1/1/1999	DI	10"	1/1/1999	O	UNK	DI	10"	UNK	BACCO	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28791	2001 N CENTRAL AVE	UNK	UNK	UNK	8"	UNK	DI	8"	UNK	O	UNK	DI	8"	UNK	SHUTS OFF FIRE SERVICE & 3" POTABLE WATER	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
28797	1702 N HUME AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28800	2005 N CENTRAL AVE	UNK	UNK	UNK	2"	1/1/2000	C	2"	1/1/2000	O	UNK	C	2"	UNK	WEILER PROPERTIES	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28804	1921 N CENTRAL AVE	UNK	UNK	UNK	1 1/2"	1/1/2000	C	1 1/2"	1/1/2000	O	UNK	C	1 1/2"	UNK	DOINE / WENDYS	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28808	2300 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
28811	2306 E ARNOLD ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34029	1613 N ADAMS AVE	UNK	C	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34031	706 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 25' - 1" COPPER WITH 1"X 3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34069	1109 W 17TH ST	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	SF	UNK	C	3/4"	UNK	STRATFORD	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
34092	1001 GEORGE DR	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	STRATFORD PLMB	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34326	609 N WEBER AVE	UNK	UNK	UNK	2"	1/1/1978	C	2"	1/1/1978	NONRES	UNK	C	2"	UNK	SHUT DOWN-JUS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
34328	701 N WEBER AVE	UNK	UNK	UNK	2"	1/1/1977	C	2"	1/1/1977	NONRES	UNK	C	2"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
34400	1222 W JEFFERSON ST	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34426	608 W 17TH STREET	UNK	UNK	UNK	1 1/2"	1/1/2002	C	1 1/2"	1/1/2002	NONRES	UNK	C	1 1/2"	UNK	FLEWELLEN PLB.- CUT ONTO 4" SERVICE TO PAVILLION	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34431	1001 E 29TH STREET	UNK	UNK	UNK	6"	1/1/1997	DI	6"	1/1/1997	NONRES	UNK	DI	6"	UNK	CUT-IN VALVE- GRIESE PARK	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
34433	513 E 17TH ST WA/SEWER	UNK	DI	UNK	6"	1/1/2003	DI	6"	1/1/2003	NONRES	UNK	DI	6"	UNK	MAC PARK SPRINKERS & RESTROOMS	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
34438	902 S ASH AVE	N	C	Y	UNK	UNK	C	UNK	UNK	SF	UNK	C	UNK	UNK	Removed Lead wipe @ main & 6' of lead pipe	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
34440	308 N HINMAN AVE	UNK	C	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34478	2400 N PEACH AVE	UNK	DI	UNK	8"	1/1/2003	P	8"	1/1/2003	O	UNK	P	8"	UNK	R.VESSER JO#5361	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
34488	1615 N JEAN AVE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34510	1406 E 26TH ST	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34529	601 W 11TH ST	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34531	413 N ASH AVE	N	C	UNK	3/4"	5/29/2014	C	3/4"	1/1/1947	SF	UNK	C	C		5/30/24: Dug and removed lead gooseneck. Tapped on top. Replaced w/ 3/4" copper wm-cs. Installed new cs & box. Connected to existing 3/4" copper after cs.	Installation Record	Y	5/29/2024	Visual insp during install or repair	Field Inspection Only	Y	11/5/2016	Cross Connection Survey	
34553	454 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	CONNECTED TO 1" COPPER @ CURB VALVE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34578	2212 S PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34672	207 W 6TH ST	UNK	DI	UNK	6"	1/1/2003	DI	6"	1/1/2003	NONRES	UNK	DI	6"	UNK	JIM JAKEL PLBG.	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
34677	115 W 6TH ST	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	3/4" copper on property side	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34726	100 N SPRUCE AVE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34728	2306 S PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34730	1624 S RODDIS AVE	UNK	DI	UNK	6"	1/1/2003	DI	6"	1/1/2003	NONRES	UNK	DI	6"	UNK	CUT-IN SLEEVE	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
34752	702 N JUNO AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34753	703 N JUNO AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34759	706 N JUNO AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	BACK TO THE WEST UNDER THE MAIN.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34759	706 N JUNO AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TO THE WEST UNDER THE MAIN.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34766	2306 N PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34768	1709 DEVINE DR	UNK	UNK	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34791	411 W ARNOLD ST	N	C	UNK	1"	1/1/2011	C	1"	1/1/2011	SF	UNK	C	1"	UNK	PEMBER. 1" COPPER OF PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34810	2202 S PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34835	1710 W ARLINGTON ST	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34844	1001 TREMMEL CT	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
34862	1219 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REDETZKE-NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34885	1401 N HUME AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34889	1216 E 4TH ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	2003-STUB-OUT, NEW 1" CORP,COPPER,VALVE,BOX. COPPER RAN 10' S OF VALVE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34897	1700 S LAEMLE AVE	UNK	UNK	UNK	2"	1/1/1971	C	2"	1/1/1971	NONRES	UNK	C	2"	UNK	4 3/4" TAPS TO A 2" LINE. 2012- OLD CURB VALVE DOEN'T WORK. INSTALLED NEW VALVE W/ BOX. NEW VALVE IS 1'W OF OLD VALVE.	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
34924	316 W IVES ST #A	UNK	C	UNK	1 1/2"	1/1/2004	P	1 1/2"	1/1/2004	SF	UNK	P	1 1/2"	UNK	STRATFORD PLBG. 27' S OF CURB VALVE COPPER ENDS & POLY BEGINS TO BLDG.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34931	609 N HUME AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34933	1511 S TAMARACK AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	REIGEL PLBG.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34937	1709 HEIDE LN	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	THE SANITARY SEWER LATERAL IS ABOVE THE WATERMAIN.	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
34993	615 S WASHINGTON AVE	N	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	SF	UNK	C	1"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
34995	605 W 11TH ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35005	1302 N CENTRAL AVE	UNK	CI-U	UNK	6"	UNK	CI-U	6"	UNK	NONRES	UNK	CI-U	6"	UNK	LOCATION VERIFIED 1/97	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
35015	1811 PECAN PKWY	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35025	307 W 27TH CIRCLE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35046	1200 S ADAMS AVE	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	SF	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35052	307 W 26TH CIRCLE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35054	407 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35065	1702 W ARLINGTON ST	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35070	1113 DEVINE DR	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35072	705 S CENTRAL AVE	UNK	DI	UNK	8"	1/1/2015	DI	8"	1/1/2015	NONRES	UNK	DI	8"	UNK	SERVES STRIP MALL ON SOUTH END OF PROP. 8" AFC VALVE WITH 8" DIP ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
35092	506 S CEDAR AVE #A	N	C	Y	3/4"	UNK	C	3/4"	UNK	SF	UNK	C	3/4"	UNK	REMOVED WIPE AT THE MAIN 3/17/95. 2022: Removed lead wipes, 3/4" copper from main to house. 3/4" curb valve	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
35100	712 E 21ST ST	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35103	1006 W 17TH ST	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35105	301 W CLEVELAND ST	N	C	UNK	1"	7/30/2020	C	1"	7/30/2020	SF	UNK	C	1"	UNK	EARTH INC. installed copper from main to cs, STRATFORD PLBG. replaced/installed new service from cs to meter (Pg. 38 of Const. Report)	Installation Record	Y	7/30/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35113	1105 DEVINE DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35209	641 S CENTRAL AVENUE	UNK	DI	UNK	8"	1/1/2004	DI	8"	1/1/2004	NONRES	UNK	DI	8"	UNK	NIKOLAY CONST. SERVICE IS OFF 6TH ST	Installation Record	Y	1/1/2004	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
35260	1212 W 5TH ST	UNK	UNK	UNK	3/4"	1/1/1964	C	3/4"	1/1/1964	SF	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
35264	103 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2001	C	1 1/2"	1/1/2001	NONRES	UNK	C	1 1/2"	UNK	MEWD. 1-1/2" copper on property side	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35271	100 N MAPLE AVE	UNK	DI	UNK	4"	1/1/2017	DI	4"	1/1/2017	NONRES	UNK	DI	4"	UNK	NEW TEE, SLEEVE IS 2.5' W OF TEE-2017	Installation Record	Y	1/1/2017	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
35288	611 E 29TH ST	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35290	209 E DOWNWIND DR	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	NONRES	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35296	1007 TREMMEL CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35299	302 S LINCOLN AVE	UNK	C	UNK	1"	9/22/2023	C	1"	9/22/2023	SF	UNK	C	1"	UNK	9/22/23 Earth Inc installed 1" corp., 24 LF - 1" copper (wm-cs), 1" cs & box, connected to existing 1" copper @ the cs. Project #5876. See pg. 16 of the const. report	Installation Record	Y	9/22/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35320	209 WILDERNESS VIEW DR	UNK	DI	UNK	6"	1/1/2003	DI	6"	1/1/2003	O	UNK	DI	6"	UNK	EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
35339	1020 TREMMEL CT	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35344	2508 HAMUS DR	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35346	1700 MARCY CT	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35358	1604 DEVINE DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35398	1008 W COLONIAL ST	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35439	400 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35442	1701 N HUME AVE	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35444	1703 N HUME AVE	UNK	UNK	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35446	2500 S OAK AVE	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35448	304 W 27TH CIRCLE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35456	205 S OAK AVENUE	UNK	C	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	NONRES	UNK	C	3/4"	UNK	REIGEL. 1-1-2020 J&R VACUUM EXCAVATED AT EOP FOUND 3/4" COPPER 6'9" DEEP; MILLER RESTROOMS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
35456	205 S OAK AVENUE	UNK	C	UNK	1 1/2"	1/1/2004	C	1 1/2"	1/1/2004	NONRES	UNK	C	1 1/2"	UNK	2004-SCHREINER	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35494	415 E 20TH ST	UNK	UNK	UNK	1"	1/1/1980	C	1"	1/1/1980	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
35577	1511 E 4TH ST	UNK	DI	UNK	8"	1/1/2005	DI	8"	1/1/2005	NONRES	UNK	DI	8"	UNK	OFF WILLOW	Installation Record	Y	1/1/2005	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
35593	3015 E 22ND ST	UNK	C	UNK	1 1/2"	1/1/2004	C	1 1/2"	1/1/2004	NONRES	UNK	C	1 1/2"	UNK	GAFFNEY PLBG. 1" copper on property side	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35675	2412 S FELKER AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35711	1225 E 18TH ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	SF	UNK	C	1"	UNK	GAFFNEY PLBG.	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35737	2814 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35743	411 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35785	2109 W SPENCER ST	UNK	DI	UNK	4"	1/1/2005	P	4"	1/1/2005	O	UNK	P	4"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
35791	1525 W ADLER RD	UNK	UNK	UNK	3/4"	1/1/1977	C	3/4"	1/1/1977	SF	UNK	C	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
35863	3111 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35892	1613 DEVINE DR	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	REDETZE	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
35895	3009 W HUETTER ST	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43895	3106 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	2005-CONNECTED TO EXISTING 3/4 COPPER-BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43899	2515 W VETERANS PKWY	UNK	C	UNK	2"	1/1/2005	C	2"	1/1/2005	O	UNK	C	2"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43902	108 W 9TH ST	N	DI	UNK	6"	UNK	DI	6"	UNK	NONRES	UNK	DI	6"	UNK	SERVICE ALSO FEEDS 110 W 9TH	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
43924	2411 E FOREST ST	UNK	C	UNK	2"	1/1/2004	C	2"	1/1/2004	NONRES	UNK	C	2"	UNK	R. VESSTER	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43958	2412 E FOREST ST	UNK	UNK	UNK	1 1/2"	1/1/1991	C	1 1/2"	1/1/1991	NONRES	UNK	C	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43972	2501 E FOREST ST	UNK	C	UNK	2"	1/1/2004	C	2"	1/1/2004	NONRES	UNK	C	2"	UNK	R. VESSTER	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43978	2909 W MANN ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43980	3000 W HUETTER ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43983	3010 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43989	1501 W ARLINGTON ST	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STRATFORD PLBG.	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43992	808 E BLODGETT ST	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	SF	UNK	C	1"	UNK	3' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN STREET	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
43998	2014 BUTTERNUT PKWY	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44000	1218 E 4TH ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-STUB-OUT, COPPER RAN 10' W CURB VALVE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44002	2726 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44005	3014 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44007	2521 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44014	1905 W SPENCER ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44027	1114 DEVINE DR	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	SF	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44054	1613 E CLEVELAND ST	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44065	3029 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44079	3009 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44081	2716 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44083	817 S HAWTHORN AVE	UNK	UNK	UNK	1"	1/1/1987	C	1"	1/1/1987	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44086	1108 W 8TH ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	SF	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44088	3013 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44093	3125 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44095	3017 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44107	1710 N CENTRAL AVE	UNK	C	UNK	2"	1/1/2005	C	2"	1/1/2005	NONRES	UNK	C	2"	UNK	2005 SERVICE INSULATED FROM STORM TO CURB BOX. 2" copper on property side	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
44119	3111 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44144	3916 S BUSINESS PARK AVE	UNK	DI	UNK	6"	1/1/2005	DI	6"	1/1/2005	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2005	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
44156	2625 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44161	1812 SAVANNAH CIRCLE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44163	1814 SAVANNAH CIRCLE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44166	164 S CENTRAL AVE #A	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44178	1901 W SPENCER ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44221	309 W 27TH CIRCLE	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44772	1911 N CENTRAL AVE	UNK	UNK	UNK	6"	1/1/1999	DI	6"	1/1/1999	O	UNK	DI	6"	UNK	VALVE. VALVE IS RODDED TO TEE.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
44789	2601 E BECKER RD	N	C	UNK	1"	1/1/2005	C	1"	1/1/2005	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44791	300 W 28TH CIRCLE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	STEEN JO# 5349	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44797	709 E 2ND ST #A	N	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003: NEW 1" CORP,COPPER,VALVE,BOX,3/4" COPPER INSIDE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44801	2311 E FOREST ST	UNK	C	UNK	2"	1/1/2005	C	2"	1/1/2005	NONRES	UNK	C	2"	UNK	R. VESSER	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44816	1704 MARCY CT	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44820	2518 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44820	2518 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44829	2001 W SPENCER ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44835	204 N WALNUT AVE	N	C	UNK	3/4"	1/1/2019	P	3/4"	1/1/2019	SF	UNK	P	3/4"	UNK	INSTALLED 3/4" COPPER MAIN TO CURB VALVE. CUSTOMER SIDE IS 3/4" PLASTIC. SERVED OFF 4" WATER MAIN	Installation Record	Y	1/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44879	101 W MCMILLAN ST SUITE 1A	UNK	UNK	UNK	6"	1/1/2000	DI	6"	1/1/2000	O	UNK	DI	6"	UNK	JAKEL PLUMBING	Installation Record	Y	1/1/2000	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
44909	1645 N CENTRAL AVE	N	C	UNK	2"	1/1/2005	C	2"	1/1/2005	NONRES	UNK	C	2"	UNK	MEYER- TAPPED OF PEACH	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44935	410 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44937	510 N PALMETTO AVE	UNK	P	UNK	6"	UNK	DI	6"	UNK	NONRES	UNK	DI	6"	UNK	See pg. 9 of the contruction report.	Installation Record	Y		Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
44948	3004 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44979	3120 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44982	3214 MANNVILLE LANE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
44991	2613 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45006	3302 FREY COURT	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45008	3101 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45012	819 W NORTH ST	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45017	1807 PRAIRIE DR	UNK	C	UNK	2"	1/1/2006	C	2"	1/1/2006	O	UNK	C	2"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45023	2300 E FOREST ST	UNK	C	UNK	2"	1/1/2005	C	2"	1/1/2005	NONRES	UNK	C	2"	UNK	R.VESSSER	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45050	2515 S MAPLE AVE	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	SERVICE COMES OFF WATERMAIN TO NORTH EAST OF BLDG.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
45061	1911 W SPENCER ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45066	3115 W VETERANS PARKWAY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45068	3110 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45108	407 W PARK ST	UNK	UNK-LG	UNK	UNK	1/1/1928	C	UNK	1/1/1928	SF	UNK	C	C		3/4" Copper on property side via Email from customer	Installation Record	N			Field Inspection Only	Y	5/5/2015	Cross Connection Survey	
45112	1214 E 4TH ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	SF	UNK	C	1"	UNK	2003-NEW 1" CORP,COPPER,VALVE,BOX. RAN COPPER 10' S OF CURB VALVE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45115	2220 N CENTRAL AVE	UNK	DI	UNK	8"	1/1/2006	DI	8"	1/1/2006	O	UNK	DI	8"	UNK	CALS PLBG. 8" DIP on property side	Installation Record	Y	1/1/2006	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
45119	1809 SAVANNAH CIRCLE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45133	708 E 21ST ST	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45323	3029 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45325	2209 W SPENCER ST	UNK	DI	UNK	8"	1/1/2005	UNK	8"	1/1/2005	O	UNK	UNK	8"	UNK	STUB-OUT 54' E OF VALVE	Installation Record	Y	1/1/2005	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
45329	1807 SAVANNAH CIRCLE	UNK	C	UNK	1"	1/1/2018	UNK	1"	1/1/2018	O	UNK	UNK	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45331	1214 S OAK AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	NONRES	UNK	C	1"	UNK	2006-NEW TAP W/SADDLE	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45362	710 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45384	2916 S CHERRY AVE	UNK	DI	UNK	6"	1/1/2005	DI	6"	1/1/2005	NONRES	UNK	DI	6"	UNK	NIKOLAY	Installation Record	Y	1/1/2005	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
45448	1826 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45450	1824 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	REDETZKY	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45508	3124 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45512	1709 N HUME AVE	UNK	UNK	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45526	400 W 29TH ST	UNK	C	UNK	2"	1/1/2006	C	2"	1/1/2006	NONRES	UNK	C	2"	UNK	NIKOLAY	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45546	2308 S HUME AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	NONRES	UNK	C	1"	UNK	RON MEYER & SON	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45563	307 W 28TH CIRCLE	UNK	C	UNK	1"	1/1/2003	P	1"	1/1/2003	SF	UNK	P	1"	UNK	STEEN JO#5349	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45568	905 TINY TIGERS CT	UNK	DI	UNK	6"	1/1/2006	DI	6"	1/1/2006	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
45574	401 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45574	401 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45581	2312 N CENTRAL AVE	UNK	DI	UNK	6"	1/1/2006	UNK	6"	1/1/2006	O	UNK	UNK	6"	UNK	CUT-IN VALVE DAVIES WATER	Installation Record	Y	1/1/2006	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
45613	200 BLUEBIRD LN	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	SF	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45622	1835 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45627	1920 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	STUB-OUT 15'	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45629	1802 W ARLINGTON ST	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45653	700 E 3RD ST	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	2003-EARTH. NEW 1" CORP,COPPER,VALVE,BOX. *STUB-OUT*	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45674	1833 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45680	2000 N LINCOLN AVE #A	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45686	3006 W MANN ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45725	1233 W BLODGETT ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	SF	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45728	3107 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45737	1922 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 13' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45741	2007 S NIKOLAI AVE	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	NONRES	UNK	C	1"	UNK	REIGEL PLBG.	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45750	1107 WILDFLOWER DR	UNK	C	UNK	1"	6/22/2006	UNK	1"	6/22/2006	O	UNK	UNK	1"	UNK	REDETZKE. 1" Copper ran 16' past curb box	Installation Record	Y	6/22/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45758	1831 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45878	303 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45880	306 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45913	2301 W VETERANS PKWY	UNK	C	UNK	2"	1/1/2005	C	2"	1/1/2005	O	UNK	C	2"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45915	200 N PINE AVE	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	SF	UNK	C	1"	UNK	2007- ABANDONED 3/4" CORP 3'S OF 1" CORP.	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45930	2713 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45932	1705 N HUME AVE	UNK	C	UNK	1"	1/1/1993	C	1"	1/1/1993	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45947	2100 S PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
45949	3020 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46008	2501 E 21ST ST	UNK	UNK	UNK	4"	1/1/1988	DI	4"	1/1/1988	NONRES	UNK	DI	4"	UNK	REIGEL	Installation Record	Y	1/1/1988	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46018	407 N APPLE AVE	N	C	UNK	1"	1/1/2007	UNK	1"	1/1/2007	SF	UNK	UNK	1"	UNK	REIGEL PLBG.	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46029	808 E 25TH ST	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	NORTHDALE	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46041	1707 W SPENCER ST	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46049	2200 N LINCOLN AVE	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	ATTACHED TO 3/4 COPPER 7' FROM CURB VALVE	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46059	1710 W SPENCER ST	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46064	717 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46082	1417 W MCMILLAN ST	UNK	DI	UNK	6"	1/1/2007	DI	6"	1/1/2007	O	UNK	DI	6"	UNK	12X6 TEE	Installation Record	Y	1/1/2007	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46084	404 W DOEGE ST	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	SF	UNK	C	3/4"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
46087	701 W KALSCHED ST	UNK	DI	UNK	8"	1/1/1975	DI	8"	1/1/1975	NONRES	UNK	DI	8"	UNK	THIS VALVE IS BURIED ABOUT 2'. ANOTHER VALVE IS 12'N	Installation Record	Y	1/1/1975	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46095	1137 W RIDGE RD	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46104	1832 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46110	2615 E 29TH ST	N	DI	UNK	8"	1/1/2007	P	8"	1/1/2007	NONRES	UNK	P	8"	UNK	PRECISION GRADING & UTILITIES	Installation Record	Y	1/1/2007	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46127	1830 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
46140	210 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	P	1 1/2"	1/1/2009	NONRES	UNK	P	1 1/2"	UNK	CONNECTED TO 1-1/2" PLASTIC 2'W OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46157	2201 S NIKOLAI AVE	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	NONRES	UNK	P	1"	UNK	SUDA PLBG.	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46160	1507 S LAEMLE AVE	UNK	UNK	UNK	3/4"	1/1/1979	P	3/4"	1/1/1979	NONRES	UNK	P	3/4"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
46195	2100 N LINCOLN AVE	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46208	1806 W SPENCER ST	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	O	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46217	1707 E 4TH ST	UNK	UNK	UNK	4"	1/1/1991	DI	4"	1/1/1991	NONRES	UNK	DI	4"	UNK	RON MEYERS	Installation Record	Y	1/1/1991	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46219	2810 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46231	2403 S PALMETTO AVE	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	SF	UNK	C	1"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
46245	2405 S PALMETTO AVE	N	C	UNK	1"	1/1/2008	UNK	1"	1/1/2008	SF	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46288	3033 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46301	401 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE WERE IT IS CAPPED. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46303	426 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	C	1 1/2"	1/1/2009	NONRES	UNK	C	1 1/2"	UNK	CONNECTED TO 2" COPPER INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46322	1902 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 13' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46328	1809 W SPENCER ST	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	O	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46343	2420 E ARNOLD ST	UNK	C	UNK	1"	1/1/2002	P	1"	1/1/2002	SF	UNK	P	1"	UNK	STEEN CONSTRUCTION	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46348	405 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46352	2108 N LINCOLN AVE	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	O	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46363	2206 N LINCOLN AVE	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	O	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46369	2304 N LINCOLN AVE	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46376	1409 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46384	2901 W 5TH ST	UNK	C	UNK	2"	1/1/2005	C	2"	1/1/2005	NONRES	UNK	C	2"	UNK	REDETZKY	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46397	808 E GRANT ST	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	NONRES	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46401	921 W ARNOLD ST	UNK	C	UNK	1"	1/1/2002	P	1"	1/1/2002	SF	UNK	P	1"	UNK	*STUB-OUT* NEW 1" CORP, CURBVALVE,COPPER	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46409	1704 N PEACH AVE	UNK	DI	UNK	4"	1/1/2008	DI	4"	1/1/2008	NONRES	UNK	DI	4"	UNK	<Null>	Installation Record	Y	1/1/2008	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46433	3013 W MANN ST	UNK	C	UNK	1 1/2"	1/1/2005	UNK	1 1/2"	1/1/2005	O	UNK	UNK	1 1/2"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46441	2116 SHORTESS DR	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46443	1231 FAIRVIEW DR	UNK	C	UNK	1"	1/1/1989	P	1"	1/1/1989	SF	UNK	P	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46454	2005 W SPENCER ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46470	710 W MCMILLAN ST	N	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	NEW COPPER FROM MAIN, 5' PAST SIDEWALK	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46496	3023 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46548	2206 S PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46559	1012 N CENTRAL AVE	UNK	UNK	UNK	1"	1/1/1979	DI	1"	1/1/1979	NONRES	UNK	DI	1"	UNK	6" DIP on property side	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
46559	1012 N CENTRAL AVE	UNK	UNK	UNK	1 1/2"	1/1/1981	DI	1 1/2"	1/1/1981	NONRES	UNK	DI	1 1/2"	UNK	MEYERS. 6" DIP on property side	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
46559	1012 N CENTRAL AVE	UNK	DI	UNK	6"	1/1/2009	DI	6"	1/1/2009	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46577	2711 S WITTMAN AVE	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46580	2707 S WITTMAN AVE	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46585	700 E 21ST ST	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46596	1906 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	P	1"	1/1/2006	O	UNK	P	1"	UNK	STUB-OUT 16'	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46608	1517 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46614	230 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	CONNECTED TO 1" COPPER @ BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46622	405 E 17TH ST	UNK	C	UNK	2"	6/23/2022	P	2"	6/23/2022	O	UNK	P	2"	UNK	Pg. 19 of construction report. Earth Inc. installed 2" corp., 2" copper, 2" cs & box. Conn. to existing 2" poly, 62' after the cs. Feeds Animal Wash Bay	Installation Record	Y	6/23/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46624	1545 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46661	1801 W SPENCER ST	UNK	C	UNK	1"	1/1/2007	P	1"	1/1/2007	O	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46700	801 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	C	1 1/2"	1/1/2009	NONRES	UNK	C	1 1/2"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46713	1207 N CENTRAL AVE	UNK	UNK	UNK	1"	1/1/1974	UNK	1"	1/1/1974	NONRES	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1974	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
46721	309 W CLEVELAND ST	UNK	C	UNK	1"	7/29/2020	P	1"	7/29/2020	SF	UNK	P	1"	UNK	Earth INC. installed copper from main to cs, 3' - 1" copper past cs to connect to existing 1" Poly (Meyers 2009) (Pg. 28 & 37 of Const. Report)	Installation Record	Y	7/29/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46723	311 W CLEVELAND ST	UNK	C	UNK	1"	7/29/2020	P	1"	7/29/2020	SF	UNK	P	1"	UNK	Earth INC. installed copper from main to cs, 9' - 1" copper past cs to connect to existing 1" Poly (Meyers 2009) (Pg. 28 & 37 of Const. Report)	Installation Record	Y	7/29/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46732	1701 W SPENCER ST	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46738	2617 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46744	1023 S LINCOLN AVE	UNK	C	UNK	1"	1/1/2009	P	1"	1/1/2009	SF	UNK	P	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46753	813 S LINCOLN AVE	N	C	UNK	1"	1/1/2009	C	1"	1/1/2009	SF	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46769	1108 E BECKER RD	UNK	C	UNK	1"	9/21/2022	P	1"	9/21/2022	SF	UNK	P	1"	UNK	Pg. 14 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 1" poly after cs.	Installation Record	Y	9/21/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46771	406 E 19TH ST	UNK	UNK	UNK	1"	1/1/2000	P	1"	1/1/2000	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46785	113 W 6TH ST	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	NONRES	UNK	C	1"	UNK	2009-CURB BOX VERIFIED. ATTACHED TO 3/4" COPPER 2' PAST VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46794	1911 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	STUB-OUT 15' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46810	1524 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46817	3500 AIRPARK RD	UNK	UNK	UNK	1"	1/1/1983	P	1"	1/1/1983	NONRES	UNK	P	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
46823	1900 W SPENCER ST	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	GAFFNEY PLUMBING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46895	1307 N ST JOSEPH AVE	UNK	DI	UNK	6"	1/1/2009	UNK	6"	1/1/2009	NONRES	UNK	UNK	6"	UNK	10x10 TEE @ MAIN WITH 10x6 REDUCER ATTACHED	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46899	1920 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	P	1"	1/1/2006	O	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46902	901 COMMERCE DR	UNK	DI	UNK	6"	1/1/2009	DI	6"	1/1/2009	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46908	408 N HUME AVE	UNK	C	UNK	1"	1/1/2010	C	1"	1/1/2010	SF	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46961	2605 S APPLE AVE	UNK	C	UNK	1"	4/16/2010	P	1"	4/16/2010	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	4/16/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46980	1908 W SPENCER ST	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
46991	1204 W MCMILLAN ST	UNK	DI	UNK	8"	1/1/2010	DI	8"	1/1/2010	NONRES	UNK	DI	8"	UNK	<Null>	Installation Record	Y	1/1/2010	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
46995	1515 N ST JOSEPH AVE	UNK	DI	UNK	10"	1/1/1998	DI	10"	1/1/1998	NONRES	UNK	DI	10"	UNK	10" REDUCED TO 6"	Installation Record	Y	1/1/1998	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47003	1617 DEVINE DR	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	REDETZE	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47004	1210 E 4TH ST	UNK	C	UNK	1"	1/1/2003	P	1"	1/1/2003	SF	UNK	P	1"	UNK	2003-STUB-OUT,NEW 1" CORP,COPEPR,VALVE,BOX. RAN COPPER 10' S. OF CURB VALVE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47025	1910 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	P	1"	1/1/2006	O	UNK	P	1"	UNK	STUB-OUT 14' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47034	2112 SHORTESS DR	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47042	3001 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47063	1929 E 26TH ST	UNK	DI	UNK	6"	1/1/2010	DI	6"	1/1/2010	NONRES	UNK	DI	6"	UNK	REIGEL PLBG.	Installation Record	Y	1/1/2010	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47083	2510 E 34TH ST	UNK	DI	UNK	6"	1/1/2009	P	6"	1/1/2009	NONRES	UNK	P	6"	UNK	<Null>	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47096	325 W MCMILLAN ST	UNK	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	O	UNK	C	3/4"	UNK	KALSCHED	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
47114	1210 S OAK AVE	UNK	C	UNK	1"	UNK	C	1"	UNK	NONRES	UNK	C	1"	UNK	2006-NEW TAP W/SADDLE	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
47116	2001 E 29TH ST	UNK	UNK	UNK	8"	1/1/1979	DI	8"	1/1/1979	NONRES	UNK	DI	8"	UNK	<Null>	Installation Record	Y	1/1/1979	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47118	2105 W SPENCER ST	UNK	C	UNK	1"	1/1/2010	C	1"	1/1/2010	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47127	3616 DOWNWIND DR	UNK	DI	UNK	6"	1/1/2010	P	6"	1/1/2010	NONRES	UNK	P	6"	UNK	<Null>	Installation Record	Y	1/1/2010	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47173	1027 W MCMILLAN ST	UNK	DI	UNK	8"	1/1/1994	DI	8"	1/1/1994	O	UNK	DI	8"	UNK	CURB VALVE WAS VALVE#567	Installation Record	Y	1/1/1994	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47177	511 N VINE AVE	UNK	C	UNK	1"	7/25/2023	P	1"	7/25/2023	NONRES	UNK	P	1"	UNK	Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 1" poly. See sheet 5 of the construction report	Installation Record	Y	7/25/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47180	1000 W 11TH ST	UNK	DI	UNK	6"	1/1/2010	DI	6"	1/1/2010	NONRES	UNK	DI	6"	UNK	SERVICE OFF OF 14TH ST. HOUSE OF THE DOVE	Installation Record	Y	1/1/2010	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47225	700 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	P	1"	1/1/2000	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47263	1521 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47281	1537 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47357	2108 SHORTESS DR	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47434	1529 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	P	1"	1/1/2008	SF	UNK	P	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
47446	1907 S LAEMLE AVE	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	NONRES	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47451	209 W 4TH ST	UNK	C	Y	3/4"	7/10/2018	C	3/4"	7/10/2018	SF	UNK	C	3/4"	UNK	ALL LEAD REMOVED AND REPLACED WITH 3/4" COPPER FROM MAIN TO HOUSE, NEW CURB STOP & BOX ALSO INSTALLED	Installation Record	Y	7/10/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47461	1517 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	P	1"	1/1/2008	SF	UNK	P	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47490	207 W 14th ST	UNK	C	UNK	1"	1/1/2011	P	1"	1/1/2011	SF	UNK	P	1"	UNK	1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47504	1010 E VETERANS PKWY	UNK	C	UNK	2"	1/1/2011	P	2"	1/1/2011	NONRES	UNK	P	2"	UNK	2" POLY PROP. SIDE-MEYER	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47511	E KALSCHED-NORTH SIDE	N	UNK	UNK	4"	1/1/2002	DI	4"	1/1/2002	SF	UNK	DI	4"	UNK	TAPPED OFF NORTH PEACH	Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47513	2 S WILLOW AVE	UNK	C	UNK	2"	1/1/2011	C	2"	1/1/2011	O	UNK	C	2"	UNK	CN RAILROAD	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47515	2017 W SPENCER ST	UNK	C	UNK	1"	1/1/2011	P	1"	1/1/2011	O	UNK	P	1"	UNK	1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47538	507 S PEACH AVE	UNK	UNK	UNK	UNK	UNK	P	UNK	UNK	SF	UNK	P	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
47618	217 W MCMILLAN ST	UNK	DI	UNK	6"	1/1/2011	DI	6"	1/1/2011	O	UNK	DI	6"	UNK	NEW 12X6 SERVICE TEE, 1.5' OF 6" DIP TO SLEEVE--2017, PEMBER, SEE HYPERLINK.	Installation Record	Y	1/1/2011	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47622	2522 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47641	311 N HINMAN AVE	UNK	C	UNK	1"	1/1/1989	UNK	1"	1/1/1989	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47654	300 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47693	714 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47722	701 E 2ND ST	UNK	C	UNK	1"	1/1/2003	P	1"	1/1/2003	SF	UNK	P	1"	UNK	STUB-OUT	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47729	1549 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47737	3117 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47747	1517 N OAK AVE	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	NONRES	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47752	709 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	P	1"	1/1/2000	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47763	310 N ST JOSEPH AVE	N	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	SF	UNK	C	1"	UNK	NEW 1" CORP & 1" CURB STOP	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47787	2502 N CENTRAL AVE	UNK	C	UNK	1"	1/1/2012	P	1"	1/1/2012	O	UNK	P	1"	UNK	SERVICE INSTALLED W/ SADDLE ON MAIN	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47791	404 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47826	306 W 28TH CIRCLE	UNK	C	UNK	1"	1/1/2003	P	1"	1/1/2003	SF	UNK	P	1"	UNK	STEEN JO # 5349	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47833	2510 N CENTRAL AVE	UNK	C	UNK	1"	1/1/2012	P	1"	1/1/2012	O	UNK	P	1"	UNK	INSTALLED W/ SADDLE ON MAIN	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47837	2101 W SPENCER ST	UNK	C	UNK	1"	1/1/2011	P	1"	1/1/2011	O	UNK	P	1"	UNK	1" PLASTIC ON PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47846	2805 S WITTMAN AVE	UNK	C	UNK	1"	1/1/2012	P	1"	1/1/2012	SF	UNK	P	1"	UNK	1" PLASTIC INSTALLED ON PROP. SIDE	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47889	409 E COMMERCE DRIVE	UNK	DI	UNK	6"	1/1/2012	UNK	6"	1/1/2012	NONRES	UNK	UNK	6"	UNK	ADVANCED CONCRETE	Installation Record	Y	1/1/2012	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47895	1809 E MCMILLAN ST	UNK	C	UNK	1"	1/1/1987	C	1"	1/1/1987	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47904	504 FAIRVIEW CT	UNK	C	UNK	1"	1/1/2012	UNK	1"	1/1/2012	SF	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
47910	3800 S BUSINESS PARK AVE	UNK	DI	UNK	6"	1/1/1997	DI	6"	1/1/1997	NONRES	UNK	DI	6"	UNK	1998	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47959	2807 S APPLE AVE	UNK	DI	UNK	4"	1/1/2012	P	4"	1/1/2012	NONRES	UNK	P	4"	UNK	4" PLASTIC OF PROP. SIDE	Installation Record	Y	1/1/2012	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
47999	2110 S PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48105	1022 S LINCOLN AVE	UNK	C	UNK	1"	1/1/2013	P	1"	1/1/2013	NONRES	UNK	P	1"	UNK	1" PLASTIC CUSTOMER SIDE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48118	2623 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48139	103 W KALSCHED ST	UNK	C	UNK	1"	1/1/2013	UNK	1"	1/1/2013	NONRES	UNK	UNK	1"	UNK	SERVICE FOR COFFEE CABIN	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48157	1201 S MAPLE AVE	N	C	UNK	1"	9/24/2013	UNK	1"	9/24/2013	SF	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	9/24/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48173	301 W 28TH CIRCLE	UNK	C	UNK	1"	1/1/2003	UNK	1"	1/1/2003	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48175	1540 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48177	1608 DEVINE DR	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	REDETZE	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48197	240 S CENTRAL AVE	UNK	C	UNK	2"	1/1/2009	C	2"	1/1/2009	NONRES	UNK	C	2"	UNK	INSTALLED 2" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48206	1101 N CENTRAL AVE	UNK	DI	UNK	6"	1/1/2013	DI	6"	1/1/2013	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2013	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
48236	1501 W MCMILLAN ST	UNK	C	UNK	2"	1/1/2002	C	2"	1/1/2002	O	UNK	C	2"	UNK		Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48259	705 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48263	1919 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48264	1416 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48317	1506 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48346	1501 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48356	505 E DEPOT ST	UNK	DI	UNK	6"	1/1/2013	DI	6"	1/1/2013	NONRES	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2013	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
48368	2809 S WITTMAN AVE	UNK	C	UNK	1"	1/1/2012	P	1"	1/1/2012	SF	UNK	P	1"	UNK	1" PLASTIC INSTALLED ON PROP. SIDE	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48428	1907 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48497	1651 N CENTRAL AVENUE	UNK	UNK	UNK	6"	1/1/1988	DI	6"	1/1/1988	NONRES	UNK	DI	6"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
48511	2313 W 5TH ST	UNK	DI	UNK	6"	1/1/2014	DI	6"	1/1/2014	NONRES	UNK	DI	6"	UNK	CUT-IN VALVE WITH MJ STAINLESS SLEEVE. 6" DIP on property side	Installation Record	Y	1/1/2014	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
48512	1524 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48512	1524 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48584	117 W 11TH ST	N	C	UNK	3/4"	1/1/2006	C	3/4"	1/1/2006	SF	UNK	C	3/4"	UNK	2006-NEW COPPER FROM CORP TO NEW CURB-STOP AND BOX	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48599	1606 N ST JOSEPH AVE	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	NONRES	UNK	C	3/4"	UNK	SCHULTZ	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
48599	1606 N ST JOSEPH AVE	UNK	DI	UNK	6"	1/1/2013	DI	6"	1/1/2013	NONRES	UNK	DI	6"	UNK	CUT-IN SS SLEEVE WITH MJ. X MJ. AFC VALVE	Installation Record	Y	1/1/2013	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
48601	1521 W ADLER RD	UNK	C	UNK	1"	1/1/2014	UNK	1"	1/1/2014	SF	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48628	1536 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	NONRES	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48632	1700 N CENTRAL AVE	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	NONRES	UNK	UNK	3/4"	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
48632	1700 N CENTRAL AVE	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	NONRES	UNK	C	3/4"	UNK	THIS SERVICE FEEDS BOTH THE BANK AND THE COFFEE SHOP.	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
48637	209 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48653	406 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2003	UNK	1"	1/1/2003	SF	UNK	UNK	1"	UNK	A-1	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48667	2614 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48691	310 W 28TH CIRCLE	UNK	C	UNK	1"	1/1/2003	UNK	1"	1/1/2003	SF	UNK	UNK	1"	UNK	STEEN JO#5349	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48726	1525 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48734	2116 N PEACH AVE	UNK	C	UNK	1"	1/1/2014	P	1"	1/1/2014	O	UNK	P	1"	UNK	IN DRIVEWAYS SOUTH SIDE	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48751	911 N CENTRAL AVE	UNK	C	UNK	2"	UNK	C	2"	UNK	NONRES	UNK	C	2"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
48819	417 E 29TH STREET	UNK	DI	UNK	8"	1/1/1999	DI	8"	1/1/1999	NONRES	UNK	DI	8"	UNK	8" FIRE SERVICE	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
48822	2608 S HUME AVE	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	NONRES	UNK	UNK	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
48894	805 S MAPLE AVE #A	UNK	UNK-LG	UNK	UNK	1/1/1925	C	UNK	1/1/1925	SF	UNK	C	C		3/4" COPPER LOCKING VALVE	Installation Record	N			Field Inspection Only	Y	3/3/2014	Cross Connection Survey	
48900	114 S SCHMIDT AVE	UNK	UNK	UNK	3/4"	1/1/1977	UNK	3/4"	1/1/1977	SF	UNK	UNK	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
48908	1004 S CENTRAL AVE	UNK	C	Y	1"	1/1/2009	C	1"	1/1/2009	NONRES	UNK	C	1"	UNK	2009- RETAPPED AND INSTALLED 11' OF 1" COPPER & CONNECTED TO 5/8" LEAD EAST OF STORM SEWER.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48910	308 N GALVIN AVE	UNK	C	UNK	1"	1/1/2014	P	1"	1/1/2014	SF	UNK	P	1"	UNK	COPPER FROM CORP TO CURB VALVE/BOX. THAN POLY	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48956	2401 N LINCOLN AVE	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48996	405 E 21ST ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
48999	3107 POPP AVE	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER-BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49045	800 E HERITAGE DR	UNK	DI	UNK	6"	1/1/2014	P	6"	1/1/2014	NONRES	UNK	P	6"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
49067	1541 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49097	1904 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 13' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49112	1802 N HUME AVE	UNK	DI	UNK	8"	1/1/2014	UNK	8"	1/1/2014	O	UNK	UNK	8"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
49118	900 E HERITAGE DR	UNK	DI	UNK	6"	1/1/2014	P	6"	1/1/2014	NONRES	UNK	P	6"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
49180	1516 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49276	1557 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49293	1515 S CHESTNUT AVE	UNK	C	UNK	1"	1/1/2015	UNK	1"	1/1/2015	SF	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49323	1205 S MAPLE AVE	N	C	UNK	1"	9/1/2015	P	1"	9/1/2015	SF	UNK	P	1"	UNK	<Null>	Installation Record	Y	9/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49460	1100 E HERITAGE DR	UNK	DI	UNK	6"	1/1/2014	P	6"	1/1/2014	NONRES	UNK	P	6"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
49573	1412 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49578	1924 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2014	UNK	1"	1/1/2014	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49602	314 W 29TH ST	UNK	C	UNK	1 1/2"	1/1/2007	P	1 1/2"	1/1/2007	NONRES	UNK	P	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49641	2215 E YELLOWSTONE DR	UNK	DI	UNK	8"	1/1/2015	UNK	8"	1/1/2015	NONRES	UNK	UNK	8"	UNK	<Null>	Installation Record	Y	1/1/2015	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
49651	1820 PRAIRIE DR	UNK	C	UNK	1"	1/1/2015	UNK	1"	1/1/2015	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49703	2710 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
49707	105 S MAPLE AVE	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	NONRES	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49717	401 E 21ST ST	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49730	1818 PRAIRIE DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49733	1822 PRAIRIE DR	UNK	C	UNK	1 1/2"	1/1/2015	UNK	1 1/2"	1/1/2015	O	UNK	UNK	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49736	1824 PRAIRIE DR	UNK	C	UNK	2"	1/1/2015	UNK	2"	1/1/2015	O	UNK	UNK	2"	UNK	<Null>	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49798	2025 W VETERANS PKWY	UNK	DI	UNK	4"	1/1/2015	P	4"	1/1/2015	O	UNK	P	4"	UNK	CUT-IN VALVE INSTALLED BY HD SUPPLY & JAKEL PLBG.	Installation Record	Y	1/1/2015	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
49842	1506 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
49866	2618 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50017	1822 PRAIRIE DR-HOUSE	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50025	3800 S DRAXLER DRIVE	UNK	C	UNK	2"	1/1/2016	UNK	2"	1/1/2016	NONRES	UNK	UNK	2"	UNK	<Null>	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50029	1800 S LAEMLE AVE	UNK	UNK	UNK	1 1/2"	1/1/1991	C	1 1/2"	1/1/1991	NONRES	UNK	C	1 1/2"	UNK	STRATFORD	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50069	2405 S PEACH AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50072	314 N JUNO AVE	UNK	C	UNK	1"	1/1/2012	UNK	1"	1/1/2012	SF	UNK	UNK	1"	UNK	STOIBER PLBG.	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50087	1553 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50103	4000 S DRAXLER DR	UNK	C	UNK	2"	7/20/2016	UNK	2"	7/20/2016	NONRES	UNK	UNK	2"	UNK	<Null>	Installation Record	Y	7/20/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50122	2909 S MALLARD AVE	UNK	C	UNK	1"	1/1/2016	P	1"	1/1/2016	NONRES	UNK	P	1"	UNK	<Null>	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50140	204 N CENTRAL AVE SUITE 101	UNK	DI	UNK	6"	1/1/2011	DI	6"	1/1/2011	NONRES	UNK	DI	6"	UNK	PEMBER. FIRE PROTECTION & POTABLE WATER SUPPLY	Installation Record	Y	1/1/2011	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
50387	605 W BLODGETT ST	UNK	C	Y	1"	7/27/2021	C	1"	7/27/2021	SF	UNK	C	1"	UNK	7/27/2021: Retapped 5' West of abandonded tap. Removed lead from wm-cs, replaced with 1" copper. Installed 1" cs & box. Connected to existing lead South of the sidewalk. 8/31/21: Gaffney replaced lead w/ 3/4" copper house to cs	Installation Record	Y	7/27/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50422	1528 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50429	1406 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50433	2818 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50495	1612 W ARLINGTON ST	UNK	C	UNK	1"	8/8/2022	C	1"	8/8/2022	SF	UNK	C	1"	UNK	8/8/22: Installed 1" tapping saddle, 1" corp., and 1" cs & box. Connected to 3/4" copper after cs.	Installation Record	Y	8/8/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50520	2717 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50525	3019 W VETERANS PKWY	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50558	1500 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50563	2000 W 5TH ST	UNK	CI-U	UNK	4"	1/1/1969	CI-U	4"	1/1/1969	NONRES	UNK	CI-U	4"	UNK	MFLD PLB	Installation Record	Y	1/1/1969	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
50586	1901 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50596	1513 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50596	1513 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
50602	416 N GALVIN AVE	UNK	UNK	UNK	1"	1/1/1986	UNK	1"	1/1/1986	SF	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51211	3015 E 24TH ST	UNK	C	UNK	2"	4/26/2018	P	2"	4/26/2018	NONRES	UNK	P	2"	UNK	REIGEL PLBG. (TYPE K COPPER IN STREET)	Installation Record	Y	4/26/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51255	1001 N CENTRAL AVE	UNK	DI	UNK	6"	1/1/2016	P	6"	1/1/2016	NONRES	UNK	P	6"	UNK	SERVICE CUT-IN ON CEDAR	Installation Record	Y	1/1/2016	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
51292	211 E 2ND ST	UNK	C	UNK	2"	1/1/2010	C	2"	1/1/2010	NONRES	UNK	C	2"	UNK	CONNECTING 2" COPPER	Installation Record	Y	1/1/2010	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51303	2721 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51312	2718 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51315	2729 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51319	305 W 29TH ST	UNK	C	UNK	1"	1/1/2017	UNK	1"	1/1/2017	SF	UNK	UNK	1"	UNK	GAFFNEY	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51347	1512 E 4TH ST	UNK	C	UNK	3/4"	UNK	P	3/4"	UNK	NONRES	UNK	P	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Previous eval	Y	2013-2018	Cross Connection Survey	
51351	301 S CENTRAL AVE	UNK	C	UNK	1 1/2"	1/1/2009	C	1 1/2"	1/1/2009	NONRES	UNK	C	1 1/2"	UNK	INSTALLED 1-1/2" COPPER TO INSIDE A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51364	700 E 2ND ST	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	SF	UNK	UNK	3/4"	UNK	SUDA PLUMBING	Installation Record	Y		Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
51376	813 N COLUMBUS AVE	UNK	C	UNK	1"	1/1/2017	UNK	1"	1/1/2017	SF	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51379	210 E DOWNWIND DR	UNK	C	UNK	2"	1/1/2017	P	2"	1/1/2017	NONRES	UNK	P	2"	UNK	2" POLY ON CUSTOMER SIDE, SUDA PLBG	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51406	3015 E 24TH ST	UNK	C	UNK	2"	1/1/2017	P	2"	1/1/2017	NONRES	UNK	P	2"	UNK	<Null>	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51408	102 E 2ND ST	UNK	DI	UNK	6"	1/1/2016	CI-U	6"	1/1/2016	O	UNK	CI-U	6"	UNK	<Null>	Installation Record	Y	1/1/2016	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
51433	1533 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51459	1510 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51476	2603 E 29TH ST	N	C	UNK	1"	1/1/2017	C	1"	1/1/2017	NONRES	UNK	C	1"	UNK	CALS PLBG	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51524	1705 HEIDE LN	UNK	C	UNK	1"	1/1/1997	UNK	1"	1/1/1997	SF	UNK	UNK	1"	UNK	THE SANITARY SEWER LATERAL IS ABOVE THE WATERMAIN	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51532	1520 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51591	1011 S CENTRAL AVE	UNK	UNK-LG	UNK	1 1/4"	1/1/1926	P	1 1/4"	1/1/1926	O	UNK	P	P		THEIR SIDE	Installation Record	N			Field Inspection Only	Y	1/1/2011	Visual Insp during install or repair	
51610	2601 S GALVIN AVE	N	UNK	UNK	8"	1/1/2017	P	8"	1/1/2017	NONRES	UNK	P	8"	UNK	HAAS: 8" CUT-IN AFC VALVE	Installation Record	Y	1/1/2017	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
51617	1614 DEVINE DR	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	REDETZE	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51626	1905 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 17' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51628	1010 W 5TH ST	N	C	UNK	1 1/2"	8/16/2018	P	1 1/2"	8/16/2018	SF	UNK	P	1 1/2"	UNK	RIEGEL SINTALLED 1-1/2" COPPER FROM CORP TO CS AND PEX FROM CS TO HOUSE	Installation Record	Y	8/16/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51641	2722 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51644	2801 S WITTMAN AVE	UNK	C	UNK	1"	1/1/2013	UNK	1"	1/1/2013	SF	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51647	2302 S PEACH AVE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51670	1927 PHEASANT RUN DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	SERVES 1106 SUNFLOWER & 1931 PHEASANT	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51672	801 W MCMILLAN ST	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51674	410 W MCMILLAN ST	UNK	DI	UNK	6"	1/1/2017	P	6"	1/1/2017	NONRES	UNK	P	6"	UNK	PEMBER--2017. 6" C-900 INSTALLED ACROSS STREET 10/2/18 AND CROSSES UNDER TRANSMISSION MAIN (20" CLEARANCE)	Installation Record	Y	1/1/2017	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
51674	410 W MCMILLAN ST	UNK	DI	UNK	6"	10/2/2018	P	6"	10/2/2018	NONRES	UNK	P	6"	UNK	SERVICE AND FIRE PROTECTION FOR YMCA	Installation Record	Y	10/2/2018	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
51677	801 S CYPRESS AVE	UNK	C	UNK	1"	8/30/2018	P	1"	8/30/2018	SF	UNK	P	1"	UNK	GAFFNEY PLUMBING	Installation Record	Y	8/30/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51700	735 S CENTRAL AVE	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	NONRES	UNK	UNK	1"	UNK	STUB-OUT 1" COPPER 14'E OF BOX. A-1 EXCAVATING. COUPLER 15'E OF MAIN	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51703	1204 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51716	1527 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	NONRES	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51879	2404 E FOREST ST	UNK	UNK	UNK	1 1/2"	1/1/1990	UNK	1 1/2"	1/1/1990	NONRES	UNK	UNK	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51884	2102 SHORTESS DR	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51887	1210 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51893	2100 SHORTESS DR	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51896	1801 SAVANNAH CIRCLE	UNK	C	UNK	1"	1/1/2005	P	1"	1/1/2005	O	UNK	P	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51899	1803 SAVANNAH CIRCLE	UNK	C	UNK	1"	1/1/2005	P	1"	1/1/2005	O	UNK	P	1"	UNK	UTILITY TOOK OWNERSHIP 2018	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51922	2812 POPP AVE	UNK	C	UNK	1"	10/18/2018	UNK	1"	10/18/2018	O	UNK	UNK	1"	UNK	GAFFNEY - VERY DEEP	Installation Record	Y	10/18/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51926	2816 POPP AVE	UNK	C	UNK	1"	10/18/2018	UNK	1"	10/18/2018	O	UNK	UNK	1"	UNK	GAFFNEY - VERY DEEP	Installation Record	Y	10/18/2018	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
51951	505 S POPPLE AVE	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	NONRES	UNK	C	2"	UNK	MEYERS, STUB-OUT	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52046	1401 E BECKER ROAD	UNK	DI	UNK	4"	8/23/2018	DI	4"	8/23/2018	NONRES	UNK	DI	4"	UNK	12X4 CUT-IN TEE, 2' 4" DIP, 4" VALVE FOR FOOTBALL FIELD	Installation Record	Y	8/23/2018	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
52069	212 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52072	2402 S PEACH AVE	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	SF	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52075	2621 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52081	3200 S CENTRAL AVENUE	UNK	UNK	UNK	10"	1/1/1985	UNK	10"	1/1/1985	NONRES	UNK	UNK	10"	UNK	SCHREEINERS	Installation Record	Y	1/1/1985	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
52087	213 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52232	907 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52285	600 S CYPRESS AVE	UNK	C	UNK	1"	8/1/2019	C	1"	8/1/2019	SF	UNK	C	1"	UNK	REIGLE RAN 4" PVC SAN. LATERAL & 1" COPPER TOGETHER (SAN. LATERAL IS 8" SOUTH OF COPPER)	Installation Record	Y	8/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52292	3500 DOWNWIND DR	UNK	C	UNK	2"	10/2/2019	UNK	2"	10/2/2019	NONRES	UNK	UNK	2"	UNK	1" CORP 1' SOUTH OF 2" CORP	Installation Record	Y	10/2/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52301	2201 S NIKOLAI AVE	UNK	C	UNK	2"	5/30/2019	UNK	2"	5/30/2019	NONRES	UNK	UNK	2"	UNK	RIEGEL PLBG.	Installation Record	Y	5/30/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52341	3414 S CHERRY AVE	UNK	C	UNK	1"	10/29/2019	C	1"	10/29/2019	NONRES	UNK	C	1"	UNK	BACH EXCAVATING, SUDA PLBG, MU WATER - TAPPED ON EAST SIDE OF MAIN & CROSSES OVER WATER MAIN TO CURB STOP	Installation Record	Y	10/29/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52345	1906 N HUME AVE	UNK	DI	UNK	4"	9/10/2018	DI	4"	9/10/2018	O	UNK	DI	4"	UNK	INSTALLED BY EARTH INC.	Installation Record	Y	9/10/2018	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
52366	2822 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52376	1112 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52391	1500 N WOOD AVE	UNK	C	UNK	1"	6/1/1984	UNK	1"	6/1/1984	SF	UNK	UNK	1"	UNK	2020 - SCHREINER RAN SERVICE TO HOUSE	Installation Record	Y	6/1/1984	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
52763	2808 POPP AVE	UNK	C	UNK	1"	10/2/2019	UNK	1"	10/2/2019	O	UNK	UNK	1"	UNK	GAFFNEY PLBG.	Installation Record	Y	10/2/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52790	1007 N HUME AVE	UNK	DI	UNK	8"	1/1/2018	DI	8"	1/1/2018	NONRES	UNK	DI	8"	UNK	INSTALLED BY EARTH INC.	Installation Record	Y	1/1/2018	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
52804	1108 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52816	2804 POPP AVE	UNK	C	UNK	1"	10/2/2019	UNK	1"	10/2/2019	O	UNK	UNK	1"	UNK	GAFFNEY PLBG.	Installation Record	Y	10/2/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52823	1829 E 26TH ST	UNK	C	UNK	2"	10/3/2019	P	2"	10/3/2019	NONRES	UNK	P	2"	UNK	REIGEL PLBG.	Installation Record	Y	10/3/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52830	1900 N HUME AVE	UNK	DI	UNK	8"	9/10/2018	DI	8"	9/10/2018	O	UNK	DI	8"	UNK	INSTALLED BY EARTH INC.	Installation Record	Y	9/10/2018	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
52844	2511 PEACHTREE CIRCLE	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	SF	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52859	700 W 11TH ST	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52865	1104 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52948	1108 WILDFLOWER DR	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE - 1108 WILDFLOWER DR.	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52957	701 EASTSIDE CIRCLE	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52960	1415 E 20TH ST	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH. ALT. ADDRESS:1414 E 20TH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
52986	2401 S PALMETTO AVE	UNK	UNK	UNK	1"	1/1/1981	UNK	1"	1/1/1981	SF	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y	2013-2018	Cross Connection Survey	
52992	2915 E 24TH ST	UNK	C	UNK	2"	10/28/2019	P	2"	10/28/2019	O	UNK	P	2"	UNK	2915 E. 24TH STREET - RIEGEL PLBG.	Installation Record	Y	10/28/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53037	1532 E 20TH ST	UNK	C	UNK	1"	1/1/2008	P	1"	1/1/2008	SF	UNK	P	1"	UNK	EARTH. 2/26/24 - Aarons plumbing installed new sewer and 1" SDR-9 CTS water service installed for new house. Permit #20240227	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53040	904 S SCHMIDT AVE	UNK	C	UNK	1"	4/24/2020	UNK	1"	4/24/2020	SF	UNK	UNK	1"	UNK	Reigels	Installation Record	Y	4/24/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53589	1230 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REDETZKE-NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53606	2800 POPP AVE	UNK	C	UNK	1"	10/4/2019	UNK	1"	10/4/2019	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	10/4/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53612	903 S MARYKNOLL AVE	UNK	C	UNK	3/4"	6/1/2020	UNK	3/4"	6/1/2020	SF	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	6/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53671	208 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53688	400 W UPHAM ST	UNK	C	Y	1 1/4"	1/1/2016	C	1 1/4"	1/1/2016	NONRES	UNK	C	1 1/4"	UNK	REMOVED MANIFOLD & LEAD WIPE, NEW 1-1/4" TAP ON DIP BETWEEN SECTIONS OF LINED PIPE, 28" OF 1-1/4" COPPER FROM CORP CONN TO EXIST 1-1/4" COPPER, EARTH--2016. CORP TAPPED ON DIP (NOT LINED). CURB VALVE W/O BOX 3' W OF PP *SHUT OFF*	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53688	400 W UPHAM ST	UNK	DI	UNK	6"	4/21/2020	P	6"	4/21/2020	NONRES	UNK	P	6"	UNK	2' - 6" DIP, 6" Clow Res. Wedge Vavle - 6" - C900 pipe on customers side	Installation Record	Y	4/21/2020	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
53728	1021 S ADAMS AVE	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53826	1007 N SCHMIDT AVE	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	SF	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
53855	2000 N HUME AVE	UNK	DI	UNK	8"	1/1/2018	DI	8"	1/1/2018	O	UNK	DI	8"	UNK	<Null>	Installation Record	Y	1/1/2018	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
53873	710 W 11TH ST	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
54446	1900 S CENTRAL AVE	UNK	UNK	UNK	4"	1/1/2013	CI-U	4"	1/1/2013	NONRES	UNK	CI-U	4"	UNK	4" AFC CUT-IN VALVE SWIMMING POOL VALVE IN MANHOLE	Installation Record	Y	1/1/2013	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
55393	1231 W JEFFERSON ST	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	SF	UNK	UNK	1"	UNK	REDETZKE-NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
55854	200 S SYCAMORE AVE	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	SF	UNK	UNK	1"	UNK	A-1	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
56062	1810 N CENTRAL AVE	UNK	P	UNK	2"	7/28/2021	P	2"	7/28/2021	O	UNK	P	2"	UNK	Reigle Plumbing - 2" tap is 14' west of the hydrant tee	Installation Record	Y	7/28/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
62239	407 S CYPRESS AVE	UNK	C	UNK	1"	9/22/2021	C	1"	9/22/2021	SF	UNK	C	1"	UNK	9/22/2021: Earth installed 1" copper 17' past the curb valve (Pg 10 of Daniels Addition inspection notes)	Installation Record	Y	9/22/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
64583	1601 GREEN ACRES DR	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	SF	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
66572	1510 N CENTRAL AVE	UNK	C	UNK	1 1/2"	10/5/2023	P	1 1/2"	10/5/2023	NONRES	UNK	P	1 1/2"	UNK	10-5-23: 1-1/2" plastic on customers side	Installation Record	Y	10/5/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
66572	1510 N CENTRAL AVE	UNK	C	UNK	2"	9/28/2023	P	2"	9/28/2023	NONRES	UNK	P	2"	UNK	9/28/23: Kluck installed 2" copper from main to cs and 2" poly on customers side. MU installed the 2" tap at the main.	Installation Record	Y	9/28/2023	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	1999: STUB-OUT, CURB BOX INSTALLED	Installation Record	Y	1/1/1999	Mech excav	SL repair/replace record	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	O	UNK	C	1"	UNK		Installation Record	Y	1/1/2002	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	6/30/2020	UNK	1"	6/30/2020	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	6/30/2020	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	6/30/2020	UNK	1"	6/30/2020	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	6/30/2020	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	P	UNK	6"	6/13/2019	P	6"	6/13/2019	O	UNK	P	6"	UNK	<Null>	Installation Record	Y	6/13/2019	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	DI	UNK	8"	1/1/2013	DI	8"	1/1/2013	O	UNK	DI	8"	UNK	<Null>	Installation Record	Y	1/1/2013	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	UNK	1"	1/1/2007	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	UNK	1"	1/1/2007	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	UNK	1"	1/1/2007	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	UNK	1"	1/1/2007	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	UNK	1"	1/1/2007	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2007	UNK	2"	1/1/2007	O	UNK	UNK	2"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2007	UNK	6"	1/1/2007	O	UNK	UNK	6"	UNK	<Null>	Installation Record	Y	1/1/2007	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1 1/2"	1/1/2006	P	1 1/2"	1/1/2006	O	UNK	P	1 1/2"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	P	UNK	3/4"	1/1/2006	C	3/4"	1/1/2006	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/2004	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2000	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1998	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1997	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	O	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	O	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	O	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	O	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	O	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	O	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	O	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1996	C	2"	1/1/1996	O	UNK	C	2"	UNK	<Null>	Installation Record	Y	1/1/1996	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1995	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	UNK	1/1/1994	C	UNK	1/1/1994	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y	1/1/1994	Mech excav	Other	N		Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1993	UNK	3/4"	1/1/1993	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1993	Mech excav	Other	N		Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	UNK	1"	1/1/1990	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	UNK	1"	1/1/1990	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1990	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1989	C	1"	1/1/1989	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/1989	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1986	UNK	1"	1/1/1986	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1986	UNK	1"	1/1/1986	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1986	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1985	UNK	1"	1/1/1985	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1985	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1984	UNK	2"	1/1/1984	O	UNK	UNK	2"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1984	C	3/4"	1/1/1984	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y	1/1/1984	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1983	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1967	UNK	3/4"	1/1/1967	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1967	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1966	UNK	3/4"	1/1/1966	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1966	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1965	UNK	2"	1/1/1965	O	UNK	UNK	2"	UNK	<Null>	Installation Record	Y	1/1/1965	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1964	UNK	3/4"	1/1/1964	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1964	UNK	3/4"	1/1/1964	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1964	UNK	3/4"	1/1/1964	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1964	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1963	UNK	3/4"	1/1/1963	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1963	UNK	3/4"	1/1/1963	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1963	UNK	3/4"	1/1/1963	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1963	UNK	3/4"	1/1/1963	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1963	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1962	UNK	3/4"	1/1/1962	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1962	UNK	3/4"	1/1/1962	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y	1/1/1962	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1961	UNK	1"	1/1/1961	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y	1/1/1961	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	5/8"	1/1/1960	UNK	5/8"	1/1/1960	O	UNK	UNK	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	5/8"	1/1/1960	UNK	5/8"	1/1/1960	O	UNK	UNK	5/8"	UNK	<Null>	Installation Record	Y	1/1/1960	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	UNK	C	1"	UNK	O	UNK	C	1"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	UNK	UNK	1"	UNK	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	UNK	UNK	1"	UNK	O	UNK	UNK	1"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1/2"	UNK	C	1/2"	UNK	O	UNK	C	1/2"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	UNK	UNK	6"	UNK	O	UNK	UNK	6"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	DI	UNK	8"	UNK	UNK	8"	UNK	O	UNK	UNK	8"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	8"	UNK	UNK	8"	UNK	O	UNK	UNK	8"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	8"	UNK	UNK	8"	UNK	O	UNK	UNK	8"	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	CI-U	UNK	UNK	UNK	CI-U	UNK	UNK	O	UNK	CI-U	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	<Null>	Installation Record	Y		Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	2011- SERVICE DISCONNECTED SOUTH OF SIDEWALK. CURBSTOP INSTALLED TO SHUT WATER OFF AND NOT CONNECTED TO REMAINING COPPER. MARKED WITH 4X4. JT (36' W & 1' S OF THE N.W.C.B. & 106' S & 12' E OF THE S.E.C.B. OF 1601 E 4TH CS ON PRIV. PROP.	Installation Record	Y	1/1/2011	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	2011-INSTALLED CURB STOP/BOX TO SHUT WATER FOR BUILDING REMOVAL. THIS SERVICE IS CONNECTED TO OR RUNS NEXT TO SERVICE FOR 211 W. DOEGE.	Installation Record	Y	1/1/2011	Mech excav	Other	N			Not serving a customer
UNK	UNK	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	2021: Dug @ watermain and found 3/4" copper. 2023: MU dug and installed cs between curb and sidewalk because of a leak in the house.	Installation Record	Y	1/1/2023	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	5/11/2023	UNK	1"	5/11/2023	O	UNK	UNK	1"	UNK	5/11/23: New 1" corp., 1" copper and 1" cs & box. Extended 1" copper 3' East of cs and pinched over.	Installation Record	Y	5/11/2023	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	6/14/2023	C	1"	6/14/2023	O	UNK	C	1"	UNK	6/14/23: MU installed w/ 1" corp, 1" copper, 1" cs & box and extended 1" copper for 15' South of cs.	Installation Record	Y	6/14/2023	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	6/19/2024	UNK	1"	6/19/2024	O	UNK	UNK	1"	UNK	6/19/2024: Empty Lot. Disconnected abandoned leap & old corp. @ wm. Installed new 1" corp (old corp is 8' East of new corp.) 1" copper and 1" cs & box. Sutbbed out to back of curb.	Installation Record	Y	6/19/2024	Mech excav	Other	N			Not serving a customer
UNK	UNK	N	C	Y	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	8/10/22: Removed lead wipe @ main and replaced w/ 3/4" copper. Connected to 3/4" copper at main.	Installation Record	Y	8/10/2022	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	9/25/2023	C	1"	9/25/2023	O	UNK	C	1"	UNK	9/25/23: Earth Inc installed 1" corp., 16.5 LF - 1" copper (wm-cs), 1" cs & box, 20 LF - 1" copper (cs to peened end) Project #5876 See pg. 17 of the const. report	Installation Record	Y	9/25/2023	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	N	1"	9/27/2021	UNK	1"	9/27/2021	O	UNK	UNK	1"	UNK	9/27/2021: Earth installed 1" copper 21' past the curb valve. (Pg 13 of Daniels Addition inspection notes)	Installation Record	Y	9/27/2021	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	9/27/2023	UNK	1"	9/27/2023	O	UNK	UNK	1"	UNK	9/27/23 Earth Inc installed 1" corp., 25.5 LF - 1" copper (wm-cs), 1" cs & box, 19.5 LF - 1" copper (cs - peened end) This is a Stub-Out and does not serve the house at 302 Lincoln. Project #5876. See pg. 18 of the const. report	Installation Record	Y	9/27/2023	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	9/28/2023	C	1"	9/28/2023	O	UNK	C	1"	UNK	9/28/23 Earth Inc installed 1" corp., 33.5 LF - 1" copper (wm-cs), 1" cs & box, 6 LF - 1" copper (cs - peened end) Project #5876 See pg. 19 of the const. report	Installation Record	Y	9/28/2023	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	P	UNK	1"	9/28/2023	P	1"	9/28/2023	O	UNK	P	1"	UNK	9/28/23: Doine - All work done in terrace.	Installation Record	Y	9/28/2023	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2017	UNK	2"	1/1/2017	O	UNK	UNK	2"	UNK	ABANDONED OLD CURB VALVE IN SIDEWALK (DOES NOT WORK)	Installation Record	Y	1/1/2017	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	DIRECTIONAL BORED. Stub-Out	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	6/5/2020	UNK	1"	6/5/2020	O	UNK	UNK	1"	UNK	Earth INC. - Installed 1' - 1" Copper after CS with smashed end (Empty Lot) (Pg. 10 of Const. Report)	Installation Record	Y	6/5/2020	Mech excav	Other	N			Not serving a customer
UNK	UNK	Y	C	UNK	1"	5/1/2024	C	1"	5/1/2024	O	UNK	C	1"	UNK	INSULATED 2X4 1981. 2022: House has been removed. 5/2024: 1" copper main to cs, 1" copper 14' past cs (Meyers)	Installation Record	Y	5/1/2024	Mech excav	Other	N			Not serving a customer
UNK	UNK	N	C	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	SERVICE IS OFF E DOEGE. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 6'9" DEEP	Installation Record	Y	1/1/2020	Mech excav	Other	N			Not serving a customer
UNK	UNK	N	L	Y	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	STUB OUT - Curb valve is off with plug installed - No curb box, 6-2020 house torn down, Lead on street side. 6/22: Dug @ main, shut corp off & disconnected lead from the main.	Installation Record	Y	6/22/2022	Mech excav	Other	N			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	STUB-OUT 13' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	STUB-OUT 16' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	STUBOUT 16'PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Other	N		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	C	UNK	1"	7/21/2020	UNK	1"	7/21/2020	O	UNK	UNK	1"	UNK	TAPPED W/ 6"X1" REPAIR CLAMP - 6" PVC SAN. LAT. RAN 6' WEST WITH WATER SERVICE. SAN. LATERAL CROSSES OVER WATERMAIN 2" - 1" COPPER STUBBED 5' NORTH OF SIDEWALK - C.S. IS LOCATED 1' SOUTH FROM COMM. LINE UTILITES - TAP THROUGH LINER USING REGULAR TAP BIT	Installation Record	Y	7/21/2020	Mech excav	Other	N			Not serving a customer
UNK	410 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	C	UNK	1/1/1926	O	UNK	UNK	UNK		1/2" COPPER LOCKING VALVE	Installation Record	N			Previous eval	N		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	1989	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	*SEE SEPARATE SERVICES* SPLITS TO Y. REPLACE WIPES, COPPER FROM Y TO HSE.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	Y	1 1/2"	1/1/1984	UNK	1 1/2"	1/1/1984	O	UNK	UNK	1 1/2"	UNK	09/2020 - DISCONNECTED LEAD FROM MAIN @ CORP. - LEFT CORP OFF	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/4"	1/1/1980	UNK	1 1/4"	1/1/1980	O	UNK	UNK	1 1/4"	UNK	1" METER	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	1/2" COPPER LOCKING VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	1/2" COPPER LOCKING VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	Y	1 1/4"	UNK	C	1 1/4"	UNK	O	UNK	C	1 1/4"	UNK	1-1/4 LEAD AND SHUT IT OFF.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	1981-LOWERED	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	1995-CURB VALVE W/ BOX INSTALLED. 3/4" copper on property side	Installation Record	Y	1/1/1995	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	1995-NEW BRASS CURB VALVE INSTALLED IN BOULEVARD. NO CURB BOX. LINE WAS TURNED OFF	Installation Record	Y	1/1/1995	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1967	C	3/4"	1/1/1967	O	UNK	C	3/4"	UNK	1998: RE-TAPPED.	Installation Record	Y	1/1/1967	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	1999: STUB-OUT, CURB BOX INSTALLED.	Installation Record	Y	1/1/1999	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	1999: STUB-OUT, CURB BOX INSTALLED.	Installation Record	Y	1/1/1999	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	1999: STUB-OUT.	Installation Record	Y	1/1/1999	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	UNK	UNK	1"	UNK	UNK	1"	UNK	O	UNK	UNK	1"	UNK	2 CURB BOXES	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	UNK	UNK	1"	UNK	O	UNK	UNK	1"	UNK	2 CURB BOXES	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2 SERVICES - SERVICE INFRONT OF BLDG 207 W 2ND IS LIVE, SERIVICE TO WEST OF BLDG 207 W 2ND IS ABANDONED	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/1982	UNK	2"	1/1/1982	O	UNK	UNK	2"	UNK	2" SERVICE. 3-1" TAPS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2000: CURB BOX CUT-IN (REIGEL)	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/4"	1/1/1965	UNK	1 1/4"	1/1/1965	O	UNK	UNK	1 1/4"	UNK	2000: HOUSE REMOVED (STUB-OUT).	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	2000: HOUSE REMOVED (STUB-OUT).	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2002: CURB BOX CUT-IN ON OLD OFFICE SERVICE.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2002-RETAPPED @ 7'W & 21'S OF NW COR. OF DOEGE & PINE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2003- CURB VALVE W/ BOX INSTALLED.TURED OFF @ CURB VALVE	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	UNK	5/8"	UNK	UNK	5/8"	UNK	O	UNK	UNK	5/8"	UNK	2003- CURB VALVE W/ BOX INSTALLED	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	UNK	1/1/2003	UNK	UNK	1/1/2003	O	UNK	UNK	UNK	UNK	2003- REPLACED SERVICE MAIN TO NEW CURB VALVE & BOX	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	UNK	5/8"	UNK	UNK	5/8"	UNK	O	UNK	UNK	5/8"	UNK	2003-CURB VALVE INSTALLED W/ NO BOX. *STUB-OUT*	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	UNK	UNK	1"	UNK	O	UNK	UNK	1"	UNK	2003-DISCONNECTED AT CURB VALVE. NEW CURB VALVE & BOX INSTALLED.	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2004- CURB-VALVE INSTALLED.HOUSE IS TORN DOWN	Installation Record	Y	1/1/2004	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	2004-INSTALLED 3/4" CORP	Installation Record	Y	1/1/2004	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	2005-BLDG. WAS REMOVED NEW 3/4" CURB VALVE W/ BOX WAS INSTALLED	Installation Record	Y	1/1/2005	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	Y	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	2007-CURB VALVE CUT IN AND PINCHED LEAD OFF. SERVICE CUT OFF NOT ATTACHED TO HSE.	Installation Record	Y	1/1/2007	Mech excav	SL repair/replace record	Y	1/1/2007	Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2007-DISCONNECTED @ CURB VALVE	Installation Record	Y	1/1/2007	Mech excav	SL repair/replace record	Y			Not serving a customer
UNK	UNK	UNK	C	UNK	UNK	UNK	C	1"	UNK	O	UNK	C	1"	UNK	2007-INSTALLED NEW 1" COPPER FROM CORP TO NEW CURB VALVE,VIA DIRECTIONAL BORE. SERVICE IS 48" BELOW CURB ON WEST SIDE	Installation Record	Y	1/1/2007	Mech excav	SL repair/replace record	Y	1/1/2007	Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	2008-CURB BOX INSTALLED	Installation Record	Y	1/1/2008	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	Y	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2009- REMOVED LEAD WIPE @ MAIN	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	Y	2"	UNK	C	2"	UNK	O	UNK	C	2"	UNK	2009- REMOVED LEAD WIPES @ MAIN. 2" LINE 3-1" TAPS. SERVICE FOR MIDDLE & NORTH STORE. THERE IS TO CURB VALVES ONLY ONE BOX	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	Y	5/8"	UNK	C	5/8"	UNK	O	UNK	C	5/8"	UNK	2009-REMOVED LEAD WIPE @ MAIN	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	L	Y	UNK	UNK	L	UNK	UNK	O	UNK	L	UNK	UNK	2009-REMOVED LEAD WIPE @ MAIN. 1998: LOWERED UNDER STORM SEWER.	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	Y	5/8"	UNK	UNK	5/8"	UNK	O	UNK	UNK	5/8"	UNK	2009-REMOVED LEAD WIPE @ MAIN. 2006 INSTALLED CURBBOX BEHIND CURB	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	Y	5/8"	UNK	UNK	5/8"	UNK	O	UNK	UNK	5/8"	UNK	2009-REMOVED LEAD WIPE @ MAIN.SERVICE DEEP ENOUGH IN STREET TO PREVENT FREEZING. SEPERATE SERVICE FOR 912 A AND B. SERVICE FOR SOUTH STORE	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	2009-REPLACED 3/4" COPPER FROM CURB VALVE TO 18'W & 23'S OF SW COR. OF WELL 17.	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	UNK	5/8"	UNK	P	5/8"	UNK	O	UNK	P	5/8"	UNK	2010- INSTALLED NEW CURB VALVE W/ BOX.REMOVED WIPES. NEW 1" PLASTIC TO INSIDE	Installation Record	Y	1/1/2010	Mech excav	SL repair/replace record	Y	1/1/2010	Cross Connection Survey	
UNK	UNK	UNK	UNK	UNK	1"	1/1/1981	UNK	1"	1/1/1981	O	UNK	UNK	1"	UNK	2012-RETAPPED DURING LINING PROJECT	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1981	UNK	1"	1/1/1981	O	UNK	UNK	1"	UNK	2012-RETAPPED DURING LINING PROJECT	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	N	C	UNK	1"	1/1/1981	UNK	1"	1/1/1981	O	UNK	UNK	1"	UNK	2012-RETAPPED DURING LINING PROJECT. 4/30/2021: fixed leak @ corp. and replaced 2' of copper and hooked up to existing.	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	UNK	UNK	1/1/1985	UNK	UNK	1/1/1985	O	UNK	UNK	UNK	UNK	2015- CURB VALVE MOVED 1'W OF CURB LINE/ NO BOX.	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	2015-CURB VALVE INSTALLED AND MOVED 1' W OF CURB LINE WITH NO BOX	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX	Installation Record	Y	1/1/2015	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	Y	1 1/2"	1/1/1966	C	1 1/2"	1/1/1966	O	UNK	C	1 1/2"	UNK	2021 - Found 3 - 1" taps into 1-1/2" manifold. No lead found	Installation Record	Y	1/1/1966	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	213 N CENTRAL FED BY 2 LINES	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	3/4" COPPER LOCKING VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	3/4" COPPER LOCKING VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	UNK	P	2"	UNK	O	UNK	P	2"	UNK	4 3/4" TAPS. 2011-CAL'S INSTALLED NEW CURB VALVE. 2009- REPLACED COPPER ON ALL 4 TAPS FROM MAIN TO YOKE.	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	C	Y	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	4'x 8' INSULATION. 2005-REMOVED LEAD WIPE INSTALLED NEW CUB VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	510 N APPLE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	9/29/23: Verified CB location, recorded with GPS.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	ANOTHER SERVICE FROM CHESTNUT. 2013-INSTALLED CURB VALVE W/ BOX	Installation Record	Y	1/1/2013	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	N	C	UNK	1"	UNK	P	1"	UNK	O	UNK	P	1"	UNK	APPROX TAP LOCATION-N:563707.848-E:646278.597	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	APT-FRONT HAS ITS OWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/1971	UNK	3/4"	1/1/1971	O	UNK	UNK	3/4"	UNK	BILL REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1969	UNK	1"	1/1/1969	O	UNK	UNK	1"	UNK	BILL REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	BOB NIKOLAY	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	O	UNK	C	3/4"	UNK	BOX AND LOWERED UNDER STORM SEWER.	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	BUILDING TAKEN DOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CALMPED OFF AT PL	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CB LOCATION VERIFIED 10/30/97	Installation Record	Y	10/30/1997	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CB LOCATION VERIFIED 6/3/97	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CB/LV UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1977	C	1"	1/1/1977	O	UNK	C	1"	UNK	CITY & UTILITY	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CLAMPED OFF 5/21/71	Installation Record	Y	5/21/1971	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CLAMPED OFF AT PL	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1972	UNK	3/4"	1/1/1972	O	UNK	UNK	3/4"	UNK	CLAMPED OUT AT PL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1/2"	UNK	UNK	1/2"	UNK	O	UNK	UNK	1/2"	UNK	COMES OFF ST. JOESPH	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CURB BOX LOCATION VERIFIED	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CURB BOX LOCATION VERIFIED 1/23/97	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	CURB BOX LOCATION VERIFIED 1/3/97	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	UNK	UNK	1"	10/27/1969	C	1"	10/27/1969	O	UNK	C	1"	UNK	CURB BOX SHUT OFF & CAPPED	Installation Record	Y	10/27/1969	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	CUT IN A CURB BOX 11-14-1996	Installation Record	Y	11/14/1996	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1973	UNK	3/4"	1/1/1973	O	UNK	UNK	3/4"	UNK	DEPT	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	DISCONNECTED 2003- CURB VALVE INSTALLED 25' N OF NEW WELL	Installation Record	Y	1/1/2003	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	UNK	5/8"	UNK	UNK	5/8"	UNK	O	UNK	UNK	5/8"	UNK	DISCONNECTED IN TERRACE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	DUPLEX WITH 1412A	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	DUPLEX WITH 203A	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	DUPLEX WITH 609A, LV/CB UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	FLUSH-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	FOUND C.B., NOT CATCHABLE--2017	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	FROM 5/8 TO 3/4 TO 1" 2/23/98.	Installation Record	Y	2/23/1998	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 24' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23 LF - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 24' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 24' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/1/2024	C	1"	8/1/2024	O	UNK	C	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 25' - 1" copper after cs.	Installation Record	Y	8/1/2025	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1968	UNK	3/4"	1/1/1968	O	UNK	UNK	3/4"	UNK	HELLER	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1979	UNK	1"	1/1/1979	O	UNK	UNK	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1979	UNK	1"	1/1/1979	O	UNK	UNK	1"	UNK	HOLIDAY	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	HOUSE IS GONE: STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	HOUSE IS GONE: STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	HOUSE MOVED 9/95	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	HOUSE REMOVED 10-4-99	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	HOUSE REMOVED 1998.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	HOUSE TORN DOWN 9/85	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	HOUSE TORN DOWN, STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1978	C	2"	1/1/1978	O	UNK	C	2"	UNK	IN FRONT ON E 29TH ST	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	IN SIDEWALK	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	UNK	C	1"	UNK	O	UNK	C	1"	UNK	IN TARGET PARKING LOT/ IN CONCRETE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	INSTALLED 3/4" CURB VALVE & CURB BOX 2000	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	INSTALLED CURB VALVE & BOX.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	Y	UNK	UNK	L	UNK	UNK	O	UNK	L	UNK	UNK	LEAD SERVICE IS PINCHED OFF AND CAPPED	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	Y	UNK	UNK	L	UNK	UNK	O	UNK	L	UNK	UNK	LEAD SERVICE IS PINCHED OFF AND CAPPED	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	LEAKS ON CUSTOMER SIDE. CURB STOP OFF	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/1975	C	3/4"	1/1/1975	O	UNK	C	3/4"	UNK	LINED WATER MAIN, MICHELS--2016	Installation Record	Y	1/1/1975	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	LOCKING VALVE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	LV/CB UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	LV/CB UNKNOWN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/4"	1/1/1985	UNK	1 1/4"	1/1/1985	O	UNK	UNK	1 1/4"	UNK	MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1985	UNK	1"	1/1/1985	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1985	UNK	1"	1/1/1985	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1/1/1985	UNK	UNK	1/1/1985	O	UNK	UNK	UNK	UNK	UNK	MEYER	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1983	UNK	1 1/2"	1/1/1983	O	UNK	UNK	1 1/2"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1983	UNK	1 1/2"	1/1/1983	O	UNK	UNK	1 1/2"	UNK	MEYER	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1982	UNK	1"	1/1/1982	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1981	UNK	1"	1/1/1981	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1981	UNK	1"	1/1/1981	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	MEYER, NO ACCOUNT-STUB OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	MEYER, STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1982	UNK	1"	1/1/1982	O	UNK	UNK	1"	UNK	MEYER, STUB-OUT	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1982	UNK	1"	1/1/1982	O	UNK	UNK	1"	UNK	MEYER, STUB-OUT	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1982	UNK	1"	1/1/1982	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1982	UNK	1"	1/1/1982	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1982	UNK	1"	1/1/1982	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1982	UNK	1"	1/1/1982	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1982	UNK	1"	1/1/1982	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1982	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1980	UNK	1"	1/1/1980	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1980	UNK	1"	1/1/1980	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1978	UNK	1"	1/1/1978	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1978	UNK	3/4"	1/1/1978	O	UNK	UNK	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1978	UNK	3/4"	1/1/1978	O	UNK	UNK	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1978	UNK	3/4"	1/1/1978	O	UNK	UNK	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1976	C	1"	1/1/1976	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	MEYERS	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	MEYERS	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	MEYERS	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1977	UNK	3/4"	1/1/1977	O	UNK	UNK	3/4"	UNK	MEYERS : 1998 WATER DEPT RE-TAPPED	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	MEYERS, NO ACCOUNT-STUB OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1980	UNK	1"	1/1/1980	O	UNK	UNK	1"	UNK	MEYERS: STUB OUT. *2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 3' - 1" COPPER WITH 1" COUPLING	Installation Record	Y	1/1/1980	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	MEYER-STUB OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	NEW CURB BOX & STOP 12-4-98.	Installation Record	Y	12/4/1998	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	Y	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	NEW CURB VALVE INSTALLED BY MEYERS. REMOVED LEAD WIPES BOTH SIDES OF VALVE.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	UNK	UNK	2"	UNK	O	UNK	UNK	2"	UNK	NO BOX	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	OFF 3RD ST	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	3/4"	UNK	L	3/4"	UNK	O	UNK	L	3/4"	UNK	OFF WEST OF CURB STOP. NO CURB BOX.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	OLD BAKERY	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	1/1/1992	UNK	UNK	1/1/1992	O	UNK	UNK	UNK	UNK	OLD BOX (NOT ATTACHED), NEW STOP JUST WEST OF MARKER BOX	Installation Record	Y	1/1/1992	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	UNK	UNK	2"	UNK	O	UNK	UNK	2"	UNK	ON E 29TH ST	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	ON FRANKLIN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	UNK	C	1"	UNK	O	UNK	C	1"	UNK	PULLED NEW COPPER FROM MAIN TO CURB STOP. MAIN AND CORP ARE DIRECTLY UNDER FIBER SLURRY. INSTALLED COPPER COMPRESSION 3' E OF MAIN.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	UNK	UNK	1"	UNK	O	UNK	UNK	1"	UNK	REDETKZE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1978	UNK	1"	1/1/1978	O	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1976	C	3/4"	1/1/1976	O	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1976	UNK	3/4"	1/1/1976	O	UNK	UNK	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1976	UNK	3/4"	1/1/1976	O	UNK	UNK	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1976	UNK	3/4"	1/1/1976	O	UNK	UNK	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1976	UNK	3/4"	1/1/1976	O	UNK	UNK	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1973	UNK	3/4"	1/1/1973	O	UNK	UNK	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1973	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1972	C	3/4"	1/1/1972	O	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1971	C	3/4"	1/1/1971	O	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1969	C	3/4"	1/1/1969	O	UNK	C	3/4"	UNK	REIGEL	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	REIGEL--2017	Installation Record	Y	1/1/2017	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	REIGEL--2017	Installation Record	Y	1/1/2017	Mech excav	SL repair/replace record	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	Y	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	REMOVED GOOSENECK, INSULATED, PAVING 1985. 11/15/24: Installed 3/4" curb stop & 1" curb box on existing 3/4" copper.	Installation Record	Y	11/15/2024	Mech excav	SL repair/replace record	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	L	Y	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	REMOVED LEAD WIPE @ MAIN. THIS IS AN ABANDONED LEAD SERVICE, IT IS PINCHED OFF AND CAPPED	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	Y	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	REMOVED LEAD WIPE 1-2000.	Installation Record	Y	1/1/2000	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	REMOVED WIPES 1989, COPPER INSIDE	Installation Record	Y	1/1/1989	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/1978	UNK	3/4"	1/1/1978	O	UNK	UNK	3/4"	UNK	RON MEYERS	Installation Record	Y	1/1/1978	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	UNK	UNK	UNK	1/1/1976	UNK	UNK	1/1/1976	O	UNK	UNK	UNK	UNK	RON MEYERS: PRIVATE SERVICE IN SOUTH DITCH	Installation Record	Y	1/1/1976	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1969	UNK	3/4"	1/1/1969	O	UNK	UNK	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1965	UNK	3/4"	1/1/1965	O	UNK	UNK	3/4"	UNK	SCHREINERS	Installation Record	Y	1/1/1965	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1964	UNK	3/4"	1/1/1964	O	UNK	UNK	3/4"	UNK	SCHREINERS INC., STUB-OUT	Installation Record	Y	1/1/1964	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	UNK	UNK	3/4"	1/1/1968	C	3/4"	1/1/1968	O	UNK	C	3/4"	UNK	SCHUH PLB	Installation Record	Y	1/1/1968	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	SE CORNER OF 410 N VINE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	SERVICE THAT COMES OFF 3RD ST AND RUNS DOWN THE EAST SIDE OF SPRUCE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	SHUT OFF @ CURB STOP: NO CURB BOX	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1971	UNK	3/4"	1/1/1971	O	UNK	UNK	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1971	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1969	UNK	3/4"	1/1/1969	O	UNK	UNK	3/4"	UNK	SPENCER	Installation Record	Y	1/1/1969	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	9/16/1966	C	3/4"	9/16/1966	O	UNK	C	3/4"	UNK	SPENCER. SHARED W/ 1402 E. 20TH ST. GAFFNEY RAN 1" COPPER FROM CS TO 1400 & TEE'D @ 1400 TO GO TO 1402	Installation Record	Y	9/16/1966	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1979	UNK	1"	1/1/1979	O	UNK	UNK	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1979	UNK	1"	1/1/1979	O	UNK	UNK	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1979	UNK	1"	1/1/1979	O	UNK	UNK	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1979	UNK	1"	1/1/1979	O	UNK	UNK	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1979	UNK	1"	1/1/1979	O	UNK	UNK	1"	UNK	STUB OUT MEYERS	Installation Record	Y	1/1/1979	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB UNDER NEW PAVEMENT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUBOUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	1/1/1977	UNK	UNK	1/1/1977	O	UNK	UNK	UNK	UNK	STUBOUT	Installation Record	Y	1/1/1977	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1984	UNK	2"	1/1/1984	O	UNK	UNK	2"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1984	UNK	2"	1/1/1984	O	UNK	UNK	2"	UNK	STUB-OUT	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1981	C	1"	1/1/1981	O	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1981	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1972	UNK	3/4"	1/1/1972	O	UNK	UNK	3/4"	UNK	STUB-OUT	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1962	UNK	3/4"	1/1/1962	O	UNK	UNK	3/4"	UNK	STUB-OUT	Installation Record	Y	1/1/1962	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	2"	UNK	UNK	2"	UNK	O	UNK	UNK	2"	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	5/8"	UNK	L	5/8"	UNK	O	UNK	L	5/8"	UNK	STUB-OUT FOUND 12-28-84, REPAIRED WIPE. INSTALLED NEW CURB VALVE (NO BOX) 4-23-01	Installation Record	Y	4/23/2001	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	STUB-OUT TO VALCANT LOT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT, REMOVED WIPE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	STUB-OUT. 1998 NEW CURB STOP/ CURB BOX AND LOWERED UNDER STORM SEWER.	Installation Record	Y	1/1/1998	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	STUB-OUT. HOUSE IS GONE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	C	UNK	UNK	O	UNK	C	UNK	UNK	STUB-OUT. HOUSE REMOVED 1998	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	1/1/1970	UNK	UNK	1/1/1970	O	UNK	UNK	UNK	UNK	STUB-OUT. NO BOX, CURB STOP BURIED (DISCONNECT)	Installation Record	Y	1/1/1970	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	2"	UNK	UNK	2"	UNK	O	UNK	UNK	2"	UNK	STUB-OUT. OLD SERVICE TO CARWASH. TURED OFF IN 1999. NEW SERVICE TO 1508 S CENTRAL COMES OFF CENTRAL.	Installation Record	Y	1/1/1999	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT: CURB STOP CUT-IN 1999.	Installation Record	Y	1/1/1999	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT: CURB STOP CUT-IN 1999.	Installation Record	Y	1/1/1999	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	STUB-OUT: M215 W MCMILLAN	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	STUB-OUT: PINCHED OFF IN MANHOLE IN TERRACE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	1 1/4"	UNK	P	1 1/4"	UNK	O	UNK	P	1 1/4"	UNK	THEIR SIDE	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	THIS SERVICE IS A FREEZE-UP	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	TIES TO THE 10" MAIN	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/1961	C	3/4"	1/1/1961	O	UNK	C	3/4"	UNK	UNDER STORM SEWER.	Installation Record	Y	1/1/1961	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	Y	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	Vacant Lot. No building to service.	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1/2"	1/1/1972	C	1/2"	1/1/1972	O	UNK	C	1/2"	UNK	VALVE DC 11/71 IS THE SHUTOFF	Installation Record	Y	1/1/1972	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	VERIFIED	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1984	UNK	1"	1/1/1984	O	UNK	UNK	1"	UNK	VERIFIED 4/22/97	Installation Record	Y	1/1/1984	Mech excav	SL repair/replace record	Y	4/22/1997	Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	WAS REMOVED	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1985	UNK	3/4"	1/1/1985	O	UNK	UNK	3/4"	UNK	WAS TORN DOWN	Installation Record	Y	1/1/1985	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	C	1"	1/1/1983	O	UNK	C	1"	UNK	WATER DEPT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	Unk	UNK	1"	UNK	UNK	1"	UNK	O	UNK	UNK	1"	UNK	WATER DEPT	Installation Record	Y		Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1983	UNK	1"	1/1/1983	O	UNK	UNK	1"	UNK	WATER DEPT/ STUB-OUT	Installation Record	Y	1/1/1983	Mech excav	SL repair/replace record	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1969	UNK	3/4"	1/1/1969	O	UNK	UNK	3/4"	UNK		Installation Record	Y	1/1/1969	Mech excav	Previous eval	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1969	UNK	3/4"	1/1/1969	O	UNK	UNK	3/4"	UNK		Installation Record	Y	1/1/1969	Mech excav	Previous eval	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	UNK	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK		Installation Record	Y		Mech excav	Previous eval	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK		Installation Record	Y		Mech excav	Previous eval	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/2001	C	1 1/2"	1/1/2001	O	UNK	C	1 1/2"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2001	C	2"	1/1/2001	O	UNK	C	2"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	9/9/2021	C	1"	9/9/2021	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	9/9/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	<Null>	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	1" COPPER PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	4/29/2021	P	1"	4/29/2021	O	UNK	P	1"	UNK	1" HDPE installed customers side	Installation Record	Y	4/29/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	UNK	C	UNK	1"	1/1/2017	UNK	1"	1/1/2017	O	UNK	UNK	1"	UNK	1" TAP & 3.5' OF 1" COPPER CONN. TO EXIST. 3/4" COPPER--2017, PEMBER	Installation Record	Y	1/1/2017	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	7/22/2019	UNK	1"	7/22/2019	O	UNK	UNK	1"	UNK	1132 W. IVES	Installation Record	Y	7/22/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	2002-LAKELAND ENT. JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	2002-LAKELAND JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	1 1/4"	1/1/2003	UNK	1 1/4"	1/1/2003	O	UNK	UNK	1 1/4"	UNK	2003- EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	2"	1/1/2003	C	2"	1/1/2003	O	UNK	C	2"	UNK	2003- NEW 2" CORP,COPPER,CURBVALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/2002	C	3/4"	1/1/2002	O	UNK	C	3/4"	UNK	2003: 3/4" TAP&CORP - 2002:INSTALLED CURB BOX. REPLACED SERVICE FROM MAIN TO CURB BOX. LOWERED UNDER SANATARY.	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	O	UNK	C	1"	UNK	2003-EARTH INC NEW 1" CORP,COPPER,VALVE,BOX.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	O	UNK	C	1"	UNK	2003-EARTH INC.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	O	UNK	C	1"	UNK	2003-EARTH INC. NEW 1" CORP,COPPER,VALVE,BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1/2"	1/1/2003	C	1/2"	1/1/2003	O	UNK	C	1/2"	UNK	2003-NEW 1" CORP CONNECTED TO EXISTING 3/4 COPPER	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2003	UNK	1"	1/1/2003	O	UNK	UNK	1"	UNK	2003-NEW 1" CORP,COPPER.EXISTING BOX & VALVE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	3/4"	1/1/2009	C	3/4"	1/1/2009	O	UNK	C	3/4"	UNK	2009-BORED NEW 3/4" COPPER MAIN TO CURB VALVE. USED EXISTING 5/8" CORP.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1 1/2"	1/1/2012	C	1 1/2"	1/1/2012	O	UNK	C	1 1/2"	UNK	2012-MU RETAPPED ON 12" & INSTALLED 15' COPPER FROM MAIN	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	1/1/2016	C	1"	1/1/2016	O	UNK	C	1"	UNK	2016- INSTALLED 1" TAP AND CONNECTED TO 1" COPPER NEAR MAIN.	Installation Record	Y	1/1/2016	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	8/13/2018	C	1"	8/13/2018	O	UNK	C	1"	UNK	2016-INSTALLED 1" TAP AND CONNECTED TO 1" COPPER NEAR MAIN.	Installation Record	Y	8/13/2018	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	2"	8/13/2020	C	2"	8/13/2020	O	UNK	C	2"	UNK	2018 - INSTALLED BY EARTH INC *33' COPPER FROM CORP TO CS, 17' COPPER FROM CS TO EAST*, SAN. FORCE MAIN RUNS NORTH AND SOUTH 3' WEST OF CS 2018 - Installed by Earth Inc. *12.5' copper from corp - cs, 12' copper from cs to west. 2023-Boson ran 2" Poly connected where 2" copper ended - Poly to Pickle Ball Bldg. Flush out located 3' South & 2' East of SEC of bldg	Installation Record	Y	8/13/2020	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	1 1/4"	1/1/1993	UNK	1 1/4"	1/1/1993	O	UNK	UNK	1 1/4"	UNK	2'N OF NEW CORP	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	3/4 COPPER PROPERTY	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	3/4" COPPER INSIDE.	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2003	C	1"	1/1/2003	O	UNK	C	1"	UNK	3/4" COPPER INSIDE. 2003: NEW CORP,COPPER,VALVE, BOX. 2014: VACUUMED & REMOVED OLD CURB BOX AND STALLED NEW IN TERRACE	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	G	1"	1/1/2006	O	UNK	G	1"	UNK	3/4" IRON INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	Y	1"	6/25/2024	C	1"	6/25/2024	O	UNK	C	1"	UNK	6/25/24:Removed lead from wm-cs. Replaced w/ 1" corp (Old corp is 2' East of new corp.), 1" copper, 1" cs & box. Connected to 1/2" copper 3' South of cs. 1/2" copper is inside of galvanized pipe.	Installation Record	Y	6/25/2024	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	N	C	UNK	1"	6/3/2022	C	1"	6/3/2022	O	UNK	C	1"	UNK	6/3/22: Installed 1" copper service for Vincent De Paul Community Garden. Reigel Plbg installed private side.	Installation Record	Y	6/3/2022	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	UNK	C	UNK	1"	8/28/2024	P	1"	8/28/2024	O	UNK	P	1"	UNK	8/28/24: 1" tap, 1" copper, 1" cs & box, 1" HDPE from cs-meter. Suda installed customers side. 4" san. lat. is 18" above wm & runs w/ water service. Tracer wire ran w/ water & sewer.	Installation Record	Y	8/28/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	8/30/2021	C	1"	8/30/2021	O	UNK	C	1"	UNK	8/30/2021 Maddrell Const. Installed 1" copper from 2"x1" 'Y' to new CS & Box, 1' South of the south edge of sidewalk. 4" of 1" copper after CS to connect to existing 3/4" copper with a 3/4 x1" compression fitting. Shared with 204 E. 8th. CS is 8' deep.	Installation Record	Y	8/30/2021	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/21/2021	P	1"	9/21/2021	O	UNK	P	1"	UNK	9/21/2021: Earth installed 1" copper 17' past the curb valve (Pg 9 Daniels Addition inspection notes). 6/21/23: Kramas Plbg. Conn to copper and ran 1" HDPE to the meter.	Installation Record	Y	9/21/2021	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	UNK	C	UNK	1"	6/1/1998	C	1"	6/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	6/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1 1/2"	1/1/1994	C	1 1/2"	1/1/1994	O	UNK	C	1 1/2"	UNK	ABANDONDED 8/14/2020. SERVICED FROM 4" CUT-IN	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	ATTACHED TO 3/4" COPPER 14'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	O	UNK	C	1"	UNK	ATTACHED TO 3/4" COPPER 5'PAST VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	Y	1"	1/1/2013	L	1"	1/1/2013	O	UNK	L	1"	UNK	ATTACHED TO 5/8 LEAD 6'S OF VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	2"	1/1/2013	C	2"	1/1/2013	O	UNK	C	2"	UNK	ATTACHED TO EXISTING 2" COPPER 2'N OF VALVE, ***THERE IS A PRIVATE CURB BOX 8' EAST OF THE METER BOX***	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	O	UNK	C	1"	UNK	ATTACHED TO EXISTING 3/4" COPPER 1' PAST VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	10/29/2019	UNK	1"	10/29/2019	O	UNK	UNK	1"	UNK	BACH EXCAVATING, SUDA PLBG, MU WATER - TAPPED ON WEST SIDE OF WATER MAIN & CROSSES OVER MAIN TO CURB STOP	Installation Record	Y	10/29/2019	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1 1/2"	1/1/2005	C	1 1/2"	1/1/2005	O	UNK	C	1 1/2"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2005	UNK	2"	1/1/2005	O	UNK	UNK	2"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1987	UNK	1"	1/1/1987	O	UNK	UNK	1"	UNK	BEING TORN DOWN	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1989	UNK	1"	1/1/1989	O	UNK	UNK	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1989	UNK	1"	1/1/1989	O	UNK	UNK	1"	UNK	BOON	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1988	C	1"	1/1/1988	O	UNK	C	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	BOON	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1 1/2"	1/1/2000	C	1 1/2"	1/1/2000	O	UNK	C	1 1/2"	UNK	BOX, & NEW COPPER.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	Y	1"	1/1/2009	L	1"	1/1/2009	O	UNK	L	1"	UNK	CONNECTED TO 5/8" LEAD 10'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/2002	L	3/4"	1/1/2002	O	UNK	L	3/4"	UNK	CORP LOCATED 7'W & 21'S OF N.W.P.L. OF DOEGE AND PINE., C.B./C.V. moved due to leak repair 2015	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	COUPLER 14'E OF MAIN. STUB-OUT 1" COPPER 14'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	COUPLER 15'E OF MAIN. STUB-OUT 1" COPPER 12'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	1"	1/1/2014	C	1"	1/1/2014	O	UNK	C	1"	UNK	CURB BOX INSTALLED	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	O	UNK	C	1"	UNK	DOINE	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	DOINE / MURPHY OIL	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1993	C	1"	1/1/1993	O	UNK	C	1"	UNK	DUG BY MYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	1"	1/1/2018	C	1"	1/1/2018	O	UNK	C	1"	UNK	DUPLEX WITH 900 E BLODGETT *2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 4' - 1" COPPER WITH 1"X3/4" COUPLING	Installation Record	Y	1/1/2018	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH- ALT. ADDRESS 1540 E 20TH	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	C	1"	1/1/2008	O	UNK	C	1"	UNK	EARTH. 2/26/24 - Aarons plumbing installed new sewer and 1" SDR-9 CTS water service installed for new house. Permit #20240092	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	1/1/2003	UNK	1"	1/1/2003	O	UNK	UNK	1"	UNK	FEED GARAGE TO N.	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1992	UNK	3/4"	1/1/1992	O	UNK	UNK	3/4"	UNK	FOR TOWER PAINTING	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	GAFFNEY	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	8/1/2020	P	1"	8/1/2020	O	UNK	P	1"	UNK	GAFFNEY PLBG	Installation Record	Y	8/1/2020	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	GAFFNEY PLBG.	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	N	1"	9/12/2024	UNK	1"	9/12/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 31	Installation Record	Y	9/12/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/11/2024	UNK	1"	9/11/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 35	Installation Record	Y	9/11/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/12/2024	UNK	1"	9/12/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 36	Installation Record	Y	9/12/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/27/2024	UNK	1"	9/27/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 27' - 1" copper after cs. Green Acres Lot 33	Installation Record	Y	9/27/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/2/2024	UNK	1"	8/2/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 1" copper after cs.	Installation Record	Y	8/2/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/4/2024	UNK	1"	9/4/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 11' - 1" copper after cs.	Installation Record	Y	9/4/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/26/2024	UNK	1"	9/26/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 19' - 1" copper after cs.	Installation Record	Y	9/26/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/7/2024	UNK	1"	8/7/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 19' - 1" copper after cs. Green Acres Lot 48	Installation Record	Y	8/7/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/1/2024	UNK	1"	10/1/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs.	Installation Record	Y	10/1/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/26/2024	UNK	1"	9/26/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs.	Installation Record	Y	9/26/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/10/2024	UNK	1"	9/10/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 20	Installation Record	Y	9/10/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/10/2024	UNK	1"	9/10/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 21	Installation Record	Y	9/10/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/5/2024	UNK	1"	9/5/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 25	Installation Record	Y	9/5/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/10/2024	UNK	1"	9/10/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 27	Installation Record	Y	9/10/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/12/2024	UNK	1"	9/12/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 29	Installation Record	Y	9/12/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/11/2024	UNK	1"	9/11/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 37	Installation Record	Y	9/11/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/12/2024	UNK	1"	9/12/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 20' - 1" copper after cs. Green Acres Lot 38	Installation Record	Y	9/12/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/30/2024	UNK	1"	9/30/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs.	Installation Record	Y	9/30/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	C	N	1"	9/5/2024	UNK	1"	9/5/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs. Green Acres Lot 22	Installation Record	Y	9/5/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/6/2024	UNK	1"	8/6/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 21' - 1" copper after cs. Green Acres Lot 52	Installation Record	Y	8/6/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/13/2024	UNK	1"	9/13/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	9/13/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/1/2024	UNK	1"	10/1/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	10/1/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/1/2024	UNK	1"	10/1/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	10/1/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/30/2024	UNK	1"	9/30/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	9/30/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/27/2024	UNK	1"	9/27/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs.	Installation Record	Y	9/27/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/11/2024	UNK	1"	9/11/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs. Green Acre Lot 30	Installation Record	Y	9/11/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/5/2024	UNK	1"	9/5/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs. Green Acres Lot 28	Installation Record	Y	9/5/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/12/2024	UNK	1"	9/12/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs. Green Acres Lot 45	Installation Record	Y	9/12/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/8/2024	UNK	1"	8/8/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs. Green Acres Lot 50	Installation Record	Y	8/8/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/8/2024	UNK	1"	8/8/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 22' - 1" copper after cs. Green Acres Lot 51	Installation Record	Y	8/8/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/7/2024	UNK	1"	10/7/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs.	Installation Record	Y	10/7/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/7/2024	UNK	1"	10/7/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs.	Installation Record	Y	10/7/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/6/2024	UNK	1"	10/6/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs.	Installation Record	Y	10/6/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/5/2024	UNK	1"	9/5/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs.	Installation Record	Y	9/5/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/6/2024	UNK	1"	8/6/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs.	Installation Record	Y	8/6/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/5/2024	UNK	1"	8/5/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs.	Installation Record	Y	8/5/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/8/2024	UNK	1"	8/8/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs. Green Acres Lot 24	Installation Record	Y	8/8/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/8/2024	UNK	1"	8/8/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs. Green Acres Lot 41	Installation Record	Y	8/8/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/6/2024	UNK	1"	8/6/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 23' - 1" copper after cs. Green Acres Lot 47	Installation Record	Y	8/6/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/10/2024	UNK	1"	9/10/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 24' - 1" copper after cs. Green Acres Lot 26	Installation Record	Y	9/10/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/7/2024	UNK	1"	8/7/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 24' - 1" copper after cs. Green Acres lot 43	Installation Record	Y	8/7/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/7/2024	UNK	1"	8/7/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 24' - 1" copper after cs. Green Acres Lot 44	Installation Record	Y	8/7/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/8/2024	UNK	1"	8/8/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 24' - 1" copper after cs. Green Acres Lot 49	Installation Record	Y	8/8/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/4/2024	UNK	1"	9/4/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 25' - 1" copper after cs.	Installation Record	Y	9/4/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/11/2024	UNK	1"	9/11/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 25' - 1" copper after cs. Green Acres Lot 32	Installation Record	Y	9/11/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/7/2024	UNK	1"	10/7/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 27' - 1" copper after cs.	Installation Record	Y	10/7/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/6/2024	UNK	1"	10/6/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 27' - 1" copper after cs.	Installation Record	Y	10/6/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	9/27/2024	UNK	1"	9/27/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 27' - 1" copper after cs. Green Acres Lot 34	Installation Record	Y	9/27/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/7/2024	UNK	1"	10/7/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 27' - 1" copper after cs. Green Acres Lot 23	Installation Record	Y	10/7/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	10/7/2024	UNK	1"	10/7/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 27' - 1" copper after cs. Green Acres Lot 24	Installation Record	Y	10/7/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	N	1"	8/5/2024	UNK	1"	8/5/2024	O	UNK	UNK	1"	UNK	Haas Construction. 1-1" corp., 1" copper (corp.-cs), 1" cs & box, 28' - 1" copper after cs. Green Acres Lot 46	Installation Record	Y	8/5/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	1/1/2008	UNK	1"	1/1/2008	O	UNK	UNK	1"	UNK	HAAS. STUB-OUT FOR VACCANT LOT. INSTALLED CURB BOX. SERVICE COMES OFF 14TH ST.	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1996	C	1 1/2"	1/1/1996	O	UNK	C	1 1/2"	UNK	IF ENTERS THE BUILDING	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	8/7/2018	C	2"	8/7/2018	O	UNK	C	2"	UNK	INSTALLED BY EARTH INC.	Installation Record	Y	8/7/2018	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	2"	8/7/2018	UNK	2"	8/7/2018	O	UNK	UNK	2"	UNK	INSTALLED BY EARTH INC. -ABANDONED SANITARY FORCE MAIN RUNS PARALLEL APPROX. 5' EAST OF WATERMAIN	Installation Record	Y	8/7/2018	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	2"	11/17/2020	P	2"	11/17/2020	O	UNK	P	2"	UNK	Installed with hydrant (Reigel Plbg. ran 2" poly after curb stop. 2" service saddle at main, copper main to cs.)	Installation Record	Y	11/17/2020	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	N	C	UNK	2"	4/20/2021	UNK	2"	4/20/2021	O	UNK	UNK	2"	UNK	Jakel PLBG. - Used a 2" x 6" stainless service saddle. Service to 1613 N. Peach is 4.5' North of 2" tap. Pipe bell inbetween both services	Installation Record	Y	4/20/2021	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	O	UNK	C	1"	UNK	LAKELAND - REPLACED FROM MAIN TO BACKSIDE OF VALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND ENT JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND ENT JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND ENT. JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2002	UNK	2"	1/1/2002	O	UNK	UNK	2"	UNK	LAKELAND JO#5306	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	O	UNK	C	1"	UNK	LAKELAND- REPLACED FROM MAIN TO BACK OF VALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2002	UNK	1"	1/1/2002	O	UNK	UNK	1"	UNK	LAKELAND- REPLACED FROM MAIN TO BACK OF VALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	O	UNK	C	1"	UNK	LAKELAND- REPLACED FROM MAIN TO BACKSIDE OF VALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	O	UNK	C	1"	UNK	LAKELAND-REPLACED FROM MAIN TO BACKSIDE OF VALVE	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	6/29/2018	UNK	1"	6/29/2018	O	UNK	UNK	1"	UNK	MARK MEYERS	Installation Record	Y	6/29/2018	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	2"	1/1/2003	C	2"	1/1/2003	O	UNK	C	2"	UNK	MEWD	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK	MEWD	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2001	UNK	1"	1/1/2001	O	UNK	UNK	1"	UNK	MEWD/ TAPPED OFF HYDRANT RUN 2' W OF VALVE	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2001	UNK	1"	1/1/2001	O	UNK	UNK	1"	UNK	MEWD/ TAPPED OFF HYDRANT RUN 2' W OF VALVE	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK	MEWD/REPLACED CORP TO CURB BOX/STUBOUT	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1 1/4"	1/1/2003	UNK	1 1/4"	1/1/2003	O	UNK	UNK	1 1/4"	UNK	MEWD-STUBOUT 2003. 8/4/23- Vac'd out curb box & removed curb box. Turned off the curb valve - 1-1/4" copper - Did not but the cb back on. JN,TK	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1990	UNK	1 1/2"	1/1/1990	O	UNK	UNK	1 1/2"	UNK	MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1990	UNK	1 1/2"	1/1/1990	O	UNK	UNK	1 1/2"	UNK	MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	UNK	1"	1/1/1990	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1987	UNK	1 1/2"	1/1/1987	O	UNK	UNK	1 1/2"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1987	UNK	1 1/2"	1/1/1987	O	UNK	UNK	1 1/2"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1987	UNK	1"	1/1/1987	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1987	UNK	1"	1/1/1987	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1987	UNK	1"	1/1/1987	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1987	UNK	1"	1/1/1987	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1987	C	3/4"	1/1/1987	O	UNK	C	3/4"	UNK	MEYER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1986	UNK	1"	1/1/1986	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1986	UNK	1"	1/1/1986	O	UNK	UNK	1"	UNK	MEYER	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1999	C	1"	1/1/1999	O	UNK	C	1"	UNK	MEYER, STUB-OUT	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	MEYER/STUB-OUT	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	6/1/2019	UNK	1"	6/1/2019	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	6/1/2019	Mech excav	Installed after lead ban	Y	2013-2018	Cross Connection Survey	
UNK	UNK	UNK	C	UNK	1"	1/1/1997	C	1"	1/1/1997	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1996	UNK	1"	1/1/1996	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	MEYERS	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1993	UNK	1"	1/1/1993	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1993	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1990	UNK	1 1/2"	1/1/1990	O	UNK	UNK	1 1/2"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1990	UNK	1 1/2"	1/1/1990	O	UNK	UNK	1 1/2"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	UNK	1"	1/1/1990	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1989	UNK	1"	1/1/1989	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	C	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1986	UNK	1"	1/1/1986	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1986	UNK	1"	1/1/1986	O	UNK	UNK	1"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1986	UNK	3/4"	1/1/1986	O	UNK	UNK	3/4"	UNK	MEYERS	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2012	UNK	1"	1/1/2012	O	UNK	UNK	1"	UNK	MEYER'S	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	2"	1/1/2005	P	2"	1/1/2005	O	UNK	P	2"	UNK	MEYERS 2" PLASTIC AFTER CURB VALVE	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	O	UNK	C	2"	UNK	MEYERS, STUB-OUT	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	O	UNK	C	2"	UNK	MEYERS, STUB-OUT	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	O	UNK	C	2"	UNK	MEYERS, STUB-OUT	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	O	UNK	C	2"	UNK	MEYERS, STUB-OUT	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	O	UNK	C	2"	UNK	MEYERS, STUB-OUT	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1991	C	2"	1/1/1991	O	UNK	C	2"	UNK	MEYERS, STUB-OUT	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	C	1"	1/1/2005	O	UNK	C	1"	UNK	MFLD UTILITIES	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1999	C	1"	1/1/1999	O	UNK	C	1"	UNK	NEW 1" CORP & CURB STOP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	O	UNK	C	3/4"	UNK	NEW 3/4" CORP & CURB STOP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	O	UNK	C	3/4"	UNK	NEW 3/4" CORP & CURB STOP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1999	L	3/4"	1/1/1999	O	UNK	L	3/4"	UNK	NEW 3/4" CORP & CURB STOP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1999	C	3/4"	1/1/1999	O	UNK	C	3/4"	UNK	NEW 3/4" CORP.	Installation Record	Y	1/1/1999	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/2002	C	3/4"	1/1/2002	O	UNK	C	3/4"	UNK	NO CONNECTION-TEMP SERVICE FOR SS BOOSTER 2002	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2004	UNK	2"	1/1/2004	O	UNK	UNK	2"	UNK	OLD ARMORY	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2011	C	1"	1/1/2011	O	UNK	C	1"	UNK	PEMBER. 1/2" COPPER PROP. SIDE	Installation Record	Y	1/1/2011	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	1"	1/1/1995	C	1"	1/1/1995	O	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	REDETKZE	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	REDETKZE	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	O	UNK	UNK	1"	UNK	REDETZE	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	UNK	1"	1/1/2008	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	UNK	1"	1/1/2008	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2008	UNK	1"	1/1/2008	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2008	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	C	1"	1/1/2006	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	2"	1/1/1991	UNK	2"	1/1/1991	O	UNK	UNK	2"	UNK	REDETZKE	Installation Record	Y	1/1/1991	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	UNK	1"	1/1/1990	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	UNK	1"	1/1/1990	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	UNK	1"	1/1/1990	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1989	C	1"	1/1/1989	O	UNK	C	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1989	UNK	1"	1/1/1989	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1989	UNK	1"	1/1/1989	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1989	UNK	1"	1/1/1989	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1989	UNK	1"	1/1/1989	O	UNK	UNK	1"	UNK	REDETZKE	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	REDETZKE - 1110 WILDFLOWER DR.	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	O	UNK	UNK	1"	UNK	REDETZKE-NO ACCOUNT.STUB OUT	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1997	C	1"	1/1/1997	O	UNK	C	1"	UNK	REIGEL	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	O	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	O	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	O	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1992	UNK	1"	1/1/1992	O	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1988	UNK	1"	1/1/1988	O	UNK	UNK	1"	UNK	REIGEL	Installation Record	Y	1/1/1988	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2007	C	1"	1/1/2007	O	UNK	C	1"	UNK	REIGEL PLBG.- STUB-OUT IS 12 BEYOND CURB BOX	Installation Record	Y	1/1/2007	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1990	C	1"	1/1/1990	O	UNK	C	1"	UNK	RON MEYER	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1992	C	1"	1/1/1992	O	UNK	C	1"	UNK	RON MEYERS SHOP	Installation Record	Y	1/1/1992	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	RON MEYERS' STUB-OUT	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1998	C	1 1/2"	1/1/1998	O	UNK	C	1 1/2"	UNK	RUNS OVER THE TOP OF THE HYD. RUN.	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1987	UNK	1"	1/1/1987	O	UNK	UNK	1"	UNK	SCHREINER	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2004	C	1"	1/1/2004	O	UNK	C	1"	UNK	SERVICE IN SANITARY SEWER SEWER TRENCH	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2014	P	1"	1/1/2014	O	UNK	P	1"	UNK	SHED ON SW COR OF H&S PROPERTY	Installation Record	Y	1/1/2014	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	O	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	O	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	O	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2004	UNK	1"	1/1/2004	O	UNK	UNK	1"	UNK	STEEN	Installation Record	Y	1/1/2004	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2002	C	1"	1/1/2002	O	UNK	C	1"	UNK	STEEN	Installation Record	Y	1/1/2002	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1989	C	1 1/2"	1/1/1989	O	UNK	C	1 1/2"	UNK	STRATFORD PLUMBING: STUB-OUT	Installation Record	Y	1/1/1989	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1986	UNK	1"	1/1/1986	O	UNK	UNK	1"	UNK	STUB OUT 1986 PAVING	Installation Record	Y	1/1/1986	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	O	UNK	C	3/4"	UNK	STUB-OUT	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1996	C	1 1/2"	1/1/1996	O	UNK	C	1 1/2"	UNK	STUB-OUT	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	O	UNK	C	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1 1/2"	1/1/1990	UNK	1 1/2"	1/1/1990	O	UNK	UNK	1 1/2"	UNK	STUB-OUT	Installation Record	Y	1/1/1990	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1987	UNK	1"	1/1/1987	O	UNK	UNK	1"	UNK	STUB-OUT	Installation Record	Y	1/1/1987	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT 1" COPPER 13'W OF BOX A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2005	UNK	1"	1/1/2005	O	UNK	UNK	1"	UNK	STUB-OUT 13' PAST CURB VALVE	Installation Record	Y	1/1/2005	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT 14' PAST BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	STUB-OUT 14' PAST BOX. BORED. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT 14'E OF BOX. A-1 EXCAVATING. COUPLER 13'E OF MAIN	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 15' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 15' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 15' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	STUB-OUT 15'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 15'PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 16' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 16' PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 16'PAST CURB VALVE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 17'	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 17'	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 18'	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT 18'	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT 5'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	STUB-OUT A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT COPPER 15'W OF BOX.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	C	1"	1/1/2009	O	UNK	C	1"	UNK	STUB-OUT COPPER 3'E OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT COPPER 4'E OF BOX.	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT NORTH OF CITY HALL PLAZA	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	9/23/2024	UNK	1"	9/23/2024	O	UNK	UNK	1"	UNK	Stub-out under sidewalk	Installation Record	Y	9/23/2024	Mech excav	Installed after lead ban	Y	8/1/2025	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	1"	1/1/2006	UNK	1"	1/1/2006	O	UNK	UNK	1"	UNK	STUB-OUT, 3/4" COPPER INSIDE	Installation Record	Y	1/1/2006	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT. 15' W OF BOX. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2009	UNK	1"	1/1/2009	O	UNK	UNK	1"	UNK	STUB-OUT. A-1 EXCAVATING	Installation Record	Y	1/1/2009	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	UNK	UNK	3/4"	1/1/1994	C	3/4"	1/1/1994	O	UNK	C	3/4"	UNK	STUB-OUT:	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/1996	C	1"	1/1/1996	O	UNK	C	1"	UNK	STUB-OUT: REDETZKE CONSTRUCTION	Installation Record	Y	1/1/1996	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2003	UNK	1"	1/1/2003	O	UNK	UNK	1"	UNK	STUB-OUT-2003: NEW 1" CORP,COPPER,VALVE & BOX	Installation Record	Y	1/1/2003	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2012	UNK	1"	1/1/2012	O	UNK	UNK	1"	UNK	TAP LOCATION N:562602.953783-E:644824.308424	Installation Record	Y	1/1/2012	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	3/4"	1/1/2001	C	3/4"	1/1/2001	O	UNK	C	3/4"	UNK	TRIERWEILER	Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2000	P	1"	1/1/2000	O	UNK	P	1"	UNK	TRIERWEILER	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2000	C	1"	1/1/2000	O	UNK	C	1"	UNK	TRIERWEILER: STUB-OUT.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	C	UNK	1 1/4"	1/1/2013	C	1 1/4"	1/1/2013	O	UNK	C	1 1/4"	UNK	TWO 1" TAPS	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban	Y	2013-2018	Visual Insp during install or repair	
UNK	UNK	UNK	C	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	O	UNK	C	3/4"	UNK	WALK.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/2000	C	3/4"	1/1/2000	O	UNK	C	3/4"	UNK	WALK.	Installation Record	Y	1/1/2000	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	1/1/1997	C	3/4"	1/1/1997	O	UNK	C	3/4"	UNK	WAS GOING TO BE USED FOR A FOUNTAIN	Installation Record	Y	1/1/1997	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1998	C	1"	1/1/1998	O	UNK	C	1"	UNK	WESTON CONSTRUCTION	Installation Record	Y	1/1/1998	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1995	C	1"	1/1/1995	O	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1995	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/1994	C	1"	1/1/1994	O	UNK	C	1"	UNK	WIMMER CONST	Installation Record	Y	1/1/1994	Mech excav	Installed after lead ban	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	UNK	UNK	1"	1/1/2001	C	1"	1/1/2001	O	UNK	C	1"	UNK		Installation Record	Y	1/1/2001	Mech excav	Installed after lead ban	Y			Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/1997	DI	6"	1/1/1997	O	UNK	DI	6"	UNK	1998	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/1997	DI	6"	1/1/1997	O	UNK	DI	6"	UNK	1998	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/1997	DI	6"	1/1/1997	O	UNK	DI	6"	UNK	1998	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/1997	DI	6"	1/1/1997	O	UNK	DI	6"	UNK	1998	Installation Record	Y	1/1/1997	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/1984	UNK	6"	1/1/1984	O	UNK	UNK	6"	UNK	& THE ALLEY	Installation Record	Y	1/1/1984	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2009	DI	6"	1/1/2009	O	UNK	DI	6"	UNK	<Null>	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	8"	7/28/2021	DI	8"	7/28/2021	O	UNK	DI	8"	UNK	12"x8" Tapping sleeve flanged. 8" AFC resiliant wedge valve flanged to MJ. MP, AP	Installation Record	Y	7/28/2021	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
UNK	UNK	UNK	UNK	UNK	6"	UNK	UNK	6"	UNK	O	UNK	UNK	6"	UNK	1983-INSULATED. THIS VALVE IS CLOSED.	Installation Record	Y	1/1/1983	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	UNK	UNK	6"	UNK	O	UNK	UNK	6"	UNK	2002: DISCONNECTED AND CAPPED.	Installation Record	Y	1/1/2002	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	8"	1/1/2004	P	8"	1/1/2004	O	UNK	P	8"	UNK	2004-DAVIES,CUT-IN VALVE IN ROAD.	Installation Record	Y	1/1/2004	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	4"	1/1/1974	UNK	4"	1/1/1974	O	UNK	UNK	4"	UNK	2006-4" LINE USED FOR PRIVATE HYD.	Installation Record	Y	1/1/1974	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	DI	UNK	4"	12/23/2020	P	4"	12/23/2020	O	UNK	P	4"	UNK	4" HDPE bored in under road, tied to 8" main w/ 8x4" tee, hymax to south 1' of tee (4" AFC valve)	Installation Record	Y	12/23/2020	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
UNK	UNK	UNK	C	UNK	4"	1/1/1971	UNK	4"	1/1/1971	O	UNK	UNK	4"	UNK	4" SPRINKLER LINE. 3/4" COPPER CLAMPED OFF 10'E OF VALVE	Installation Record	Y	1/1/1971	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	8"	UNK	UNK	8"	UNK	O	UNK	UNK	8"	UNK	8" FIRE SERVICE	Installation Record	Y		Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	12"	1/1/2011	DI	12"	1/1/2011	O	UNK	DI	12"	UNK	AHERN. DIP ALL THE WAY INTO BLDG.	Installation Record	Y	1/1/2011	Mech excav	Diameter > 2"	Y	2021-2025	Visual Insp during install or repair	
UNK	UNK	N	DI	UNK	4"	UNK	UNK	4"	UNK	O	UNK	UNK	4"	UNK	ALSO VALVE 33' W OF THIS LOCATION	Installation Record	Y		Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2009	DI	6"	1/1/2009	O	UNK	DI	6"	UNK	AUGUST WINTER	Installation Record	Y	1/1/2009	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/1999	DI	6"	1/1/1999	O	UNK	DI	6"	UNK	BACCO CONST.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/1999	DI	6"	1/1/1999	O	UNK	DI	6"	UNK	BACCO: SERVICE ENTENDS TO R/W.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	4"	1/1/2005	UNK	4"	1/1/2005	O	UNK	UNK	4"	UNK	BADGER ENVIRONMENTAL	Installation Record	Y	1/1/2005	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2007	UNK	6"	1/1/2007	O	UNK	UNK	6"	UNK	BOB NIKOLAY	Installation Record	Y	1/1/2007	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	P	UNK	6"	7/16/2024	P	6"	7/16/2024	O	UNK	P	6"	UNK	C900	Installation Record	Y	7/16/2024	Mech excav	Diameter > 2"	Y	2021-2025	Visual insp at meter	
UNK	UNK	UNK	UNK	UNK	4"	1/1/1970	UNK	4"	1/1/1970	O	UNK	UNK	4"	UNK	CAPPED-OFF	Installation Record	Y	1/1/1970	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	4"	8/14/2020	DI	4"	8/14/2020	O	UNK	DI	4"	UNK	CUT-IN SERVICE. ABANDONED 1-1/2" CORP. 4' WEST OF TEE	Installation Record	Y	8/14/2020	Mech excav	Diameter > 2"	Y	2021-2025	Visual Insp during install or repair	
UNK	UNK	UNK	DI	UNK	6"	1/1/2015	DI	6"	1/1/2015	O	UNK	DI	6"	UNK	CUT-IN VALVE	Installation Record	Y	1/1/2015	Mech excav	Diameter > 2"	Y	2021-2025	Visual Insp during install or repair	

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	DI	UNK	6"	1/1/2012	DI	6"	1/1/2012	O	UNK	DI	6"	UNK	CUT-IN VALVE. 6" LINE THEN INCREASED TO 8" 20'N OF VALVE	Installation Record	Y	1/1/2012	Mech excav	Diameter > 2"	Y	2021-2025	Visual Insp during install or repair	
UNK	UNK	UNK	DI	UNK	8"	1/1/2006	UNK	8"	1/1/2006	O	UNK	UNK	8"	UNK	END OF SERVICE TEES OFF TO HYD AND CAPPED ON OTHER	Installation Record	Y	1/1/2006	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	8"	1/1/1999	DI	8"	1/1/1999	O	UNK	DI	8"	UNK	FIRE SERVICE	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	8"	1/1/1989	DI	8"	1/1/1989	O	UNK	DI	8"	UNK	FIRE SERVICE	Installation Record	Y	1/1/1989	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/1985	UNK	6"	1/1/1985	O	UNK	UNK	6"	UNK	FIRE SERVICE	Installation Record	Y	1/1/1985	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	8"	UNK	UNK	8"	UNK	O	UNK	UNK	8"	UNK	FIRE SERVICE COMBINED WITH POTABLE WATER SERVICE	Installation Record	Y		Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/1999	DI	6"	1/1/1999	O	UNK	DI	6"	UNK	FIRE SERVICE: 215'W OF VALVE 287.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2006	DI	6"	1/1/2006	O	UNK	DI	6"	UNK	GAFFNEY	Installation Record	Y	1/1/2006	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	DI	UNK	6"	1/1/1999	DI	6"	1/1/1999	O	UNK	DI	6"	UNK	INSIDE PROPERTY LINE.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2004	DI	6"	1/1/2004	O	UNK	DI	6"	UNK	LAKELAND ENT. 78'N & 20'E OF VALVE 1373 OR 37'S & 12'E OF VALVE 1372	Installation Record	Y	1/1/2004	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	UNK	UNK	6"	UNK	O	UNK	UNK	6"	UNK	MEYERS: SPRINKLER SYSYTEM	Installation Record	Y		Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	4"	1/1/1968	DI	4"	1/1/1968	O	UNK	DI	4"	UNK	MFLD PLB	Installation Record	Y	1/1/1968	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	4"	1/1/2006	CI-U	4"	1/1/2006	O	UNK	CI-U	4"	UNK	MFLD UTILITIES	Installation Record	Y	1/1/2006	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	11/20/2019	P	6"	11/20/2019	O	UNK	P	6"	UNK	MID-WISCONSIN CONSTRUCTION - LIVE TAP (CORE & MAIN) SS SLEEVE, 6" CUT-IN MECHANICAL JOINT VALVE AFC H.D. STEM. 6" C900 PLASTIC ON CUSTOMER SIDE	Installation Record	Y	11/20/2019	Mech excav	Diameter > 2"	Y	2021-2025	Visual Insp during install or repair	
UNK	UNK	UNK	DI	UNK	8"	9/25/2019	DI	8"	9/25/2019	O	UNK	DI	8"	UNK	NEW SERVICE VALVE INSTALLED IN 2019 (8" AFC VALVE)	Installation Record	Y	9/25/2019	Mech excav	Diameter > 2"	Y	2021-2025	Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	8"	1/1/1988	UNK	8"	1/1/1988	O	UNK	UNK	8"	UNK	ON PRIVATE PROPERTY	Installation Record	Y	1/1/1988	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	UNK	DI	6"	UNK	O	UNK	DI	6"	UNK	PLAN.	Installation Record	Y		Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/1999	DI	6"	1/1/1999	O	UNK	DI	6"	UNK	PRIVATE HYD THAT IS SHUT.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2005	DI	6"	1/1/2005	O	UNK	DI	6"	UNK	REDETZKE	Installation Record	Y	1/1/2005	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	8"	1/1/1991	DI	8"	1/1/1991	O	UNK	DI	8"	UNK	REIGEL	Installation Record	Y	1/1/1991	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2005	P	6"	1/1/2005	O	UNK	P	6"	UNK	REIGEL PLBG	Installation Record	Y	1/1/2005	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2003	DI	6"	1/1/2003	O	UNK	DI	6"	UNK	REIGEL PLBG. FIRE SERVICE ONLY	Installation Record	Y	1/1/2003	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	10/15/2019	DI	6"	10/15/2019	O	UNK	DI	6"	UNK	REIGEL PLBG/DOINE	Installation Record	Y	10/15/2019	Mech excav	Diameter > 2"	Y	2021-2025	Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	6"	1/1/1968	CI-U	6"	1/1/1968	O	UNK	CI-U	6"	UNK	SCHREINER	Installation Record	Y	1/1/1968	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	4"	UNK	CI-U	4"	UNK	O	UNK	CI-U	4"	UNK	SERVICES LAUNDRY ROOM & SMALL BOILER OFF THE WORKSHOP. 3" Cast	Installation Record	Y		Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	P	UNK	6"	1/1/2014	P	6"	1/1/2014	O	UNK	P	6"	UNK	STAINLESS MJ TAPPING SLEEVE CUT-IN VALVE CONNECTED TO BORED HDPE PIPE	Installation Record	Y	1/1/2014	Mech excav	Diameter > 2"	Y	2021-2025	Visual Insp during install or repair	
UNK	UNK	UNK	UNK	UNK	10"	1/1/1993	DI	10"	1/1/1993	O	UNK	DI	10"	UNK	STUB-OUT	Installation Record	Y	1/1/1993	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/1996	DI	6"	1/1/1996	O	UNK	DI	6"	UNK	THIS IS A STUB-OUT FROM VALVE IN STREET-20' OF 6" PIPE TO WEST.	Installation Record	Y	1/1/1996	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	N	DI	UNK	6"	1/1/1999	UNK	6"	1/1/1999	O	UNK	UNK	6"	UNK	THIS SERVICE WAS LOOPED. SERVES ONLY SOUTH WING	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	8"	1/1/1999	DI	8"	1/1/1999	O	UNK	DI	8"	UNK	TO TEE WITH 8" PLUG TO NORTH.	Installation Record	Y	1/1/1999	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2001	UNK	6"	1/1/2001	O	UNK	UNK	6"	UNK	USP 6" VALVE. REDUCED TO 4" TO BLDG.	Installation Record	Y	1/1/2001	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	UNK	UNK	6"	1/1/2000	DI	6"	1/1/2000	O	UNK	DI	6"	UNK	VALVE IS IN CURB LINE.	Installation Record	Y	1/1/2000	Mech excav	Diameter > 2"	Y		Visual Insp during install or repair	Not serving a customer
UNK	613 N CENTRAL AVE	UNK	UNK-LG	UNK	UNK	1/1/1922	C	3/4"	1/1/1922	O	UNK	UNK	UNK		3/4" COPPER LOCKING VALVE	Installation Record	N			Field inspection only	Y		Visual Insp during install or repair	Not serving a customer
UNK	304 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	UNK-NOLG	UNK	10/4/1999	O	UNK	UNK	UNK		HOUSE REMOVED 10-4-99	Installation Record	N			Field Inspection Only	Y		Visual Insp during install or repair	Not serving a customer
UNK	315 W 5TH ST	UNK	UNK-LG	UNK	UNK	1/1/1946	C	UNK	1/1/2017	O	UNK	C	C		REIGEL--2017	Installation Record	N			Field Inspection Only	Y		Visual Insp during install or repair	Not serving a customer
UNK	404 W 6TH ST	UNK	UNK-LG	UNK	UNK	1/1/1926	UNK-NOLG	UNK	1/1/2017	O	UNK	UNK	UNK		REIGEL--2017	Installation Record	N			Field Inspection Only	Y		Visual Insp during install or repair	Not serving a customer
UNK	UNK	UNK	L	Y	5/8"	UNK	UNK	5/8"	UNK	O	UNK	UNK	5/8"	UNK	2009-REMOVED LEAD WIPE @ MAIN. 2011-INSTALLED CURB VALVE ON PROP. SIDE 12'W OF EXISTING CURB BOX TO SHUT OFF WATER AND DISCONNECTED SERVICE. MARKED WITH 2X4	Installation Record	Y	1/1/2009	Mech excav	SL repair/replace record				Not serving a customer
UNK	UNK	N	C	UNK	3/4"	UNK	C	3/4"	UNK	O	UNK	C	3/4"	UNK	2010-SERVICE DISCONNECTED FROM HOME AND INSTALLED CURB VALVE. PROP. IS FED FROM PRIVATE WELL. SERVICE STILL LIVE TO CURB VALVE	Installation Record	Y	1/1/2010	Mech excav	SL repair/replace record				Not serving a customer
UNK	UNK	UNK	C	UNK	1"	UNK	C	1"	UNK	O	UNK	C	1"	UNK	2022: new 1" from main to curb valve. 3/4" copper on owners side. Used existing corp.	Installation Record	Y	1/1/2022	Mech excav	SL repair/replace record				Not serving a customer
UNK	UNK	UNK	C	UNK	3/4"	UNK	UNK	3/4"	UNK	O	UNK	UNK	3/4"	UNK	6/21/2021: Dug @ watermain and found 3/4" copper	Installation Record	Y	6/21/2021	Mech excav	SL repair/replace record				Not serving a customer
UNK	UNK	UNK	L	Y	UNK	UNK	UNK	UNK	UNK	O	UNK	UNK	UNK	UNK	STUB-OUT; 2007- REMOVED LEAD WIPE CURB BOX IS NEXT TO VALVE	Installation Record	Y	1/1/2007	Mech excav	SL repair/replace record				Not serving a customer
UNK	UNK	N	C	UNK	1"	10/14/2022	C	1"	10/14/2022	O	UNK	C	1"	UNK	10/14/22: 1" copper service stubbed to terrace. 1" cs & box installed.	Installation Record	Y	10/14/2022	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	2"	4/30/2018	P	2"	4/30/2018	O	UNK	P	2"	UNK	2019 - RETAPPED. RUNS WITH SEWER LATERAL	Installation Record	Y	4/30/2018	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	Y	1"	6/1/2022	C	1"	6/1/2022	O	UNK	C	1"	UNK	6/1/22: Removed lead from main to cs, replaced w/ 1" copper. Installed new 1" tap and 1" cs & box. Conn. to existing 3/4" copper after cs	Installation Record	Y	6/1/2022	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	Y	3/4"	8/3/2021	UNK	3/4"	8/3/2021	O	UNK	UNK	3/4"	UNK	8/3/2021: Replaced Lead w/ 3/4" Copper from WM-CS. Left Service disconnected after CS. Worked with Aaron's Plbg.	Installation Record	Y	8/3/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/21/2021	UNK	1"	9/21/2021	O	UNK	UNK	1"	UNK	9/21/2021: Earth installed 1" copper 18' past the curb valve (Pg 9 Daniels Addition inspection notes)	Installation Record	Y	9/21/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/22/2021	UNK	1"	9/22/2021	O	UNK	UNK	1"	UNK	9/22/2021: Earth installed 1" copper 17' past the curb valve (Pg 10 of Daniels Addition inspection notes)	Installation Record	Y	9/22/2021	Mech excav	Installed after lead ban				Not serving a customer

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	Building Type	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
UNK	UNK	UNK	C	N	1"	9/22/2021	UNK	1"	9/22/2021	O	UNK	UNK	1"	UNK	9/22/2021: Earth installed 1" copper 17' past the curb valve (Pg 10 of Daniels Addition inspection notes)	Installation Record	Y	9/22/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/22/2021	UNK	1"	9/22/2021	O	UNK	UNK	1"	UNK	9/22/2021: Earth installed 1" copper 17' past the curb valve (Pg 10 of Daniels Addition inspection notes)	Installation Record	Y	9/22/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/22/2021	UNK	1"	9/22/2021	O	UNK	UNK	1"	UNK	9/22/2021: Earth installed 1" copper 17' past the curb valve (Pg 10 of Daniels Addition inspection notes)	Installation Record	Y	9/22/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/22/2021	UNK	1"	9/22/2021	O	UNK	UNK	1"	UNK	9/22/2021: Earth installed 1" copper 17' past the curb valve (Pg 10 of Daniels Addtion inspection notes)	Installation Record	Y	9/22/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/22/2021	UNK	1"	9/22/2021	O	UNK	UNK	1"	UNK	9/22/2021: Earthinstalled 1" copper 17' past the curb valve (Pg 10 of Daniels Addtion inspection notes)	Installation Record	Y	9/22/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/22/2021	UNK	1"	9/22/2021	O	UNK	UNK	1"	UNK	9/22/2021: Earthinstalled 1" copper 25' past the curb valve (Pg 10 of Daniels Addition inspection notes)	Installation Record	Y	9/22/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/23/2021	UNK	1"	9/23/2021	O	UNK	UNK	1"	UNK	9/23/2021: Earth installed 1" copper 17' past the curb valve (Pg 11 of Daniels Addition inspection notes)	Installation Record	Y	9/23/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/23/2021	UNK	1"	9/23/2021	O	UNK	UNK	1"	UNK	9/23/2021: Earth installed 1" copper 17' past the curb valve (Pg 11 of Daniels Addition inspection notes)	Installation Record	Y	9/23/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/23/2021	UNK	1"	9/23/2021	O	UNK	UNK	1"	UNK	9/23/2021: Earth installed 1" copper 17' past the curb valve (Pg 11 of Daniels Addition inspection notes)	Installation Record	Y	9/23/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/23/2021	UNK	1"	9/23/2021	O	UNK	UNK	1"	UNK	9/23/2021: Earth installed 1" copper 17' past the curb valve (Pg 11 of Daniels Addition inspection notes)	Installation Record	Y	9/23/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/23/2021	UNK	1"	9/23/2021	O	UNK	UNK	1"	UNK	9/23/2021: Earth installed 1" copper 26' past the curb valve (Pg 11 of Daniels Addition inspection notes)	Installation Record	Y	9/23/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/23/2021	UNK	1"	9/23/2021	O	UNK	UNK	1"	UNK	9/23/2021: Earthinstalled 1" copper 17' past the curb valve (Pg 11 of Daniels Addition inspection notes)	Installation Record	Y	9/23/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/24/2021	UNK	1"	9/24/2021	O	UNK	UNK	1"	UNK	9/24/2021: Earth installed 1" copper 16' past the curb valve (Pg 12 of Daniels Addition inspection notes)	Installation Record	Y	9/24/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/24/2021	UNK	1"	9/24/2021	O	UNK	UNK	1"	UNK	9/24/2021: Earth installed 1" copper 20' past the curb valve (Pg 12 of Daniels Addition inspection notes)	Installation Record	Y	9/24/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/24/2021	UNK	1"	9/24/2021	O	UNK	UNK	1"	UNK	9/24/2021: Earth installed 1" copper 20' past the curb valve (Pg 12 of Daniels Addition inspection notes)	Installation Record	Y	9/24/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	N	1"	9/24/2021	UNK	1"	9/24/2021	O	UNK	UNK	1"	UNK	9/24/2021: Earth installed 1" copper 22' past the curb valve (Pg 12 of Daniels Addition inspection notes)	Installation Record	Y	9/24/2021	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	O	UNK	C	1"	UNK	CONNECTED TO 3/4" COPPER ON PROP. SIDE	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	N	C	UNK	1"	1/1/2015	C	1"	1/1/2015	O	UNK	C	1"	UNK	Stub-Out	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2015	C	1"	1/1/2015	O	UNK	C	1"	UNK	Stub-Out	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2015	UNK	1"	1/1/2015	O	UNK	UNK	1"	UNK	STUB-OUT 1" COPPER 11' PAST CURB STOP	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2015	UNK	1"	1/1/2015	O	UNK	UNK	1"	UNK	STUBOUT 1" COPPER 3' PAST CURB STOP	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2013	C	1"	1/1/2013	O	UNK	C	1"	UNK	STUB-OUT 10' PAST VALVE	Installation Record	Y	1/1/2013	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	2"	1/1/2015	UNK	2"	1/1/2015	O	UNK	UNK	2"	UNK	STUB-OUT 2" COPPER 7.5' PAST CURB STOP	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	1"	1/1/2015	UNK	1"	1/1/2015	O	UNK	UNK	1"	UNK	STUB-OUT 5' OF COPPER PAST CURB STOP	Installation Record	Y	1/1/2015	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	C	UNK	1"	6/14/2018	UNK	1"	6/14/2018	O	UNK	UNK	1"	UNK	STUB-OUT GAFFNEY	Installation Record	Y	6/14/2018	Mech excav	Installed after lead ban				Not serving a customer
UNK	UNK	UNK	DI	UNK	6"	1/1/2017	CI-U	6"	1/1/2017	O	UNK	CI-U	6"	UNK	<Null>	Installation Record	Y	1/1/2017	Mech excav	Diameter > 2"				Not serving a customer
UNK	UNK	UNK	DI	UNK	8"	1/1/2010	DI	8"	1/1/2010	O	UNK	DI	8"	UNK	<Null>	Installation Record	Y	1/1/2010	Mech excav	Diameter > 2"				Not serving a customer
UNK	UNK	N	DI	UNK	4"	11/22/2022	P	4"	11/22/2022	O	UNK	P	4"	UNK	11/22/22: Installed 8"x4" Tee w/ Hymax cut-in sleeve North side of the Tee. Turned Tee up 45 degrees with 2'7"- 4" DIP to 45 bend, 3'-4" DIP to 4" valve. Wood Excavation installed 4" PVC after the valve. (Deep valve, need long key)	Installation Record	Y	11/22/2022	Mech excav	Diameter > 2"				Not serving a customer
UNK	UNK	UNK	DI	UNK	4"	1/1/2010	P	4"	1/1/2010	O	UNK	P	4"	UNK	SPRINKLER	Installation Record	Y	1/1/2010	Mech excav	Diameter > 2"				Not serving a customer