

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-------------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|---|--|--|---|---|--|--|---|---|---|
| 6 | 223 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 10 | 243 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 14 | 321 S Central Ave | N | C | Y | 1" | 1/1/2009 | L | 1" | UNK | NONRES | UNK | L | 1" | UNK | CONNECTED TO 5/8" LEAD 11'E OF BOX. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 17 | 327 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 23 | 333 S Central Ave | N | C | Y | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | CONNECTED TO 5/8" LEAD 12'E OF BOX. A-1 EXCAVATING. 4/23: Received note from owner that service is copper inside at the entrance. | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 26 | 343 S Central Ave | N | C | UNK | 1 1/2" | 1/1/2009 | C | 1 1/2" | UNK | NONRES | UNK | C | 1 1/2" | UNK | INSTALLED 1-1/2" COPPER TO INSIDE. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 29 | 345 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 39 | 421 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | CONNECTED TO 1" COPPER 12'E OF BOX | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 42 | 435 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | INSTALLED 1" COPPER TO INSIDE. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 45 | 107 E 5TH ST | N | C | UNK | 1" | 1/1/2015 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 48 | 551 S Central Ave | N | C | Y | 1" | 1/1/2009 | L | 1" | 1/1/2009 | NONRES | UNK | L | UNK | 1/1/2009 | ATTACHED TO 5/8 LEAD 1'E OG BOX. A-1 EXCAVATING | SL repair/replace record | Y | 1/1/2009 | Visual insp during install or repair | Previous eval | Y | 6/13/2013 | Cross connection survey | |
| 53 | 601 S Central Ave | N | UNK-NOLG | UNK | 4" | 1/1/1926 | CI-U | 4" | 1/1/1926 | NONRES | UNK | CI-U | CI-U | | 2010- REMOVED MANHOLE & INSTALLED VALVE BOX | Installation Record | N | | | Field Inspection Only | Y | 1/17/2024 | Cross Connection Survey | |
| 65 | 109 E 9TH ST | N | UNK-LG | UNK | UNK | 1/1/1926 | L | UNK | 1/1/1926 | NONRES | UNK | UNK | UNK | | LOCKING VALVE. Lead on property side per customer. | Previous eval | Y | 1/1/2022 | Customer self id | Field inspection only | Y | 1/1/2022 | Customer self id | |
| 68 | 901 S Central Ave | N | P | Y | 2" | 7/9/2021 | P | 2" | UNK | NONRES | UNK | P | 2" | UNK | 7/9/2021: Removed 4-Lead Goosneck manifold @ WM and 2" existing copper from manifold to CS. Installed new 2" tap 5' West of existing taps. Gaffney installed 2" CS & Box & 2" HDPE from CS - Meter. | Installation Record | Y | 7/9/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 75 | 630 S Central Ave-Water | N | DI | UNK | 4" | 1/1/2009 | DI | 4" | UNK | NONRES | UNK | DI | 4" | UNK | POTABLE SERVICE | Installation Record | Y | 1/1/2009 | Mech excav | Diameter > 2" | Y | 2021-2025 | Visual insp at meter | |
| 78 | 510 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | INSTALLED 1" COPPER INTO BLDG. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 84 | 105 W 5TH ST | N | C | UNK | 1" | 1/1/2013 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | ATTACHED TO EXISTING 3/4" COPPER 5' PAST VALVE | Installation Record | Y | 1/1/2013 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 90 | 450 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER 11'W OF BOX. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 93 | 444 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER 10'W OF BOX. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 99 | 434 S Central Ave | N | DI | UNK | 6" | 1/1/2009 | DI | 6" | UNK | NONRES | UNK | DI | 6" | UNK | A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Diameter > 2" | Y | 2021-2025 | Visual insp at meter | |
| 106 | 414 S Central Ave | N | C | Y | 1" | 1/1/2009 | L | 1" | 1/1/2009 | NONRES | UNK | L | UNK | 1/1/2009 | CONNECTED TO 5/8 LEAD 10.5'W OF BOX A-1 EXCAVATING | SL repair/replace record | Y | 1/1/2009 | Visual insp during install or repair | Previous eval | Y | 6/11/2014 | Cross connection survey | |
| 108 | 400 S Central Ave | N | C | UNK | 1 1/2" | 1/1/2013 | C | 1 1/2" | UNK | NONRES | UNK | C | 1 1/2" | UNK | ATTACHED TO 1-1/2" COPPER 3' PAST VALVE | Installation Record | Y | 1/1/2013 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 112 | 222 S Central Ave | N | C | UNK | 2" | 1/1/2013 | C | 2" | 1/1/2013 | O | UNK | C | 2" | UNK | ATTACHED TO EXISTING 2" COPPER 2'N OF VALVE, ***THERE IS A PRIVATE CURB BOX 8' EAST OF THE METER BOX*** | Installation Record | Y | 1/1/2013 | Mech excav | Installed after lead ban | Y | 2013-2018 | Visual Insp during install or repair | |
| 115 | 107 W 3RD ST | N | C | Y | 1" | 1/1/2013 | L | 1" | 1/1/2013 | NONRES | UNK | L | UNK | 1/1/2013 | CONNECTED TO 5/8 LEAD 2.5'N OF VALVE | SL repair/replace record | Y | 1/1/2013 | Visual insp during install or repair | Previous eval | Y | 1/1/2013 | Visual Insp during install or repair | |
| 120 | 236 S Central Ave | N | C | Y | 1 1/2" | 1/1/2009 | L | 1 1/2" | 1/1/2009 | NONRES | UNK | L | UNK | 1/1/2009 | CONNECTED TO 1-1/2" LEAD 10'W OF BOX | SL repair/replace record | Y | 1/1/2009 | Visual insp during install or repair | Previous eval | Y | 12/15/2014 | Cross connection survey | |
| 129 | 115 W 2ND ST | N | C | UNK | 2" | 1/1/2013 | C | 2" | UNK | NONRES | UNK | C | 2" | UNK | ATTACHED TO EXISTING 2" COPPER @ CURB VALVE | Installation Record | Y | 1/1/2013 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 134 | 166 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | ATTACHED TO 1" COPPER 10'W OF BOX. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 144 | 140 S Central Ave | N | C | UNK | 1" | 1/1/2001 | L | 1" | 1/1/2001 | NONRES | UNK | L | UNK | 1/1/2001 | MEWD | SL repair/replace record | Y | 1/1/2001 | Visual insp during install or repair | Previous eval | Y | 10/11/2013 | Cross connection survey | |
| 155 | 126 S Central Ave | N | C | UNK | 1 1/2" | 1/1/2001 | C | 1 1/2" | UNK | NONRES | UNK | C | 1 1/2" | UNK | MEWD. 1-1/2" copper on property side | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 158 | 122 S Central Ave | N | C | UNK | 1" | 1/1/2001 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | MEWD. 3/4" copper on property side | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 165 | 300 N Central Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | NONRES | UNK | C | C | | SERVICE COMES OFF A PRIVATE LINE ON BLODGETT ST | Installation Record | N | | | Field Inspection Only | Y | 9/16/2013 | Cross Connection Survey | |
| 168 | 308 N Central Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | DUPLEX WITH 308A, LV/CB UNKNOWN | Installation Record | N | | | Field Inspection Only | Y | 6/2/2014 | Cross Connection Survey | |
| 174 | 316 N Central Ave | N | C | UNK | 1" | 6/4/2020 | C | 1" | UNK | SF | UNK | C | 1" | UNK | EARTH INC. - CONNECTED TO EXISTING 3/4" COPPER 2.5' BEHIND CURB STOP. DUPLEX W/ 316 N. CENTRAL AVE. (Pg. 9 of Const. Report) | Installation Record | Y | 6/4/2020 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 177 | 104 W CLEVELAND ST | N | C | Y | 1" | 6/9/2020 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | Earth INC. - Removed lead on street side, connected to existing 3/4" copper 1' behind CS with 1" copper. (Pg. 12 of Const. Report) | Installation Record | Y | 6/9/2020 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 184 | 311 N Central Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | DUPLEX WITH 311A, LV/CB UNKNOWN. 3/4" copper on property side | Installation Record | N | | | Field Inspection Only | Y | 6/9/2014 | Cross Connection Survey | |
| 187 | 305 N Central Ave | N | L | UNK | 5/8" | 1/1/1926 | P | 5/8" | 1/1/1926 | NONRES | UNK | P | UNK | 1/1/1926 | 2008-REPLACED LEAD WIPE WITH NEW CURB VALVE. | SL repair/replace record | Y | 2008 | Mech excav | Field inspection only | Y | 1/1/2011 | Visual Insp during install or repair | |
| 227 | 133 S Central Ave #A | N | C | Y | 1" | 1/1/2001 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | Verified Lead on customer side via customer photo. MEWD. 10/22: Customer replaced lead service w/ 1" copper. | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 230 | 137 S Central Ave | N | C | UNK | 1" | 1/1/2001 | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | MEWD | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 234 | 145 S Central Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | UNK | NONRES | UNK | C | 3/4" | UNK | MEWD | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 238 | 113 E 2ND ST | N | C | UNK | 2" | 1/1/2015 | P | 2" | UNK | NONRES | UNK | P | 2" | UNK | 2" PLASTIC ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 241 | 206 W KALSCHED ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | INSULATED 2X2 1981 | Installation Record | Y | 1/1/1981 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 247 | 1110 N CHESTNUT AVE | UNK | UNK-LG | UNK | 5/8" | UNK | C | 5/8" | UNK | SF | UNK | C | 5/8" | UNK | INSULATED | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 250 | 308 W KALSCHED ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | INSULATED 1981 | Installation Record | Y | 1/1/1981 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 253 | 312 W KALSCHED ST | N | C | UNK | 1" | 1/1/1962 | C | 1" | 1/1/1962 | SF | UNK | C | 1" | UNK | INSULATED 2X4 1981, 1-1-2020 J&R VACUUM EXCAVATED MID TERRACE, FOUND 1" COPPER 7'1" DEEP | Installation Record | Y | 1/1/1962 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 256 | 400 W KALSCHED ST | UNK | UNK-LG | UNK | 5/8" | 1/1/1963 | C | 5/8" | 1/1/1963 | SF | UNK | C | 5/8" | UNK | SCHREINERS | Installation Record | Y | 1/1/1963 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 259 | 408 W KALSCHED ST | N | UNK-NOLG | UNK | UNK | UNK | UNK-NOLG | UNK | UNK | SF | UNK | UNK-NOLG | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 262 | 412 W KALSCHED ST | N | UNK-NOLG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | SCHUH | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 265 | 416 W KALSCHED ST | N | C | UNK | 1" | 1/1/1969 | C | 1" | 1/1/1969 | SF | UNK | C | 1" | UNK | 1-1-2020 J&R VACUUM EXCAVATED AT CB, FOUND 1" COPPER 8' DEEP | Installation Record | Y | 1/1/1969 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 268 | 418 W KALSCHED ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1970 | C | 3/4" | 1/1/1970 | SF | UNK | C | 3/4" | UNK | SCHREINERS | Installation Record | Y | 1/1/1970 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 271 | 424 W KALSCHED ST | N | C | UNK | 3/4" | 1/1/1970 | C | 3/4" | 1/1/1970 | SF | UNK | C | 3/4" | UNK | SCHREINERS. 1-1-2020 J&R VACUUM EXCAVATED 1' FROM CB FOUND 3/4" COPPER 7'7" DEEP | Installation Record | Y | 1/1/1970 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 274 | 419 W KALSCHED ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 277 | 409 W KALSCHED ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CB/LV UNKNOWN | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 280 | 405 W KALSCHED ST | UNK | UNK-LG | UNK | 3/4" | 1/1/1965 | C | 3/4" | 1/1/1965 | SF | UNK | C | 3/4" | UNK | MFLD PLB | Installation Record | Y | 1/1/1965 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 283 | 401 W KALSCHED ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | STRAIGHT OUT OF EAST SIDE OF HOUSE | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 286 | 1208 N FIG AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1974 | C | 3/4" | 1/1/1974 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1974 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 289 | 404 W LEONHARD ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1971 | C | 3/4" | 1/1/1971 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1971 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 292 | 412 W LEONHARD ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1971 | C | 3/4" | 1/1/1971 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1971 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 295 | 416 W LEONHARD ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1974 | C | 3/4" | 1/1/1974 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1974 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 298 | 422 W LEONHARD ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1971 | C | 3/4" | 1/1/1971 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1971 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 304 | 514 W UPHAM ST | N | C | UNK | 1" | 1/1/1969 | C | 1" | 1/1/1969 | NONRES | UNK | C | 1" | UNK | 2003-NEW 1" CORP CONNECTED TO EXISTING 1" COPPER | Installation Record | Y | 1/1/1969 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 307 | 1211 N WALNUT AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1976 | C | 3/4" | 1/1/1976 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1976 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 310 | 1205 N WALNUT AVE | N | C | UNK | 1" | 1/1/2003 | C | 1" | 1/1/2003 | SF | UNK | C | 1" | UNK | 2003-NEW 1" CORP CONNECTED TO EXISTING 3/4" COPPER | Installation Record | Y | 1/1/2003 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 316 | 421 W JEFFERSON ST | N | UNK-NOLG | UNK | 1" | 1/1/1974 | C | 1" | 1/1/1974 | SF | UNK | C | 1" | UNK | MEYERS | Installation Record | Y | 1/1/1974 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 319 | 415 W JEFFERSON ST | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 322 | 411 W JEFFERSON ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1973 | C | 3/4" | 1/1/1973 | SF | UNK | C | 3/4" | UNK | MEYER | Installation Record | Y | 1/1/1973 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 325 | 407 W JEFFERSON ST | N | C | UNK | 3/4" | 1/1/1967 | C | 3/4" | 1/1/1967 | SF | UNK | C | 3/4" | UNK | 1-1-2020 J&R VACUUM EXCAVATED 1" FROM CB, FOUND 3/4" COPPER 7 1/2" DEEP | Installation Record | Y | 1/1/1967 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 328 | 403 W JEFFERSON ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 331 | 315 W JEFFERSON ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 334 | 313 W JEFFERSON ST | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 7" DEEP | Installation Record | Y | 1/1/2020 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 337 | 311 W JEFFERSON ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 340 | 307 W JEFFERSON ST | N | L | UNK | 3/4" | 1/1/1958 | C | 3/4" | 1/1/1958 | SF | UNK | C | UNK | 1/1/1958 | 2011-REMOVED LEAD WIPE & INSTALLED 1" CURB STOP/BOX. INSTALLED 1" PLASTIC FROM STOP TO INSIDE. | SL repair/replace record | Y | 2011 | Mech excav | Field inspection only | Y | 8/25/2016 | Cross Connection Survey | |
| 343 | 301 W JEFFERSON ST | N | C | UNK | 3/4" | 9/22/1995 | C | 3/4" | 9/22/1995 | SF | UNK | C | 3/4" | UNK | REMOVED WIPE @MAIN, INSTALLED 3/4" COPPER FROM MAIN TO CURB VALVE. INSTALLED NEW CURB VALVE. INSULATED MAIN WITH STYROFOAM | Installation Record | Y | 9/22/1995 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 349 | 119 W JEFFERSON ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 352 | 117 W JEFFERSON ST | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2020 J&R vac excavated @ EOP, found copper 6" deep. 9/3/2024: removed lead wipe @ wm, replaced w/ 3/4" copper. | Installation Record | Y | 9/3/2024 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 355 | 113 W JEFFERSON ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 358 | 1200 N CENTRAL AVE | N | CI-U | UNK | 6" | 1/1/1978 | CI-U | 6" | 1/1/1978 | NONRES | UNK | CI-U | 6" | UNK | MEYERS | Installation Record | Y | 1/1/1978 | Mech excav | Diameter > 2" | Y | 2021-2025 | Visual insp at meter | |
| 361 | 114 W JEFFERSON ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | UNK | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 364 | 1009 N CHESTNUT AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 367 | 304 W JEFFERSON ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 370 | 306 W JEFFERSON ST | N | L | UNK | 3/4" | 1/1/1959 | C | 3/4" | 1/1/1959 | SF | UNK | C | UNK | 1/1/1959 | 2006-REMOVED LEAD WIPE @ MAIN | SL repair/replace record | Y | 2006 | Mech excav | Field inspection only | Y | 9/16/2016 | Cross Connection Survey | |
| 373 | 308 W JEFFERSON ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 376 | 316 W JEFFERSON ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 379 | 1010 N FIG AVE | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 382 | 404 W JEFFERSON ST | N | C | UNK | 1" | 1/1/1963 | C | 1" | 1/1/1963 | SF | UNK | C | 1" | UNK | 1-1-2020 J&R VACUUM EXCAVATED, FOUND 1" COPPER 6 7/8" DEEP | Installation Record | Y | 1/1/1963 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 385 | 412 W JEFFERSON ST | N | C | UNK | 3/4" | 1/1/1960 | C | 3/4" | 1/1/1960 | SF | UNK | C | 3/4" | UNK | 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 3/4" COPPER 7 7/8" DEEP | Installation Record | Y | 1/1/1960 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 388 | 414 W JEFFERSON ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | 1999: MEYERS INSTALLED A CURB BOX | Installation Record | Y | 1/1/1999 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 391 | 1013 N WALNUT AVE | N | C | UNK | 1" | 1/1/2004 | C | 1" | UNK | SF | UNK | C | 1" | UNK | 2004-INSTALLED 1" CORP.COPPER,VALVE,BOX. | Installation Record | Y | 1/1/2004 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 394 | 1009 N WALNUT AVE | N | C | UNK | 1" | 1/1/2004 | C | 1" | UNK | SF | UNK | C | 1" | UNK | 2004-INSTALLED 1" CORP.COPPER,VALVE,BOX,INSULATED @MAIN | Installation Record | Y | 1/1/2004 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 397 | 1007 N WALNUT AVE | N | C | UNK | UNK | 1/1/2004 | C | UNK | UNK | SF | UNK | C | UNK | UNK | 2004-INSTALLED 1" CORP.COPPER,VALVE,BOX,INSULATED SERVICE | Installation Record | Y | 1/1/2004 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 400 | 423 W IVES ST | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2004-INSTALLED 3/4 CORP. | Installation Record | Y | 1/1/2004 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 403 | 904 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | UNK | SF | UNK | C | 1" | UNK | 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 406 | 902 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | UNK | SF | UNK | C | 1" | UNK | 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 409 | 814 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | UNK | SF | UNK | C | 1" | UNK | 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 412 | 800 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | UNK | SF | UNK | C | 1" | UNK | 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 415 | 414 W IVES ST | UNK | UNK-LG | UNK | 5/8" | 8/10/1960 | C | 5/8" | UNK | SF | UNK | C | 5/8" | UNK | <Null> | Installation Record | Y | 8/10/1960 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 418 | 410 W IVES ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 421 | 419 W IVES ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 424 | 415 W IVES ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 427 | 407 W IVES ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 430 | 403 W IVES ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 433 | 401 W IVES ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 436 | 315 W IVES ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 439 | 313 W IVES ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 442 | 311 W IVES ST | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | 2020 J&R VACUUM EXCAVATED @ BOC, FOUND COPPER 6 10" DEEP | Installation Record | Y | 1/1/2020 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 445 | 307 W IVES ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 448 | 203 W IVES ST | N | UNK-NOLG | UNK | 1" | 1/1/1979 | C | 1" | 1/1/1979 | SF | UNK | C | 1" | UNK | STUB-OUT MEYERS. 3/4" Copper on property side confirmed by JN | Installation Record | Y | 1/1/1979 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 451 | 117 W IVES ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 454 | 115 W IVES ST | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2020 J&R VAC EXCAVATED @ BOC, FOUND COPPER 7 1" DEEP | Installation Record | Y | 1/1/2020 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 457 | 111 W IVES ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 460 | 109 W IVES ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 463 | 1100 N CENTRAL AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/2000 | C | 3/4" | 1/1/2000 | NONRES | UNK | C | 3/4" | UNK | RETAPPED 2000 | Installation Record | Y | 1/1/2000 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 466 | 113 W HARRISON ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 469 | 115 W HARRISON ST | UNK | UNK-LG | | | | | | | | | | | | | | | | | | | | | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 511 | 111 W Franklin St | N | UNK-LG | UNK | UNK | 1/1/1927 | C | UNK | 1/1/1927 | SF | UNK | C | C | | REPLACED 10' OF LEAD FROM THE MAIN TOWARD THE CURB BOX | Installation Record | N | | | Field Inspection Only | Y | 9/8/2016 | Cross Connection Survey | |
| 514 | 115 W Franklin St | N | L | UNK | 3/4" | 1/1/1943 | C | 3/4" | 1/1/1943 | SF | UNK | C | UNK | 1/1/1943 | 2006-REMOVED LEAD WIPE @ MAIN | SL repair/replace record | Y | 2006 | Mech excav | Field inspection only | Y | 5/18/2020 | Cross Connection Survey | |
| 517 | 610 N CHESTNUT AVE | N | UNK-LG | UNK | UNK | 1/1/1938 | C | 3/4" | 1/1/1938 | SF | UNK | UNK | UNK | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 8/15/2016 | Cross Connection Survey | |
| 520 | 608 N CHESTNUT AVE | N | UNK-LG | UNK | UNK | 1/1/1947 | C | UNK | 1/1/1947 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 8/27/2016 | Cross Connection Survey | |
| 523 | 606 N CHESTNUT AVE | N | UNK-LG | UNK | UNK | 1/1/1935 | C | UNK | 1/1/1935 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 8/15/2016 | Cross Connection Survey | |
| 526 | 600 N CHESTNUT AVE | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | REMOVED WIPE & INSULATED 1987 CORNER HOUSE | Installation Record | N | | | Field Inspection Only | Y | 8/23/2016 | Cross Connection Survey | |
| 529 | 204 W Edison St | N | UNK-LG | UNK | UNK | 1/1/1944 | C | UNK | 1/1/1944 | SF | UNK | C | C | | | Installation Record | N | | | Field Inspection Only | Y | 8/18/2016 | Cross Connection Survey | |
| 532 | 508 N CHESTNUT AVE | N | C | UNK | 3/4" | 9/7/2017 | C | 3/4" | 9/7/2017 | SF | UNK | C | 3/4" | UNK | NEW COPPER INSTALLED FROM MAIN TO INSIDE HOUSE, GAFFNEY PLBG--2017 | Installation Record | Y | 9/7/2017 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 541 | 201 W DOEGE ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 544 | 205 W DOEGE ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | GOOSENECK | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 547 | 209 W DOEGE ST | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 7/29/2016 | Cross Connection Survey | |
| 556 | 511 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | DIRECTIONAL BORED. 3/4" COPPER INSIDE. | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 559 | 212 W Edison St | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | SERVICE COMES OFF 16" ON WALNUT. DIRECTIONAL BORED. 5/8" COPPER INSIDE. | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 562 | 603 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 565 | 607 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | DIRECTIONAL BORED, 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 568 | 611 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | DIRECTIONAL BORED, 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 571 | 615 N WALNUT AVE | N | C | Y | 1" | 1/1/2006 | L | 1" | 1/1/2006 | SF | UNK | L | UNK | 1/1/2006 | DIRECTIOAL BORED LEAD ON PROP.SIDE / COPPER INSIDE | SL repair/replace record | Y | 1/1/2006 | Visual Insp during install or repair | Previous eval | Y | 9/12/2016 | Cross connection survey | |
| 574 | 612 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 580 | 508 N WALNUT AVE | N | C | UNK | 1" | 1/1/2006 | L | 1" | 1/1/2006 | SF | UNK | L | UNK | 1/1/2006 | 5/8" LEAD INSIDE | SL repair/replace record | Y | 1/1/2006 | Visual Insp during install or repair | Previous eval | Y | 8/25/2016 | Cross connection survey | |
| 586 | 400 W DOEGE ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 589 | 314 W DOEGE ST | N | L | UNK | 5/8" | 1/1/1940 | C | 5/8" | 1/1/1940 | SF | UNK | C | UNK | 1/1/1940 | 2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 4"9" DEEP | Previous eval | Y | 2020 | Mech excav | Field inspection only | Y | 1/6/2014 | Visual Insp during install or repair | |
| 592 | 412 N WALNUT AVE | N | C | Y | 1" | 1/1/2021 | C | 1" | 1/1/2021 | SF | UNK | C | 1" | UNK | 2021: Replaced lead with copper from main to meter. Installed 1" corp 3' East of old 3/4" corp. New curb valve and 1" copper to meter | Installation Record | Y | 1/1/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 595 | 406 N WALNUT AVE | N | C | UNK | 1" | 1/1/2002 | C | 1" | 1/1/2002 | SF | UNK | C | 1" | UNK | NEW 1" CORP, 1" COPER FOR CORP TO CURB BOX. 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2002 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 598 | 409 N WALNUT AVE | N | C | UNK | 1" | 1/1/2002 | C | 1" | 1/1/2002 | SF | UNK | C | 1" | UNK | NEW 1" CORP, 1" COPPER FROM CORP TO CURB BOX. 3/4" COPPER INSIDE | Installation Record | Y | 1/1/2002 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 601 | 208 W DOEGE ST | N | C | UNK | 1" | 1/1/1962 | C | 1" | 1/1/1962 | SF | UNK | C | 1" | UNK | Y'D SERVICE WITH 208 W DOEGE. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 4'6" DEEP | Installation Record | Y | 1/1/1962 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 604 | 109 W DOEGE ST | N | UNK-LG | UNK | UNK | 1/1/1939 | C | UNK | 1/1/1939 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 8/10/2016 | Cross Connection Survey | |
| 607 | 113 W DOEGE ST | N | UNK-LG | UNK | UNK | 1/1/1947 | C | UNK | 1/1/1947 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 8/10/2016 | Cross Connection Survey | |
| 610 | 507 N CHESTNUT AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 613 | 513 N CHESTNUT AVE | N | UNK-LG | UNK | 3/4" | 1/1/1926 | C | 3/4" | 1/1/1926 | SF | UNK | C | C | | Y-CONNECTION INSTALLED. | Installation Record | N | | | Field Inspection Only | Y | 9/7/2016 | Cross Connection Survey | |
| 616 | 109 W Edison St | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 1" COPPER OFF CHESTNUT TO "Y" & 3/4" CONTINUES TO 109 W. EDISON. | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 619 | 611 N CHESTNUT AVE | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 9/14/2016 | Cross Connection Survey | |
| 622 | 613 N CHESTNUT AVE | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | SERVICE IS OFF FRANKLIN. 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 5'9" DEEP | Installation Record | Y | 1/1/2020 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 625 | 507 N CEDAR AVE | N | C | Y | 3/4" | 6/1/2022 | C | 3/4" | 6/1/2022 | SF | UNK | C | 3/4" | UNK | 6/22: Dug & removed lead from wm-sidewalk. Replaced w/ 1" copper, new 1" corp., 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 6/1/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 628 | 306 E Edison St | N | C | UNK | 1" | 8/21/2023 | C | 1" | UNK | SF | UNK | C | 1" | UNK | Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 17 of the construction report | Installation Record | Y | 8/21/2023 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 631 | 603 N CEDAR AVE | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER 5'7" DEEP | Installation Record | Y | 1/1/2020 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 634 | 607 N CEDAR AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 6/2/22: Dug @ wm & found 3' lead gooseneck. Removed and replaced w/ 3/4" copper. Re-used exisiting corp., connected to existing 3/4" copper. | Installation Record | Y | 6/2/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 637 | 609 N CEDAR AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 6/22: Dug @ wm & found 3' lead gooseneck. Removed lead & replaced w/ 3/4" copper. Reused existing corp & connected to existing 3/4" copper. | Installation Record | Y | 6/2/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 640 | 613 N CEDAR AVE | N | C | Y | 1" | 6/24/2022 | C | 1" | 6/24/2022 | SF | UNK | C | 1" | UNK | 6/24/22: Replaced lead from wm - sidewalk w/ 1" copper. Connected to existing 3/4" copper @ the sidewalk. Used existing corp due to there being no space for a new tap. Stopped 1" copper 2' from wm & conn. to exist. corp w/ 3/4" copper | Installation Record | Y | 6/24/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 643 | 312 E FRANKLIN ST | N | C | UNK | 1" | 6/16/2022 | C | 1" | 6/16/2022 | SF | UNK | C | 1" | UNK | Pg. 16 of Construction Report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 6/16/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 646 | 400 E FRANKLIN ST | N | C | UNK | 1" | 6/16/2022 | C | 1" | 6/16/2022 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 6/16/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 649 | 701 N CEDAR AVE | N | C | Y | 1" | 6/23/2022 | C | 1" | 6/23/2022 | SF | UNK | C | 1" | UNK | 6/23/22: Removed lead from wm - sidewalk. Installed 1" copper, new 1" cs & box and new 1" tap and corp. Connected to existing 3/4" copper on the east edge of the sidewalk. Abandoned existing corp. 3' South of the new corp. | Installation Record | Y | 6/23/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 652 | 703 N CEDAR AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1995 | C | 3/4" | 1/1/1995 | SF | UNK | C | 3/4" | UNK | CURB STOP PUT IN DURING SEWER REPAIR | Installation Record | Y | 1/1/1995 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 655 | 709 N CEDAR AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 6/22: Dug @ wm & found 3' lead gooseneck. Removed lead & replaced w/ 3/4" copper. Reused existing corp & connected to existing 3/4" copper. | Installation Record | Y | 6/2/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 658 | 717 N CEDAR AVE | N | C | Y | 3/4" | 1/1/2017 | C | 3/4" | 1/1/2017 | SF | UNK | C | 3/4" | UNK | REMOVED LEAD WIPE IN STREET--2017 | Installation Record | Y | 1/1/2017 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 661 | 306 E GRANT ST | N | C | UNK | 1" | 5/2/2022 | C | 1" | 5/2/2022 | SF | UNK | C | 1" | UNK | 5/2/22: Installed new 1" tap w/ tapping saddle, 12" - 1" copper, connected to existing 3/4" copper. | Installation Record | Y | 5/2/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 664 | 712 N CHERRY AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1971 | C | 3/4" | 1/1/1971 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1971 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 667 | 706 N CHERRY AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1972 | C | 3/4" | 1/1/1972 | SF | UNK | C | 3/4" | UNK | STRATFORD | Installation Record | Y | 1/1/1972 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 670 | 304 E GRANT ST | N | C | UNK | 1" | 5/24/2022 | C | 1" | 5/24/2022 | SF | UNK | C | 1" | UNK | 5/25/22: Installed 8" tapping saddle w/ 1" C.C., ran 1" copper to new curb valve and box and extended 1" copper to South edge of sidewalk. Original service in the driveway was abandoned when new wm was installed. | Installation Record | Y | 5/24/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 675 | 910 N CEDAR AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1972 | C | 3/4" | 1/1/1972 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1972 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 678 | 904 N Cedar Ave | N | C | UNK | 3/4" | 10/1/2019 | P | 3/4" | 10/1/2019 | SF | UNK | P | 3/4" | UNK | GAFFNEY PLBG - 3/4" COPPER FROM CURB VAVLE TO BACK OF CURB. 1" PLASTIC FROM CURB VAVLE TO HOUSE. FEEDS 904 AND 906 N CEDAR | Installation Record | Y | 10/1/2019 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 681 | 900 N CEDAR AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 684 | 812 N CEDAR AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 690 | 808 N CEDAR AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 693 | 215 E GRANT ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 696 | 211 E GRANT ST | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | 2020 J&R VACUUM EXCAVATED @ BOC, FOUND COPPER 7"6" DEEP | Installation Record | Y | 1/1/2020 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 703 | 714 N CEDAR AVE | N | C | Y | 1" | 5/18/2021 | C | 1" | 5/18/2021 | SF | UNK | C | 1" | UNK | 5/18/21 - Abandoned old corp. 3' North of new corp. Replaced lead w/ 1" copper from wm to house. (Reigel). Reduced to 3/4" copper 6" after cs. Reigel replaced galvanized on customer side with 3/4" copper | Installation Record | Y | 5/18/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 706 | 710 N CEDAR AVE | N | C | UNK | 3/4" | 1/1/2017 | C | 3/4" | 1/1/2017 | SF | UNK | C | 3/4" | UNK | REPLACED FROM METER TO MAIN 2017 | Installation Record | Y | 1/1/2017 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 709 | 708 N CEDAR AVE | N | C | Y | 1" | 6/1/2022 | C | 1" | 6/1/2022 | SF | UNK | C | 1" | UNK | 6/22: Dug & found Lead from wm - sidewalk. Replaced w/ 1" copper. Abandoned existing corp and installed new 1" corp. Also installed new 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 6/1/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 712 | 704 N CEDAR AVE | N | C | Y | 1" | 6/1/2022 | C | 1" | 6/1/2022 | SF | UNK | C | 1" | UNK | 6/22: Dug & found lead from wm - sidewalk. Removed lead & replaced w/ 1" copper. Abandoned old corp & installed new 1" corp. Connected to existing 3/4" copper 18" East of the 1" cs. | Installation Record | Y | 6/1/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 715 | 610 N CEDAR AVE | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | 2020 J&R VAC EXCAVATED @ EOP, FOUND COPPER | Installation Record | Y | 1/1/2020 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 718 | 606 N CEDAR AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 6/22: Dug @ wm & found 3' Lead gooseneck. Removed lead & replaced w/ 3/4" copper. Reused existing corp. | Installation Record | Y | 6/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 721 | 213 E EDISON ST | N | C | Y | 1" | 6/1/2022 | L | 1" | 6/1/2022 | SF | UNK | L | UNK | 6/1/2022 | 6/22: Dug & removed lead from wm-cs. Replaced lead w/ 1" copper, new 1" corp. connected to existing 3/4" copper 12" East of cs. Found 6" of 3/4" copper connected to lead after the cs. Lead is in the house before the meter. | SL repair/replace record | Y | 6/1/2022 | Visual insp during install or repair | Previous eval | Y | 10/20/2016 | Cross connection survey | |
| 724 | 214 E EDISON ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 727 | 508 N CEDAR AVE | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 6/27/22: Dug @ wm and found 3/4" copper buried in 3/4" dean stone. Found newer cb also that wasn't mapped. | Installation Record | Y | 6/27/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 730 | 504 N CEDAR AVE | N | C | Y | 3/4" | 9/25/2020 | C | 3/4" | 9/25/2020 | SF | UNK | C | 3/4" | UNK | 9-25-2020 REMOVED LEAD WIPE AT WM, INSTALLED NEW 3/4" COPPER FROM MAIN TO NEW CS & BOX, 3/4" COPPER ON CUSTOMER SIDE. 2022: Removed all lead from service, 3/4" copper frm main to meter. Service is 100% copper. | Installation Record | Y | 9/25/2020 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 733 | 215 E DOEGE ST | N | C | UNK | 1" | UNK | C | 1" | UNK | SF | UNK | C | 1" | UNK | CB/LV UNKNOWN. 6/22: Dug & found 1" copper from wm-cs. Installed 1" curb box due to street dept. damaging during ditching. | Installation Record | Y | 6/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 736 | 212 E DOEGE ST | N | UNK-LG | UNK | UNK | 1/1/1928 | C | UNK | 1/1/1928 | SF | UNK | C | C | UNK | <Null> | Installation Record | N | | | Field Inspection Only | Y | 9/20/2016 | Cross Connection Survey | |
| 739 | 210 E BECKER RD | N | UNK-NOLG | UNK | 1" | 1/1/1986 | C | 1" | 1/1/1986 | SF | UNK | C | 1" | UNK | STRATFORD | Installation Record | Y | 1/1/1986 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 743 | 501 N MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1927 | C | UNK | 1/1/1927 | SF | UNK | C | C | UNK | <Null> | Installation Record | N | | | Field Inspection Only | Y | 10/24/2016 | Cross Connection Survey | |
| 746 | 505 N MAPLE AVE | N | C | Y | 3/4" | 9/13/2017 | C | 3/4" | 9/13/2017 | SF | UNK | C | 3/4" | UNK | REPLACED LEAD W/ 3/4" COPPER FROM MAIN TO INSIDE OF HOUSE--2017 | Installation Record | Y | 9/13/2017 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 749 | 507 N MAPLE AVE | N | C | Y | 3/4" | 10/18/2017 | C | 3/4" | 10/18/2017 | SF | UNK | C | 3/4" | UNK | 1982-RETAPPED, LOWERED, INSULATED/REMOVED LEAD & INSTALLED NEW COPPER FROM MAIN TO HOUSE, INSULATED--2017 | Installation Record | Y | 10/18/2017 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 752 | 513 N MAPLE AVE | N | C | Y | 1" | 7/15/2021 | C | 1" | 7/15/2021 | SF | UNK | C | 1" | UNK | 7/15/2021: Retapped 6" South of old tap. 1" copper pulled in from wm-cs (replaced full lead), Aaron Plbg. replaced lead w/ 1" HDPE from cs-meter. Installed new cs & box | Installation Record | Y | 7/15/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 755 | 209 E EDISON ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 758 | 207 E EDISON ST | N | UNK-LG | UNK | UNK | 1/1/1946 | C | UNK | 1/1/1946 | SF | UNK | C | C | UNK | <Null> | Installation Record | N | | | Field Inspection Only | Y | 10/10/2016 | Cross Connection Survey | |
| 761 | 605 N MAPLE AVE | N | C | Y | 3/4" | 11/22/2022 | C | 3/4" | 11/22/2022 | SF | UNK | C | 3/4" | UNK | 11/22/22: Removed all lead, replaced w/ 3/4" copper from main to house. (Kasner) | Installation Record | Y | 11/22/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 764 | 609 N MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1930 | C | UNK | 1/1/1930 | SF | UNK | C | C | UNK | <Null> | Installation Record | N | | | Field Inspection Only | Y | 9/20/2016 | Cross Connection Survey | |
| 767 | 701 N MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1942 | C | UNK | 1/1/1942 | SF | UNK | C | C | UNK | <Null> | Installation Record | N | | | Field Inspection Only | Y | 9/19/2016 | Cross Connection Survey | |
| 770 | 703 N MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1946 | C | UNK | 1/1/1946 | SF | UNK | C | C | UNK | <Null> | Installation Record | N | | | Field Inspection Only | Y | 9/27/2016 | Cross Connection Survey | |
| 773 | 705 N MAPLE AVE | N | UNK-LG | UNK | UNK | UNK | G | UNK | UNK | SF | UNK | G | UNK | UNK | IRON | Installation record | N | | | Previous eval | Y | 9/27/2016 | Cross connection survey | |
| 776 | 707 N MAPLE AVE | N | L | UNK | UNK | 1/1/1926 | P | UNK | 1/1/1926 | SF | UNK | P | UNK | 1/1/1926 | 2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 7" DEEP; 3/4" Copper Inside | Previous eval | Y | 2020 | Mech excav | Field inspection only | Y | 12/18/2017 | Visual Insp during install or repair | |
| 779 | 709 N MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1925 | C | UNK | 1/1/1925 | SF | UNK | C | C | UNK | <Null> | Installation Record | N | | | Field Inspection Only | Y | 9/6/2016 | Cross Connection Survey | |
| 783 | 713 N MAPLE AVE | N | C | Y | 1" | 11/29/2023 | C | 1" | 11/29/2023 | SF | UNK | C | 1" | UNK | 11/29/23: Replaced 3/4" copper and lead in the street w/ 1" copper. used existing corp. | Installation Record | Y | 11/29/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 786 | 207 E GRANT ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 789 | 803 N MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 792 | 815 N MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 795 | 901 N MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 798 | 907 N MAPLE AVE | N | C | UNK | 3/4" | 1/1/2003 | C | 3/4" | 1/1/2003 | SF | UNK | C | 3/4" | UNK | 2003-REPLACED SERVICE MAIN TO LOT LINE | Installation Record | Y | 1/1/2003 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 801 | 911 N MAPLE AVE | N | C | UNK | UNK | 1/1/2003 | C | UNK | 1/1/2003 | SF | UNK | C | UNK | UNK | 2003- NEW 3/4 COPPER MAIN TO TERRACE LOWERED UNDER STORM | Installation Record | Y | 1/1/2003 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 804 | 913 N MAPLE AVE | N | C | UNK | UNK | 1/1/2003 | C | UNK | 1/1/2003 | SF | UNK | C | UNK | UNK | 2003- NEW 3/4 COPPER MAIN TO LOT LINE | Installation Record | Y | 1/1/2003 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 824 | 908 N MAPLE AVE | N | C | UNK | UNK | 1/1/2003 | C | UNK | 1/1/2003 | SF | UNK | C | UNK | UNK | 2003-NEW 3/4 COPPER MAIN TO TERRACE | Installation Record | Y | 1/1/2003 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 830 | 900 N MAPLE AVE | N | C | UNK | 3/4" | 1/1/2003 | C | 3/4" | 1/1/2003 | SF | UNK | C | 3/4" | UNK | 2003-REPLACED & LOWERED FROM MAIN TO CURB VALVE - REPLACE FROM CS TO HOUSE WITH 3/4" COPPER 2018 | Installation Record | Y | 1/1/2003 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 833 | 109 E HARRISON ST | N | C | UNK | UNK | 1/1/2003 | C | UNK | 1/1/2003 | SF | UNK | C | UNK | UNK | 2003- NEW 3/4 COPPER FROM MAIN TO 2" BEHIND GAS MAIN | Installation Record | Y | 1/1/2003 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 839 | 808 N MAPLE AVE | N | C | Y | 1" | 11/9/2022 | C | 1" | 11/9/2022 | SF | UNK | C | 1" | UNK | 11-9-22: Removed lead both property side & street side and replaced w/ copper. | Installation Record | Y | 11/9/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 842 | 800 N MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 845 | 704 N MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1922 | P | UNK | 1/1/1922 | SF | UNK | P | P | UNK | <Null> | Installation Record | N | | | Field Inspection Only | Y | 9/30/2016 | Cross Connection Survey | |
| 849 | 608 N MAPLE AVE | N | L | UNK | UNK | 1/1/1945 | C | UNK | 1/1/1945 | SF | UNK | C | UNK | 1/1/1945 | 2012-REMOVED LEAD WIPE AT CURB VALVE(GAFFNEY PLBG.) | Previous eval | Y | 2012 | Mech excav | Field inspection only | Y | 9/6/2016 | Visual Insp during install or repair | |
| 852 | 506 N MAPLE AVE | N | C | Y | 3/4" | 1/1/2017 | C | 3/4" | 1/1/2017 | SF | UNK | C | 3/4" | UNK | REMOVED LEAD & INSTALLED NEW COPPER FROM MAIN TO C.8/C.V., INSULATED--2017 | Installation Record | Y | 1/1/2017 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|---|--|--|---|---|--|--|---|---|---|
| 855 | 504 N Maple Ave | N | C | Y | 1" | 1/1/2017 | C | 1" | 1/1/2017 | SF | UNK | C | 1" | UNK | 2017-REPLACED LEAD SERVICE FROM CORP TO CURB VALVE WITH 3/4" COPPER. 4/24/23: Gaffney replaced galvanized w/ 3/4" copper cs-meter. Installed new 3/4" cs & box. | Installation Record | Y | 1/1/2017 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 858 | 412 N Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1927 | C | UNK | 1/1/1927 | SF | UNK | C | C | | 1982-RETAPPED, LOWERED & INSULATED | Installation Record | Y | 1/1/1982 | Mech excav | Field Inspection Only | Y | 9/2/2016 | Cross Connection Survey | |
| 864 | 408 N Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1922 | C | UNK | 1/1/1922 | SF | UNK | C | C | | 1982-RETAPPED, LOWERED & INSULATED | Installation Record | Y | 1/1/1982 | Mech excav | Field Inspection Only | Y | 9/1/2016 | Cross Connection Survey | |
| 868 | 505 N Central Ave | N | L | UNK | 5/8" | 1/1/1926 | C | 5/8" | 1/1/1926 | NONRES | UNK | C | UNK | 1/1/1926 | 2020 J&R VAC EXCAVATED @ EOP, FOUND LEAD 6"6" DEEP | Previous eval | Y | 2020 | Mech excav | Field inspection only | Y | 6/24/2013 | Cross Connection Survey | |
| 871 | 507 N Central Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | NONRES | UNK | C | C | | LOCATION VERIFIED 1/97 | Installation Record | Y | 1/1/1997 | Mech excav | Field Inspection Only | Y | 6/20/2013 | Cross Connection Survey | |
| 880 | 701 N Central Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | NONRES | UNK | C | C | | 3/4" COPPER LOCKING VALVE. 3/4" copper on property side | Installation Record | N | | | Field Inspection Only | Y | 6/20/2013 | Cross Connection Survey | |
| 883 | 712 N Central Ave | N | C | Y | 1" | 5/11/2021 | UNK-NOLG | 1" | 5/11/2021 | NONRES | UNK | UNK-NOLG | 1" | UNK | 5/11/2021-Lead removed in street (main-cs). New tap 5' South of old tap and 2.5' North of new tap for 708 N. Central Ave. Installed new CS & Box, did not connect to anything after CS. | Installation Record | Y | 5/11/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 886 | 706 N Central Ave | N | L | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | NONRES | UNK | C | UNK | 1/1/1926 | 2009-REIGELS INSTALLED CURB VALVE W/ BOX | SL repair/replace record | Y | 2009 | Mech excav | Field inspection only | Y | 12/2/2014 | Cross Connection Survey | |
| 889 | 702 N Central Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | NONRES | UNK | C | C | | LOCATION VERIFIED 1/97 | Installation Record | N | | | Field Inspection Only | Y | 12/3/2014 | Cross Connection Survey | |
| 894 | 700 N Central Ave | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 901 | 500 N Central Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | NONRES | UNK | C | C | | 1/2" COPPER LOCKING VALVE | Installation Record | N | | | Field Inspection Only | Y | 12/8/2014 | Cross Connection Survey | |
| 904 | 500 N Cherry Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 907 | 504 N Cherry Ave | N | C | Y | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX 8/23/22-Customer replaced lead w/ 1" copper | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 910 | 512 N Cherry Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX. CONNECTED TO COPPER ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 913 | 313 E Edison St | N | C | UNK | 1" | 8/23/2023 | C | 1" | 8/23/2023 | SF | UNK | C | 1" | UNK | Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 18 of the construction report | Installation Record | Y | 8/23/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 916 | 411 E Edison St | N | C | UNK | 1" | 8/1/2023 | C | 1" | UNK | SF | UNK | C | 1" | UNK | Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 19 of the construction report | Installation Record | Y | 8/1/2023 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 919 | 503 E Edison St | N | C | UNK | 1" | 8/1/2023 | C | 1" | 8/1/2023 | SF | UNK | C | 1" | UNK | Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper. See sheet 19 of the construction report | Installation Record | Y | 8/1/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 922 | 513 E Edison St | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 925 | 515 E Becker Rd | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 931 | 606 N Ash Ave | N | C | UNK | 1" | 6/8/2021 | C | 1" | 6/8/2021 | SF | UNK | C | 1" | UNK | 30' of 1" Type 'K' Copper from WM - CS then 14.5' of 1" from CS to existing 3/4" Copper | Installation Record | Y | 6/8/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 933 | 608 N Ash Ave | N | C | UNK | 1" | 6/7/2021 | C | 1" | 6/7/2021 | SF | UNK | C | 1" | UNK | 30' - 1" Type 'K' Copper from WM - CS then 15' - 1" Copper from CS to existing 3/4" Copper | Installation Record | Y | 6/7/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 936 | 610 N Ash Ave | N | C | UNK | 1" | 6/4/2021 | C | 1" | 6/4/2021 | SF | UNK | C | 1" | UNK | 30' - 1" Type 'K' Copper from WM - CS then 10' of 1" Copper from CS to existing 3/4" Copper | Installation Record | Y | 6/4/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 939 | 612 N Ash Ave | N | C | UNK | 1" | 6/3/2021 | C | 1" | 6/3/2021 | SF | UNK | C | 1" | UNK | 30' - 1" Type 'K' Copper from WM - CS then 12" - 1" Copper to existing 3/4" Copper | Installation Record | Y | 6/3/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 942 | 614 N Ash Ave | N | C | UNK | 1" | 6/3/2021 | C | 1" | 6/3/2021 | SF | UNK | C | 1" | UNK | 6/3/2021-30' of 1" copper from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper | Installation Record | Y | 6/3/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 945 | 616 N Ash Ave | N | C | UNK | 1" | 6/2/2021 | C | 1" | 6/2/2021 | SF | UNK | C | 1" | UNK | 6/2/2021-28' of 1" from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper | Installation Record | Y | 6/2/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 948 | 620 N Ash Ave | N | C | UNK | 1" | 6/2/2021 | C | 1" | 6/2/2021 | SF | UNK | C | 1" | UNK | 6/2/2021- 30' of 1" copper from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper | Installation Record | Y | 6/2/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 951 | 622 N Ash Ave | N | C | UNK | 1" | 6/1/2021 | C | 1" | 6/1/2021 | SF | UNK | C | 1" | UNK | 27' of 1" from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper. Water service is 5' north of sanitary manhole & insulated | Installation Record | Y | 6/1/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 954 | 626 N Ash Ave | N | C | UNK | 1" | 6/1/2021 | C | 1" | 6/1/2021 | SF | UNK | C | 1" | UNK | 27' of 1" from main to curb box - 12" of 1" from curb valve to existing 3/4" copper | Installation Record | Y | 6/1/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 957 | 623 N Plum Ave | N | C | Y | 1" | 5/27/2022 | C | 1" | 5/27/2022 | SF | UNK | C | 1" | UNK | 5/27/22: Pg. 7 of construction report. Installed new 1" corp., 4' - 1" copper, connected to existing 3/4" copper. Tap is 40' East from hyd tee. (no lead) | Installation Record | Y | 5/27/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 960 | 618 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 963 | 626 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 966 | 707 N Plum Ave | N | C | UNK | 1" | 1/1/1966 | C | 1" | 1/1/1966 | SF | UNK | C | 1" | UNK | SCHREINERS. 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 6" DEEP | Installation Record | Y | 1/1/1966 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 969 | 711 N Plum Ave | N | UNK-NOLG | UNK | 3/4" | 1/1/1969 | C | 3/4" | 1/1/1969 | SF | UNK | C | 3/4" | UNK | BILL REIGEL/DUPLEX WITH 713 N PLUM | Installation Record | Y | 1/1/1969 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 972 | 605 E Franklin St | N | C | UNK | 1" | 5/19/2022 | C | 1" | 5/19/2022 | SF | UNK | C | 1" | UNK | 5/19/22: Pg 3 of Cons. Report. Replaced existing 3/4" copper service w/ 1" copper, 1" corp. and 1" cs & box. Conn. to exist. 3/4" copper @ the sidewalk. | Installation Record | Y | 5/19/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 975 | 712 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 978 | 716 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 981 | 720 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 984 | 627 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 987 | 701 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 990 | 713 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 993 | 721 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 996 | 725 N Peach Ave | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 999 | 801 N Peach Ave | N | C | UNK | 1" | 1/1/2001 | C | 1" | 1/1/2001 | NONRES | UNK | C | 1" | UNK | 2001-3/4" CORP.CURB VALVE & BOX.SERVICE IS OFF GRANT ST. | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1002 | 815 N Peach Ave | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1005 | 901 N Peach Ave | N | UNK-NOLG | UNK | 3/4" | 1/1/1972 | C | 3/4" | 1/1/1972 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1972 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1008 | 724 N Peach Ave | N | C | UNK | 1" | 5/11/2022 | C | 1" | 5/11/2022 | SF | UNK | C | 1" | UNK | 1-1-2020 J&R VACUUM EXCAVATED 2" FROM CB, FOUND 3/4" COPPER 7"3" DEEP. 5/11/22: Installed new 1" tap w/ tapping saddle, 18" - 1" copper, connected to existing 3/4" copper. | Installation Record | Y | 5/11/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1011 | 606 E Grant St | N | C | UNK | 1" | 5/12/2022 | C | 1" | 5/12/2022 | SF | UNK | C | 1" | UNK | 5/12/22: Installed new 1" tap w/ tapping saddle, 18" - 1" copper, connected to existing 3/4" copper. | Installation Record | Y | 5/12/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1014 | 508 E Grant St | N | C | UNK | 1" | 5/9/2022 | C | 1" | 5/9/2022 | SF | UNK | C | 1" | UNK | 5/9/22: Installed new 1" tap w/ tapping saddle, 30" - 1" copper, connected to existing 3/4" copper. | Installation Record | Y | 5/9/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|---|--|--|---|---|--|--|---|---|---|
| 1017 | 504 E GRANT ST | N | C | UNK | 1" | 5/9/2022 | C | 1" | 5/9/2022 | SF | UNK | C | 1" | UNK | 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 7" DEEP, 5/9/22: Installed new 1" tap w/ tapping saddle, 18" - 1" copper, connected to existing 3/4" copper. | Installation Record | Y | 5/9/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1020 | 500 E GRANT ST | N | C | UNK | 1" | 5/5/2022 | C | 1" | 5/5/2022 | SF | UNK | C | 1" | UNK | 5/5/22: Installed new 1" tap w/ tapping saddle, 4' - 1" copper, connected to existing 3/4" copper. | Installation Record | Y | 5/5/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1023 | 408 E GRANT ST | N | C | UNK | 1" | 5/4/2022 | C | 1" | 5/4/2022 | SF | UNK | C | 1" | UNK | 5/4/22: Installed new 1" tap w/ tapping saddle, 12" - 1" copper, connected to existing 3/4" copper. | Installation Record | Y | 5/4/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1029 | 509 E FOREST ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1032 | 513 E FOREST ST | N | C | UNK | 3/4" | 1/1/1969 | C | 3/4" | 1/1/1969 | SF | UNK | C | 3/4" | UNK | 1-1-2020 J&R VACUUM EXCAVATED 6" FROM CB, FOUND 3/4" COPPER 6"7" DEEP | Installation Record | Y | 1/1/1969 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1035 | 504 E FOREST ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1967 | C | 3/4" | 1/1/1967 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1967 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1038 | 500 E FOREST ST | UNK | UNK-LG | UNK | 5/8" | 1/1/1966 | C | 5/8" | 1/1/1966 | SF | UNK | C | 5/8" | UNK | <Null> | Installation Record | Y | 1/1/1966 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1041 | 422 E FOREST ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1044 | 412 E FOREST ST | N | C | UNK | 1" | 1/1/1970 | C | 1" | 1/1/1970 | SF | UNK | C | 1" | UNK | GAFFNEY. J&R VACUUM EXCAVATED 1-1-2020, FOUND 1" COPPER 1" FROM CB 7" DEEP | Installation Record | Y | 1/1/1970 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1047 | 415 E FRANKLIN ST | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2022 - Replaced lead gooseneck at water main, replaced w/ 3/4" copper. | Installation Record | Y | 1/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1050 | 417 E FRANKLIN ST | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1053 | 419 E FRANKLIN ST | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1056 | 425 E FRANKLIN ST | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1059 | 509 E FRANKLIN ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1971 | C | 3/4" | 1/1/1971 | SF | UNK | C | 3/4" | UNK | REIGEL | Installation Record | Y | 1/1/1971 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1062 | 623 N ASH AVE | N | C | UNK | 1" | 6/1/2021 | C | 1" | 6/1/2021 | SF | UNK | C | 1" | UNK | 17" of 1" from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper | Installation Record | Y | 6/1/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1065 | 619 N ASH AVE | N | C | UNK | 1" | 6/2/2021 | C | 1" | 6/2/2021 | SF | UNK | C | 1" | UNK | 6/2/2021-18" of 1" copper from main to curb valve - 12" of 1" from curb valve to existing 3/4" copper | Installation Record | Y | 6/2/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1068 | 613 N ASH AVE | N | C | UNK | 1" | 6/3/2021 | C | 1" | 6/3/2021 | SF | UNK | C | 1" | UNK | 17" of 1" Copper from main to curb valve. 12" of 1" from curb valve to existing 3/4" Copper | Installation Record | Y | 6/3/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1071 | 611 N ASH AVE | N | C | UNK | 1" | 6/4/2021 | C | 1" | 6/4/2021 | SF | UNK | C | 1" | UNK | 17" - 1" Type 'K' Copper from WM - CS then 12" - 1" Copper from CS to existing 3/4" Copper | Installation Record | Y | 6/4/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1074 | 609 N ASH AVE | N | C | UNK | 1" | 6/7/2021 | C | 1" | 6/7/2021 | SF | UNK | C | 1" | UNK | 17" - 1" Type 'K' Copper from WM - CS then 8" of 1" Copper from CS to 3/4" Copper then 12" - 3/4" Copper to existing 5/8" Copper | Installation Record | Y | 6/7/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1077 | 613 E BECKER RD | N | UNK-LG | UNK | UNK | 1/1/1940 | C | UNK | 1/1/1940 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 12/1/2016 | Cross Connection Survey | |
| 1080 | 615 E BECKER RD | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1083 | 610 N PLUM AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1086 | 614 N PLUM AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1089 | 622 N PLUM AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1092 | 626 N PLUM AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1095 | 617 E BECKER RD | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWIELER/ SERVICE COME OFF BECKER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1098 | 611 N PEACH AVE | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIEWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1101 | 601 N PEACH AVE | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1104 | 713 E BECKER RD | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1110 | 708 E BECKER RD | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1113 | 517 N PEACH AVE | N | C | UNK | 3/4" | 1/1/2001 | UNK-NOLG | 3/4" | 1/1/2001 | SF | UNK | UNK-NOLG | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1116 | 515 N PEACH AVE | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | TRIERWEILER | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1119 | 513 N PEACH AVE | N | C | Y | 3/4" | UNK | C | 3/4" | 6/27/2023 | SF | UNK | C | 3/4" | UNK | 6/27/23: Dug @ wm, replaced lead gooseneck and 12'-3/4" copper. connected to existing 3/4" copper @ swr. main. Meyers replaced sanitary lateral from main to house. Found 3/4" copper East of the sidewalk. | Installation Record | Y | 6/27/2023 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1122 | 511 N PEACH AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 6/27/23: Dug @ wm, replaced 18" lead wipe w/ 3/4" copper. Conn. to existing 3/4" copper @ wm. | Installation Record | Y | 6/27/2023 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1125 | 507 N PEACH AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1128 | 501 N PEACH AVE | N | UNK-LG | UNK | UNK | 1/1/1941 | C | UNK | 1/1/1941 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/14/2016 | Cross Connection Survey | |
| 1131 | 500 N PEACH AVE | N | UNK-LG | UNK | UNK | 1/1/1930 | C | UNK | 1/1/1930 | SF | UNK | C | C | | C.B. LOCATION VERIFIED 5/19/97 | Installation Record | Y | 5/19/1997 | Mech excav | Field Inspection Only | Y | 11/21/2016 | Cross Connection Survey | |
| 1134 | 504 N PEACH AVE | N | UNK-LG | UNK | UNK | 1/1/1930 | C | UNK | 1/1/1930 | SF | UNK | C | C | | 1/2" COPPER LOCKING VALVE | Installation Record | N | | | Field Inspection Only | Y | 12/20/2016 | Cross Connection Survey | |
| 1137 | 508 N PEACH AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1140 | 514 N PEACH AVE | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 12/28/2016 | Cross Connection Survey | |
| 1143 | 515 N ASH AVE | N | C | Y | 1" | 5/19/2021 | C | 1" | 5/19/2021 | SF | UNK | C | 1" | UNK | 5-19-21 - New 1" tap 3' East of old tap (left in place). Removed lead from main to cs & replaced w/ 1" copper. Installed new 1" cs. Reigel Plbg installed 3/4" copper to house. | Installation Record | Y | 5/19/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1146 | 511 N ASH AVE | N | C | Y | 1" | 6/7/2024 | L | 5/8" | 1/1/1929 | SF | UNK | C | C | | 6/7/24: Removd lead from wm-cs. Replaced w/ 1" corp, 1" copper, 1" cs & box. Conn. to existing 5/8" lead 18" after cs. Old corp is 4' North of new corp. | SL repair/replace record | Y | 6/7/2024 | Visual insp during install or repair | Field Inspection Only | Y | 6/7/2024 | Visual Insp during install or repair | |
| 1149 | 509 N ASH AVE | N | C | UNK | 1" | 6/10/2024 | C | 1" | 6/10/2024 | SF | UNK | C | 1" | UNK | 6/10/24: Installed new 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 12" after cs. | Installation Record | Y | 6/10/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1152 | 507 N ASH AVE | N | C | UNK | 1" | 6/10/2024 | C | 3/4" | 1/1/1947 | SF | UNK | C | C | | <Null> | Installation Record | Y | 6/10/2024 | Visual insp during install or repair | Field Inspection Only | Y | 10/21/2016 | Cross Connection Survey | |
| 1155 | 505 N ASH AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 6/7/24: Lead wipe removed at wm. Connected to existing 3/4" copper at wm. | Installation Record | Y | 6/7/2024 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1158 | 503 N ASH AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1976 | C | 3/4" | 1/1/1976 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1976 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1161 | 501 N ASH AVE | N | C | Y | 1" | 6/5/2024 | C | 3/4" | 1/1/1947 | SF | UNK | C | C | | 6/5/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 12" after cs. Old corp is 1.5' North of old corp. | SL repair/replace record | Y | 6/5/2024 | Visual insp during install or repair | Field Inspection Only | Y | 6/5/2024 | Visual Insp during install or repair | |
| 1164 | 500 N ASH AVE | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | NEW 3/4" CURB VALVE & BOX INSTALLED. 3/4" COPPER INSTALLED ALL THE WAY TO WWATER MAIN. | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1167 | 508 N ASH AVE | N | C | Y | 3/4" | 10/6/2000 | C | 3/4" | 10/6/2000 | SF | UNK | C | 3/4" | UNK | CURB BOX CUT-IN 10-6-00. LEAD REPLACED FROM MAIN TO CURB BOX. | Installation Record | Y | 10/6/2000 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1170 | 512 N ASH AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 7/6/2021 - Removed Lead from WM-CS & replaced with copper. 1/2" Copper on property side. | Installation Record | Y | 7/6/2021 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1176 | 512 N VINE AVE | N | C | UNK | 1" | 8/28/2023 | C | 1" | 8/28/2023 | SF | UNK | C | 1" | UNK | Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 1/2" copper that was pushed through iron pipe. See sheet 20 of the construction report | Installation Record | Y | 8/28/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 1179 | 508 N Vine Ave | N | C | UNK | 1" | 7/26/2023 | C | 1" | UNK | SF | UNK | C | 1" | UNK | Removed 3/4" copper and replaced w/ 1" copper from main to existing 3/4" CS & Box. See sheet 6 of the construction report | Installation Record | Y | 7/26/2023 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1182 | 503 N Vine Ave | N | C | Y | 1" | 7/25/2023 | C | 1" | 7/25/2023 | SF | UNK | C | 1" | UNK | Removed lead and 3/4" copper and replaced w/ 1" copper from main to existing 3/4" CS & Box. See sheet 5 of the construction report. | Installation Record | Y | 7/25/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1185 | 501 N Vine Ave | N | C | UNK | 1" | 7/26/2023 | C | 1" | 7/26/2023 | SF | UNK | C | 1" | UNK | Installed 1" CU from main to existing 3/4" copper at the cs. See sheet 6 of the construction report | Installation Record | Y | 7/26/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1188 | 413 N Vine Ave | N | C | Y | 1" | 5/23/2024 | C | 3/4" | 1/1/1937 | SF | UNK | C | C | | 5/23/24: Replaced lead from wm-cs with 1" corp, 1" cu & 1" cs & box. connected to existing 3/4" copper. Old corp is 2' North of old corp. | SL repair/replace record | Y | 5/23/2024 | Visual insp during install or repair | Field Inspection Only | Y | 5/23/2024 | Visual Insp during install or repair | |
| 1191 | 407 N Vine Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | CORP IS 46' W & 10' N OF S.W.C.H., RETAPPED - OLD CORP IS 2' NORTH, INSULATED TO SEWER. 10/2023: Meyers installed cs & box and verified 3/4" copper crossing the street | Installation Record | Y | 10/1/2023 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1194 | 405 N Vine Ave | N | C | UNK | 3/4" | 1/1/2013 | C | 3/4" | 1/1/2013 | SF | UNK | C | 3/4" | UNK | 2013-INSTALLED NEW COPPER FROM MAIN TO CURB. RETAPPED CORP IS 57'W & 2'S OF SW COR. OF HSE. OLD CORP. IS 3'N | Installation Record | Y | 1/1/2013 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1197 | 401 N Vine Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 3/4 COPPER LOCKING VALVE CORP IS 59'W & 34'S OF NW COR. OF HSE. OLD CORP IS 3'N ON TOP. 5/17/2024: Dug and verified 3/4" copper at main and cs. Installed new cs & box @ the sidewalk. | Installation Record | Y | 5/17/2024 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1200 | 308 N Vine Ave | N | C | Y | UNK | 4/11/1990 | C | UNK | 4/11/1990 | SF | UNK | C | UNK | UNK | LEAD REMOVED & INSULATED 4/90 | Installation Record | Y | 4/11/1990 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1203 | 400 N Vine Ave | N | C | Y | 1" | 5/17/2024 | C | 3/4" | 1/1/1929 | SF | UNK | C | C | | 5/17/2024: Removed 3'-3/4" copper @ wm & lead to sidewalk. Replaced w/ new 1" corp., 1" copper & 1" cs & box. Connected to existing 3/4" copper 12" West of the cs. 6" clay San. lateral is on top of wm. | SL repair/replace record | Y | 5/17/2024 | Visual insp during install or repair | Field Inspection Only | Y | 5/17/2024 | Visual Insp during install or repair | |
| 1206 | 404 N Vine Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | RETAPPED CORP IS 49'E & 2'S OF NE COR. OF HSE. INSULATED. OLD CORP IS 2'N. 5/21/2024: Dug and verified 3/4" copper at main and cs. | Installation Record | Y | 5/21/2024 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1209 | 412 N Vine Ave | N | C | Y | UNK | 4/1/1990 | C | 3/4" | 1/1/1929 | SF | UNK | C | C | | 4-90: Retapped new coper to curb box then. 5/21/2024: Dug and verified 3/4" copper at main and cs. | SL repair/replace record | Y | 5/21/2024 | Visual insp during install or repair | Field Inspection Only | Y | 5/21/2024 | Visual Insp during install or repair | |
| 1212 | 409 N Cherry Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1215 | 407 N Cherry Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1218 | 405 N Cherry Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1221 | 401 N Cherry Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1227 | 313 N Cherry Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | REPLACED COPPER FROM CORP TO NEW CURB BOX | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1230 | 400 N Cherry Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1236 | 408 N Cherry Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2015- INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1239 | 505 N Cherry Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1242 | 405 N Cedar Ave | N | C | UNK | 1" | 4/30/2024 | C | 1" | 4/30/2024 | SF | UNK | C | 1" | UNK | Old corp is 3' South of new corp. 1"x3/4" fitting is 24" West of curb stop (on street side of curb stop) | Installation Record | Y | 4/30/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1248 | 113 E Arnold St | N | L | UNK | 3/4" | 1/1/1926 | C | 3/4" | 1/1/1926 | SF | UNK | C | UNK | 1/1/1926 | 3/4" Copper inside, Lead outside, removed wipe 2/23/95 | SL repair/replace record | Y | 1995 | Mech excav | Field inspection only | Y | 11/15/2016 | Cross Connection Survey | |
| 1251 | 204 N Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/29/2016 | Cross Connection Survey | |
| 1254 | 208 N Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | CB/LV UNKNOWN | Installation Record | N | | | Field Inspection Only | Y | 12/22/2016 | Cross Connection Survey | |
| 1257 | 108 E Blodgett St | N | UNK-LG | UNK | UNK | 1/1/1941 | C | UNK | 1/1/1941 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/15/2016 | Cross Connection Survey | |
| 1261 | 302 N Maple Ave | N | C | Y | 1" | 5/13/2024 | L | 5/8" | 1/1/1927 | SF | UNK | C | C | | 5/13/2024: Removed lead, installed 1" cbv, connected to lead homeowner side. | SL repair/replace record | Y | 5/13/2024 | Visual insp during install or repair | Field Inspection Only | Y | 5/13/2024 | Visual Insp during install or repair | |
| 1264 | 304 N Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1925 | C | UNK | 1/1/1925 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 8/30/2013 | Cross Connection Survey | |
| 1267 | 313 N Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1925 | C | UNK | 1/1/1925 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/3/2016 | Cross Connection Survey | |
| 1270 | 311 N Maple Ave | N | C | UNK | 1" | 6/21/2023 | C | 1" | 6/21/2023 | SF | UNK | C | 1" | UNK | 6/21/23: Installed 1" corp, 1" copper wm-cs. Corp is 3' North of corp for 308 N. Maple. Meyers replaced galvanized w/ 1" copper from cs-meter and installed 1" cs & box. Unmarked 1/2" GAS runs parellel with service 3' north of service. | Installation Record | Y | 6/21/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1273 | 303 N Maple Ave | N | C | Y | 1" | 5/15/2024 | C | 3/4" | 1/1/1925 | SF | UNK | C | C | | 5/15/2024: Replaced lead with 1" copper from wm - cs. Attached to existing 3/4" copper coming out of cs. Old corp. is 3' South of the new one. | SL repair/replace record | Y | 5/15/2024 | Visual insp during install or repair | Field Inspection Only | Y | 5/15/2024 | Visual Insp during install or repair | |
| 1276 | 213 N Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | CURB STOP BUT NO BOX | Installation Record | N | | | Field Inspection Only | Y | 12/6/2016 | Cross Connection Survey | |
| 1279 | 211 N Maple Ave | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | 2015-CAL'S INSTALLED NEW CURB BOX | Installation Record | Y | 1/1/2015 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1282 | 207 N Maple Ave | N | L | UNK | UNK | 1/1/1926 | P | UNK | 1/1/1926 | SF | UNK | P | UNK | 1/1/1926 | 4/12/2016 - REPLACED OLD CORP, AND 5' OF 3/4" COPPER CONNECTED TO LEAD SERVICE | SL repair/replace record | Y | 2016 | Mech excav | Field inspection only | Y | 12/9/2016 | Cross Connection Survey | |
| 1285 | 201 N Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/17/2016 | Cross Connection Survey | |
| 1291 | 113 N Maple Ave | N | C | UNK | 1" | 9/26/2017 | P | 1" | 9/26/2017 | SF | UNK | P | 1" | UNK | NEW TAP, COPPER AND C.B./C.V.--2017 | Installation Record | Y | 9/26/2017 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1303 | 207 E Arnold St | N | L | Y | UNK | UNK | L | UNK | UNK | SF | UNK | L | UNK | UNK | 2003-REMOVED LEAD WIPE & INSTALLED CURB VALVE W/ BOX | Installation Record | Y | 1/1/2003 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1306 | 209 E Arnold St | N | UNK-LG | UNK | UNK | 1/1/1937 | C | UNK | 1/1/1937 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/16/2016 | Cross Connection Survey | |
| 1309 | 200 N Cedar Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | 2015- VERIFIED SERVICE COME OFF OF ARNOLD | Installation Record | Y | 1/1/2015 | Mech excav | Field Inspection Only | Y | 11/8/2016 | Cross Connection Survey | |
| 1312 | 201 N Cedar Ave | N | C | UNK | 1" | 1/1/2015 | C | 1" | 1/1/2015 | SF | UNK | C | 1" | UNK | 3/4" COPPER ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1315 | 205 N Cedar Ave | N | C | UNK | 1" | 1/1/2015 | P | 1" | 1/1/2015 | SF | UNK | P | 1" | UNK | 1" PLASTIC ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1318 | 207 N Cedar Ave | N | C | UNK | 1" | 1/1/2015 | P | 1" | 1/1/2015 | SF | UNK | P | 1" | UNK | 1" PLASTIC ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1321 | 208 E Blodgett St | N | C | Y | 1" | UNK | C | 1" | 6/27/2023 | SF | UNK | C | 1" | UNK | 6/27/23: Replaced lead wm-cs w/ 1" tap, 1" corp, 1" copper wm-cs. Gaffney replaced lead with 3/4" copper from cs-meter. Gaffney also installed a 1" cs & box. | Installation Record | Y | 6/27/2023 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1324 | 300 N Cedar Ave | N | UNK-LG | UNK | UNK | 1/1/1925 | C | UNK | 1/1/1925 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/14/2016 | Cross Connection Survey | |
| 1327 | 304 N Cedar Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2008-INSTALLED COPPER FROM MAIN TO CURB VALVE.INSTALLED CURB VALVE & BOX | Installation Record | Y | 1/1/2008 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1330 | 306 N Cedar Ave | N | C | UNK | 3/4" | 1/1/2008 | C | 3/4" | 1/1/2008 | SF | UNK | C | 3/4" | UNK | 2008-INSTALLED COPPER FROM MAIN TO CURB VALVE. INSTALLED CURB VALVE. | Installation Record | Y | 1/1/2008 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 1333 | 308 N Cedar Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 4/26/24: Verified all 3/4" copper from main to 9' to the West (bottom of ditch) | Installation Record | Y | 4/26/2024 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1336 | 309 N Cedar Ave | N | C | UNK | 1" | 4/25/2024 | C | 1" | 4/25/2024 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 4/25/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1339 | 305 N Cedar Ave | N | C | UNK | 3/4" | 1/1/1935 | C | 3/4" | 1/1/1935 | SF | UNK | C | C | | 5/1/24: Dug and verified 3/4" copper from wm-cs. Corp is 40' East & 5' North of the NECH @ 302 N Cedar. Moved cs out of the driveway. | Installation Record | Y | 5/1/2024 | Mech excav | Field Inspection Only | Y | 5/3/2024 | Mech excav | |
| 1343 | 309 E Blodgett St | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | TYPE 'K' COPPER - LEAD REPLACEMENT | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1346 | 308 E Blodgett St | N | C | Y | 3/4" | 8/19/2019 | C | 3/4" | 8/19/2019 | SF | UNK | C | 3/4" | UNK | TYPE K COPPER - LEAD REPLACEMENT - REIGELS | Installation Record | Y | 8/19/2019 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1349 | 314 E Blodgett St | N | C | Y | 3/4" | 8/23/2018 | C | 3/4" | 8/23/2018 | SF | UNK | C | 3/4" | UNK | 8-23-18 REMOVED ALL LEAD AND REPLACED WITH 3/4" COPPER FROM MAIN TO HOUSE | Installation Record | Y | 8/23/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1352 | 206 N Cherry Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/16/2016 | Cross Connection Survey | |
| 1355 | 204 N Cherry Ave | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1358 | 200 N Cherry Ave | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1361 | 308 E Arnold St | N | UNK-LG | UNK | UNK | 1/1/1969 | C | UNK | 1/1/1969 | NONRES | UNK | C | C | | SCHREINERS | Installation Record | N | | | Field Inspection Only | Y | 6/17/2013 | Cross Connection Survey | |
| 1365 | 400 E Arnold St | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | NONRES | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 2/24/2015 | Cross Connection Survey | |
| 1367 | 201 N Cherry Ave | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1370 | 205 N Cherry Ave | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CURB BOX. | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1373 | 402 E Blodgett St | N | C | UNK | 3/4" | 5/6/2024 | P | 3/4" | 5/6/2024 | SF | UNK | P | 3/4" | UNK | 5/6/24: Hit existing corp., removed & replaced w/ 6"x12" sleeve w/ 1" CC. Conn. to existing 3/4" copper 3' South of main. Dug @ cs, verified copper on street side & copper-hdpe on customer side. Corp is 10' East of cs. | Installation Record | Y | 5/6/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1376 | 401 E Blodgett St | N | C | Y | 1" | 5/6/2024 | C | 1" | 5/6/2024 | SF | UNK | C | 1" | UNK | 5/6/24: Removed lead from wm-cs replaced w/ new 1" corp, 1" cs & box. Connected to existing 3/4" copper 12" North of cs. Old corp is 6' West of the new corp. | Installation Record | Y | 5/6/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1379 | 405 E Blodgett St | N | C | Y | 1" | 5/1/2024 | C | 1/2" | 1/1/1938 | SF | UNK | C | C | | 5/1/24: Lead removed from wm-cs. Replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing 1/2" copper after cs. | SL repair/replace record | Y | 5/1/2024 | Visual insp during install or repair | Field Inspection Only | Y | 5/1/2024 | Visual Insp during install or repair | |
| 1382 | 414 E Blodgett St | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | Service feeds both 412 & 414 E. Blodgett. 5/10/24: Verified copper @ main and terrace. One tap at main and found two curb stops in the terrace. Assumed service is y'd under curb and gutter. | Installation Record | Y | 5/10/2024 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1385 | 112 N Vine Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/12/2016 | Cross Connection Survey | |
| 1388 | 110 N Vine Ave | N | L | UNK | 5/8" | 1/1/1926 | C | 5/8" | 1/1/1926 | SF | UNK | C | UNK | 1/1/1926 | 5/8 LEAD TO CURBSTOP-3/4 COPPER TO HOUSE 2002 | SL repair/replace record | Y | 2002 | Mech excav | Field inspection only | Y | 1/1/2005 | Visual Insp during install or repair | |
| 1391 | 108 N Vine Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/8/2016 | Cross Connection Survey | |
| 1394 | 413 E Depot St | N | UNK-LG | UNK | UNK | 1/1/1920 | C | UNK | 1/1/1920 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/28/2016 | Cross Connection Survey | |
| 1400 | 309 E Depot St | N | UNK-LG | UNK | UNK | 1/1/1920 | C | UNK | 1/1/1920 | NONRES | UNK | C | C | | CB LOCATION VERIFIED 6/4/97. 2020 - Property side material verified per customer | Installation Record | N | | | Field Inspection Only | Y | 11/25/2014 | Cross Connection Survey | |
| 1404 | 111 N Vine Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/10/2016 | Cross Connection Survey | |
| 1407 | 117 N Vine Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | SERVICE COMES OFF OF ARNOLD | Installation Record | N | | | Field Inspection Only | Y | 11/28/2016 | Cross Connection Survey | |
| 1410 | 208 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN FROM CURB VALVE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1413 | 304 N Ash Ave | N | C | UNK | 3/4" | 1/1/1999 | C | 3/4" | 1/1/1999 | SF | UNK | C | 3/4" | UNK | 1999-INSTALLED COPPER FROM MAIN TO INSIDE OF HOUSE | Installation Record | Y | 1/1/1999 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1416 | 312 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1419 | 400 N Ash Ave | N | C | Y | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | REPLACED THE LEAD FROM THE MAIN TO THE CURB STOP | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1422 | 404 N Ash Ave | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | IRON UNDER SIDEWALK | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1425 | 406 N Ash Ave | N | C | Y | 1" | 6/3/2024 | G | UNK | UNK | SF | UNK | UNK | UNK | UNK | 6/3/24: Removed lead from wm-cs. Replaced w/ 1" corp., 1" copper, 1" cs & box. Connected to existing galvanized 30" after cs (under sidewalk). Old corp. is 2' South of new corp. | SL repair/replace record | Y | 6/3/2024 | Visual insp during install or repair | Field Inspection Only | Y | 6/3/2024 | Visual Insp during install or repair | |
| 1428 | 408 N Ash Ave | N | C | Y | 1" | 5/29/2024 | L | 5/8" | 1/1/1946 | SF | UNK | C | C | | 5/29/2024: Removed lead and replaced w/ copper from wm-cs. old corp is 3' North of new corp. san lateral is above wm. 7' of 1" copper from cs to 1X3/4" fitting then 12" of 3/4" copper to 5/8" lead. | SL repair/replace record | Y | 5/29/2024 | Mech excav | Field Inspection Only | Y | 5/29/2024 | Visual Insp during install or repair | |
| 1431 | 412 N Ash Ave | N | C | UNK | 1" | 5/29/2024 | C | 3/4" | 1/1/1929 | SF | UNK | C | C | | New corp. is 4' North of old corp. from cs - 12" of 3/4" copper to new 1" copper on street side - curb stop does work. | SL repair/replace record | Y | 5/29/2024 | Visual insp during install or repair | Field Inspection Only | Y | 5/30/2024 | Mech excav | |
| 1437 | 409 N Ash Ave | N | C | Y | 1" | 5/28/2024 | C | 1" | 5/28/2024 | SF | UNK | C | 1" | UNK | 1" tap, 1" copper from main to curb stop(removed existing lead). 3/4" copper on private side. Old corp. is 1.5' South of new, tapped on top. | Installation Record | Y | 5/28/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1440 | 603 E Cleveland St | N | C | Y | 1" | 8/26/2021 | C | 1" | 8/26/2021 | SF | UNK | C | 1" | UNK | All lead removed, new 1" tap & 1" curb stop. Old corp is 3' North of the new tap | Installation Record | Y | 8/26/2021 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1443 | 313 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | P | 3/4" | 1/1/2015 | SF | UNK | P | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1446 | 311 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1449 | 307 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1452 | 303 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1455 | 301 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1458 | 213 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1461 | 205 N Ash Ave | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2019-CUSTOMER REPLACED THERE PORTION OF SERVICE I; 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1464 | 600 E Arnold St | N | C | UNK | 1 1/4" | 1/1/1985 | C | 1 1/4" | 1/1/1985 | NONRES | UNK | C | 1 1/4" | UNK | TIES TO THE 4" MAIN. 1" copper to 600 E. Arnold | Installation Record | Y | 1/1/1985 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1469 | 612 E Arnold St | N | C | UNK | 1" | 1/1/2003 | C | 1" | 1/1/2003 | NONRES | UNK | C | 1" | UNK | 2003-NEW 1" CORP,COPPER,VALVE,BOX | Installation Record | Y | 1/1/2003 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1472 | 200 N Peach Ave | N | C | UNK | 1" | 1/1/2003 | C | 1" | 1/1/2003 | SF | UNK | C | 1" | UNK | NEW 1" CORP,COPPER,VALVE,BOX. 1" COPPER 5' W OF CURBVALVE | Installation Record | Y | 1/1/2003 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1475 | 204 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1928 | C | UNK | 1/1/1928 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/10/2016 | Cross Connection Survey | |
| 1478 | 210 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/2/2016 | Cross Connection Survey | |
| 1481 | 212 N Peach Ave | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | Y | 1/1/2005 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1484 | 304 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1928 | C | UNK | 1/1/1928 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/23/2016 | Cross Connection Survey | |
| 1487 | 306 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1928 | C | UNK | 1/1/1928 | SF | UNK | C | C | | 1/2" COPPER LOCKING VALVE | Installation Record | N | | | Field Inspection Only | Y | 11/16/2016 | Cross Connection Survey | |
| 1490 | 310 N Peach Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2005-INSTALLED NEW 3/4" CURB VALVE AND CURB BOX | Installation Record | Y | 1/1/2005 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1493 | 312 N Peach Ave | N | C | Y | 1" | 11/14/2024 | C | 3/4" | 1/1/1927 | SF | UNK | C | C | | 11/14/24: Removed Lead Street Side | Installation Record | Y | 11/14/2024 | Mech excav | Field Inspection Only | Y | 11/28/2016 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 1496 | 400 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1929 | C | UNK | 1/1/1929 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/19/2017 | Cross Connection Survey | |
| 1499 | 402 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1929 | C | UNK | 1/1/1929 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/16/2016 | Cross Connection Survey | |
| 1502 | 406 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1927 | C | UNK | 1/1/1927 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 11/21/2016 | Cross Connection Survey | |
| 1505 | 410 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 6/26/2017 | Cross Connection Survey | |
| 1508 | 412 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1947 | C | UNK | 1/1/1947 | SF | UNK | C | C | | 1/2" COPPER LOCKING VALVE | Installation Record | N | | | Field Inspection Only | Y | 10/25/2016 | Cross Connection Survey | |
| 1511 | 413 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | O | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 12/29/2016 | Cross Connection Survey | |
| 1514 | 409 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1938 | C | UNK | 1/1/1938 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 1/3/2017 | Cross Connection Survey | |
| 1517 | 407 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | 2015-NEW CURB VALVE INSTALLED | Installation Record | N | | | Field Inspection Only | Y | 12/2/2016 | Cross Connection Survey | |
| 1520 | 405 N Peach Ave | N | C | Y | 3/4" | 6/26/2023 | C | 3/4" | 6/26/2023 | SF | UNK | C | 3/4" | UNK | 6/26/23: Removed lead gooseneck and replaced with 3/4" copper. conn. to existing 3/4" copper @ wm. Cut in 3/4" cs at the West edge of walk between sidewalk and FIBOR OPTIC. | Installation Record | Y | 6/26/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1523 | 401 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 8/15/2013 | Cross Connection Survey | |
| 1526 | 313 N Peach Ave | N | C | Y | 1" | 11/14/2024 | C | 3/4" | 1/1/1926 | SF | UNK | C | C | | 11/14/24: Removed Lead Street Side | Installation Record | Y | 11/14/2024 | Mech excav | Field Inspection Only | Y | 2/24/2017 | Cross Connection Survey | |
| 1529 | 309 N Peach Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 10/26/2016 | Cross Connection Survey | |
| 1532 | 307 N Peach Ave | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CB/LV UNKNOWN; 2018-INSIDE SERVICE MATERIAL VERIFIED VIA VAC EX. | Installation Record | Y | 1/1/2018 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1535 | 301 N Peach Ave | N | C | UNK | 1" | 1/1/2018 | G | 1" | 1/1/2018 | SF | UNK | G | UNK | 1/1/2018 | INSTALLED 1" CORP AND TAPPING SADDLE, 18' - 1" COPPER, 1" CS & BOX, CONNECTED TO 3/4" GALVANIZED PIP @ BACK OF WALK ON CUSTOMERS SIDE | SL repair/replace record | Y | 1/1/2018 | Visual insp during install or repair | Previous eval | Y | 11/22/2016 | Cross connection survey | |
| 1538 | 700 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 30' - 1" COPPER TO CS, CONNECTED TO 3/4" COPPER ON CUSTOMER SIDE | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1541 | 704 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | CONNECTED TO 3/4" CU ON CUSTOMER SIDE | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1548 | 712 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | CONNECTED TO EXISTING 3/4" CU ON CUSTOMERS SIDE (BACK OF WALK) | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1551 | 713 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | CONNECTED TO NEW 3/4" CU ON CUSTOMERS SIDE | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1554 | 803 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | 2018 - Installed 1" corp with tapping saddle, 1' of 1" cu connected to existing 3/4" copper. 5/23/24: 1" cu from main to cs and connected to 3/4" cu customer side. | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1557 | 800 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | 1/2" COPPER W/ LOCKING VALVE RE-TAPPED 27" OF COPPER CONNECTION MADE 45°N & 2°E OF NE COR. OF HSE. *2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 3' - 1" COPPER WITH 1"X3/4" COUPLING | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1563 | 1006 E BLODGETT ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1968 | C | 3/4" | 1/1/1968 | O | UNK | C | 3/4" | UNK | SCHUH PLB | Installation Record | Y | 1/1/1968 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1566 | 907 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER ON CUSTOMERS SIDE | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1569 | 211 N ELM AVE | N | C | UNK | 1" | 1/1/2004 | C | 1" | 1/1/2004 | SF | UNK | C | 1" | UNK | 2004-NEW 1" CORP,COPPER,CURB VALVE W/BOX. | Installation Record | Y | 1/1/2004 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1572 | 203 N ELM AVE | N | C | UNK | 3/4" | 1/1/2004 | C | 3/4" | 1/1/2004 | SF | UNK | C | 3/4" | UNK | 2004-NEW 3/4 CORP ATTACHED TO EXISTING COPPER. NEW CURB VALVE W/BOX | Installation Record | Y | 1/1/2004 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1575 | 901 E ARNOLD ST | N | C | UNK | 1" | 1/1/2004 | C | 1" | 1/1/2004 | SF | UNK | C | 1" | UNK | 2004-NEW 1"CORP,COPPER,CURB VALVE W/BOX. | Installation Record | Y | 1/1/2004 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1578 | 815 E ARNOLD ST | N | C | UNK | 1" | 1/1/2004 | C | 1" | 1/1/2004 | SF | UNK | C | 1" | UNK | 2004-NEW 1" CORP,COPPER,CURB VALVE W/BOX. | Installation Record | Y | 1/1/2004 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1581 | 809 E ARNOLD ST | N | C | UNK | 1" | 1/1/2005 | C | 1" | 1/1/2005 | SF | UNK | C | 1" | UNK | MFLD UTILITIES | Installation Record | Y | 1/1/2005 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1584 | 801 E ARNOLD ST | N | C | UNK | 3/4" | 1/1/2005 | C | 3/4" | 1/1/2005 | SF | UNK | C | 3/4" | UNK | NEW COPPER FROM MAIN TO EDGE OF DRIVEWAY-MFLD UTILITIES | Installation Record | Y | 1/1/2005 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1587 | 717 E ARNOLD ST | N | C | UNK | 3/4" | 1/1/2005 | C | 3/4" | 1/1/2005 | SF | UNK | C | 3/4" | UNK | MFLD UTILITIES | Installation Record | Y | 1/1/2005 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1592 | 114 N APPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | NONRES | UNK | C | UNK | UNK | 3/4" copper on customer side | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1595 | 801 E DEPOT ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | UNK | UNK | C | UNK | UNK | CB/LV UNKNOWN | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1598 | 109 N APPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1601 | 115 N APPLE AVE | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | CB LOCATION VERIFIED 5/9/97 | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1604 | 804 E ARNOLD ST | N | C | UNK | 3/4" | 1/1/2005 | C | 3/4" | 1/1/2005 | SF | UNK | C | 3/4" | UNK | MFLD UTILITIES | Installation Record | Y | 1/1/2005 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1607 | 810 E ARNOLD ST | N | C | UNK | 3/4" | 1/1/2005 | C | 3/4" | 1/1/2005 | SF | UNK | C | 3/4" | UNK | MFLD UTILITIES | Installation Record | Y | 1/1/2005 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1610 | 114 N ELM AVE | N | C | UNK | UNK | 1/1/2004 | C | UNK | 1/1/2004 | SF | UNK | C | UNK | UNK | NEW 3/4" CORP ATTACHED TO EXISTING SERVICE @ MAIN | Installation Record | Y | 1/1/2004 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1613 | 108 N ELM AVE | N | C | UNK | 3/4" | 1/1/2004 | UNK-NOLG | 3/4" | 1/1/2004 | SF | UNK | UNK-NOLG | 3/4" | UNK | 2004-NEW 3/4 CORP ATTACHED TO EXISTING 3/4 COPPER @ MAIN | Installation Record | Y | 1/1/2004 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1616 | 105 N ELM AVE | N | C | UNK | 1" | 1/1/2004 | C | 1" | 1/1/2004 | SF | UNK | C | 1" | UNK | 2004-NEW 1" CORP, COPPER,CURB VALVE W/ BOX | Installation Record | Y | 1/1/2004 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1619 | 104 N PALMETTO AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1979 | C | 3/4" | 1/1/1979 | SF | UNK | C | 3/4" | UNK | MAIN SHALLOW/INSULATED | Installation Record | Y | 1/1/1979 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1622 | 103 N PALMETTO AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1979 | C | 3/4" | 1/1/1979 | SF | UNK | C | 3/4" | UNK | MAIN SHALLOW/INSULATED | Installation Record | Y | 1/1/1979 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1625 | 109 N PALMETTO AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1628 | 111 N PALMETTO AVE | N | UNK-NOLG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1631 | 115 N PALMETTO AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1977 | C | 3/4" | 1/1/1977 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1634 | 102 N PURDY AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | SERVICE IS OFF PURDY | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1637 | 101 N PURDY AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | Mark Meyers - Service is off of Purdy - just north of Sanitary manhole. removed lead/copper from wm-cs replaced w/ 3/4" copper. Connected to existing 3/4" copper. | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1640 | 105 N PURDY AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1975 | C | 3/4" | 1/1/1975 | SF | UNK | C | 3/4" | UNK | REIGEL | Installation Record | Y | 1/1/1975 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1643 | 109 N PURDY AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1972 | C | 3/4" | 1/1/1972 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1972 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1646 | 1100 E ARNOLD ST | N | UNK-NOLG | UNK | UNK | 1/1/1960 | C | UNK | 1/1/1960 | SF | UNK | C | UNK | UNK | <Null> | Installation Record | Y | 1/1/1960 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1649 | 1103 E ARNOLD ST | N | C | UNK | 3/4" | 1/1/1999 | C | 3/4" | 1/1/1999 | SF | UNK | C | 3/4" | UNK | MEYERS: PROPERTY ALSO HAS A PRIVATE WELL. | Installation Record | Y | 1/1/1999 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1652 | 205 N PURDY AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1655 | 207 N PURDY AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1658 | 209 N PURDY AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | 2000: NEW CURB BOX. | Installation Record | Y | 1/1/2000 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1661 | 213 N PURDY AVE | N | C | UNK | 1" | 1/1/1980 | C | 1" | 1/1/1980 | SF | UNK | C | 1" | UNK | 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"X3/4" COUPLING | Installation Record | Y | 1/1/1980 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1664 | 304 N HINMAN AVE | N | C | UNK | 1/2" | UNK | C | 1/2" | UNK | SF | UNK | C | 1/2" | UNK | RETAPPED OFF OF HINMAN 5-8-92 | Installation Record | Y | 5/8/1992 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1667 | 212 N HINMAN AVE | N | C | Y | UNK | 1/1/2001 | C | UNK | 1/1/2001 | SF | UNK | C | UNK | UNK | 2001: REMOVED THE LEAD FROM THE MAIN TO THE CURB BOX/ REPLACED WITH COPPER. | Installation Record | Y | 1/1/2001 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1670 | 204 N HINMAN AVE | N | C | Y | 1" | 6/12/2024 | C | 3/4" | 1/1/1926 | SF | UNK | C | C | | 6/12/24: Removed lead from wm-cs, replaced w/ 1" copper, 1" cs & box. Used existing corp. Connected to existing 3/4" copper 8" west of cs. | SL repair/replace record | Y | 6/12/2024 | Visual insp during install or repair | Field Inspection Only | Y | 6/12/2024 | Visual Insp during install or repair | |
| 1673 | 200 N HINMAN AVE | N | C | Y | 3/4" | UNK | C | 3/4" | 9/25/2001 | SF | UNK | C | 3/4" | UNK | 9/25/01: REMOVED LEAD FROM SANITARY DITCH TO CURB BOX. 2022 - Replaced lead w/ copper wm-house 7/1/22: Lead wipe removed | Installation Record | Y | 7/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 1676 | 112 N HINMAN AVE | N | C | UNK | 3/4" | 1/1/2001 | C | 3/4" | 1/1/2001 | SF | UNK | C | 3/4" | UNK | 2001: NEW SERVICE FROM MAIN TO CURB-BOX. NEW SERVICE FROM C.S. TO HOUSE (MEYERS 2020) | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1679 | 108 N HINMAN AVE | N | C | Y | 1" | 1/1/2001 | C | 1" | 1/1/2001 | SF | UNK | C | 1" | UNK | 2001: REMOVED ALL LEAD FROM MAIN TO CURB-BOX. 12/2/22: Meyers replaced lead w/ 1" copper from cs-meter. Also installed cs & box. | Installation Record | Y | 1/1/2001 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1682 | 103 N HINMAN AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1975 | C | 3/4" | 1/1/1975 | SF | UNK | C | 3/4" | UNK | REIGEL | Installation Record | Y | 1/1/1975 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1685 | 109 N HINMAN AVE | N | C | N | 3/4" | 1/1/1926 | C | 3/4" | 1/1/1926 | SF | UNK | C | C | | 6/14/24: Dug and verified 3/4" copper from wm-cs. | SL repair/replace record | Y | 6/14/2024 | Mech excav | Field Inspection Only | Y | 6/14/2024 | Mech excav | |
| 1688 | 113 N HINMAN AVE | N | C | UNK | 3/4" | 1/1/2022 | C | 3/4" | 1/1/2022 | SF | UNK | C | 3/4" | UNK | 2022: 3/4" copper from main to cs. 5' of 3/4" copper from cs to existing 3/4" copper. Insulated | Installation Record | Y | 1/1/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1691 | 117 N HINMAN AVE | N | C | Y | 3/4" | 9/16/1994 | C | 3/4" | 9/16/1994 | SF | UNK | C | 3/4" | UNK | Lead was replaced from the main to the curb box | Installation Record | Y | 9/16/1994 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1694 | 205 N HINMAN AVE | N | C | UNK | 3/4" | 1/1/1926 | C | 3/4" | 1/1/1926 | SF | UNK | C | C | | 9/94: New cs & box. 6/12/24: Dug and verified 3/4" copper @ wm. | Field Inspection only | Y | 6/12/2024 | Mech excav | Field Inspection Only | Y | 1/6/2017 | Cross Connection Survey | |
| 1697 | 207 N HINMAN AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 6/11/24: Dug and verified 3/4" copper from wm-cs. No Lead. MU installed a 3/4" cs & box. | Installation Record | Y | 6/11/2024 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1700 | 213 N HINMAN AVE | N | C | UNK | 3/4" | 6/20/2018 | C | 3/4" | 6/20/2018 | SF | UNK | C | 3/4" | UNK | NEW 3/4" COPPER MAIN - CURB BOX, ATTACHED TO EXISTING COPPER | Installation Record | Y | 6/20/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1703 | 1300 E BLODGETT ST | N | C | UNK | 1" | 1/1/1972 | C | 1" | 1/1/1972 | SF | UNK | C | 1" | UNK | REIGEL. 2018 - INSTALLED 1" CORP WITH TAPPING SADDLE, 3' - 1" COPPER WITH 1"x3/4" COUPLING | Installation Record | Y | 1/1/1972 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1706 | 1310 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | LOWERED & INSULATED 6/80. 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 3' - 1" COPPER WITH 1"x3/4" COUPLING | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1709 | 1402 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | 2018 - 1" CORP AND TAPPING SADDLE, 3' OF 1" CU CONNECTED TO EXISTING 3/4" CU IN STREET | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1712 | 1406 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | 2018 - INSTALLED NEW 1" CORP WITH TAPPING SADDLE, 4' - 1" COPPER, CONNECT TO EXISTING 3/4" COPPER IN ROAD | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1715 | 1405 E BLODGETT ST | N | C | UNK | 1" | 1/1/2018 | C | 1" | 1/1/2018 | SF | UNK | C | 1" | UNK | 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"x3/4" COUPLING | Installation Record | Y | 1/1/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1718 | 301 N JUNO AVE | N | C | UNK | 1" | 1/1/1970 | C | 1" | 1/1/1970 | SF | UNK | C | 1" | UNK | MEYERS. 2018 - INSTALLED 1" CORP AND TAPPING SADDLE, 2' - 1" COPPER WITH 1"x3/4" COUPLING | Installation Record | Y | 1/1/1970 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1721 | 306 N JUNO AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1975 | C | 3/4" | 1/1/1975 | SF | UNK | C | 3/4" | UNK | MEYERS(GAFFNEY) | Installation Record | Y | 1/1/1975 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1724 | 409 N JUNO AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1976 | C | 3/4" | 1/1/1976 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1976 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1727 | 400 N JUNO AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1730 | 1308 E DOEGE ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | SERVICE IS OFF JUNO. 3/4" copper on customer side | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1733 | 1406 E DOEGE ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1977 | C | 3/4" | 1/1/1977 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1736 | 1410 E DOEGE ST | N | UNK-NOLG | UNK | 1" | 1/1/1977 | C | 1" | 1/1/1977 | SF | UNK | C | 1" | UNK | MEYERS | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1742 | 1205 E DOEGE ST | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 3/4" C.V./C.B. INSTALLED BY BACH EXC--2017 | Installation Record | Y | 1/1/2017 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1745 | 1201 E DOEGE ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | A "Y" CONNECTION W/1203 DOEGE. CURB VALVE FOR #1203 ONLY | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1748 | 1209 E DOEGE ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1977 | C | 3/4" | 1/1/1977 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1751 | 413 N HINMAN AVE | N | UNK-NOLG | UNK | UNK | 1/1/1969 | C | UNK | 1/1/1969 | SF | UNK | C | UNK | UNK | <Null> | Installation Record | Y | 1/1/1969 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1754 | 407 N HINMAN AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 5/12/2021 - Verified all 3/4" copper from main. No lead found. | Installation Record | Y | 5/12/2021 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1757 | 405 N HINMAN AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | REMOVED LEAD WIPE @ MAIN 4/29/98. Ran 3/4" copper from main connected to existing 3/4" copper - RE, JT Verified 5-12-2021 | Installation Record | Y | 5/12/2021 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1760 | 403 N HINMAN AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 5/15/2021: Removed 3' lead gooseneck - ran 3/4" copper from main, connected to existing 3/4" copper | Installation Record | Y | 5/15/2021 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1763 | 1110 E CLEVELAND ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1969 | C | 3/4" | 1/1/1969 | SF | UNK | C | 3/4" | UNK | SCHREINERS | Installation Record | Y | 1/1/1969 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1766 | 1100 E CLEVELAND ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | 2004-RE-TAPPED SERVICE | Installation Record | Y | 1/1/2004 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1769 | 402 N PALMETTO AVE | N | C | UNK | 1" | 1/1/1993 | C | 1" | 1/1/1993 | SF | UNK | C | 1" | UNK | DUPLEX WITH 404 N PALMETTO | Installation Record | Y | 1/1/1993 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1772 | 401 N PALMETTO AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1775 | 1101 E CLEVELAND ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1778 | 1105 E CLEVELAND ST | UNK | UNK-LG | UNK | 5/8" | 1/1/1961 | C | 5/8" | 1/1/1961 | SF | UNK | C | 5/8" | UNK | <Null> | Installation Record | Y | 1/1/1961 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 1781 | 402 N HINMAN AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 5/13/2021 - Removed 3' lead gooseneck - Ran 3/4" copper from main and connected to existing 3/4" copper | Installation Record | Y | 5/13/2021 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1785 | 404 N HINMAN AVE #A | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | REMOVED LEAD WIPE @ MAIN 4/29/98. Ran 3/4" copper from main connected to existing 3/4" copper (Verified 5/12/2021) | Installation Record | Y | 5/12/2021 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1788 | 1122 E DOEGE ST | N | C | UNK | 3/4" | 1/1/2003 | C | 3/4" | 1/1/2003 | SF | UNK | C | 3/4" | UNK | 2003- MEYER. COPPER REPLACED FROM CORP TO NEW CURB VALVE | Installation Record | Y | 1/1/2003 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1791 | 1115 E DOEGE ST | N | C | UNK | UNK | 1/1/1950 | G | UNK | UNK | SF | UNK | G | UNK | UNK | galvanized on customer side per customer | Installation Record | N | | | Previous eval | Y | 8/28/2006 | Cross connection survey | |
| 1794 | 506 N HINMAN AVE | N | C | UNK | 1" | 9/6/2022 | C | 1" | 9/6/2022 | SF | UNK | C | 1" | UNK | Pg. 5 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs. | Installation Record | Y | 9/6/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1797 | 511 N HINMAN AVE | N | C | UNK | 1" | 9/7/2022 | C | 1" | 9/7/2022 | SF | UNK | C | 1" | UNK | Pg. 6 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs. | Installation Record | Y | 9/7/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1800 | 513 N HINMAN AVE | N | C | UNK | 1" | 9/8/2022 | C | 1" | 9/8/2022 | SF | UNK | C | 1" | UNK | Pg. 7 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs. | Installation Record | Y | 9/8/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1803 | 515 N HINMAN AVE | N | C | UNK | 1" | 9/13/2022 | C | 1" | 9/13/2022 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 9/13/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1806 | 606 N HINMAN AVE | N | C | UNK | 1" | 9/20/2022 | C | 1" | 9/20/2022 | SF | UNK | C | 1" | UNK | Pg. 13 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 9/20/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1809 | 605 N HINMAN AVE | N | C | UNK | 1" | 9/14/2022 | C | 1" | 9/14/2022 | SF | UNK | C | 1" | UNK | Pg. 10 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs. | Installation Record | Y | 9/14/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1812 | 607 N HINMAN AVE | N | C | UNK | 1" | 9/19/2022 | C | 1" | 9/19/2022 | SF | UNK | C | 1" | UNK | Pg. 12 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 9/19/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1815 | 609 N HINMAN AVE | N | C | UNK | 1" | 9/21/2022 | C | 1" | 9/21/2022 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 9/21/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1818 | 703 N HINMAN AVE | N | C | UNK | 1" | 9/26/2022 | C | 1" | 9/26/2022 | SF | UNK | C | 1" | UNK | Pg. 16 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs. | Installation Record | Y | 9/26/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|---|--|--|---|---|--|--|---|---|---|
| 1821 | 707 N HINMAN AVE | N | C | UNK | 1" | 9/26/2022 | C | 1" | 9/26/2022 | SF | UNK | C | 1" | UNK | Pg. 16 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs. | Installation Record | Y | 9/26/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1824 | 711 N HINMAN AVE | N | C | UNK | 1" | 9/22/2022 | C | 1" | 9/22/2022 | SF | UNK | C | 1" | UNK | Pg. 15 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 9/22/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1827 | 724 N HINMAN AVE | N | C | UNK | 1" | 9/20/2022 | C | 1" | 9/20/2022 | SF | UNK | C | 1" | UNK | Pg. 13 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 9/20/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1830 | 718 N HINMAN AVE | N | C | UNK | 1" | 9/20/2022 | C | 1" | 9/20/2022 | SF | UNK | C | 1" | UNK | Pg. 13 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 9/20/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1833 | 708 N HINMAN AVE | N | C | UNK | 1" | 9/28/2022 | C | 1" | 9/28/2022 | SF | UNK | C | 1" | UNK | Pg. 18 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs. | Installation Record | Y | 9/28/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1836 | 706 N HINMAN AVE | N | C | UNK | 1" | 9/13/2022 | C | 1" | 9/13/2022 | SF | UNK | C | 1" | UNK | Pg. 9 of construction report. Installed 1" corp., 2'-1" copper, connected to existing 1" copper at the water main. Main is below sanitary lateral | Installation Record | Y | 9/13/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1839 | 1115 E FILLMORE ST | N | C | UNK | 1" | 9/27/2022 | C | 1" | 9/27/2022 | SF | UNK | C | 1" | UNK | Pg. 17 of construction report. Installed 1" corp., 1" cs & box, and 1" copper. Connected to existing copper after cs. | Installation Record | Y | 9/27/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1842 | 1111 E FILLMORE ST | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1845 | 1109 E FILLMORE ST | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1848 | 705 N PALMETTO AVE | N | C | UNK | 1" | 7/10/2023 | C | 1" | 7/10/2023 | SF | UNK | C | 1" | UNK | 1' of 1" copper from CS to existing 3/4" copper. (pg. 17 of construction report) | Installation Record | Y | 7/10/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1851 | 707 N PALMETTO AVE | N | C | UNK | 1" | 7/10/2023 | C | 1" | 7/10/2023 | SF | UNK | C | 1" | UNK | 1' of 1" copper from CS to existing 3/4" copper. (pg. 17 of construction report) | Installation Record | Y | 7/10/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1854 | 1116 E FILLMORE ST | N | C | UNK | 1" | 9/21/2022 | C | 1" | 9/21/2022 | SF | UNK | C | 1" | UNK | Pg. 14 of construction report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 9/21/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1857 | 1110 E FILLMORE ST | N | C | UNK | 1" | 1/1/2006 | C | 1" | 1/1/2006 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/2006 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1860 | 607 N PALMETTO AVE | N | C | UNK | 1" | 7/5/2023 | C | 1" | 7/5/2023 | SF | UNK | C | 1" | UNK | 1' of 1" copper from CS to existing 3/4" copper. (pg. 14 of construction report) | Installation Record | Y | 7/5/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1863 | 603 N PALMETTO AVE | N | C | UNK | 1" | 6/22/2023 | C | 1" | 6/22/2023 | SF | UNK | C | 1" | UNK | 1' of 1" copper from CS to existing 3/4" copper. (pg. 8 of construction report) | Installation Record | Y | 6/22/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1866 | 1117 E EDISON ST | N | C | UNK | 1" | 9/13/2022 | C | 1" | 9/13/2022 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 9/13/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1869 | 1116 E EDISON ST | N | C | UNK | 1" | 9/7/2022 | UNK-NOLG | 1" | 9/7/2022 | SF | UNK | UNK-NOLG | 1" | UNK | Pg. 6 of construction report. Installed 1" corp., 1" copper, 1" cs & box. Conn. to existing 3/4" copper after cs. WM is below sanitary lateral. | Installation Record | Y | 9/7/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1872 | 1112 E EDISON ST | N | C | UNK | 1" | 7/22/2019 | C | 1" | 7/22/2019 | SF | UNK | C | 1" | UNK | CORP LOCATION IS 12' WEST OF SERVICE TO 11109 E. EDISON. INSTALLED NEW 1" SADDLE , 1" CORP CONNECTED TO EXISTING 3/4" COPPER 4' SOUTH OF CORP | Installation Record | Y | 7/22/2019 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1875 | 513 N PALMETTO AVE | N | C | UNK | 1" | 6/22/2023 | C | 1" | 6/22/2023 | SF | UNK | C | 1" | UNK | 1' of 1" copper from CS to existing 3/4" copper. (pg. 8 of construction report) | Installation Record | Y | 6/22/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1878 | 509 N PALMETTO AVE | N | C | UNK | 1" | 6/22/2023 | C | 1" | 6/22/2023 | SF | UNK | C | 1" | UNK | 1' of 1" copper from CS to existing 3/4" copper. (pg. 8 of construction report) | Installation Record | Y | 6/22/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1881 | 1101 E DOEGE ST | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2011-REMOVED LEAD WIPE AT MAIN | Installation Record | Y | 1/1/2011 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1884 | 1103 E DOEGE ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1887 | 1105 E DOEGE ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1890 | 1109 E DOEGE ST | N | C | UNK | 1" | 1/1/1968 | C | 1" | 1/1/1968 | SF | UNK | C | 1" | UNK | 1-1-2020 J&R VACUUM EXCAVATED AT CB, FOUND 1" COPPER 7'6" DEEP | Installation Record | Y | 1/1/1968 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1893 | 1114 E DOEGE ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1896 | 902 E DOEGE ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1899 | 812 E DOEGE ST | N | C | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CB Verified 3-97 | Installation Record | Y | 3/1/1997 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1902 | 810 E DOEGE ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1905 | 806 E DOEGE ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1908 | 800 E DOEGE ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CB LOCATION VERIFIED 6/3/97 | Installation Record | N | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | | |
| 1911 | 401 N APPLE AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | SERVICE IS OFF OF APPLE | Installation Record | N | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | | |
| 1914 | 806 E CLEVELAND ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1975 | C | 3/4" | 1/1/1975 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1975 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1917 | 905 E CLEVELAND ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1973 | C | 3/4" | 1/1/1973 | SF | UNK | C | 3/4" | UNK | MEYERS. 3/4" copper on property side | Installation Record | Y | 1/1/1973 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1920 | 800 E CLEVELAND ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1972 | C | 3/4" | 1/1/1972 | SF | UNK | C | 3/4" | UNK | REIGEL | Installation Record | Y | 1/1/1972 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1923 | 312 N APPLE AVE | N | UNK | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1926 | 400 N APPLE AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | 1998: MEYERS INSTALLED CURB BOX. | Installation Record | Y | 1/1/1998 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 1929 | 406 N APPLE AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1936 | 518 N APPLE AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1939 | 520 N APPLE AVE | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | Previous eval | Y | 2013-2018 | Cross Connection Survey | | |
| 1962 | 201 S MAPLE AVE | N | C | UNK | 1" | 1/1/2015 | C | 1" | 1/1/2015 | NONRES | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1967 | 211 S MAPLE AVE | N | DI | UNK | 6" | 10/15/2019 | DI | 6" | 10/15/2019 | O | UNK | DI | 6" | UNK | REIGEL PLBG/DOINE | Installation Record | Y | 10/15/2019 | Mech excav | Diameter > 2" | Y | 2021-2025 | Visual Insp during install or repair | |
| 1975 | 305 S MAPLE AVE | N | C | Y | 1" | 1/1/2015 | C | 1" | 1/1/2015 | SF | UNK | C | 1" | UNK | 4/20/21 - Meyers removed remaining lead on customers side & installed 3/4" copper. 1" x 3/4" reducer on backside of walk. | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1978 | 307 S MAPLE AVE | N | C | UNK | 1" | 1/1/2015 | C | 1" | 1/1/2015 | SF | UNK | C | 1" | UNK | CONNECTED TO 1/2" COPPER ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1981 | 309 S MAPLE AVE | N | C | UNK | 1" | 1/1/2015 | C | 1" | 1/1/2015 | SF | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1985 | 200 E 4TH ST | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | NONRES | UNK | C | C | | 3/4" copper on customer side | Installation Record | N | | Field Inspection Only | Y | 7/5/2013 | Cross Connection Survey | | |
| 1991 | 411 S MAPLE AVE | N | C | Y | 1" | 1/1/2015 | C | 1" | 1/1/2015 | SF | UNK | C | 1" | UNK | CONNECTED TO LEAD ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1994 | 413 S MAPLE AVE | N | C | UNK | 1" | 1/1/2015 | C | 1" | 1/1/2015 | SF | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 1998 | 503 S MAPLE AVE | N | C | UNK | 1" | 1/1/2015 | P | 1" | 1/1/2015 | SF | UNK | P | 1" | UNK | CONNECTED TO 1" PLASTIC ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2002 | 509 S MAPLE AVE | N | C | UNK | 1" | 1/1/2015 | C | 1" | 1/1/2015 | SF | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER ON PROP SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2006 | 511 S MAPLE AVE | N | C | UNK | 1" | 1/1/2015 | C | 1" | 1/1/2015 | SF | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2011 | 809 S MAPLE AVE | N | L | UNK | 5/8" | 1/1/1925 | C | 5/8" | 1/1/1925 | SF | UNK | C | UNK | 1/1/1925 | 2005-LEAD WIPE REMOVED AT BOX. | SL repair/replace record | Y | 2005 | Mech excav | Field inspection only | Y | 5/4/2017 | Cross Connection Survey | |
| 2017 | 204 E 9TH ST | N | C | Y | 3/4" | 10/12/2018 | C | 3/4" | 10/12/2018 | SF | UNK | C | 3/4" | UNK | REMOVED LEAD & REPLACED WITH 3/4" (TYPE K) COPPER TO CS - MEYERS INSTALLED 3/4" COPPER TO HOUSE | Installation Record | Y | 10/12/2018 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2020 | 909 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | Field Inspection Only | Y | 6/1/2017 | Cross Connection Survey | | |
| 2023 | 207 E 10TH ST | N | UNK-LG | UNK | UNK | 1/1/1930 | C | UNK | 1/1/1930 | SF | UNK | C | C | | 3/4" COPPER LOCKING VALVE | Installation Record | N | | Field Inspection Only | Y | 10/27/2015 | Cross Connection Survey | | |
| 2026 | 206 E 10TH ST | N | UNK-LG | UNK | UNK | 1/1/1930 | C | UNK | 1/1/1930 | SF | UNK | C | C | | CB LOCATION VERIFIED 6/12/97 | Installation Record | N | | Field Inspection Only | Y | 8/22/2014 | Cross Connection Survey | | |
| 2029 | 200 E 10TH ST | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | O | UNK | C | C | | NEW CURB VALVE INSTALLED BY MEYERS. REMOVED LEAD WIPES BOTH SIDES OF VALVE. | Installation Record | N | | Field Inspection Only | Y | 5/19/2017 | Cross Connection Survey | | |
| 2032 | 1107 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | Field Inspection Only | Y | 10/9/2014 | Cross Connection Survey | | |
| 2035 | 1109 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | Field Inspection Only | Y | 3/9/2017 | Cross Connection Survey | | |
| 2038 | 1111 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1945 | C | UNK | 1/1/1945 | SF | UNK | C | C | | <Null> | | | | | | | | | |

| Site ID | Locational Identifier | Lead GooseNeck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 2046 | 1701 S Central Ave | N | C | UNK | 1-1/2" | 1/1/2009 | C | 1-1/2" | 1/1/2009 | NONRES | UNK | L | UNK | 1/1/2009 | ATTACHED TO EXISTING 1-1/2" COPPER. A-1 EXCAVATING | SL repair/replace record | Y | 1/1/2009 | Visual insp during install or repair | Previous eval | Y | 5/4/2017 | Cross connection survey | |
| 2049 | 2011 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | 1/1/2009 | NONRES | UNK | C | 1" | UNK | ATTACHED TO 1" COPPER @ CURB VALVE. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2052 | 1806 S Central Ave | N | C | UNK | 2" | 1/1/2009 | C | 2" | 1/1/2009 | NONRES | UNK | C | 2" | UNK | BORED-CONNECTED TO 2" COPPER. A-1 EXCAVATING | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2055 | 1702 S Central Ave | N | C | UNK | 1" | 1/1/2009 | C | 1" | 1/1/2009 | NONRES | UNK | C | 1" | UNK | BORED, A-1 EXCAVATING. ATTACHED TO 3/4" COPPER | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2058 | 1610 S Central Ave | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | NONRES | UNK | C | 3/4" | UNK | 1998-NEW CURB STOP & BOX AND LOWERED UNDER STORM SEWER | Installation Record | Y | 1/1/1998 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2061 | 1604 S Roddis Ave | N | C | UNK | 1" | UNK | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | 2009-INSTALLED NEW COPPER FROM MAIN TO CURB STOP W/ BOX. | Installation Record | Y | 1/1/2009 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2064 | 1600 S Roddis Ave | N | C | Y | 1" | UNK | C | 1" | UNK | NONRES | UNK | C | 1" | UNK | 2009- REMOVED LEAD WIPE @ MAIN AND INSTALLED 12' OF 1" COPPER UNDER STORM SEWER TO MAIN. 3/4" copper on property side | Installation Record | Y | 1/1/2009 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2067 | 1202 S Maple Ave | N | UNK-LG | UNK | UNK | UNK | G | UNK | UNK | SF | UNK | G | UNK | UNK | 2013- NEW 3/4" TAP AND REMOVED LEAD WIPE AT MAIN | Installation record | Y | 1/1/2013 | Visual insp during install or repair | Previous eval | Y | 6/8/2017 | Cross connection survey | |
| 2070 | 1112 S Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | LOCKING VALVE | Installation Record | N | | | Field Inspection Only | Y | 5/9/2017 | Cross Connection Survey | |
| 2073 | 1110 S Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/4/2017 | Cross Connection Survey | |
| 2076 | 1104 S Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/15/2017 | Cross Connection Survey | |
| 2079 | 1102 S Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 10/16/2014 | Cross Connection Survey | |
| 2081 | 112 E 11TH ST | N | C | UNK | 1" | 1/1/2000 | C | 1" | 1/1/2000 | NONRES | UNK | C | 1" | UNK | TAPPED OFF MAPLE | Installation Record | Y | 1/1/2000 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2084 | 109 E 11TH ST | N | C | UNK | 3/4" | 8/1/2019 | C | 3/4" | 8/1/2019 | SF | UNK | C | 3/4" | UNK | CB/LV UNKNOWN - REMOVED 2" GALVANIZED MAIN, REPLACED W/ 2" POLY, MEYERS PULLED 3/4" CU FROM HOUSE TO NEW MAIN, INSTALLED NEW CB | Installation Record | Y | 8/1/2019 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2087 | 912 S Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/8/2017 | Cross Connection Survey | |
| 2090 | 908 S Maple Ave | N | C | Y | 3/4" | 10/15/2020 | C | 3/4" | 10/15/2020 | SF | UNK | C | 3/4" | UNK | 10/15/2020 - Removed lead and replaced with copper on both sides (meyers) | Installation Record | Y | 10/15/2020 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2093 | 904 S Maple Ave | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/12/2017 | Cross Connection Survey | |
| 2096 | 804 S Maple Ave | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2105 | 504 S Maple Ave | N | C | UNK | 1" | 1/1/2017 | C | 3/4" | 4/24/2023 | SF | UNK | C | UNK | 4/24/2023 | 2017-REPLACED LEAD SERVICE FROM CORP TO CURB VALVE WITH 3/4" COPPER. 4/24/23: Gaffney replaced galvanized w/ 3/4" copper cs-meter. Installed new 3/4" cs & box. | SL repair/replace record | Y | 1/1/2017 | Visual insp during install or repair | Previous eval | Y | 1/1/2017 | Visual Insp during install or repair | |
| 2108 | 118 E 3RD ST | N | C | UNK | 1" | 1/1/2015 | C | 1" | 1/1/2015 | O | UNK | C | 1" | UNK | 1" COPPER ON PROP. SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2111 | 116 E 3RD ST | N | C | UNK | 2" | 1/1/2015 | P | 2" | 1/1/2015 | NONRES | UNK | P | 2" | UNK | 2" PLASTIC ON PROP SIDE | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2115 | 210 E 2ND ST | N | C | UNK | 1" | 1/1/2010 | C | 1" | 1/1/2010 | SF | UNK | C | 1" | UNK | CONNECTED TO 3/4" COPPER | Installation Record | Y | 1/1/2010 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2118 | 200 S Cedar Ave | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 1" Copper on property side. 8/24/2022: Removed lead wipe @ main. Servic is 100% copper. lead free 3/4" copper | Installation Record | Y | 8/24/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2122 | 208 S Cedar Ave | N | C | Y | 1" | 8/24/2022 | C | 1" | 8/24/2022 | SF | UNK | C | 1" | UNK | 8/24/22: Removed lead and installed new 1" copper, used existing corp. New 1" curb valve & box. 3/4" copper on customers side. | Installation Record | Y | 8/24/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2125 | 210 S Cedar Ave | N | C | Y | 1" | 8/25/2022 | C | 1" | 8/25/2022 | SF | UNK | C | 1" | UNK | 8/25/22: Removed lead & installed new 1" Copper used existing corp. w/ tapping saddle. New 1" curb valve & box. Hooked to 3/4" copper on customers side | Installation Record | Y | 8/25/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2128 | 212 S Cedar Ave | N | C | Y | 1" | 8/25/2022 | C | 1" | 8/25/2022 | SF | UNK | C | 1" | UNK | 8/25/22: Removed lead and installed new 1" copper, used existing corp. New 1" box and curb valve. Hooked to 3/4" copper on customers side. | Installation Record | Y | 8/25/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2131 | 306 S Cedar Ave | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 9/22: Removed lead wipe @ main. Hooked to 3/4" copper | Installation Record | Y | 9/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2134 | 312 S Cedar Ave | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 9/6/22: Removed lead wipe @ main, service is 100% copper, 3/4" copper inside. | Installation Record | Y | 9/6/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2137 | 210 E 4TH ST | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | REMOVED LEAD WIPE 1-2000. | Installation Record | Y | 1/1/2000 | Mech excav | Field Inspection Only | Y | 4/27/2017 | Cross Connection Survey | |
| 2140 | 212 E 4TH ST | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2000: REMOVED LEAD GOOSE - NECK - 3/4" COPPER. 2022: Verified 3/4" copper. No lead service | Installation Record | Y | 1/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2143 | 404 S Cedar Ave | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2022: Removed lead wipes. Service is 100% copper | Installation Record | Y | 1/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2146 | 408 S Cedar Ave | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2003-INSTALLED NEW CURB VALVE W/ BOX. 1990- REMOVED LEAD WIPE IN STREET. 2022: Removed Lead wipe - no lead on service, 100% copper | Installation Record | Y | 1/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2153 | 212 E 5TH ST | N | C | UNK | 3/4" | 1/1/2019 | C | 3/4" | 1/1/2019 | SF | UNK | C | 3/4" | UNK | JAKEL PLBG. - CLAY TILE SANITARY LATERAL IS ABOVE THE WATER MAIN | Installation Record | Y | 1/1/2019 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2158 | 804 S Cedar Ave | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 1/2" COPPER LOCKING VALVE. 2022: Removed lead wipe, fixed leak | Installation Record | Y | 1/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2161 | 806 S Cedar Ave | N | C | UNK | 1" | 9/26/2022 | C | 1" | 9/26/2022 | SF | UNK | C | 1" | UNK | 2022: 1" copper frommain to curb valve, used existing corp, new 1" cs & box. 3/4" copper on house side | Installation Record | Y | 9/26/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2164 | 213 E 9TH ST | N | C | Y | 3/4" | 9/14/2020 | C | 3/4" | 9/14/2020 | SF | UNK | C | 3/4" | UNK | 2017-CURB STOP W/ BOX INSTALLED BY BACH EXCAVATING. 9-14-2020 - Removed lead from Corp. to CS & replaced w/ 3/4" copper. connected to existing CS. 3/10/21 - Meyers removed lead & replaced w/ 3/4" copper on property side (cs - meter) | Installation Record | Y | 9/14/2020 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2167 | 902 S Cedar Ave | N | C | Y | 1" | 9/28/2022 | C | 1" | 9/28/2022 | SF | UNK | C | 1" | UNK | 2022: removed lead wipes, new 1" copper from main to cs. Used existing corp. Hooked to 3/4" copper on house side | Installation Record | Y | 9/28/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2170 | 904 S Cedar Ave | N | C | Y | 3/4" | 9/28/2022 | C | 3/4" | 9/28/2022 | SF | UNK | C | 3/4" | UNK | CALS PLBG INSTALLED CURB VALVE/BOX. 2022: Removed lead wipe 2022 lead free service | Installation Record | Y | 9/28/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2174 | 910 S Cedar Ave | N | C | UNK | 1" | 1/1/2022 | C | 1" | 1/1/2022 | SF | UNK | C | 1" | UNK | 2022: New 1" copper from main to cs. New 1" cs & box. New 1" corp w/ Mainbreak 6" sleeve with 1" C.C. Hooked to 3/4" copper on owners side. | Installation Record | Y | 1/1/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2178 | 1008 S Cedar Ave | N | CI-U | UNK | 6" | UNK | G | 2" | UNK | NONRES | UNK | G | UNK | UNK | 10/31/22: Dug @ the wm , found a 6"x6" tee. Dug behind the curb and found a 6" service valve 2' West of the Curb. Cast iron both sides of the service valve. Verified 2" galvanized inside. | SL repair/replace record | Y | 10/31/2022 | Visual insp during install or repair | Previous eval | Y | 10/31/2022 | Visual insp at meter | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|---|--|--|---|---|--|--|---|---|---|
| 2182 | 1102 S CEDAR AVE | N | C | Y | 1" | 10/21/2022 | C | 1" | 10/21/2022 | SF | UNK | C | 1" | UNK | 2022: Verified no lead in service, existing 1" copper from main. Appears to may have been replaced with sewer lateral in the past | Installation Record | Y | 10/21/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2185 | 1106 S CEDAR AVE | N | C | UNK | 1" | 10/1/2022 | C | 1" | 10/1/2022 | SF | UNK | C | 1" | UNK | 2022: New 1" copper form main to curb valve. Reused curb valve (3/4"), and found 3/4" copper inside. Installed new box and used the existing corp. | Installation Record | Y | 10/1/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2188 | 1108 S CEDAR AVE | N | C | Y | 1" | 10/13/2022 | C | 1" | 10/13/2022 | SF | UNK | C | 1" | UNK | 10/13/22: Removed lead & replaced w/ 1" copper from wm-cs. Installed new 1" tap with sleeve and reused existing 3/4" cs but replaced the box. Verified 3/4" copper on customers side. | Installation Record | Y | 10/13/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2191 | 215 E 14TH ST | N | C | UNK | 1" | 7/30/2024 | C | 3/4" | 1/1/1946 | SF | UNK | C | C | | Earth Inc. 13' of 1" copper from cs to existing 3/4" copper. See sheet 26 of the construction report. | SL repair/replace record | Y | 7/30/2024 | Mech excav | Field Inspection Only | Y | 7/30/2024 | Visual Insp during install or repair | |
| 2194 | 211 E 14TH ST | N | C | UNK | 1" | 7/19/2024 | C | 1" | 7/19/2024 | SF | UNK | C | 1" | UNK | Earth Inc. 9' - 1" copper from cs to existing 3/4" copper. See sheet 22 of the construction report. | Installation Record | Y | 7/19/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2197 | 1411 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1924 | C | UNK | 1/1/1924 | SF | UNK | C | C | | REMOVE WIPES 1989 COPPER INSIDE | Installation Record | N | | | Field Inspection Only | Y | 5/24/2017 | Cross Connection Survey | |
| 2200 | 1501 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1922 | C | UNK | 1/1/1922 | SF | UNK | C | C | | REMOVED WIPES AT MAIN & BOX 1989 | Installation Record | N | | | Field Inspection Only | Y | 10/6/2014 | Cross Connection Survey | |
| 2203 | 1505 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1922 | C | UNK | 1/1/1922 | SF | UNK | C | C | | REMOVED WIPE AT CURB STOP 1989 | Installation Record | N | | | Field Inspection Only | Y | 5/2/2017 | Cross Connection Survey | |
| 2207 | 1509 S MAPLE AVE | N | C | UNK | 3/4" | 1/1/1989 | C | 3/4" | 1/1/1989 | SF | UNK | C | 3/4" | UNK | NEW LINE FROM MAIN | Installation Record | Y | 1/1/1989 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2210 | 1511 S MAPLE AVE | N | C | UNK | 3/4" | 1/1/1989 | C | 3/4" | 1/1/1989 | SF | UNK | C | 3/4" | UNK | COPPER & IRON INSIDE | Installation Record | Y | 1/1/1989 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2213 | 1607 S MAPLE AVE | N | C | Y | 1" | 9/23/2024 | C | 1" | 9/23/2024 | SF | UNK | C | 1" | UNK | 12/20/2022: Existing cs was leaking on curstomer side. Gaffney removed & replaced w/ 1" cs & box & connected to exist. 1/2" copper. MU removed lead and replaced w/ 1" copper from wm - cs. Insulated at wm and cs. 9/24: MU installed 1" corp w/ saddle, 1" cu | Installation Record | Y | 9/23/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2216 | 207 E 17TH ST | N | C | UNK | 1" | 8/8/2022 | C | 1" | 8/8/2022 | SF | UNK | C | 1" | UNK | Pg. 28 of the construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 12.5' after cs. | Installation Record | Y | 8/8/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2219 | 209 E 17TH ST | N | C | UNK | 1" | 8/8/2022 | C | 1" | 8/8/2022 | SF | UNK | C | 1" | UNK | Pg. 28 of the construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 10' after cs. | Installation Record | Y | 8/8/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2222 | 208 E 17TH ST | N | C | UNK | 1" | 8/9/2022 | C | 1" | 8/9/2022 | SF | UNK | C | 1" | UNK | Pg. 29 of the construction report. Earth Inc. installed 1" corp., 1" copper, 1" cs & box. Connected to existing 3/4" copper 9.5' after cs. | Installation Record | Y | 8/9/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2225 | 1705 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1933 | C | UNK | 1/1/1933 | SF | UNK | C | C | | Y CONNECTED WITH 1707. 3/4" COPPER LOCKING VALVE | Installation Record | N | | | Field Inspection Only | Y | 4/24/2017 | Cross Connection Survey | |
| 2228 | 1803 S MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | LOWERED ACROSS ROAD | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2231 | 1809 S MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | LOWERED IN STREET, REMOVED WIPES INSULATED AT MAIN 1989 | Installation Record | Y | 1/1/1989 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2234 | 1909 S MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | REMOVED WIPE, LOWERED & INSULATED 1989 | Installation Record | Y | 1/1/1989 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2237 | 1911 S MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | REMOVED WIPE, LOWERED & INSULATED 1989 | Installation Record | Y | 1/1/1989 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2240 | 2001 S MAPLE AVE | UNK | UNK-LG | UNK | 5/8" | 1/1/1960 | C | 5/8" | 1/1/1960 | SF | UNK | C | 5/8" | UNK | 1988 | Installation Record | Y | 1/1/1960 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2243 | 1904 S MAPLE AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | REMOVED WIPE, INSULATED 1989 | Installation Record | Y | 1/1/1989 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2248 | 1814 S MAPLE AVE | N | C | UNK | UNK | 1/1/1989 | C | UNK | 1/1/1989 | SF | UNK | C | UNK | UNK | REMOVED WIPE ALL COPPER 1989 | Installation Record | Y | 1/1/1989 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2250 | 116 E 17TH ST | N | C | UNK | 3/4" | 1/1/1990 | C | 3/4" | 1/1/1990 | SF | UNK | C | 3/4" | UNK | REIGEL | Installation Record | Y | 1/1/1990 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2253 | 112 E 17TH ST | N | C | UNK | 3/4" | 1/1/1990 | C | 3/4" | 1/1/1990 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1990 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2256 | 111 E 17TH ST | N | C | UNK | UNK | 1/1/1990 | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | Y | 1/1/1990 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2259 | 113 E 17TH ST | N | C | UNK | UNK | 1/1/1990 | C | UNK | 1/1/1990 | SF | UNK | C | UNK | UNK | <Null> | Installation Record | Y | 1/1/1990 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2262 | 115 E 17TH ST | N | C | UNK | 3/4" | 1/1/1990 | C | 3/4" | 1/1/1990 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1990 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2266 | 1414 S MAPLE AVE | N | C | UNK | 2" | 4/1/2014 | C | 2" | 4/1/2014 | SF | UNK | C | 2" | UNK | Removed wipes @ main & CS - copper inside (Removed flair fitting customer side of vavle 04/01/2014) | Installation Record | Y | 4/1/2014 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2269 | 208 E 14TH ST | N | C | UNK | 1" | 7/30/2024 | C | 3/4" | 1/1/1925 | SF | UNK | C | C | | Earth Inc. 13.5' of 1" copper from cs to existing 3/4" copper | SL repair/replace record | Y | 7/30/2024 | Mech excav | Field Inspection Only | Y | 7/30/2024 | Visual Insp during install or repair | |
| 2272 | 210 E 14TH ST | N | C | UNK | 1" | 7/30/2024 | C | 1" | 7/30/2024 | SF | UNK | C | 1" | UNK | Earth Inc. 12.5' of 1" copper from cs to existing 3/4" copper | Installation Record | Y | 7/30/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2275 | 214 E 14TH ST | N | C | UNK | 1" | 7/30/2024 | C | 3/4" | 1/1/1926 | SF | UNK | C | C | | Earth Inc. 12.5' of 1" copper from cs to existing 3/4" copper. | SL repair/replace record | Y | 7/30/2024 | Mech excav | Field Inspection Only | Y | 7/30/2024 | Visual Insp during install or repair | |
| 2278 | 300 E 14TH ST | N | C | Y | 1" | 7/22/2024 | C | 3/4" | 1/1/1932 | SF | UNK | C | C | | Earth Inc. 11' of 1" copper from cs to existing 3/4" copper. See sheet 23 of the construction report. | SL repair/replace record | Y | 7/22/2024 | Mech excav | Field Inspection Only | Y | 7/22/2024 | Visual Insp during install or repair | |
| 2281 | 302 E 14TH ST | N | C | UNK | 1" | 7/23/2024 | C | 1" | 7/23/2024 | SF | UNK | C | 1" | UNK | Earth Inc. 12' of 1" copper from cs to existing 3/4" copper. See sheet 24 of the construction report. | Installation Record | Y | 7/23/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2284 | 1408 S CEDAR AVE | N | UNK-LG | UNK | UNK | 1/1/1932 | C | UNK | 1/1/1932 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/26/2017 | Cross Connection Survey | |
| 2287 | 1504 S CEDAR AVE | N | C | Y | 3/4" | 6/13/2023 | C | 3/4" | 6/13/2023 | SF | UNK | C | 3/4" | UNK | 6/13/23: Replaced lead w/ 3/4" copper from wm-cs. Meyers replaced lead with 3/4" copper from cs-meter and also installed a new 3/4" cs & box. | Installation Record | Y | 6/13/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2290 | 1506 S CEDAR AVE | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 4/17/2017 | Cross Connection Survey | |
| 2293 | 1508 S CEDAR AVE | N | UNK-LG | UNK | UNK | 1/1/1940 | C | UNK | 1/1/1940 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 4/28/2017 | Cross Connection Survey | |
| 2296 | 1514 S CEDAR AVE | N | C | UNK | 1" | 7/26/2022 | C | 1" | 7/26/2022 | SF | UNK | C | 1" | UNK | 7/26/22: All new copper & curb valve. 1" copper on Utility side, 3/4" copper on customer side. | Installation Record | Y | 7/26/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2299 | 1606 S CEDAR AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | <Null> | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2302 | 1610 S CEDAR AVE | N | UNK-LG | UNK | UNK | 1/1/1938 | C | UNK | 1/1/1938 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 4/24/2017 | Cross Connection Survey | |
| 2305 | 1612 S CEDAR AVE | N | UNK-LG | UNK | UNK | 1/1/1946 | C | UNK | 1/1/1946 | SF | UNK | C | C | | 3/4" COPPER LOCKING VALVE | Installation Record | N | | | Field Inspection Only | Y | 4/21/2017 | Cross Connection Survey | |
| 2308 | 1614 S CEDAR AVE | N | UNK-LG | UNK | UNK | 1/1/1947 | C | UNK | 1/1/1947 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/3/2017 | Cross Connection Survey | |
| 2311 | 1616 S CEDAR AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CB/LV UNKNOWN | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2314 | 1706 S CEDAR AVE | N | C | UNK | 3/4" | 1/1/1967 | C | 3/4" | 1/1/1967 | SF | UNK | C | 3/4" | UNK | MFLD PLB. 7-1-2022: 3/4" Copper main to cs. - 3/4" copper on customer side. New box & rod installed | Installation Record | Y | 1/1/1967 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2317 | 1800 S CEDAR AVE | N | C | UNK | 1" | 1/1/1966 | C | 1" | 1/1/1966 | SF | UNK | C | 1" | UNK | 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 6'6" DEEP | Installation Record | Y | 1/1/1966 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2320 | 1804 S CEDAR AVE | UNK | UNK-LG | UNK | 3/4" | 1/1/1963 | C | 3/4" | 1/1/1963 | SF | UNK | C | 3/4" | UNK | SCHRIENERS | Installation Record | Y | 1/1/1963 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2323 | 1808 S CEDAR AVE | UNK | UNK-LG | UNK | 3/4" | 1/1/1966 | C | 3/4" | 1/1/1966 | SF | UNK | C | 3/4" | UNK | MFLD PLB. 3/4" copper on property side | Installation Record | Y | 1/1/1966 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2326 | 1812 S CEDAR AVE | N | UNK-NOLG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 3/4" copper on property side | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2329 | 1900 S CEDAR AVE | UNK | UNK-LG | UNK | 3/4" | 1/1/1966 | C | 3/4" | 1/1/1966 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1966 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2332 | 1906 S CEDAR AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1972 | C | 3/4" | 1/1/1972 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1972 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2335 | 2000 S CEDAR AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1974 | C | 3/4" | 1/1/1974 | SF | UNK | C | 3/4" | UNK | REIGEL | Installation Record | Y | 1/1/1974 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2338 | 2004 S CEDAR AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1971 | C | 3/4" | 1/1/1971 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1971 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2341 | 401 E 20TH ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1977 | C | 3/4" | 1/1/1977 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2346 | 1801 S CEDAR AVE | UNK | UNK-LG | UNK | 3/4" | 1/1/1963 | UNK-LG | 3/4" | 1/1/1963 | SF | UNK | UNK-LG | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1963 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 2349 | 1707 S CEDAR AVE | UNK | UNK-LG | UNK | 3/4" | 1/1/1964 | C | 3/4" | 1/1/1964 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1964 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2352 | 1701 S CEDAR AVE | UNK | UNK-LG | UNK | 3/4" | 1/1/1964 | C | 3/4" | 1/1/1964 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1964 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2355 | 1621 S CEDAR AVE | N | C | Y | 1" | 7/25/2022 | C | 1" | UNK | SF | UNK | C | 1" | UNK | Pg. 21 of construction reports. Removed lead gooseneck and replaced with 1" corp, 1" copper and connected to existing 3/4" copper @ main. | Installation Record | Y | 7/25/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2358 | 1601 S CEDAR AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2361 | 1505 S CEDAR AVE | N | UNK-NOLG | UNK | 3/4" | 1/1/1973 | C | 3/4" | 1/1/1973 | SF | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1973 | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2364 | 308 E 15TH ST | N | UNK-LG | UNK | UNK | 1/1/1925 | C | UNK | 1/1/1925 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/9/2017 | Cross Connection Survey | |
| 2367 | 310 E 15TH ST | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 2020 J&R VACUUM EXCAVATED @ EOP, FOUND COPPER 7'9" DEEP | Installation Record | Y | 1/1/2020 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2370 | 314 E 15TH ST | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2373 | 1501 S CEDAR AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CB/LV UNKNOWN | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2376 | 1406 S PROSPECT AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2379 | 1411 S PROSPECT AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | 8-2022: removed 5' lead wipe from main to sewer, 3/4" copper was found | Installation Record | Y | 8/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2382 | 1409 S PROSPECT AVE | N | UNK-LG | UNK | UNK | 1/1/1946 | C | UNK | 1/1/1946 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 5/10/2017 | Cross Connection Survey | |
| 2385 | 1405 S PROSPECT AVE | N | UNK-LG | UNK | UNK | UNK | L | UNK | UNK | SF | UNK | L | UNK | UNK | | Installation record | N | | | Previous eval | Y | 7/26/2017 | Cross connection survey | |
| 2388 | 310 E 14TH ST | N | C | UNK | 1" | 7/23/2024 | C | 3/4" | 1/1/1926 | SF | UNK | C | C | | Earth Inc. 13' of 1" copper from cs to existing 3/4" copper. See sheet 24 of the construction report. | SL repair/replace record | Y | 7/23/2024 | Mech excav | Field Inspection Only | Y | 7/23/2024 | Visual Insp during install or repair | |
| 2391 | 314 E 14TH ST | N | C | UNK | 1" | 7/23/2024 | C | 1" | 7/23/2024 | SF | UNK | C | 1" | UNK | Earth Inc. 10' of 1" copper from cs to existing 3/4" copper. See sheet 24 of the construction report. | Installation Record | Y | 7/23/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2394 | 318 E 14TH ST | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | 3/4" COPPER LOCKING VALVE | Installation Record | N | | | Field Inspection Only | Y | 5/3/2017 | Cross Connection Survey | |
| 2397 | 1404 S CHERRY AVE | N | UNK-LG | UNK | UNK | 1/1/1930 | C | UNK | 1/1/1930 | SF | UNK | C | C | | <Null> | Installation Record | N | | | Field Inspection Only | Y | 4/21/2017 | Cross Connection Survey | |
| 2400 | 1412 S CHERRY AVE | N | C | Y | 3/4" | 7/3/2024 | C | 3/4" | 1/1/1935 | SF | UNK | C | C | | 7/3/2024: Removed lead from wm-cs and replaced w/ 3/4" copper. Connected to existing 3/4" copper after cs. | SL repair/replace record | Y | 7/3/2024 | Visual insp during install or repair | Field Inspection Only | Y | 7/3/2024 | Visual Insp during install or repair | |
| 2403 | 1500 S CHERRY AVE | UNK | UNK-LG | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2406 | 1504 S CHERRY AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2408 | 1505 S CHERRY AVE | N | UNK-LG | UNK | UNK | 1/1/1926 | C | UNK | 1/1/1926 | SF | UNK | C | C | | MEYERS 09/13/97 - REMOVED LEAD WIPE @ CURB VALVE, INSTALLED NEW CURB VAVEL | Installation Record | Y | 9/13/1997 | Mech excav | Field Inspection Only | Y | 6/1/2017 | Cross Connection Survey | |
| 2411 | 1415 S CHERRY AVE | N | C | UNK | 3/4" | 1/1/1926 | C | 3/4" | 1/1/1926 | SF | UNK | C | C | | 7/3/2024: Dug and removed lead goosneck @ main. Connected to 3/4" copper. | Installation Record | Y | 7/3/2024 | Mech excav | Field Inspection Only | Y | 7/3/2024 | Mech excav | |
| 2414 | 1409 S CHERRY AVE | N | C | UNK | 1" | 1/1/1968 | C | 1" | 1/1/1968 | SF | UNK | C | 1" | UNK | MFLD PLB. 1-1-2020 J&R VACUUM EXCAVATED AT CB, FOUND 1" COPPER 6'1" DEEP | Installation Record | Y | 1/1/1968 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2417 | 404 E 14TH ST | N | C | UNK | 1" | 7/31/2024 | P | 1" | 1/1/1926 | SF | UNK | C | C | | Earth Inc. 11' of 1" copper from cs to existing1" plastic. See sheet 27 of the construction report. | SL repair/replace record | Y | 7/31/2024 | Mech excav | Field Inspection Only | Y | 7/31/2024 | Visual Insp during install or repair | |
| 2420 | 406 E 14TH ST | N | C | Y | 1" | 8/2/2024 | C | 3/4" | 1/1/1931 | SF | UNK | C | C | | Earth Inc. 13.5' of 1" copper from cs to existing 3/4" copper. See sheet 28 of the construction report. | SL repair/replace record | Y | 8/2/2024 | Mech excav | Field Inspection Only | Y | 8/2/2024 | Visual Insp during install or repair | |
| 2423 | 408 E 14TH ST | N | C | UNK | 1" | 8/2/2024 | C | 1" | 8/2/2024 | SF | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 8/2/2024 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2426 | 207 N PALMETTO AVE | N | C | UNK | 3/4" | 1/1/1977 | C | 3/4" | 1/1/1977 | SF | UNK | C | 3/4" | UNK | STRATFORD, *2018 - SERVICE TAPPED AFTER HYDRANT TEE, 3/4" TAP, 3' - 3/4" COPPER WITH 3/4" COUPLING | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2429 | 308 E 20TH ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1977 | C | 3/4" | 1/1/1977 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2438 | 711 N GALVIN AVE | N | C | UNK | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | SANITARY GOES TO INTERSECTION OF BECKER & GALVIN | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2479 | 1817 E MCMILLAN ST | N | C | UNK | 3/4" | 1/1/1986 | C | 3/4" | 1/1/1986 | O | UNK | C | 3/4" | UNK | <Null> | Installation Record | Y | 1/1/1986 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2483 | 1801 E MCMILLAN ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | O | UNK | C | UNK | UNK | CB VERIFIED 12-97 | Installation Record | Y | 12/1/1997 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2639 | 919 W MCMILLAN ST | N | C | UNK | 1" | 1/1/1994 | C | 1" | 1/1/1994 | O | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/1994 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2646 | 1003 W MCMILLAN ST | N | C | UNK | 1" | 1/1/1994 | C | 1" | 1/1/1994 | O | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/1994 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2649 | 1011 W MCMILLAN ST | N | C | UNK | 1" | 1/1/1994 | C | 1" | 1/1/1994 | O | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/1994 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2658 | 1101 W MCMILLAN ST | N | C | UNK | UNK | UNK | C | UNK | UNK | O | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2715 | 1406 S CENTRAL AVE | N | L | UNK | 5/8" | 1/1/1963 | C | 5/8" | 1/1/1963 | NONRES | UNK | C | UNK | 1/1/1963 | LEAD ON BOTH SIDES OF NEW CURB BOX, FROM HOUSE TO CURB-2016 MEYERS | SL repair/replace record | Y | 2016 | Mech excav | Field inspection only | Y | 7/24/2014 | Cross Connection Survey | |
| 2718 | 1100 N WALNUT AVE | N | C | UNK | 3/4" | 1/1/1973 | C | 3/4" | 1/1/1973 | SF | UNK | C | 3/4" | UNK | 2004-NEW 3/4" CORP | Installation Record | Y | 1/1/1973 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2721 | 312 E 20TH ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1977 | C | 3/4" | 1/1/1977 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2729 | 110 W HARRISON ST | N | C | UNK | 3/4" | 1/1/2007 | C | 3/4" | 1/1/2007 | SF | UNK | C | 3/4" | UNK | 2007-INSTALLED 3/4" COPPER FROM CORP TO TERRACE | Installation Record | Y | 1/1/2007 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2733 | 141 S CENTRAL AVE | N | C | UNK | 3/4" | 1/1/2001 | L | 3/4" | 1/1/2001 | NONRES | UNK | L | UNK | 1/1/2001 | 2009-REPAIRED AND REPLACED 4-1/2' OF 3/4" COPPER INCLUDING CURB VALVE. | SL repair/replace record | Y | 1/1/2001 | Visual insp during install or repair | Previous eval | Y | 9/17/2013 | Visual insp at meter | |
| 2736 | 407 E 20TH ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1977 | C | 3/4" | 1/1/1977 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1977 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2740 | 710 E DEPOT ST | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | NONRES | UNK | C | UNK | UNK | 3/4" copper on property side | Installation Record | N | | | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2750 | 108 W 2ND ST | N | C | UNK | 1" | 1/1/2013 | C | 1" | 1/1/2013 | NONRES | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/2013 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2752 | 148 S CENTRAL AVE | N | C | UNK | 3/4" | 1/1/2001 | L | 3/4" | 1/1/2001 | NONRES | UNK | L | UNK | 1/1/2001 | MEWD | SL repair/replace record | Y | 1/1/2001 | Visual insp during install or repair | Previous eval | Y | 12/2/2021 | Cross connection survey | |
| 2755 | 201 N ASH AVE | N | L | Y | UNK | UNK | L | UNK | UNK | SF | UNK | L | UNK | UNK | 2009-REMOVED LEAD WIPE @ MAIN. INSTALLED 4' 3/4" COPPER. REMOVED FROM FREEZE-UP. | Installation Record | Y | 1/1/2009 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2758 | 901 W MCMILLAN ST | N | C | UNK | 1" | 1/1/1994 | C | 1" | 1/1/1994 | O | UNK | C | 1" | UNK | <Null> | Installation Record | Y | 1/1/1994 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2762 | 721 N PLUM AVE | N | C | UNK | 1" | 1/1/1965 | C | 1" | 1/1/1965 | SF | UNK | C | 1" | UNK | 1-1-2020 J&R VACUUM EXCAVATED @ CB, FOUND 1" COPPER 6'2" DEEP | Installation Record | Y | 1/1/1965 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2767 | 804 N CEDAR AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | N | | | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2771 | 510 N PEACH AVE | N | C | Y | 1" | 6/26/2023 | C | 1" | 6/26/2023 | SF | UNK | C | 1" | UNK | 6/26/23: Mu removed lead from wm-cs. Replaced w/ 1" corp, 1" copper. Meyers replaced lead from cs-meter w/ 1" copper, 1" cs & box. | Installation Record | Y | 6/26/2023 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2776 | 112 W HARRISON ST | N | C | UNK | 3/4" | 1/1/2007 | C | 3/4" | 1/1/2007 | SF | UNK | C | 3/4" | UNK | 2007-INSTALLED NEW COPPER FROM CORP TO TERRACE | Installation Record | Y | 1/1/2007 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2780 | 711 N CHERRY AVE | UNK | UNK-LG | UNK | UNK | 1/1/1965 | C | UNK | 1/1/1965 | SF | UNK | C | UNK | UNK | SERVICE COMES OFF OF FOREST | Installation Record | Y | 1/1/1965 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2783 | 411 E 20TH ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1978 | C | 3/4" | 1/1/1978 | SF | UNK | C | 3/4" | UNK | MEYERS | Installation Record | Y | 1/1/1978 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2798 | 912 S CEDAR AVE | N | C | Y | 1" | 10/12/2022 | C | 1" | 10/12/2022 | SF | UNK | C | 1" | UNK | 10/12/22: Removed lead from wm-cs and replaced w/ 1" copper and new 1" cs & box. Used existing corp., connected to existing 3/4" copper on customers side. | Installation Record | Y | 10/12/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2805 | 701 N PLUM AVE | N | C | Y | 3/4" | 5/19/2022 | C | 3/4" | 5/19/2022 | SF | UNK | C | 3/4" | UNK | 5/19/22: Pg. 3 of construction report. Installed new 1" corp., 18" - 1" copper, connected to existing 3/4" copper @ main. (no lead) | Installation Record | Y | 5/19/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2812 | 313 E FRANKLIN ST | N | C | UNK | 1" | 6/15/2022 | C | 1" | 6/15/2022 | SF | UNK | C | 1" | UNK | Pg. 15 of Construction Report. Installed 1" corp., 1" copper and 1" cs & box. Connected to existing 3/4" copper after cs. | Installation Record | Y | 6/15/2022 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2815 | 210 N ASH AVE | N | C | UNK | 3/4" | 1/1/2015 | C | 3/4" | 1/1/2015 | SF | UNK | C | 3/4" | UNK | 2015-INSTALLED COPPER FROM MAIN TO CURB VALVE/BOX | Installation Record | Y | 1/1/2015 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |

| Site ID | Locational Identifier | Lead Gooseneck Currently Present? | Current Street Side Service Line Material | Was Street Side Service Line Material Ever Previously Lead? | Street Side Service Line Size | Street Side Service Line Install Date | Current Property Side Service Line Material | Property Side Service Line Size | Property Side Service Line Install Date | Building Type | Point-of-Entry or Point-of-Use Treatment Present? | Building Plumbing Material 1 | Building Plumbing Material 2 | Building Plumbing Material Install Date | Comments | Basis of Street Side Material Classification | Was Street Side Material Field Verified? | Date of Street Side Field Verification, if Applicable | Method of Street Side Field Verification, if Applicable | Basis of Property Side Material Classification | Was Property Side Material Field Verified? | Date of Property Side Field Verification, if Applicable | Method of Property Side Field Verification, if Applicable | Notes on Basis of Material Classification |
|---------|-----------------------|-----------------------------------|---|---|-------------------------------|---------------------------------------|---|---------------------------------|---|---------------|---|------------------------------|------------------------------|---|--|--|--|---|---|--|--|---|---|---|
| 2821 | 406 E 20TH ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CB LOCATION VERIFIED 8/18/97 | Installation Record | Y | 8/18/1997 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2824 | 1708 S MAPLE AVE | N | UNK-LG | UNK | UNK | 1/1/1947 | C | UNK | 1/1/1947 | SF | UNK | C | C | | REMOVED LEAD WIPES & LEAD 1989 | Installation Record | Y | 1/1/1989 | Mech excav | Field Inspection Only | Y | 4/29/2013 | Cross Connection Survey | |
| 2830 | 506 N CEDAR AVE | N | C | Y | 3/4" | UNK | C | 3/4" | UNK | SF | UNK | C | 3/4" | UNK | LV/CB UNKNOWN. 6/22: Dug @ the wm and found 3/4" copper. (No Lead) | Installation Record | Y | 6/1/2022 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2833 | 415 E FOREST ST | N | UNK-NOLG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | | Installation Record | Y | | Mech excav | Previous eval | Y | 2013-2018 | Cross Connection Survey | |
| 2836 | 711 N CHESTNUT AVE | UNK | UNK-LG | UNK | UNK | UNK | C | UNK | UNK | SF | UNK | C | UNK | UNK | CB/LV UNKNOWN | Installation Record | Y | | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2839 | 1003 S MAPLE AVE | N | UNK-LG | UNK | UNK | UNK | C | 3/4" | UNK | SF | UNK | G | UNK | UNK | INSTALLED NEW CURB VALVE/BOX, CONNECTED TO 3/4" IRON-2015 | Installation record | Y | 1/1/2015 | Visual insp during install or repair | Previous eval | Y | 1/1/2015 | Cross connection survey | |
| 2842 | 101 W 4TH ST | N | C | UNK | 2" | 1/1/2013 | C | 2" | 1/1/2013 | NONRES | UNK | C | 2" | UNK | ATTACHED TO 2" COPPER | Installation Record | Y | 1/1/2013 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2855 | 1712 S MAPLE AVE | N | L | UNK | UNK | 1/1/1946 | C | UNK | 1/1/1946 | SF | UNK | C | UNK | 1/1/1946 | 2009-REMOVED LEAD WIPE @ MAIN. INSTALLED CURB STOP W/ BOX AND 5" COPPER UNDER STORM SEWER. | SL repair/replace record | Y | 2009 | Mech excav | Field inspection only | Y | 5/22/2017 | Cross Connection Survey | |
| 2858 | 1603 S MAPLE AVE | N | C | UNK | 1" | 9/23/2024 | C | UNK | 1/1/1922 | SF | UNK | C | C | | 9/23/24: Installed 1" corp w/ saddle, 1" copper, 1" cs & box. Connected to existing 3/4" copper. | SL repair/replace record | Y | 9/23/2024 | Visual insp during install or repair | Field Inspection Only | Y | 9/23/2024 | Visual Insp during install or repair | |
| 2862 | 1114 N WALNUT AVE | N | C | UNK | 1" | 1/1/1975 | C | 1" | 1/1/1975 | SF | UNK | C | 1" | UNK | 2003-NEW 1" CORP CONNECTED TO EXISTING 1" COPPER. 1-1/2" S OF VALVE | Installation Record | Y | 1/1/1975 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2866 | 309 E EDISON ST | N | C | UNK | 1" | 8/23/2023 | C | 1" | UNK | SF | UNK | C | 1" | UNK | Installed new 1" corp, 1" copper, 1" cs & box. Connected to existing 3/4" copper 6' North of CS. See sheet 18 of the construction report | Installation Record | Y | 8/23/2023 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2874 | 500 S CENTRAL AVE | N | C | UNK | 1 1/2" | 1/1/2009 | C | 1 1/2" | 1/1/2009 | NONRES | UNK | C | 1 1/2" | UNK | INSTALLED 1-1/2" INTO BLDG. A-1 EXCAVATING MEYERS | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |
| 2879 | 406 W LEONHARD ST | N | UNK-NOLG | UNK | 3/4" | 1/1/1974 | C | 3/4" | 1/1/1974 | SF | UNK | C | 3/4" | UNK | | Installation Record | Y | 1/1/1974 | Mech excav | SL repair/replace record | Y | 2013-2018 | Cross Connection Survey | |
| 2884 | 100 E 14TH ST | N | C | UNK | 1" | 1/1/2009 | C | 1" | 1/1/2009 | NONRES | UNK | C | 1" | UNK | A-1 EXCAVATING. 7' FROM BOX TO 3/4" COPPER | Installation Record | Y | 1/1/2009 | Mech excav | Installed after lead ban | Y | 2013-2018 | Cross Connection Survey | |